

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9586B - III

Kr 03

Not Authored

11 Sep @ 1650h

ROEL

Vehicle No.:
 Chassis No.:
 Date of Accident :
 Vehicle Make:
 Vehicle Model:
 Third Party Insurer :

SHD 9586B - ROEL
 KL1LA69RJB106871
 22.04.2015
 CHEVROLET
 CHEVROLET EPICA 2.0
 III

PART			LIST		
1	1	Rear Fender RH	\$	R 1,145.00	X
2	1	Rear Fender Inner Cowling RH	\$	su 76.60	X
3	1	Rear Tail Lamp RH	\$	su 479.30	X
4	1	Bootlid	\$	R 973.00	X
5	1	Bootlid inner trim board	\$	su 400.00	X
6	1	Bootlid Weatherstrip	\$	su 344.28	X
7	1	Bootlid Lock - Top	\$	R 466.56	X
8	1	Bootlid 'CHEVROLET' Badge	\$	nn 120.62	X
9	1	Bootlid Logo	\$	nn 138.84	X
10	1	Bootlid 'EPICA LT' Badge	\$	nn 119.84	X
11	1	Bootlid Reflector Centre	\$	su 217.97	X
12	1	Bootlid Reflector RH	\$	su 128.40	X
13	1	Bootlid Reflector LH	\$	su 128.40	X
14	1	Rear Bumper	\$	Bulcra 1,202.00	✓
15	1	Rear Bumper Beam	\$	R 239.94	X
16	1	Rear Bumper Centre Absorber	\$	su 260.00	X
17	1	Rear Bumper Side Retainer RH	\$	cm 68.76	✓
18	1	Rear Bumper Reflectors RH	\$	su 119.74	X

TOTAL	\$	6,629.25
10%	\$	662.93
	\$	5,966.33

Special Nett

1Set	Rear Bumper Parking Sensor	\$	su 300.00	X
1 Set	Rear Bumper Fastener Clip	\$	nn 30.00	✓
1 Set	Rear Fender Liner Clip	\$	nn 30.00	X
2	Rear Windscreen Sealant	\$	nn 100.00	X
1	Rear Windscreen Inner Sponge Seal	\$	nn 80.00	X
1	Rear Tyre RH	\$	su 360.00	X
1	Rear Wheel Rim RH	\$	su 254.00	X
1	Hub Cup Rim	\$	su 35.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9586B - III**ROEL**

1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00 <i>X</i>
1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00 <i>X</i>

TOTAL	\$	1,249.00
--------------	-----------	-----------------

TOTAL PARTS	\$	7,215.33
--------------------	-----------	-----------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 <i>400</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
Putty and Spray Painting Of The Affected	\$	2,700.00 <i>400</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>100</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>X</i>
To transfer of boot fittings and conduct water seepage test.	\$	170.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 <i>60</i>

TOTAL	\$	6,790.00
--------------	-----------	-----------------

Over All Total	\$	14,005.33
-----------------------	-----------	------------------

REPAIR DAYS**10 DAYS***2 days*