

WINE CA TOP

1/8/2010

INS. CASE OWNER:

Dolly Ann

CC3 /AIG1500 7002

1 Kua34

LKK:  
IDAC:

Surveyor:

ICENTVETH

DOI:

21-04-15

Date / Time:

28-04-15  
21-04-15

Registered in Merimen:

24-04-15

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKM 2247 T.

Claim No.:

785370788 SG

Name of Insured:

Daimler South East Asia P/L

Policy No.:

0999995587

Insured Tel No.:

HP:

Make / Model:

Mercedes-Benz C160

Excess Sec II :SS

D.O.A:

19-04-15

Place of Accident:

Junction of Meon Highway & Mountbatten

Is driver the owner? ( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Shirley Chong Kuan Mun

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

9239816

(V/L: YES / NO Insured Liability:

% Final ? Yes / No

SHO 9749 Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans-Cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver's Own Vehicle Number:

Insurance Company:

SHO 9749 Z X; SKM 2247 T X

STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA:

Medical Bill:

Approval Email:

Payment Breakdown Form:

Others:

13-07-16

BASED ON DAMAGE PROFILE, IMPACT MORE ON LEFT REAR BUMPER  
END, SO LIABILITY SHOULD BE 50-50% None in favor % UNLESS  
HE HAS CCTV FOOTAGE AS EVIDENCE, STILL SUBJECT TO TP's  
ACCEPTANCE.

RECEIVE accident photo Review File.

10-03-17

Based on the scene photo it clearly indicated THAT TAXI'S  
POSITION IS SLANTING FROM RIGHT LANE TO LEFT WHICH  
SUPPORTS OI'S VERSION.

05-04-17

SCENE PHOTO LIKELY SHOW THAT TAXI WAS CUTTING LANE FROM  
RIGHT TO LEFT, THEREFORE TO REJECT IST.

temporary close

RECEIVED 19 JUN 2018

COPY SENT  
19/6/18

FINAL SETTLEMENT		Date :	Confirm with		
Repair Cost:	SS		Final Liability:	50 % (Agreed / Assessed)	BOLA S/N No. : NCL
Loss of Rental:	SS	( days)			If NO or B 28, Ass. Lia :
Loss of Use:	SS	(\$ x days)		1) Claim status: Normal/Reject/Private Settle	
Disbursement:				2) Report Format: W/P	
Legal Cost :	SS			3) Survey fee: \$250.00	
Total:	SS		Global Sum: SS		

ASS. REC. BY:

REF:

AIG/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 97492Yr Regn: 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perodua

Latitude

C.C

1995Colour: M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading: 203385

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VIFIABL15AUC. 276168

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Feikon 215/60R16R: Perodua

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 5 mmL/Bal. 6 mmL/Bal. 5 mmD.O.A. 19/4/15D.O.I. 21/4/15

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/12

4917.35 Confirm Tariff  
Avail for injury claim

(47 1/2 x 132.68)

Global by 2850 KIV

(Red - \$ 23218.07 / 857.2)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG15007002/Kua3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 24-04-2015



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 2247T	Veh. Inspected	SHD 9749Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/04/2015

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	19/04/2015	Inspection Date	21/04/2015
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**CLEAR (AUTO CLAIM PD & BI TECHNICAL REPORT)**

File Handler :

File Reference Number:

Insured Version of Accident:

Third Party Version of Accident:

Liability Assessment:

Police Investigation Result: No

**Exposure:**

OD:

Reserves / Settled

: /

PD:

Reserves / Settled

: /

BI:

Reserves / Settled

: /

**TOTAL**

Reserves / Settled

: /

Management Alert : Yes/No –

Major Loss Report : Yes/No –

**Suspected Fraud: Yes / No -**

If "Yes", please attach Red Flag Checklist.

**US Citizen: Yes/No -**

If "Yes", provide the following data:

1. First Name:
2. Last Name:
3. Passport Number:
4. Social Security Number:

**Coverage:**

1. Name Driver Policy In order: Yes / No.

If "No", please provide details:

2. Policy Effective Dates:
3. Date of Loss:
4. Coverage Provided: Comp / TPFT / TP only
5. Breach of Policy T & C: Yes / No.

If "Yes", please comment:

REFER TO MERIMEN

**Independent Evidence:** Yes / No

**Insured Engaged:** Yes / No. -

**Investigation Firm Appointed:**

**Surveyor/Re-surveyor Appointed:** LKK

Claim Advice on Feature:

Make/Model/Year:

TP Survey Report (SR):

Days Recommended for Repairs:

TP Workshop Name:

Workshop Quantum:

COR = \$

LOR/U = \$

SR Fees = \$

LTA/GIA/TP search Fee = \$

Legal cost & Incidentals = \$

Total = \$

Global Sum = \$

**Claims Examiner's Comments:**

Claim Advice on Feature: C (TPBI)

Bodily Injuries / Quantum:

Claimant's Name:

Gender/ Age:

Occupation/Salary:

Hospital / Clinic Medical Report obtained from:

Doctor's Clinical Observation:

Doctor's Diagnosis:

Medical Leave Period:

Further Follow Up:

Injury Quantum:

General Damages =

(specify injuries/damages)

Special Damages =

(specify damages)

Disbursements =

Costs & incidentals =

Total =

**Recovery / Subrogation:**

**Reason WOS Issued:**

**File Handler's Recommendations:**

**Action Plan:**

**Comments:**

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 9749Z - AIG****ROEL***Not Authorised**1-B1**84917.35*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 9749Z - ROEL**

VF1ABL15AUC276168

RENAULT

LATITUDE

19.04.2015

**AIG**

<b>PART</b>			<b>LIST</b>	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 710.55 —
2	1	BUMPER LOWER REAR	\$	<i>D.I</i> 492.84 —
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 72.74 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>NIP</i> 87.16 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 28.84 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 27.96 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>NIP D.I</i> 87.16 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>D.I</i> 28.84 —
9	1	BUMPER BEAM REAR	\$	<i>R</i> 498.41 X
10	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 144.84 X
11	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 144.84 X
12	1	FENDER PANEL REAR LH	\$	<i>Bu</i> 2,114.83 —
13	1	WHEELARCH REAR LH	\$	<i>Sm</i> 348.38 X
14	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	<i>R</i> 1,948.10 X
15	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sm</i> 430.42 X
16	1	BOOT REAR	\$	<i>R</i> 1,841.46 X
17	1	BOOT FINISHER (Moulding)	\$	<i>Sm</i> 358.25 X
18	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 207.08 X
19	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 316.25 X
20	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 316.25 X
21	1	BOOT BADGE 'RENAULT'	\$	<i>Nu</i> 144.46 X
22	1	BOOT BADGE	\$	<i>Nu</i> 144.46 X
23	1	TAILLAMP LH	\$	<i>Sm</i> 354.20 X
24	1	TAILLAMP PANEL LH	\$	<i>R</i> 632.50 X
25	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 1,403.77 X
26	1	SPARE WHEEL PANEL TRIM	\$	<i>Sm</i> 392.44 X
27	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 943.44 X
28	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 259.33 X

<b>TOTAL</b>	<b>\$</b>	<b>14,479.80</b>
<b>10%</b>	<b>\$</b>	<b>1,447.98</b>
	<b>\$</b>	<b>13,031.82</b>

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 9749Z - AIG****ROEL****Specical Nett**

1SET	PARKING AID	\$	600.00 X
1SET	REAR BUMPER CLIP	\$	66.00
1SET	BUMPER BRACKET CTR CLIP	\$	33.00
1SET	BUMEPB BRACKET SIDE CLIP LH RR	\$	10.00 X
1SET	BUMEPB RETAINER LH CLIP RR	\$	20.00 X
1SET	BUMPER LOWER REAR CLIP	\$	66.00
1SET	BUMPER BEAM BOLT	\$	33.00 X
1SET	WHEELARCH CLIP REAR LH	\$	45.00 X
1	BOOT STICKER "Trans-cab"	\$	30.00 X
1	BOOT STICKER "6555-3333"	\$	30.00 X
2	Rear Windscreen Sealant	\$	80.00 40.00
1	Rear Windscreen Inner Sponge Seal	\$	150.00 30.00
1	RIM (ROUE 7J 16H 2547)LH RR	\$	385.00 X
1	TYRE LH RR	\$	330.00 X
1	CAP HUB LH REAR	\$	35.60 X

**TOTAL \$ 1,913.60****TOTAL PARTS \$ 14,945.42**

Putty And Spray Painting Of The Affected Portion. \$ 5,400.00 700

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 6,000.00 600

To Rust-Proofing Of The Affected Areas. \$ 170.00 30

To reinstall rear bumper parking sensor. \$ 170.00 60

To transfer of bootlid fittings, attachments and perform water seepage test. \$ 170.00 X

To check steering geometry and computer wheel alignment \$ 220.00 X



**TRANS-CAB AUTO SERVICES PTE LTD****ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 9749Z - AIG**

To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 ^
To transfer of door fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 100%
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 100%
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X

**TOTAL \$ 13,190.00****Over All Total \$ 28,135.42****Repair Days****4-20 Days  
(PARTS BY PARTS)**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To supply damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No liability for claims is allowed
- Supplemental survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Accident Scene Photo



## Thin Thin (LKKAUTO)

**From:** Thin Thin (LKKAUTO)  
**Sent:** Monday, 18 June 2018 8:48 PM  
**To:** Mei Kwan (LKKAUTO); Dally Amri, Mimi Zarina  
**Cc:** PRDSG.DFILE; Admin A; Vivian Lau (LKKAUTO); KKLau  
**Subject:** RE: #7851370788SG#027#PD claim\_SHD9749Z DOA; 19/04/2015 \*\*\* LKK REF: CC3/AIG15007002/Kua3

Dear Sir / Madam,

We refer to the below matter.

Please be inform that we have offered 50% liability to TP.

TP's repairer did not submit the LOD until now. In view of no further development, we will proceed to temporary close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly.

Thank you,

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Monday, 21 May 2018 3:48 PM  
**To:** Dally Amri, Mimi Zarina <MimiZarina.DallyAmri@aig.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>  
**Cc:** PRDSG.DFILE <PRDSG.DFILE@aig.com>; Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>  
**Subject:** RE: #7851370788SG#027#PD claim\_SHD9749Z DOA; 19/04/2015 \*\*\* LKK REF: CC3/AIG15007002/Kua3

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC3/AIG15007002/Kua3	Thin Thin - 6841 2360

Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Dally Amri, Mimi Zarina [<mailto:MimiZarina.DallyAmri@aig.com>]

**Sent:** Monday, 21 May, 2018 11:07 AM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** PRDSG.DFILE <[PRDSG.DFILE@aig.com](mailto:PRDSG.DFILE@aig.com)>

**Subject:** #7851370788SG#027#PD claim\_SHD9749Z DOA; 19/04/2015

Dear LKK

We would like to acquire progress and updates of this case as it is still not close for quite some time.

Thank you.

Regards,

Mimi Zarina @ Mimi

AIG

Express Claims Adjuster

Claims Operations | AIG Shared Services

**IMPORTANT NOTICE:**

The information in this email (and any attachments hereto) is confidential and may be protected by legal privileges and work product immunities. If you are not the intended recipient, you must not use or disseminate the information. Receipt by anyone other than the intended recipient is not a waiver of any attorney-client or work product privilege. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[MimiZarina.DallyAmri@aig.com](mailto:MimiZarina.DallyAmri@aig.com) | [www.AIG.com](http://www.AIG.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG15007002/Kua3

19 JULY 2016

**DAIMLER SOUTH EAST ASIA PTE LTD**

3 TEMASEK AVENUE  
#27-01 CENTENNIAL TOWER  
SINGAPORE 039190  
ATTN: MANAGEMENT

Dear Sir/Madam,

**ACCIDENT INVOLVING SKM 2247T & SHD 9749Z ON 19/04/2015**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 29/07/2016, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
Fax: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2015 20:07 <a href="#">Edit Reg</a>		21 Apr 2015 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,917.35</b> <a href="#">Edit Estimates</a>	<b>S\$4,917.35</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [\[Created by adjuster\]](#)

Insured:	<b>DAIMLER SOUTH EAST ASIA PTE LTD</b> , Co. Reg. No.: 199000355E			
Main Claimant:	<b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K			
Vehicle Reg. No.:	<b>SHD9749Z</b>	Date of Loss:	19/04/2015 20:00 - :59 <b>[16 Months and 15 Days From LTA Reg Date (Man Yr)]</b>	
Claim Type:	<b>TP / 7851370788SG</b>	Policy/Cover Note No.:	0999995587 (Comprehensive) Coverage: 01/01/2015 - 31/12/2015	
Vehicle Reg. No. (Insured):	<b>SKM2247T</b>	Policy No. (Claimant):	D-12047359MFSH/4268	
	Excess:			
Repairer:	<b>Trans-cab Auto Services Pte Ltd (HQ)</b> No. 42 Sungei Kadut St 1, 729346 Sungei Kadut - Tel: 62876666			
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Dally Amri, Mimi Zarina</b> ] MimiZarina.DallyAmri@aig.com			
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311			
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 06/05/2015]</b>			

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (14/11/2016): **claim status**
- AIG\_SG (13/10/2016): **pd claim status**
- AIG\_SG (15/09/2016): **pd claim status**
- AIG\_SG (20/07/2016): **Claim Status**
- AIG\_SG (16/06/2016): **Re: Claim Status**
- AIG\_SG (26/01/2016): **Claim Status**
- AIG\_SG (28/12/2015): **pd claim status**

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SHD9749Z (7851370788SG)  
[SKM2247T]**

**TP**

**TRANS-CAB SERVICES PTE LTD**

**Apr 19 2015 8:00PM**

**[DAIMLER SOUTH EAST ASIA PTE LTD]**

**Trans-cab Auto Services Pte Ltd**

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <span style="border: 1px solid black; padding: 0 5px;">View in Browser</span>
------------------	---------------	--------------------	--------------	--------------	--

  

Photos/Images				3 per page <span style="border: 1px solid black; padding: 0 5px;">v</span>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	24/04/15 20:05	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	24/04/15 20:05	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
4	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
9	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
10	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
11	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
12	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
13	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>
14	24/04/15 20:05	General View		Load JPG	<input checked="" type="checkbox"/>

  

Documentation				1 per page <span style="border: 1px solid black; padding: 0 5px;">v</span>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	27/04/15 09:59	TP ESTIMATE		Load PDF	
2	27/04/15 09:59	TP GIA REPORT		Load PDF	
3	25/06/18 14:45	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	27/04/15 12:19	OI GIA REPORT		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

  

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<span style="font-size: 1.2em;">^</span> <span style="font-size: 1.2em;">v</span>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG15007002/KUA3Q2

Date: 25/06/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995587  
**Claimant Vehicle No :** SHD9749Z **Insured Vehicle No :** SKM2247T  
**Date of Loss:** 19/04/2015 **Nature of Claim:** TP **Claim No:** 7851370788SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

**Reg No:** SHD9749Z  
**Make & Model:** RENAULT LATITUDE, 2.0 D dCi (A) **Engine No:** M9R8839C000727  
**Reg. Date:** 04/12/2013 (Man. Year: 2013) **Chassis No:** VF1ABL15AUC276168  
**Colour:** Metallic White/Red **Odometer:** 203385 km  
**Engine Capacity:** 1995 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

## CONDITION OF TYRES

**Front Tyre Size:** 215/60 R16 **Rear Tyre Size:** 215/60 R16  
**Front Left Side:** Falken 6 mm **Rear Left Side:** Rovelo 5 mm  
**Front Right Side:** Falken 6 mm **Rear Right Side:** Rovelo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,945.42	3,247.35	11,698.07	78.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,190.00	1,670.00	11,520.00	87.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>28,135.42</b>	<b>4,917.35</b>	<b>23,218.07</b>	<b>82.52</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,969.48</b>	<b>344.21</b>	<b>1,625.27</b>	<b>82.52</b>
<b>Nett Amount (S\$)</b>	<b>30,104.90</b>	<b>5,261.56</b>	<b>24,843.34</b>	<b>82.52</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

**Date of Assignment:** 21/04/2015  
**Date Inspected:** 21/04/2015 **Inspected At:** Trans-cab Auto Services Pte Ltd (HQ)  
 No. 42 Sungei Kadut St 1  
 Singapore 729346  
**Estimated Period of Repair:** 4.0 days

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	710.55 FL	*710.55 FL
2	1		*BUMPER LOWER REAR	Distorted	492.84 FL	*492.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	72.74 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	No such part	87.16 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	28.84 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	27.96 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	No such part	87.16 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Distorted	28.84 FL	*28.84 FL
9	1		*BUMPER BEAM REAR	Repair	498.41 FL	*- FL
10	1		*BUMPER BEAM BRACKET LH REAR	Repair	144.84 FL	*- FL
11	1		*BUMPER BEAM BRACKET RH REAR	Repair	144.84 FL	*- FL
12	1		*FENDER PANEL REAR LH	Buckled	2,114.83 FL	*2,114.83 FL
13	1		*WHEELARCH REAR LH	Serviceable	348.38 FL	*- FL
14	1		*FENDER WHEEL HOUSE PANEL REAR LH	Repair	1,948.10 FL	*- FL
15	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	430.42 FL	*- FL
16	1		*BOOT REAR	Repair	1,841.46 FL	*- FL
17	1		*BOOT FINISHER (MOULDING	Serviceable	358.25 FL	*- FL
18	1		*BOOT WEATHERSTRIP	Serviceable	207.08 FL	*- FL
19	1		*BOOT REFLECTOR LAMP LH	Serviceable	316.25 FL	*- FL
20	1		*BOOT REFLECTOR LAMP RH	Serviceable	316.25 FL	*- FL
21	1		*BOOT BADGE RENAULT	Not Necessary	144.46 FL	*- FL
22	1		*BOOT BADGE	Not Necessary	144.46 FL	*- FL
23	1		*TAILLAMP LH	Serviceable	354.20 FL	*- FL
24	1		*TAILLAMP PANEL LH	Repair	632.50 FL	*- FL
25	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,403.77 FL	*- FL
26	1		*SPARE WHEEL PANEL TRIM	Serviceable	392.44 FL	*- FL
27	1		*OUTER PANEL REAR (END PANEL)	Repair	943.44 FL	*- FL
28	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	259.33 FL	*- FL
29	1		*SET PARKING AID	Serviceable	600.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
31	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
32	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
33	1		*SET BUMPER RETAINER LH CLIP RR	Not Necessary	20.00 FS	*- FS
34	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
35	1		*SET BUMPER BEAM BOLT	Serviceable	33.00 FS	*- FS
36	1		*SET WHEELARCH CLIP REAR LH	Not Necessary	45.00 FS	*- FS
37	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
38	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
39	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	150.00 FS	*30.00 FS
41	1		*RIM (ROUE 7J 16H 2547)LH RR	Serviceable	385.00 FS	*- FS
42	1		*TYRE LH RR	Serviceable	330.00 FS	*- FS
43	1		*CAB HUB LH REAR	Serviceable	35.60 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,393.40 3,582.06

- List Item Discount on L Items 10.00/10.00% (\$\$) 1,447.98 334.71

Total Parts (\$\$) 14,945.42 3,247.35

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	5,400.00	700.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	660.00
3	TO RUST-PROOFING THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	100.00
10	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
11	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>13,190.00</b>	<b>1,670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >