

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 9714J - CHINA

ROEL

Not Arhenz

*1-B,
 83045.98*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 9714J - ROEL
VF1ABL15AUC273336
RENAULT
LATITUDE
28.04.2015
CHINA

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 807.32 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 253.00 X
3	1	BUMPER BEAM FRT	\$	<i>n</i> 585.95 X
4	1	BUMPER RETAINER FRT RH	\$	<i>Sm</i> 97.06 X
5	1	BUMPER SUPPORT FRT RH	\$	<i>Sm</i> 15.31 X
6	1	BUMPER RETAINER FRT LH	\$	<i>Di</i> 97.06 ✓
7	1	BUMPER SUPPORT FRT LH	\$	<i>Sm</i> 15.31 X
8	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 132.83 X
9	1	AIR CLEANER LOWER	\$	<i>Sm</i> 226.05 X
10	1	LOWER ARM LH	\$	<i>Sm</i> 439.59 X
11	1	KUNCKLE ARM LH	\$	<i>Sm</i> 542.94 X
12	1	KUNCKLE HUB+BEARING LH	\$	<i>nn</i> 319.03 X
13	1	ABSORBER FRT LH	\$	<i>Sm</i> 231.12 X
14	1	ABSORBER DUST COVER	\$	<i>Sm</i> 146.61 X
15	1	BONNET	\$	<i>n</i> 1,244.63 X
16	1	RADAITOR GRILLE	\$	<i>Sm</i> 1,094.73 X
17	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>nn</i> 144.46 X
18	1	RADAITOR GRILLE FRAME	\$	<i>Sm</i> 867.79 X
19	1	FRAME FULL SUPPORT PANEL	\$	<i>n</i> 394.81 X
20	1	HEADLALMP LH	\$	<i>mjers</i> 759.25 ✓
21	1	FENDER PANEL FRT LH	\$	<i>Bu</i> 502.46 ✓
22	1	FENDER WHEELARCH FRT LH	\$	<i>Div</i> 89.44 ✓
23	1	DOOR MIRROR LH	\$	<i>Sm</i> 950.90 X
24	1	DOOR PANEL FRT LH	\$	<i>n</i> 1,823.50 X
25	1	DOOR SEAL FRT LH	\$	<i>Sm</i> 46.68 X

TOTAL	\$	11,827.83
10%	\$	1,182.78
	\$	10,645.05

Specical Nett

1SET FRONT BUMPER CLIP

\$

nn 66.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 9714J - CHINA

ROEL

1SET	BUMPER RETAINER CLIP FRT LH	\$	<i>nn</i> 15.20 X
1SET	WHEELARCH CLIP LH	\$	<i>nn</i> 66.00 ✓
1	RIM LH FRT	\$	<i>nn</i> 385.00 X
1	TYRE LH FRT	\$	<i>nn</i> 330.00 X
1	CAP HUB LH FRT	\$	<i>nn</i> 35.00 X
1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X
1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X

TOTAL	\$	1,007.20
TOTAL PARTS	\$	11,652.25

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

Putty and spray painting of the affected portion.

\$ 3,000.00 *400*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 *60*

To transfer of door fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

To check brake efficiency, final checking and testing.

\$ *nn* 380.00 X

To rust-proofing of the affected areas.

\$ 170.00 *30*

TOTAL \$ 7,080.00

Over All Total \$ 18,732.25

(PARTS BY PARTS) Repair Days

10 DAYS
2 days