

Police Station Of Origin:

Nanyang N.P.C

2 Jurong West Avenue 5 SINGAPORE 649482

Tel No: 1800-7929999



T/20150617/2142

1 of 3

Report No T/20150617/2142

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/06/2015 19:09	Vide Report No.:	Station Diary No.: 112
--	------------------	---------------------------

Name of Informant: AHMAD SYAHID BIN SANIF	Address: APT BLK 180A RIVERVALE CRESCENT #08-331 SINGAPORE 541180
--	---

ID Type / ID No.: NRIC NO / S9538011E	Contact No.: Home/Office: Mobile: 84397714
--	---

Nationality: SINGAPORE CITIZEN	Email:
-----------------------------------	--------

Sex: Male	Age: 19	Date of Birth: 18/10/1995	Type of Informant: Driver
--------------	------------	------------------------------	------------------------------

Race: Malay	Language:	Institution / School Name:
----------------	-----------	----------------------------

Occupation: TRANSPORT OPERATOR	Driving Licence Information: Class: 3	Date of Expiry:
-----------------------------------	--	-----------------

Type of Accident: Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 17/06/2015 11:30	Type of Location: Roundabout
Location: Along Road 1 Traveling Towards Road 2 STADIUM WALK STADIUM DRIVE Stadium Walk towards Stadium Drive (Tanjung Rhu)			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No

Vehicle No.	Vehicle Type	Damage	No. of Injuries
MID46212	MUV Transporter	Slightly Damaged	10
SJC3845A	Car	Slightly Damaged	1

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE 649482
Tel No: 1800-7929999



T/20150617/2142

2 of 3

Report No. T/20150617/2142

CONTINUATION OF REPORT

Name	AHMAD SYAHID BIN SANEF		ID No.	S9538011E
Related Vehicle	NIL		Contact No.	84397714
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL		Degree of Injury	NIL
Name	Tan Lee Leng		ID No.	S8742876A
Related Vehicle	NIL		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL		Degree of Injury	NIL

Brief Details.

On the 17.6.2015 at about 1130hrs, I was driving my military vehicle, MID 46212 in the stadium roundabout towards Tanjung Rhu. I later entered the third lane nearest to the exit. While turning left in the roundabout, a civilian vehicle, SJC 3845A driven by Tan Lee Leng, S8742876A was on the second lane in the roundabout trying to exit into the stadium boulevard. Tan Lee Leng did not attempt to brake to avoid the collision. her vehicle then grazed against the right rear of the military vehicle and it continued dragging towards the right side of the military vehicle as Tan Lee Leng was trying to exit Stadium Boulevard. No injury was sustained, vehicle suffered slight dent at the right side of the vehicle between the two tyres.

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE 649482
Tel No: 1800-7929999



T/20150617/2142

3 of 3

Report No. T/20150617/2142

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/
Siah Jun Jie

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
17/06/2015 19:09

Officer In Charge Of Case:
TP / GIA /
Esther Chong
Contact No.: 65476368

Classification Of Case:

Authentication Stamp
NP168



Signature :

SN 127

Singapore Police Force

Fy/15/16/0020



SMRT AUTOMOTIVE SERVICES PTE LTD
3 MO KIO STREET #2
SPORE 548140

Maintenance Engineering Support

100 Chu Kang Way, Singapore 68948
4, Kranji Camp 3

D. Sir,

T. of Repair: Accident Damaged / Mod
V. le No.: MID 4621
V. le Model: MB SPRINTER S15CDI/4315 TRANSPORTER
V. le Grouping: A / B
C. act Ref No.: 8013100664

Job carried out by SMRT Automotive Services Pte Ltd

T. Repair Labour Cost:	\$ 1,211.14	38.5 hrs @ \$ 31.64 per hr
S. Cost:	\$ 1,554.30	
T. Transportation Cost:	\$ 301.72	
1 Total Cost:	\$ 3,076.16	

D. try Period:	14	Days from date of Purchase Order (PO) Approval
V. ty Period:	90	Days from the date of quotation

Yours Faithfully,
S. Automotive Services Pte Ltd

NA: Brijesh
Amount: Executive

Authority Use Only:

Inspection of Reports	Ref No.	Date Created	Date Released	Released By: (Rank & Name)	Signed:
P. Request (PR) No.:					
P. Order (PO) No.:					

→ chbn
The fap not clear.
The Amount is
\$ 3,076.16

S151046Z
1W0 VENU S/O T SUPPIAH
TA INVESTIGATION WO
HQ TRANSPORT



SMRT AUTOMOTIVE SERVICES PTE LTD
 6 JIVO MO KIO STREET #2
 SINGAPORE 349140

Scope/ Inspection Report

Particulars of Vehicle

Type of Repair: Accident / Damaged / Mod
 Contract Ref No: 801310056
 Vehicle No.: MIO 46212
 Vehicle Model: MB SPRINTER 515CDI/4325 TRANSPORTER
 Vehicle Grouping: A / B

Chassis Number: WDB906687 25 589268
 Engine Number: 651955 30 79679
 Meter Reading: 3850

Inspected By:
 Date Inspected:

Robin Koh

18.06.2015

scope of work and total labour manhours are agreed by customer.

Total Labour Manhours: 38.5

Delivery Period: 14

Contractor Cost:

Transportation/ Towing Service: 2

Task ID	Job Description	Work Done	Quoted Hrs	Remarks
	Trade Jobs			
10	RH middle side moulding dented (No. 3)	RPL	0.5	
	Remove & install RH middle side moulding			
20	RH middle side moulding dented (No. 4)	RPL	0.5	
	Remove & install RH middle side moulding			
30	RH middle side moulding dented (No. 5)	RPL	0.5	
	Remove & install RH middle side moulding			
40	RH side signal lamp broken	RPL	0.5	
	Remove, install RH side signal lamp assembly & connect wiring			
50	RH rear tyre scratches	RPL	0.5	
	Remove & install RH rear tyre			
60	RH middle side panel dented	RPL	20	
	Remove, install rear cabin internal cabinet to facilitate repairs, panel beat on RH middle side panel			
70	Spray paint on repaired areas body	RPL & REP	16	
	Respray & putty on RH front to rear side panel			
	Total Hrs		38.5	
	Towing Service			
80	To provide towing service for above vehicle from Jurong Camp 2 (ITU) - to SMRT Workshop		\$ 151.86	
90	To provide towing service for above vehicle from SMRT Workshop to Jurong Camp 2 (ITU)		\$ 151.86	
	Total		\$ 303.72	

Legend: REP- Repair, RPL- Replace, INFO- Information Only



Particulars of Vehicle

Type of Repair:	Accident / Damaged / New
Contract Ref No:	401310056
Vehicle No.:	MID 46212
Vehicle Model:	MY SPHINTA R315CD/432S TRANSPORTER
Vehicle Grouping:	A / B
Chassis Number:	WOB90665 25 589258
Engine Number:	651955 30 99679
Odometer Reading:	3850

Mark Up Rate:
20%

[illegible]

Total:

Total Spare Price:	\$ 2894.30
Total Mark Up Price:	\$ 161.30
Max Allowable Mark Up:	\$ 161.30

Total Spare Price including allowable Mark Up Prices: \$ 1,354.80

RESTRICTED

fy/15/16/0020

PHOTOGRAPHS OF ACCIDENT



Picture B-1. Photo accident vehicle

RESTRICTED



Picture B-2. Photo showing rear left of the vehicle



Picture B-3. Photo showing rear back of the vehicle

RESTRICTED



Picture B-4. Photo showing the right side of the vehicle



Picture B-5. Photo showing the closed up damage of the vehicle (part 1)

RESTRICTED



Picture B-6, Photo showing the closed up damage of the vehicle (part 2)



Picture B-7, Photo showing the closed up damage of the civilian vehicle