

LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE
HQ-TRANSPORT COMMAND
KRANJI CAMP 3
151 CHUA CHU KANG WAY
SINGAPORE 688248

REF No. CC2/MIDA15010239

REF Date 09/12/2015

Code MIDA

DISBURSEMENT FEE

Vehicle No. **MID 46212**
Insured
Claim No FY 15/16/0020
Policy No
Accident Date 17/06/2015
Inspection Date

<u>LKK Cost of Claim paid to claimant on behalf of MINDEF</u>		
Repair Cost of SJC 3845A @50%	\$	1,083.50
Surveyor Fees	\$	160.50
Total Fee	\$	1,244.00

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "LKK AUTO CONSULTANTS PTE LTD".

LKK AUTO CONSULTANTS PTE LTD

KKH