

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5653Y - CHINA**RIZA***Not Authorised*
1.B.1

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5653Y - RIZA

VF1ABL15AUC281150

RENAULT

LATITUDE

03.07.2015

CHINA**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bur</i> 968.79 ✓
2	1	BUMPER SPOILER FRT	\$	<i>D/S</i> 139.81 ✓
3	1	BUMPER ABSORBER FRT	\$	303.60 ?
4	1	BUMPER BRACKET FRT LH	\$	<i>R</i> 116.47 X
5	1	BUMPER SUPPORT FRT LH	\$	<i>R</i> 18.37 X
6	1	BUMPER BRACKET FRT RH	\$	<i>R</i> 115.98 X
7	1	BUMPER SUPPORT FRT RH	\$	<i>R</i> 18.37 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sen</i> 363.71 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>D/S/Ref</i> 205.23 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sen</i> 159.39 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sen</i> 159.39 X
12	1	BUMPER BEAM FRT	\$	703.14 ?
13	1	RADAITOR GRILLE	\$	<i>CM</i> 1,313.68 ✓
14	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sen</i> 173.36 ✓
15	1	RADAITOR GRILLE FRAME	\$	<i>CM</i> 1,041.35 ✓
16	1	FRAME FULL SUPPORT PANEL	\$	473.77 ?
17	1	FRAME FULL SUPPORT BRACKET	\$	69.07 ?
18	1	FRONT BRACE PANEL	\$	<i>R</i> 136.32 X
19	1	SUBFRAME OUTER FRT	\$	<i>Sen</i> 2,040.34 X
20	1	HEADLAMP LH	\$	<i>Ref</i> 911.10 ✓
21	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 134.59 X
22	1	HEADLAMP RH	\$	911.10 ?
23	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 134.59 X
24	1	HORN L70Y LH	\$	<i>Sen</i> 241.67 X
25	1	HORN L70Y RH	\$	<i>Sen</i> 241.67 X
26	1	HORN BRACKET	\$	<i>R</i> 31.12 X
27	1	BONNET	\$	<i>R</i> 1,493.56 X
28	1	BONNET INSULATOR	\$	<i>Sen</i> 312.10 X
29	1	BONNET STRUT LH	\$	<i>Sen</i> 166.29 X
30	1	BONNET STRUT RH	\$	<i>Sen</i> 166.29 X
31	1	BONNET HINGE LH	\$	<i>R</i> 267.93 ✓
32	1	BONNET HINGE RH	\$	<i>R</i> 267.93 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5653Y - CHINA

RIZA

33	1	BONNET LOCK	\$	R	234.99 X
34	1	BONNET CABLE	\$	Sm	91.69 X
35	1	FENDER PANEL FRT LH	\$	R	602.95 X
36	1	FENDER PANEL FRT RH	\$	R	602.95 X
37	1	WHEELARCH FRT LH	\$	Sm	107.32 X
38	1	WHEELARCH FRT RH	\$	Sm	214.49 X
39	1	RADIATOR	\$		924.77 ?
40	1	ENGINE UNDERTRAY	\$	Sm	434.60 X
41	1	A/C CONDENSER	\$	Pur	1,554.13 ✓
42	1	TRANSMISSION COOLER	\$		852.66 ?
43	1	DOOR PANEL REAR LH	\$	R	2,188.20 X
44	1	DOOR SEAL REAR LH	\$	Sm	68.02 X
45	1	DOOR PANEL REAR RH	\$	R	2,188.20 X
46	1	DOOR SEAL REAR RH	\$	Sm	68.02 X
47	1	BUMPER COVER REAR	\$	Bt	852.66 ✓
48	1	BUMPER BRACKET CTR REAR	\$	CMT	87.29 ✓
49	1	BUMEPB BRACKET SIDE LH REAR	\$	Dis	34.61 ✓
50	1	BUMEPB RETAINER LH REAR	\$	NSP	104.59 X
51	1	BUMEPB BRACKET SIDE RH REAR	\$	Dis	34.61 ✓
52	1	BUMEPB RETAINER RH REAR	\$	NSP	104.59 ^
53	1	BUMPER LOWER REAR	\$	Bt	591.41 ✓
54	1	BUMPER BEAM REAR	\$	Bt	598.08 ✓
55	1	BUMPER BEAM BRACKET LH REAR	\$	Bt	173.81 ✓
56	1	BUMPER BEAM BRACKET RH REAR	\$	Bt	173.81 ✓
57	1	BUMPER REFLECTOR LH	\$	Sm	33.55 X
58	1	BUMPER REFLECTOR RH	\$	Bt	33.55 ✓
59	1	BOOT REAR	\$	Bt	2,209.75 ✓
60	1	BOOT FINISHER	\$		361.58 ?
61	1	BOOT LOCK	\$	net	155.90 ✓
62	1	BOOT LOCK CATCH	\$	Dis	57.23 ✓
63	1	BOOT WHEATERSTRIP	\$	Dis/bt	248.50 ✓
64	1	BOOT REFLECTOR LAMP LH	\$		379.50 ?
65	1	BOOT REFLECTOR LAMP RH	\$	CMT	379.50 ✓
66	1	BOOT BADGE 'RENAULT'	\$	net	173.35 ✓
67	1	BOOT BADGE	\$	net	173.35 ✓
68	1	BOOT STRUT LH	\$	Sm	212.36 X
69	1	BOOT STRUT RH	\$	Sm	212.36 X
70	1	BOOT HINGE LH	\$	R	282.96 X
71	1	BOOT HINGE RH	\$	R	282.96 X
72	2	LICENCE PLATE LAMP	\$	Sm	84.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5653Y - CHINA**RIZA**

73	2	BOOT RUBBER PLUG	\$	Sen 170.63 X
74	1	WINDSCREEN REAR	\$	Sen 1,125.60 X
75	1	TAILLAMP LH	\$	425.04 ?
76	1	TAILLAMP PANEL LH	\$	R 759.00 X
77	1	TAILLAMP RH	\$	Bu 425.04 ✓
78	1	TAILLAMP PANEL RH	\$	Bu 759.00 ✓
79	1	FENDER PANEL REAR LH	\$	R 2,537.80 X
80	1	FENDER PANEL REAR RH	\$	Bu 2,537.80 ✓
81	1	FENDER WHEELARCH REAR LH	\$	R 418.06 X
82	1	FENDER WHEELARCH REAR RH	\$	R 418.06 X
83	1	AIR VENT RH	\$	74.83 ?
84	1	FENDER PANEL INNER TRIM REAR RH	\$	De form 516.50 ✓
85	1	FENDER PANEL INNER TRIM REAR LH	\$	Sen 516.50 X
86	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	R 2,337.72 X
87	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	R 2,337.72 X
88	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu Bu 1,684.52 ✓
89	1	SPARE WHEEL PANEL TRIM (Luggage Floor Pan	\$	De form 470.93 ✓
90	1	OUTER PANEL REAR (End Panel)	\$	Bu 1,132.13 ✓
91	1	OUTER PANEL REAR (End Panel)TRIM	\$	De 308.48 ✓
92	1	EXHAUST REAR	\$	Bu 5,760.00 ✓
93	1	EXHAUST CAP REAR	\$	Bu 177.30 ✓
94	1	WINDSCREEN REAR	\$	Repair 1,125.60 X

TOTAL	\$	57,987.16
10%	\$	5,798.72
	\$	52,188.45

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	na 52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	na 66.00 ✓
3	1	TOW COVER FRT	\$	Sen 14.50 X
4	1SET	RADAIOR GRILLE SCREW	\$	na 16.00 ✓
5	1SET	BUMPER GRILLE LOWER CLIP	\$	na 69.00 ✓
6	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00 ✓
7	2	FRAME FULL SUPPORT PANEL NUT	\$	Sen 20.00 X
8	2	FRAME FULL SUPPORT PANEL STUD	\$	Sen 30.00 X
9	2	BONNET CABLE CLIP	\$	na 6.40 X
10	1SET	WHEELARCH CLIP LH	\$	na 30.50 X
11	1SET	WHEELARCH CLIP RH	\$	na 29.40 X
12	1SET	DOOR CASING CLIP	\$	na 6.40 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5653Y - CHINA**RIZA**

13	1SET	DOOR SEAL CLIP FRT RH	\$	na 18.50 X
14	1	DOOR STICKER "TRANS-CAB" LH	\$	na 80.00 X
15	1	DOOR STICKER "CLASSIC" LH	\$	na 30.00 X
16	1	DOOR STICKER "TRANS-CAB" RH	\$	na 80.00 X
17	1	DOOR STICKER "CLASSIC" RH	\$	na 30.00 X
18	1	RIM RH RR	\$	Sn 385.00 X
19	1	TYRE RH RR	\$	Sn 330.00 7
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn 385.00 X
21	1	SPARE TYRE	\$	Sn 330.00 X
22	1SET	WHEELARCH CLIP LH RR	\$	na 32.34 X
23	1SET	WHEELARCH CLIP RH RR	\$	na 32.34 X
24	1SET	PARKING AID	\$	Tn 600.00 ✓
25	1SET	BUMPER RR RIVET	\$	na 28.60 —
26	1SET	BUMPER RR CLIP	\$	na 66.00 —
27	1SET	REFLECTOR SCREW (Necessary)	\$	na 25.00 X
28	1SET	BUMPER BEAM BOLT (Necessary)	\$	Sn 22.22 X
29	2	DOOR STICKER "6555-3333" LH/RH	\$	na 160.00 X
30	1SET	BOOT FINISHER CLIP	\$	na 25.10 X
31	1	Rear boots sticker "trans-cab"	\$	na 30.00 —
32	1	Rear boots sticker "6555-3333"	\$	na 30.00 —
33	2	Rear windscreen sealant	\$	na 80.00 455N
34	1	Windscreen moulding	\$	na 100.00 305N
35	1	Rear Windscreen Inner Sponge Seal	\$	na 100.00 X
36	1	EXHAUST MOUNTING REAR	\$	Tn 65.50 —
37	1	EXHAUST BRACKET REAR	\$	R 22.22 X
38	1SET	Front licence plate with holder	\$	na 80.00 455N
39	1SET	Rear licence plate with holder	\$	na 80.00 455N

TOTAL	\$	3,658.02
TOTAL PARTS	\$	55,846.47

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2400 16,800.00
Towing Fees.	\$	120.00 506
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
Putty and spray painting of the affected portion.	\$	18,000.00 17606

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5653Y - CHINA**RIZA**

To rust-proofing of the affected areas.	\$	170.00	1500
To vacuum, replace, refix and recharge Air - condenser	\$	380.00	1000
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	500
To replace, refix and top up coolant for radiator	\$	170.00	500
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1200
To check steering geometry and computer wheel alignment	\$	220.00	600
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To check ABS brake efficiency, final checking and testing.	\$	na 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 2500
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To transfer of door fittings, attachment and perform water seepage test.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	400
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	Repair 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	7 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	800

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5653Y - CHINA

RIZA

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	600
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	1200
To reinstall rear bumper parking sensor.	\$	170.00	600
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	7800
To repair and realign rear exhaust pipe.	\$	170.00	
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	2400
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00	X

TOTAL \$ 41,470.00

Over All Total \$ 97,316.47

< parts by parts > Repair Days

60 DAYS