

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5653Y - CHINA

RIZA

Not Authorised
1-B1

Vehicle No.:	SHC 5653Y - RIZA
Chassis No.:	VF1ABL15AUC281150
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	03.07.2015
Third Party Insurer :	CHINA

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Br</i> 968.79 ✓✓
2	1	BUMPER SPOILER FRT	\$	<i>Dr's</i> 139.81 ✓✓
3	1	BUMPER ABSORBER FRT	\$	svc 303.60 X
4	1	BUMPER BRACKET FRT LH	\$	<i>R</i> 116.47 X
5	1	BUMPER SUPPORT FRT LH	\$	<i>R</i> 18.37 X
6	1	BUMPER BRACKET FRT RH	\$	<i>R</i> 115.98 X
7	1	BUMPER SUPPORT FRT RH	\$	<i>R</i> 18.37 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Br</i> 363.71 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Dr's/Br</i> 205.23 ✓✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Br</i> 159.39 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Br</i> 159.39 X
12	1	BUMPER BEAM FRT	\$	svc 703.14 X
13	1	RADAI TOR GRILLE	\$	<i>CM</i> 1,313.68 ✓✓
14	1	RADAI TOR GRILLE BADGE 'RENAULT'	\$	<i>Br</i> 173.36 ✓✓
15	1	RADAI TOR GRILLE FRAME	\$	<i>CM</i> 1,041.35 ✓✓
16	1	FRAME FULL SUPPORT PANEL	\$	svc 473.77 X
17	1	FRAME FULL SUPPORT BRACKET	\$	svc 69.07 X
18	1	FRONT BRACE PANEL	\$	<i>R</i> 136.32 X
19	1	SUBFRAME OUTER FRT	\$	<i>Br</i> 2,040.34 X
20	1	HEADLALMP LH	\$	<i>Dr</i> 911.10 ✓✓
21	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 134.59 X
22	1	HEADLALMP RH	\$	svc 911.10 X
23	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 134.59 X
24	1	HORN L70Y LH	\$	<i>Br</i> 241.67 X
25	1	HORN L70Y RH	\$	<i>Br</i> 241.67 X
26	1	HORN BRACKET	\$	<i>R</i> 31.12 X
27	1	BONNET	\$	<i>R</i> 1,493.56 X
28	1	BONNET INSULATOR	\$	<i>Br</i> 312.10 X
29	1	BONNET STRUT LH	\$	<i>Br</i> 166.29 X
30	1	BONNET STRUT RH	\$	<i>svc</i> 166.29 X
31	1	BONNET HINGE LH	\$	<i>R</i> 267.93 ✓
32	1	BONNET HINGE RH	\$	<i>R</i> 267.93 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5653Y - CHINA

RIZA

33	1	BONNET LOCK	\$
34	1	BONNET CABLE	\$
35	1	FENDER PANEL FRT LH	\$
36	1	FENDER PANEL FRT RH	\$
37	1	WHEELARCH FRT LH	\$
38	1	WHEELARCH FRT RH	\$
39	1	RADIATOR	\$
40	1	ENGINE UNDERTRAY	\$
41	1	A/C CONDENSER	\$
42	1	TRANSMISSION COOLER	\$
43	1	DOOR PANEL REAR LH	\$
44	1	DOOR SEAL REAR LH	\$
45	1	DOOR PANEL REAR RH	\$
46	1	DOOR SEAL REAR RH	\$
47	1	BUMPER COVER REAR	\$
48	1	BUMPER BRACKET CTR REAR	\$
49	1	BUMPER BRACKET SIDE LH REAR	\$
50	1	BUMPER RETAINER LH REAR	\$
51	1	BUMPER BRACKET SIDE RH REAR	\$
52	1	BUMPER RETAINER RH REAR	\$
53	1	BUMPER LOWER REAR	\$
54	1	BUMPER BEAM REAR	\$
55	1	BUMPER BEAM BRACKET LH REAR	\$
56	1	BUMPER BEAM BRACKET RH REAR	\$
57	1	BUMPER REFLECTOR LH	\$
58	1	BUMPER REFLECTOR RH	\$
59	1	BOOT REAR	\$
60	1	BOOT FINISHER	\$
61	1	BOOT LOCK	\$
62	1	BOOT LOCK CATCH	\$
63	1	BOOT WHEATERSTRIP	\$
64	1	BOOT REFLECTOR LAMP LH	\$
65	1	BOOT REFLECTOR LAMP RH	\$
66	1	BOOT BADGE 'RENAULT'	\$
67	1	BOOT BADGE	\$
68	1	BOOT STRUT LH	\$
69	1	BOOT STRUT RH	\$
70	1	BOOT HINGE LH	\$
71	1	BOOT HINGE RH	\$
72	2	LICENCE PLATE LAMP	\$

R	234.99	X
Sm	91.69	X
R	602.95	X
R	602.95	X
Sm	107.32	X
Sm	214.49	X
SVC	924.77	X
Sm	434.60	X
Pur	1,554.13	✓✓
SVC	852.66	X
R	2,188.20	X
Sm	68.02	X
R	2,188.20	X
Sm	68.02	X
Bt	852.66	✓✓
CMA	87.29	✓✓
Dis	34.61	✓✓
NSP	104.59	X
Dis	34.61	✓✓
NSP	104.59	X
At	591.41	✓✓
Rt	598.08	✓✓
Bt	173.81	✓✓
Bt	173.81	✓✓
Sm	33.55	X
Bu	33.55	✓✓
Bt	2,209.75	✓✓
SVC	361.58	X
Net	155.90	✓✓
Dis	57.23	✓✓
Dis/Lit	248.50	✓✓
SVC	379.50	X
CMA	379.50	✓✓
Net	173.35	✓✓
Net	173.35	✓✓
Sm	212.36	X
Sm	212.36	X
R	282.96	X
R	282.96	X
Sm	84.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5653Y - CHINA**RIZA**

73	2	BOOT RUBBER PLUG	\$	Sm 170.63 X
74	1	WINDSCREEN REAR	\$	Sm 1,125.60 X
75	1	TAILLAMP LH	\$	svc 425.04 X
76	1	TAILLAMP PANEL LH	\$	R 759.00 X
77	1	TAILLAMP RH	\$	Bu 425.04 ✓✓
78	1	TAILLAMP PANEL RH	\$	Bt 759.00 ✓✓
79	1	FENDER PANEL REAR LH	\$	R 2,537.80 X
80	1	FENDER PANEL REAR RH	\$	Bu 2,537.80 ✓✓
81	1	FENDER WHEELARCH REAR LH	\$	R 418.06 X
82	1	FENDER WHEELARCH REAR RH	\$	R 418.06 X
83	1	AIR VENT RH	\$	svc 74.83 X
84	1	FENDER PANEL INNER TRIM REAR RH	\$	Reform 516.50 ✓✓
85	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm 516.50 X
86	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	R 2,337.72 X
87	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	R 2,337.72 X
88	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bt/Bu 1,684.52 ✓✓
89	1	SPARE WHEEL PANEL TRIM (Luggage Floor Pan)	\$	Reform 470.93 ✓✓
90	1	OUTER PANEL REAR (End Panel)	\$	Bt 1,132.13 ✓✓
91	1	OUTER PANEL REAR (End Panel)TRIM	\$	Reform 308.48 ✓✓
92	1	EXHAUST REAR	\$	Bt 5,760.00 ✓✓
93	1	EXHAUST CAP REAR	\$	Bt 177.30 ✓✓
94	1	WINDSCREEN REAR	\$	Reform 1,125.60 X

TOTAL	\$	57,987.16
10%	\$	5,798.72
	\$	52,188.45

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	Re 52.00 ✓✓
2	1SET	BUMPER CLIP FRT	\$	Re 66.00 ✓✓
3	1	TOW COVER FRT	\$	Sm 14.50 X
4	1SET	RADAIOR GRILLE SCREW	\$	Re 16.00 ✓✓
5	1SET	BUMPER GRILLE LOWER CLIP	\$	Re 69.00 ✓✓
6	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Re 70.00 ✓✓
7	2	FRAME FULL SUPPORT PANEL NUT	\$	Sm 20.00 X
8	2	FRAME FULL SUPPORT PANEL STUD	\$	Sm 30.00 X
9	2	BONNET CABLE CLIP	\$	Re 6.40 X
10	1SET	WHEELARCH CLIP LH	\$	Re 30.50 X
11	1SET	WHEELARCH CLIP RH	\$	Re 29.40 X
12	1SET	DOOR CASING CLIP	\$	Re 6.40 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5653Y - CHINA**RIZA**

13	1SET	DOOR SEAL CLIP FRT RH	\$	na 18.50 X
14	1	DOOR STICKER "TRANS-CAB" LH	\$	na 80.00 X
15	1	DOOR STICKER "CLASSIC" LH	\$	na 30.00 X
16	1	DOOR STICKER "TRANS-CAB" RH	\$	na 80.00 X
17	1	DOOR STICKER "CLASSIC" RH	\$	na 30.00 X
18	1	RIM RH RR	\$	sn 385.00 X
19	1	TYRE RH RR	\$	sve 330.00 X
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn 385.00 X
21	1	SPARE TYRE	\$	sn 330.00 X
22	1SET	WHEELARCH CLIP LH RR	\$	na 32.34 X
23	1SET	WHEELARCH CLIP RH RR	\$	na 32.34 X
24	1SET	PARKING AID	\$	tn 600.00 ✓
25	1SET	BUMPER RR RIVET	\$	na 28.60 ✓
26	1SET	BUMPER RR CLIP	\$	na 66.00 ✓
27	1SET	REFLECTOR SCREW (Necessary)	\$	na 25.00 X
28	1SET	BUMPER BEAM BOLT (Necessary)	\$	sn 22.22 X
29	2	DOOR STICKER "6555-3333" LH/RH	\$	na 160.00 X
30	1SET	BOOT FINISHER CLIP	\$	na 25.10 X
31	1	Rear boots sticker "trans-cab"	\$	na 30.00 ✓
32	1	Rear boots sticker "6555-3333"	\$	na 30.00 ✓
33	2	Rear windscreen sealant	\$	na 80.00 45min ✓
34	1	Windscreen moulding	\$	na 100.00 30min ✓
35	1	Rear Windscreen Inner Sponge Seal	\$	na 100.00 X
36	1	EXHAUST MOUNTING REAR	\$	tn 65.50 ✓
37	1	EXHAUST BRACKET REAR	\$	R 22.22 X
38	1SET	Front licence plate with holder	\$	By 80.00 45min ✓
39	1SET	Rear licence plate with holder	\$	Del 80.00 45min ✓

TOTAL	\$	3,658.02
TOTAL PARTS	\$	55,846.47

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 16,800.00 2400 ✓

Towing Fees.

\$ 120.00 50 ✓

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 18,000.00 1760 ✓

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5653Y - CHINA

RIZA

To rust-proofing of the affected areas.	\$	170.00 150 ✓
To vacuum, replace, refix and recharge Air - condenser	\$	380.00 100 ✓
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 50 ✓
To replace, refix and top up coolant for radiator	\$	170.00 50 ✓
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 120 ✓
To check steering geometry and computer wheel alignment	\$	220.00 60 ✓
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 } 250 ✓
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 }
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 40 ✓
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	Repair 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	5 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 80 ✓

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5653Y - CHINA

RIZA

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>600</i> ✓
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>Revised</i> 380.00 X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00 <i>1200</i> ✓
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i> ✓
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00 <i>800</i> ✓
To repair and realign rear exhaust pipe.	\$	170.00 }
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 <i>2400</i> ✓
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	<i>nn</i> 380.00 X

TOTAL	\$	41,470.00
--------------	-----------	------------------

Over All Total	\$	97,316.47
-----------------------	-----------	------------------

< parts by parts > Repair Days

78 **60 DAYS**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____