

MCS Auto

1100 SERANGOON ROAD SINGAPORE 328195

TEL : 62969939 FAX : 62964038

Company Registration No. 53126812L

Email : mcs.auto@yahoo.com.sg

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

Date of Accident :	11/06/2015	Days of Repair	4 days
Vehicle No :	FBF 5009 M	Chassis No :	5YP303051
Make & Model :	Yamaha T135	Engine No :	5YP303051
Year of Manufacture :	2011	Registration Date :	2011

S/No:	Spare parts Description	Qty	List Price	Remark
1	Handle bar	1	115.00	
2	Handle bar bracket	1	55.00	
3	Handle grip	2	40.00	
4	Headlamp cowling	1	78.00	
5	Headlamp rear cowling	1	55.00	
6	Brake lever	1	25.00	
7	View mirror	2	70.00	
8	Front basket	1	55.00	
9	Headlamp assy	1	170.00	
10	Front cowling	1	155.00	
11	Front cowling stay	1	45.00	
12	Front signal lamp RH	1	56.00	
13	Front side fairing RH	1	96.00	
14	Front inner panel	1	85.00	
15	Front fender	1	65.00	
16	Front sports rim	1	350.00	
17	Front brake disc	1	195.00	
18	Front footrest rubber L/R @ \$15.00	2	30.00	
19	Front stepbar	1	55.00	
20	Engine cover RH	1	85.00	
21	Rear side board RH	1	155.00	
22	Brake pedal	1	65.00	
23	Kick starter	1	75.00	
24	Pillion grip	1	55.00	
25	Exhaust assy	1	420.00	
26	Front exhaust protector	1	45.00	
27	Rear exhaust protector	1	75.00	
28	Rear mudguard	1	85.00	
29	Taillamp assy	1	95.00	

Less 10% : \$2,950.00
 (A) Sub Total : \$2,655.00

S/No:	Spare parts Description	Qty	S/Nett
1	Rear box and bracket	1	\$250.00
2	Fork oil	2	\$24.00
3	Fork oil seal	2	\$40.00

(B) Sub Total : \$314.00
 (A+B) Parts Total : \$2,969.00

S/No:	Labour Charges	Amount
1	Transportation	\$50.00
2	Body frame alignment	\$250.00
3	Front rim balancing	\$50.00
4	Front fork alignment	\$80.00
5	Repalce, align and adjust damaged parts. Check wiring and lighting system.	\$250.00

(C) Labour Total : \$680.00
Total Amount : \$3,649.00