

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895
 Email: service@kkimhin.com.sg

No. : 27178

Vehicle Insured : SHC 3734 K
 Accident Date : 05-Aug-2015

Date : 13-Aug-2015


Our Ref : 150577 (III) / XW

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
 Singapore

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3 CVT (2014) SKP2351J

1 pc	front number plate base		66.20
	garnish]	
1 pc	front bumper		458.30
2 pcs	front bumper side retainer	@ S\$ 28.40	56.80
	(LH&RH)]	
10 pcs	front bumper clips	@ S\$ 3.90	39.00
1 pc	front bumper lower centre		45.70
	grille]	
2 pcs	front bumper lower side grille	@ S\$ 28.00	56.00
	(LH&RH)]	
1 pc	front bumper towing cover		26.00
2 pcs	front bumper inner air guide	@ S\$ 28.70	57.40
	(LH&RH)]	
1 pc	front bumper reinforcement		203.30
2 pcs	front bumper reinforcement	@ S\$ 36.90	73.80
	bracket (LH&RH)]	
2 pcs	horn	@ S\$ 62.90	125.80
1 pc	horn wireharness		690.00
1 pc	wiper washer tank		72.00
2 pcs	wiper washer tank motor	@ S\$ 75.00	150.00
2 pcs	wiper washer tank hose	@ S\$ 70.00	140.00
1 pc	wiper washer tank neck cap		15.00
1 pc	front grille		320.00
10 pcs	front grille clips	@ S\$ 3.90	39.00
2 pcs	headlamp assy (LH&RH)	@ S\$650.00	1,300.00
2 pcs	headlamp lower bracket (LH&RH)	@ S\$ 35.00	70.00
2 pcs	front fender (LH&RH)	@ S\$530.00	1,060.00
2 pcs	front fender inner shield	@ S\$ 95.00	190.00
	(LH&RH)]	
20 pcs	front fender inner shield	@ S\$ 3.90	78.00
	clips]	




金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895
 Email: service@kkinhin.com.sg

Vehicle Insured : SHC 3734 K
 Our Ref : 150577

Page : 2
 No. : 27178

1 pc	o/s front fender inner panel		290.30
1 pc	o/s front chassis member		605.60
1 pc	o/s front fender lower inner panel		290.00
1 pc	front support panel		486.90
1 pc	front support panel top garnish		39.00
10 pcs	front support panel top garnish clips	@ S\$ 4.50	45.00
1 pc	ABS pump assy		2,760.70
1 pc	aircon condenser		986.40
1 pc	aircon condenser discharge pipe		184.00
1 pc	aircon condenser suction pipe		158.00
1 pc	aircon condenser liquid pipe		392.00
1 pc	aircon condenser fan cowling		58.66
1 pc	aircon condenser fan motor		402.00
1 pc	aircon condenser fan blade		40.00
1 pc	aircon compressor		1,406.80
1 pc	radiator		1,540.00
2 pcs	radiator top bush (LH&RH)	@ S\$ 26.00	52.00
2 pcs	radiator bottom bush (LH&RH)	@ S\$ 26.00	52.00
1 pc	radiator fan cowling		90.00
1 pc	radiator fan motor		210.00
1 pc	radiator fan blade		54.00
1 pc	radiator top hose		30.00
1 pc	radiator bottom hose		30.00
1 pc	water pump assy		275.00
1 pc	water pump gasket		35.00
1 pc	alternator		2,100.00
1 pc	fan belt		90.00
1 pc	fan belt tensional bearing		230.00
1 pc	bonnet		685.00
2 pcs	bonnet inner rubber lid(LH&RH)	@ S\$ 25.00	50.00
2 pcs	bonnet outer rubber lid(LH&RH)	@ S\$ 25.00	50.00
6 pcs	bonnet insulator clips	@ S\$ 3.90	23.40
2 pcs	bonnet hinges	@ S\$ 40.00	80.00



金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895
 Email: service@kkinhin.com.sg

Vehicle Insured : SHC 3734 K
 Our Ref : 150577

Page : 3
 No. : 27178

1 pc	bonnet lock		55.00
1 pc	bonnet pull lock cable		30.00
1 pc	battery cover		25.00
1 pc	battery tray		25.00
1 pc	engine mounting - LH		140.50
1 pc	engine mounting - RH		154.90
1 pc	engine mounting - rear		95.00
1 pc	front windscreen glass		52.00
	moulding		
2 pcs	front crash sensor (LH&RH)] @ S\$170.00	340.00
1 pc	front passenger airbag		2,236.80
1 pc	front passenger seat belt		413.20
1 pc	steering air bag		1,640.30
1 pc	steering clock spring		350.00
1 pc	driver seat belt		413.20
2 pcs	centre pillar inner trim-] @ S\$ 95.00	190.00
	bottom		
1 pc	airbag control unit		890.00
1 pc	dashboard - top		930.00
1 pc	o/s front rim		1,060.00
1 pc	o/s front shock absorber		371.10
1 pc	o/s front shock absorber		58.80
	mounting		
1 pc	o/s front shock absorber]]	34.70
	mounting bearing		
1 pc	o/s front shock absorber]]	39.60
	stopper		
1 pc	o/s front shock absorber]]	39.60
	cover		
1 pc	o/s front knuckle arm		314.00
1 pc	o/s front knuckle arm bearing		66.00
1 pc	o/s front bearing hub		253.00
1 pc	o/s front lower arm		200.00
1 pc	o/s front stabilizer bar		65.00
	linkage]]	
1 pc	o/s front stabilizer bar bush		20.00
1 pc	o/s front tie rod		115.00

Con't Page 4 ...



金興(龔)汽車私人有限公司


新民通道 (大牌 34 座) 門牌 114 號
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895
 Email: service@kkinhin.com.sg

Vehicle Insured : SHC 3734 K
 Our Ref : 150577

Page : 4
 No. : 27178

1 pc o/s front tie rod end	92.00	
1 pc steering rack & pinion	1,490.00	
1 pc steering cross member	960.00	

	32,313.76	
Less 20% :	-6,462.75	
	-----	25,851.01
1 pc front number plate	40.00	sn
1 pc front bumper "L" plate	75.00	sn
1 pc front bumper "L" plate bracket	50.00	sn
2 pcs front bumper "L" plate bracket @ S\$ 5.00	10.00	sn
rivet]		
1 pc brake oil	30.00	sn
1 pc radiator coolant	48.00	sn
1 pc battery	200.00	sn
1 pc front windscreen glass sealant	40.00	sn
1 pc front windscreen glass damping seal]	20.00	sn
1 pc o/s front tyre	320.00	sn
To tow accident vehicle to workshop by normal towing	50.00	
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	1,300.00	
To focus headlamps. To check front wiring and lighting operation.	50.00	
To remove and renew front windscreen glass and conduct water leak test.	120.00	
To remove aircon condenser, pipes and driers. Vaccum and recharge gas	100.00	



金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SHC 3734 K

Our Ref : 150577

Page : 5

No. : 27178

To apply undersealing	120.00
To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.	250.00
To remove and renew air bag sensors seat belts assy, to rewiring and re-setting program	350.00
To remove and refit engine assy in order to facilitate repairing works	300.00
To dismantle and check front under-carriages. To replace affected portions.	240.00
To conduct front wheel alignment test.	80.00
To check and realignment on chassis member.	300.00
To putty and respray on affected portions.	1,300.00
Total :	S\$31,244.01

Singapore Dollars Thirty One Thousand Two Hundred and Forty Four and Cent One Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.