INo. CASE	OWNER:	CC 6/111150	13859 1K	hasse	IDAC:
Surveyor:		. 48	SIGNMENT 14. of 15	Date / Time :	14.58.15 erimen: 17.08.15
Insured Ve Name of In	chicle No.:		Claim No. Policy No. Make / Model	: <u>M</u>	15071174 HZ SONATA 2.0(A)
Excess Sec Is driver the If NO, Dri	: II :S\$	D.O.A: 4.07.1 NO) Nature of Accident: NAMA CHYE	Place of Accid	PRT: YES/NO;	
INSRS: WSP: L Liability: RMKS:	Emfor	INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
Date/ Time	FOR CSO ONL	SII			
- Mr	Is driver the owner? If NO, Driver Name / Driver's Own Vehicle	? (YES / NO) Age :	ce Company:	Finalisation: Email AIG for OI (Apt letter to OI:	DATE / PIC GIA:
	- no neer 40 245 12357 - X	GBEITDOIGO O HIWY3W>	d.o.a - 17/115	Call OI: After call ltr to OI: Type Report: Prepare Invoice:	
20108/15	- WIRE KONIEN	DO SEND LETTER TO OI. NED, OIP FRENK - END FOR LIMBIUTY MANDA	obb tp.		Check List: Handler Typist
03/09/15	- III APPROVED - EWALL LIABILY - TO PINALISE	WHOLLTY.		OI Apt Ltr: Authorisation To A Release Voucher: Final Repair Bill: Car Rental Invoice: LTA / GIA:	
08-8-19	REAR ENDED. LIA	BILITY IS DOWN ACCIDENT OCS SOONEST POSSIBLE IN OR	ON 2015 ASK	Medical Bill: Approval Email: Payment Breakdo Others:	
				C	1919
FINAL SETTLEMENT		Confirm with			ENDER TP)
Repair Cost: Loss of Rental: Loss of Use:	S\$ S\$	Final Liability: (days) (\$ x days)	1) Claim status:		BOLA S/N No. : 27 If NO or B 28, Ass. Lia : rivate Settle
Disbursement:		<u> </u>	2) Report Form		w/P
Legal Cost : Total:	SS SS	Global Sum: SS	3) Survey fee:	195 Vikiliamoko en	\$ 220.00
× 5 1022	0.0	Giobai Sum: 53	the state of the s		

4.

Veh No: Y2 2932 Yr Regn: OP, O/ Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Zsuzu NPR c.c 4570 Colour Yellow A/C: Insured / Std / NI / NA Sp.Reading // 33289 T/Radio: Insured / Std / NI / NA Eng/No: C/No: NPR 7/2 7*427792
Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil / S/Rim / STD A/Rim or Tyre Size: F:
Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: ee: Site Insp (\$)S = RSSI Interview (\$) Fhotos Tech, Invs (\$) Others



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	nationale Des Experts En Autor	nobile	
IN	DIA INTERNATION	IAL INSURANCE PL	Ref : CC6/III150138		
	CECIL STREET 5-02 IOB BUILDING	3 SINGAPORE 049711	Date: 17-08-2015 Code: III2		
1.		Policy Particul	ars :- THIRD PARTY CLA	IM	
	Insured Veh.	SHC 1522T	Veh. Inspected	YL 293L	
	Policy No.	MCOM0016	Coverage (\$)	0.00	
	Claim No.	MCT15071074	Excess (\$)	0.00	
	Assign From		Assign Date	14/08/2015	
2.		Vehicle P	articulars & Condition	table a process	
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	*	Steering		
	Brakes		Modification		
	General				
3.		Con	ditions of Tyres		
		Size	Make	Balance	
_	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
- Care	L/H Rear Tyre			mm	
l		Descri	ption of Damages		
i.		Gene	eral Information		
	Accident Date	28/07/2015	Inspection Date	14/08/2015	
	Survey held at	K KIM HIN AUTO PTE LTD			
		BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708			
a.	Street in less stone I	LACK WHITE PRODUCTION OF	Remarks		

...CLAIM SUBFOLDER...(Pending for Approval)

This claim might not be processed online because the insurer has not indicated that they want to start processing TP claims.

Click on 'Edit Rep. Info / Close' to update payment information and close the case.

LAIM SUE	FOLDER TRAC	KING					
Cisi							
Main	05 Aug 2015 14:53		05 Aug 2015 15:02 \$\$3,029.00		1110 SP4100 2111	Pending for Appr	oval
	Main	Refer	rence	Claim Details		Documents	Show All
CLAIM SL	JBFOLDER DET	AILS	19 miles 2 mil		THE RESERVE AND ADDRESS.	The second second	A STATE OF THE PARTY OF THE PAR
Insured:		UNKNOWN	NRIC: 0				
Main Claim	ant:			RIC: 201323288W	,		
Vehicle Reg	. No.:	YL293L	and the end,			20/07/2007	C40 140.
Claim Type	:	TP		Date of Loss: 28/07/2015 12:00 - Policy/Cover Note No.:		00 - :59	
Vehicle Reg	No. (Insured):						
Repairer:			Auto Pte Ltd (HQ)	PROFILE Blk 34	(Gaimant): , #01-114, Sin	8-V0007063-MVA Ming Drive, 575708 Si	n Ming - Tel:
Handling Ir	nsurer:	India Inter	national Insurance	Pte Ltd (HO) -	Tel: 63476100		
Claimant's	Insurer:	QBE Insura	nce (International) Ltd (HQ) - Tel:	62246633		
ASSOCIA	TED MAIL RECE						
	no mail for this ca					View All	Compose Case Mail
mere are n	io man for this ca	se.					
	-						



CO. REG. NO: 199402370D GST NO: M2-0123250-3

AUTO PTELTO

金興(龔)汽車私人有限公司

新民通道(大牌34座)門牌114號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

TP INSURER: UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

Claimant Insurer: QBE Insurance (International) Ltd

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

150565

Policy No:

YL293L

Date of Loss:

Driveable?

28/07/2015

Vehicle Reg. No.: Party At Fault:

UNKNOWN

Driver (TP):

RAHMAT BIN TALIB

Vehicle Reg. Date:

20/09/2001

Make/Model: Vehicle Colour:

ISUZU NPR71L, 4.6 D (M)

SILVER

Engine No: Odometer:

4HG1819573

0 KM

Chassis No:

NPR71L7427792 Not Arthors

3,241.03

Paint Type:

List Item Discount:

15.00 %

Total Loss?

NO

Est. Duration of

Repair (day)

43

LKK Auto Consultants hence notify the Repairer of the following:

. To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and t to final approval from Insurance Company PLEASE REFER TO SKETCH PLAN.

Description of Accident/Loss

Acknowledged by Repairer

Nett Amount (S\$)

Remarks:

VEHICLE NOT IN. PLEASE ARRANGE SURVEY. THANKS.

Present Location:

K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS		
Parts		Amount
Miscellaneous Items		2,079.00
Labour		0.00
Paintwork Labour		950.00
Towing		0.00
Towning		0.00
	Gross Total (S\$)	3,029.00
	+ GST 7.00% (S\$)	212 03

REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 05 Aug 2015)

Parts:

N/A

ISUZU NPR71L 4.6 D (M) (Model not available in database)

Labour: Print Code:

Repairer's

(Price-denominated Standard List)

K Kim Hin Auto Pte Ltd/YL293L/05/08/2015 15:02

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*O/S TAILLAMP ASSY	15.00	0.00	P1 *255.00 FL -
2	1		*REAR EXHAUST MUFFLER	By 15.00	0.00	
3	27		*O/S REAR STOPPER			*850.00 FL
4	1		*REAR NUMBER PLATE LAMP ASSY	Pd 15.00	0.00	*100.00 FL 👉
5	1		*REAR NUMBER PLATE	nd 0	0.00	*135.00 FL 🥧
6	1		*REAR REINFORCEMENT	0	15113155	*40.00 FS 20
F=Fra	nchise (part. S=SpcNett	L L=ListItemDisc.	0	0.00	*900.00FS _
				Total (S\$)		2,280.00
			- List Item Discount on L It	ems (S\$)		201.00
			Total F	arts (S\$)		2,079.00

K Kim Hin Auto Pte Ltd/YL293L/05/08/2015 15:02. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimate:	s on	l abour
Louinate	3 011	Labour

		Lab.Type	Amount
abour	<u>Items</u>		2
TO RE	REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, EFIX AND TO RENEW AFFECTED PARTS.	New	33 450.00
2 TO	PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	33 450.00
то	FOCUS TAILLAMPS. TO CHECK REAR WIRING AND LIGHTING OPERATION.	New	20 50.00
	Gross Labou	r Cost (S\$)	950.00

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

7.628	
This claim is handled by: XIAOWEI	
	Generated using Merimen e-Claims Internet Estimation & Adjusting System

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

201323288W

Vehicle Details

Vehicle No.:

YL293L

Vehicle to be

Yes

Exported:

Intended Deregistration Date:

29 Jul 2015

Vehicle Make:

ISUZU

Vehicle Model

NPR71LU5GS

Primary Colour

Silver

Manufacturing Year.

2001

Engine No.:

4HG1819573

Chassis No.:

NPR71L7427792

Maximum Power

Output:

Open Market Value:

\$26,629.00

Original Registration

20 Sep 2001

Date: First Registration

20 Sep 2001

Date:

Transfer Count: Actual ARF Paid

\$1,332.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility

Expiry Date:

PARF Rebate

\$0.00

Intended COE Rebate Details

COE Expiry Date:

31 Jul 2021

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$26,177.00

COE Rebate Amount:

\$15,720.00

Total Rebate

Amount:

\$15,720.00

The information contained herein is correct as at 29 Jul 2015

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the **Back** or **Forward** buttons on your browser as this may after the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2015 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service

Mei Kwan (LKK Auto)

From:

Adeline Tham <adelinetham@iii.com.sg> on behalf of Motor Claim - III

<motorclaim@iii.com.sg>

Sent:

Wednesday, 19 August, 2015 11:31 AM

To:

Mei Kwan (LKK Auto)

Cc:

KKLau; Vic; Jas Khine (LKK Auto); Admin A; Neo Wei Min Mike

Subject:

RE: PODS III Ref:[MCT15071074] LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T (India) and YL293L (TP) along/at Hill Street

Attachments:

Full page photo.pdf; TP ESTIMATE.PDF; TP GIA REPORT.PDF; shc1522t-sas.PDF

Follow Up Flag:

Follow up

Flag Status:

Flagged

Categories:

HMK

Hi Mei Kwan,

As per request, we have attached OI GIA Report.

Kindly note that our claim handler will be Mr Mike.

Best Regards,
Adeline Tham
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04/#05 IOB Building
Singapore 049711

Tel: 63476100 Extn: 215 Fax: 62244174

From: Mei Kwan (LKK Auto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, 17 August, 2015 7:53 PM

To: Motor Claim - III

Cc: KKLau; Vic; Jas Khine (LKK Auto); Admin A

Subject: PODS III Ref: (TBA) LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T (India)

and YL293L (TP) along/at Hill Street

PODS - Express Settlements

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle YL 293L at M/s K Kim Hin Auto Pte Ltd - Sin Ming.

Enclosed herewith a copy of TP's SAS report, estimated cost of repair and photographs of TP vehicle in its damaged condition for your perusal.

Please be informed that estimated cost of repair is \$3,241.03.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Vic

From:

Vic

Sent: To:

Tuesday, 1 September, 2015 3:25 PM Motor Claim - III; Neo Wei Min Mike

Cc:

KKLau; Jas Khine (LKK Auto); Admin A; Vic

Subject:

Attachments:

RE: PODS III Ref:[MCT15071074] LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T (India) and YL293L (TP) along/at Hill Street Full page photo.pdf, TP ESTIMATE.PDF; TP GIA REPORT.PDF; shc1522t-sas.pdf

PODS - Express Settlements

PODS III Ref:[MCT15071074] LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T (India) and YL293L (TP) along/at Hill Street

Dear Mr Mike,

We advise liability as follows for Direct Settlement:

Liability

: __100%__ (e.g. 50% or 100%)

Officer-In-Charge Mandate

(e.g. agree or disagree)

Remarks

: BOLA 27 (OID rear-ended TP)

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Adeline Tham [mailto:adelinetham@iii.com.sg] On Behalf Of Motor Claim - III

Sent: Wednesday, 19 August, 2015 11:31 AM

To: Mei Kwan (LKK Auto)

Cc: KKLau; Vic; Jas Khine (LKK Auto); Admin A; Neo Wei Min Mike

Subject: RE: PODS III Ref:[MCT15071074] LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T

(India) and YL293L (TP) along/at Hill Street

Hi Mei Kwan,

As per request, we have attached OI GIA Report.

Kindly note that our claim handler will be Mr Mike.

Best Regards,

Adeline Tham

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building

Singapore 049711

Tel: 63476100 Extn: 215 Fax: 62244174

Vic

From:

Neo Wei Min Mike [mike@iii.com.sg] Sent:

To: Cc:

Wednesday, 2 September, 2015 8:15 PM Vic; Gunaseelan; Manivel Priyadarshini KKLau; Jas Khine (LKK Auto); Admin A

Subject:

RE: PODS III Ref:[MCT15071074] LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T (India)

and YL293L (TP) along/at Hill Street

Full page photo.pdf; TP ESTIMATE.PDF; TP GIA REPORT.PDF; shc1522t-sas.pdf; ATT00001.txt Attachments:

Dear Vic.

Please proceed.

Dear Guna

Please assist 1st letter

Thank you

Best regards Mike Neo

Motor Claims Dept

India International Insurance

64 Cecil Street #04/#05 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 227 Fax: 62244174

Email: mike@iii.com.sq Co. Reg Number: 198703792K

From: Vic [mailto:vicalpeh@lkkauto.com] Sent: Tuesday, 1 September, 2015 3:25 PM To: Motor Claim - III; Neo Wei Min Mike Cc: KKLau; Jas Khine (LKK Auto); Admin A; Vic

Subject: RE: PODS III Ref:[MCT15071074] LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T

(India) and YL293L (TP) along/at Hill Street

PODS - Express Settlements

PODS III Ref:[MCT15071074] LKK Ref:CC6/III15013859/Kha3 Accident on 28.07.2015 involving SHC1522T (India) and YL293L (TP) along/at Hill Street

Dear Mr Mike,

We advise liability as follows for Direct Settlement:

Liability

: ___100%__ (e.g. 50% or 100%)

Officer-In-Charge Mandate

_____ (e.g. agree or disagree)

Remarks

: BOLA 27 (OID rear-ended TP)

Vic

From:

Vic

Sent:

Thursday, 3 September, 2015 2:17 PM

To:

K KIM HIN

sandrakhong@gmail.com; simon@kkimhin.com.sg; Admin A; Vic

Subject:

Your Ref: YL 293L_ACCIDENT INVOLVING VEHICLES SHC 1522T AND YL 293L ON 28/07/2015

Your Ref: YL 293L

"WITHOUT PREJUDICE"

Our Ref: CC6/III15013859/Kha3

Dear XiaoWei,

ACCIDENT INVOLVING VEHICLES SHC 1522T AND YL 293L ON 28/07/2015

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: <u>vicalpeh@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Vivian Lau (LKKAuto)

From:

Vivian Lau (LKKAuto)

Sent:

Monday, 2 September, 2019 5:52 PM

To:

III Claims III (motorclaim@iii.com.sg)

Cc:

Admin A; Hsiao Tong (LKKAuto)

Subject:

Your ref: MCT15071074,Our Ref: CC6/III15013859/Kwa3,ACCIDENT INVOLVING SHC

1522T AND YL 293L ON 28/07/2018 ALONG Hill Street

Your ref: MCT15071074

Our Ref: CC6/III15013859/Kwa3

Dear Sirs

ACCIDENT INVOLVING SHC 1522T AND YL 293L ON 28/07/2018 ALONG Hill Street

We refer to the above matter.

Please be inform that we had given 10 days' notice to TP repairer. TP's repairer did not submit the LOD until now.

In view of no further development, we will proceed to temporary close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: <u>Vivianlau@lkkauto.com</u>] fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	rnationale Des Experts En Auto	mobile
INI	DIA INTERNATION	IAL INSURANCE PL	Ref : CC6/III150138	359/Kwa3s2
	CECIL STREET 5-02 IOB BUILDING	G SINGAPORE 049711	Date: 04-09-2019 Code: III2	
1.		Policy Particul	ars :- THIRD PARTY CLA	JM
	Insured Veh.	SHC 1522T	Veh. Inspected	YL 293L
	Policy No.	MCOM0016	Coverage (\$)	0.00
	Claim No.	MCT15071074	Excess (\$)	0.00
	Assign From		Assign Date	14/08/2015
2.		Vehicle P	articulars & Condition	Kesabalan kesasa
	Make & Model	ISUZU NPR	c.c	4570
	Engine No.	HIDDEN	Year of Reg.	2001
	Chassis No.	NPR71L7427792	Colour	YELLOW
	Odometer	133289	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		,7.30 .00
١.		Con	ditions of Tyres	Charles a beginning to
		Size	Make	Balance
	R/H Front Tyre	7.00 R16X12	HEADWAY	8 mm
	L/H Front Tyre	7.00 R16X12	HEADWAY	8 mm
	R/H Rear Tyre	185 R14X8 (D)	YOKOHAMA	8/8 mm
	L/H Rear Tyre	185 R14X8 (D)	YOKOHAMA	8/8 mm
		Descri	ption of Damages	SECTION AND SECULO
	DAMAGES SEE D	STAINED DAMAGES AT THE F ETAILS.	REAR PORTION.	
		Gene	eral Information	
	Accident Date	28/07/2015	Inspection Date	14/08/2015
	Survey held at	K KIM HIN AUTO PTE LTD		
		BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		
а.			Remarks	
	A)THE INSPECTION B)IN ACCORDANCE	N WAS CONDUCTED ON A"W E TO YOUR INSTRUCTIONS,	/ITHOUT PREJUDICE" BASIS WE HAVE NOT AUTHORISE	S. ED REPAIRS
ο,		Estima	te Days of Repair	
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 293L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted
	REPLACEMENT OF PARTS		τοι κοπορ (ψ))	(\$)
1	O/S TAILLAMP ASSY REAR EXHAUST MUFFLER O/S REAR STOPPER REAR NUMBER PLATE LAMP ASSY LESS 15% DISCOUNT	CRACKED BENT MISSING 1PC ONLY DENTED	255.00 850.00 100.00 135.00 -201.00	255.00 850.00 50.00 135.00 -193.50
	SPECIAL NETT ITEMS		1,139.00	1,096.50
	REAR NUMBER PLATE (SN) REAR REINFORCEMENT (SN)	DENTED BENT	40.00 900.00	20.00 900.00
	LABOUR		940.00	920.00
- 1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		450.00	350.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		450.00	350.00
	TO FOCUS TAILLAMPS. TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	20.00
			950.00	720.00
- 0	GRAND TOTAL		3,029.00	2,736.50
N APPEN	RECOMMENDED COST OF LUMP SUM REPAIRS			2 450 00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	2,150.00
--	----------

Report Ref No. CC6/III15013859/Kwa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.