

TP III
VIC

SJH1367A. 2008 July
BMW 523i 2497cc
WBAKU12080CW25299.

Front LH Door	Dented	1534 ✓
Front LH Door Weatherstripe	m	225 ✓
Rear LH Door	Repair	1642 x
Rear LH Door Weatherstripe	.1H m	230 x
Rear LH Wheel Pin.	1000	1250 x

Panel Beating	800 400
Spray Painting	1000 800
To perform wheel alignment.	150 x
To transfer front and rear door fittings.	300. 80

List: 1259.

1583.10.

Labour: 1280

total: 2863.10

L/S: 2250

04 hrs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: