

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHF 536U -

Not Authored
1-B.1
85099.01
Resurvey B4 paint
SHF 536U - ROEL
 VF1ABL15AUC278303
 RENAULT
 LATITUDE
 26.09.2015
EQ

ROEL

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>R</i> 968.78 X
2	1	BUMPER RETAINER FRT LH	\$	<i>Sm</i> 116.47 X
3	1	BUMPER SUPPORT FRT LH	\$	<i>Sm</i> 18.37 X
4	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 159.40 X
5	1	HEADLAMP LH	\$	<i>Sm</i> 911.10 X
6	1	FENDER PANEL FRT LH	\$	<i>B</i> 602.95 ✓
7	1	FENDER WHEELARCH FRT LH	\$	<i>Sm</i> 107.33 X
8	1	DOOR MIRROR LH	\$	<i>CM</i> 1,141.08 ✓
9	1	DOOR PANEL FRT LH	\$	<i>B</i> 2,188.20 ✓
10	1	DOOR HINGE UPPER LH	\$	<i>R</i> 211.15 X
11	1	DOOR HINGE LOWER	\$	<i>R</i> 231.19 X
12	1	DOOR LOCK FRT LH	\$	<i>R</i> 699.04 X
13	1	DOOR HANDLE OUTER FRT LH	\$	<i>Sm</i> 198.55 X
14	1	DOOR HANDLE CAP FRT LH	\$	<i>Sm</i> 20.34 X
15	1	DOOR HANDLE SEAL FRT LH	\$	<i>Sm</i> 6.07 X
16	1	DOOR HANDLE COVER FRT LH	\$	<i>Sm</i> 10.18 X
17	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 759.61 X
18	1	DOOR PANEL REAR LH	\$	<i>R</i> 2,188.20 X
19	1	DOOR LOCK REAR LH	\$	<i>R</i> 699.04 X
20	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sm</i> 97.31 X
21	1	DOOR HANDLE MODULE REAR LH	\$	<i>Sm</i> 102.77 X
22	1	FENDER PANEL REAR LH	\$	<i>R</i> 2,537.80 X
23	1	BUMPER COVER REAR	\$	<i>Sm</i> 852.66 X

TOTAL	\$	14,827.58
10%	\$	1,482.76
	\$	13,344.83

Specical Nett

1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 X
1SET	WHEELARCH CLIP LH	\$	<i>nn</i> 66.00 X
1	CAP HUB LH FRT	\$	<i>nn</i> 35.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHF 536U -**ROEL**

1	RIM LH FRT	\$	Sm 385.00 X
1	TYRE LH FRT	\$	Sm 330.00 X
1	CAP HUB LH RR	\$	Sm 35.00 X
1	RIM LH RR	\$	Sm 385.00 X
1	TYRE LH RR	\$	Sm 330.00 X
1	DOOR STICKER "Trans-cab"	\$	nn 80.00 60/60
1	DOOR STICKER "Classic"	\$	nn 30.00 15/15
1	DOOR STICKER "6555-3333"	\$	nn 80.00 X
1SET	REAR BUMPER CLIP	\$	nn 66.00 X

TOTAL	\$	1,888.00
TOTAL PARTS	\$	15,232.83

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 500/

To Check Electrical Lighting Concerned.

\$ 170.00 20/

Putty and spray painting of the affected portion.

\$ 3,000.00 750/

To check steering geometry and computer wheel alignment

\$ 220.00 60/

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ 170.00 60/

To rust-proofing of the affected areas.

\$ 170.00 60/

TOTAL	\$	6,700.00
Over All Total	\$	21,932.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey **(PARTS BY PARTS)**
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Repair Days

10 Days

3 days