

<u>XO 2071 B</u>	<u>Condition</u>	<u>Price</u>
Front Cabin	DD	\$45,402.21
Front windscreen glass	BR	\$1882.10
Front windscreen glass rubber	CRA	\$220
Front Bumper	DD	\$2200.83
Front bumper headlamp RH	BR	\$1286.44
Side mirror RH assy	BR	\$1465
Front bumper fog lamp RH	BR	\$278.21
Front bumper fog lamp garnish RH	BR	\$136.42
Front bumper headlamp garnish RH	BR	\$118.18
Step garnish RH	BR	\$485
Step aluminium lower RH	BR	\$220
Step aluminium upper RH	BR	\$220
Step garnish reflector RH	BR	\$25.26
Intercooler	CRA	\$3000
		56,939.65
		- 10%
		<u>51,245.68</u>

- Labour
1. Remove & refit front cabin \$1200
 2. Remove & refit front bumper, windscreen glass front, R & R air hose, R & R brake hose, & cooling system \$1500
 3. Electric checked \$50
 4. Total painting \$1000
- 3750
- P- 51,245.68
L- 3750
54,995.68
L/S - 43,996.54
= 44,000 12 days repair