



新 福 德 車 廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: n60_newhockteck@hotmail.com

Tel: 6747 9241 Fax: 6741 7276

RCB No.: 52989088K GST Reg No.: M90368118A

ALG
(LEE, ADRIAN)

ONG KOK HOOI

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

30th Nov 2015

Accident date: 28th Nov 2015

Estimated repair cost for vehicle no: SGK9405R KIA PICANTO 1.1 M '06

S/n	Qty	Items	U/price	Amount
1	1	Rear R/H Tail Lamp <i>mounted</i>		\$289.00 ✓
2	1	Rear R/H Fender <i>Paint</i>		\$766.00 x
3	1	Rear Bumper <i>Paint</i>		\$363.00 ✓
4	1	Rear R/H Bumper Side Retainer <i>Pin</i>		\$28.00 ✓
5	1	Rear R/H Door <i>Paint</i>		\$634.00 x
6	1	Rear R/H Door Protector <i>bt</i>		\$138.00 ✓
7	1	Rear R/H Rim <i>bt</i>		\$650.00 35d(Sw)
8	1	Rear R/H Shock Absorber <i>7 not</i>		\$225.00 x
9	1	Rear Axle <i>7 not</i>		\$1,151.00 x
10	2	Rear Axle Bearing <i>7 not</i>	\$342.00 ✓	\$684.00 x

Subtotal :- \$4,928.00

Labour charges

To remove & refit cushion

~~\$280.00~~ 60

To remove & refit rear undercarriage

~~\$380.00~~ x - 250

To remove & refit reverse sensor

~~\$100.00~~ 50

To check wheel alignment computer

~~\$150.00~~ 80

To remove & refit rear R/H door inner lock, trim board, gear, motor & glass

~~\$180.00~~ x

To check wiring

~~\$80.00~~ 30

Tuff Kote

~~\$150.00~~ 30

Towing Fee

~~\$100.00~~ x

Panel beating

1250.

~~\$1,600.00~~ 400.

Spray painting

~~\$1,500.00~~ 600

Subtotal :- \$4,520.00

Total:- \$9,448.00

total: 2336.2 //
L/S: 1.8K
OAPop.