

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : Chartis Singapore Insurance Pte Ltd
Motor Claims Dept

Date : 02 Dec 2015

Dear Sirs :

Fax : 6880 4838

RE : ESTIMATE COST FOR TOYOTA WISH 1.8A - SKP5614G

ACCIDENT INVOLVING SKP5614G, SJY2250G, SGH3295X ON 01.12.15

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front bumper.	1pc	✓
2	Front bumper retainer @\$	2pcs	✓
3	Front fog lamp grille @\$	2pcs	xm
4	Front bumper lower grille.	1pc	xm
5	Front center grille.	1pc	xm
6	Front bumper reinforcement.	1pc	?
7	Front bumper sponge.	1pc	?
8	Front number plate.	1pc	✓
9	Front headlamp @\$	2pcs	xm.
10	Front bonnet.	1pc	xm xm
11	Front bonnet hinge @\$	2pcs	xm
12	Front bonnet lock.	1pc	xm
13	Front bonnet dupper chorme.	1pc	xm
14	Front fender o/s.	1pc	xm
15	Front support panel.	1pc	xm
16	Rear bumper.	1pc	✓
17	Rear bumper retainer @\$	2pcs	✓
18	Rear bumper reflector @\$	2pcs	?
19	Rear end panel.	1pc	Rx
20	Rear end panel top garnish.	1pc	xm
Sum Carried Forward			

Sum Carried Forward

21	Rear rubber.	1pc	no -
22	Rear lamp @\$	2pcs	?
23	Rear spare tyre panel.	1pc	x 2
24	Rear bootlid.	1pc	no -
25	Rear bootlid hinge @\$	2pcs	x 2
26	Rear bootlid absorber @\$	2pcs	x 2
27	Rear bootlid lock.	1pc	?
28	Rear bootlid outer chrome /wish.	1pc	?
29	Emblem.	1pc	no -
		\$	-

Less 25%

30	Sealant.	2pcs	\$	40.00	-
31	Front number plate.	1pc	\$	35.00	no -
32	Rear number plate.	1pc	\$	35.00	no -
33	Rear sensor.	1set	\$	220.00	no -
34	Coolant.		\$	35.00	?

Sum Carried Forward

Handwritten notes and calculations in the left margin, including a vertical list of numbers and symbols like 'x', 'no', and '25%'.

Sum Carried Forward

Labour Charge & Misc

To remove, replace, repair & install
damaged parts -front.

To R & R wiring (front /rear).

To R & R front radiator.

To R & R air con system.

To refill & top up air con gas.

To putty & spray painting -front.

To remove, replace, repair & install
damaged parts -rear.

To anti rust.

To remove & refit upholster.

To R & R rear windscreen glass.

To putty & spray painting -rear.

Total

\$ 900.00 600.
\$ 80.00 80.
\$ 120.00 120.
\$ 150.00 150.
\$ 1,100.00 200.
\$ 1,000.00 600.
\$ 150.00 80.
\$ 250.00 100.
\$ 150.00 150.
\$ 1,200.00 600.

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Not Andy
John 6 day

tel: 62563561

fax: 62568915

2 day

2/12/15
1500