

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9709P - AXA

ROEL

Not Notified
2 Bys & 2400/

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9709P - ROEL
 KL1LA69RJB123666
 CHEVROLET
 EPICA 2.0
 06.12.15
AXA

PART

LIST

1	1	Front Bumper	\$	<i>Det.</i> <i>MIT</i> 1,202.00	<i>+</i>
2	1	Front Bumper Lower Absorber	\$	<i>MIT</i> 180.00	<i>+</i>
3	1	Front Bumper Reinforcement	\$	<i>R</i> <i>R</i> 356.00	<i>x</i>
4	1	Front Bumper Retainer RH	\$	<i>R</i> <i>R</i> 102.00	<i>x</i>
5	1	Front Bumper Retainer LH	\$	<i>R</i> <i>R</i> 102.00	<i>x</i>
6	1	Front Bumper Lower Grille	\$	78.00	<i>x</i>
7	1	Front Bumper Lower Stiffener	\$	134.37	<i>x</i>
8	1	Front Bumper Fog Lamp Outer Cover RH	\$	32.40	<i>x</i>
9	1	Front Bumper Fog Lamp Outer Cover LH	\$	32.40	<i>x</i>
10	1	Front Support Panel AssY	\$	1,222.32	<i>x</i>
11	1	Headlamp RH (Lamp A-Head RH)	\$	816.00	<i>x</i>
12	1	Headlamp LH (Lamp A-Head LH)	\$	816.00	<i>x</i>
13	1	Bonnet (Panel A-Hood)	\$	1,250.00	<i>x</i>
14	1	Bonnet Moulding	\$	257.00	<i>x</i>
15	1	Centre 'CHEVROLET' Logo Badge	\$	144.30	<i>x</i>
16	1	Bonnet lock	\$	60.00	<i>x</i>
17	1	Radiator Grille	\$	367.00	<i>x</i>
18	1	Front Fender RH	\$	837.60	<i>x</i>
19	1	Front Fender LH	\$	837.60	<i>x</i>
20	1	Front Fender Liner RH	\$	47.00	<i>x</i>
21	1	Front Fender Liner LH	\$	47.00	<i>x</i>
22	1	Rear Bumper	\$	<i>MIT</i> 1,202.00	<i>✓</i>
23	1	Rear Bumper Beam	\$	<i>R</i> 239.94	<i>x</i>
24	1	Rear Bumper Centre Absorber	\$	<i>MIT</i> 260.00	<i>✓</i>
25	1	Rear Bumper Side Retainer RH	\$	<i>R</i> 68.76	<i>x</i>
26	1	Rear Bumper Side Retainer LH	\$	<i>R</i> 68.76	<i>x</i>
27	1	Rear Bumper Reflectors RH	\$	<i>MIT</i> 119.74	<i>✓</i>
28	1	Rear Bumper Reflectors LH	\$	<i>MIT</i> 119.74	<i>✓</i>
29	1	Rear Bumper Tow Hook Cover	\$	<i>MIT</i> 93.00	<i>✓</i>
30	1	Rear End Panel Outer	\$	<i>R</i> 623.76	<i>x</i>
31	1	Rear End Panel Inner Trim	\$	<i>R</i> 263.84	<i>x</i>
32	1	Bootlid	\$	<i>R</i> 973.00	<i>x</i>
33	1	Bootlid Weatherstrip	\$	<i>R</i> 344.28	<i>x</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9709P - AXA**ROEL**

34	1	Bootlid 'CHEVROLET' Badge	\$	120.62	X
35	1	Bootlid Logo	\$	138.84	X
36	1	Bootlid 'EPICA LT' Badge	\$	119.84	X
37	1	Bootlid Reflector RH	\$	128.40	X
38	1	Bootlid Reflector LH	\$	128.40	X
39	1	Rear Tail Lamp RH	\$	479.30	X
40	1	Rear Tail Lamp LH	\$	479.30	X
41	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	1,110.00	X
42	1	Rear Fender RH	\$	1,145.00	X
43	1	Rear Fender Inner Cowling RH	\$	298.00	X
44	1	Rear Fender Inner Trim RH	\$	418.44	X

TOTAL	\$	17,863.95
10%	\$	1,786.40
	\$	16,077.56

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	24.00	X
2	1 Set	Radiator Grille Top Cover Clip	\$	10.00	X
3	1 Cans	Radiator Coolant	\$	60.00	X
4	1 Set	Radiator Grille clip	\$	35.00	X
5	2Set	Front Fender Liner Clip	\$	60.00	X
6	1 Set	Front Licence Plate With Holder	\$	80.00	X
7	1 Set	Rear Bumper Parking Sensor	\$	300.00	X
8	1 Set	Rear Bumper Fastener Clip	\$	30.00	X
9	1	Rear Boot Sticker 'Trans-cab'	\$	30.00	X
10	1	Rear Boot Sticker '6555-3333'	\$	30.00	X
11	1Set	Bootlid inner trim board Clip	\$	40.00	X
12	1	Rear Exhaust Mounting	\$	10.00	X
13	1 Set	Rear Fender Inner Trim Clip RH	\$	30.00	X
14	1 Set	Rear Fender Inner Cowling RH Clip	\$	30.00	X
15	2	Rear Windscreen Sealant	\$	100.00	X
16	1	Rear Windscreen Inner Sponge Seal	\$	100.00	X

TOTAL	\$	969.00
TOTAL PARTS	\$	17,046.56

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00

To Check Electrical Lighting Concerned.

\$ 170.00

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9709P - AXA

ROEL

To Rust-Proofing Of The Affected Areas.	\$	170.00 X
Putty And Spray Painting Of The Affected	\$	2,700.00 4 col
To reinstall rear bumper parking sensor.	\$	170.00 6cl
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
Towing fees	\$	120.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
TOTAL	\$	7,080.00
Over All Total	\$	24,126.56

Repair Days

10 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: