

SINGAPORE ARMED FORCES
STATEMENT OF DRIVER / WITNESS


STATEMENT OF	1SG KEERAN KUMAR				ALIASES		
NRIC NO.	S9108385Z	AGE		MALE/FEMALE	MALE		
EMPLOYMENT	TPT LDR	DRIVING LICENSE NO	SAF/TPT/N/01129/11	NATIONALITY	SINGAPOREAN		
DIALECT	NA	LANGUAGE SPOKEN	EL	TEL NO			
ADDRESS							
INTERPRETED BY	NA	RANK		TIME		DATE	SIGNATURE
RECORDED BY	NA	RANK		TIME		DATE	SIGNATURE
<p>I, S9108385Z, 1SG KEERAN KUMAR, have the following to say about the incident, On 23/1/2016, I was Driving Grade 1 Staff car MID 18 from Pasir Laba Camp towards Marina Mandarin Hotel. At around 1310hrs while I was along the 1st lane on AYE under Clementi Flyover, I noticed a yellow taxi SHB 3368P executing brake after which I started to apply my brake to slow my vehicle. I then notice another Black Toyota (EM 2028E) which was behind the yellow taxi executing an emergency brake. Immediately I stepped on my brake to try to stop my vehicle however it was too late. My vehicle had hit into the rear of the Black Toyota. A few seconds later, I felt another impact from the back of my vehicle. That's when I realized that my vehicle had been hit by another civilian vehicle grey BMW (SFF1944S). At around 1312hrs, I called my OC, CPT Charles to inform him of the incident.</p> <p>That's all I have to say for about the incident.</p>							
DATE	23 JAN 16		SIGNATURE OF DRIVER/WITNESS				

All statements and further statements are to timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.

Statements of witness must be signed by the Witness.

RESTRICTED


Under Clementi Fly Over
Along AVE Towards City



LEGEND

-  Yellow Taxi
SH 3368
-  Black Toyota
EM 2088E
-  Grade 1
MID 18
-  Grey BMW
SFF 1944S

Under Clementi Fly Over
Along AVE Towards City




LEGEND

-  Yellow Taxi
SH 3368
-  Black Toyota
EM 2088E
-  Grade 1
MID 18
-  Grey BMW
SFF 1944S

RESTRICTED


Under Clementti Fly Over
Along AVE Towards City



LEGEND

-  Yellow Taxi
SH 3368
-  Black Toyota
EM 2088E
-  Grade 1
MID 18
-  Grey BMW
SFF 1944S

Under Clementti Fly Over
Along AVE Towards City



LEGEND

-  Yellow Taxi
SH 3368
-  Black Toyota
EM 2088E
-  Grade 1
MID 18
-  Grey BMW
SFF 1944S



SINGAPORE POLICE FORCE



T/20160123/2116

1 of 4

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

Report No. T/20160123/2116

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/01/2016 16:08		Vide Report No.:		Station Diary No.: 27	
Informant's Particulars					
Name of Informant: KEERAN KUMAR S/O PREMKUMAR			Address: APT BLK 388 YISHUN RING ROAD #03-1669 SINGAPORE 760388		
ID Type / ID No.: NRIC NO / S9108385Z			Contact No.: Home/Office: Mobile: 90601949		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 24	Date of Birth: 25/02/1991	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: ARMY TRANSPORT LEADER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 23/01/2016 13:10	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE GOING TOWARDS CTE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Seats
EM2028E	Car				Slightly Damaged	1
MID18	Car				Slightly Damaged	3
SFF1944S	Car				Slightly Damaged	1
SHB3368P	Car				Slightly Damaged	2



**SINGAPORE
POLICE FORCE**



T/20160123/2116

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

2 of 4

Report No. T/20160123/2116

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KEERAN KUMAR S/O PREMKUMAR	ID No.	S9108385Z
Related Vehicle	MID18 (Car)	Contact No.	90601949
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN WEE SEONG	ID No.	S1658864D
Related Vehicle	SHB3368P (Car)	Contact No.	96828622
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 23/01/2016 at about 1310hrs I was driving along the first lane at AYE going towards CTE. Underneath the flyover after the Clementi Road Exit, I noticed that a taxi (SHB3368P : Yellow Taxi) which was two cars ahead of me performed his emergency brake abruptly. Immediately upon seeing it, I also applied my emergency brakes however I was unable to stop in time and I collided with the vehicle (EM2028E : Black Toyota) in front of me. Consequently, the vehicle (SFF1944S : Grey BMW) behind me collided with the rear of my vehicle.

I wish to inform that the abrupt actions by the taxi driver had caused the chain collision involving 4 vehicles. When I queried with the Taxi driver on the reason why he performed his emergency brake, he told me that there is an object on the road. On the contrary, when I drove my vehicle after the incident, I did not see any object there.

Traffic Police was not at scene and we did not exchange particulars. No one was injured during the accident and the vehicles involved only had minor damages. That is all.



**SINGAPORE
POLICE FORCE**



T/20160123/2116

3 of 4

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

Report No. T/20160123/2116

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20160123/2116

4 of 4

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

Report No. T/20160123/2116

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

ABDULLAH BIN ROHAIZAD

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Esther Chong

Contact No.: 65476388

SN 120

Authentication Stamp

NP168



Signature :

Signature Of Informant:

Date/Time:

23/01/2016 16:08

Classification Of Case:

13-10-17:17:44


1/ 3



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 19640087W
GST Reg No. NR-0500111-X

TAX INVOICE

Invoice Name & Address				Owner Name & Vehicle Info			
Ministry Of Defence				Cust No/Name	WM000130/Ministry Of Defence		
HQ Maintenance & Engineering Supp				Reg No/Reg Date	MID18 / 05/05/2010		
161 Choa Chu Kang Way				Date In/Mileage	02/02/2016/ 144570		
Blk 822 #02-14 Kranji Camp 3				Chassis No	WDD2120482A178290		
Singapore 688248(Attn:ME4 Kevin)				Engine No	27188030041180		
Contact No 63074217Kevin Ho				Make/Model	MB/E 200 CGI SEDAN (W212)		
				Colour/Trim	021 197 Obsidian Bl/042 208 Leather Gr		
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
WM000130	Credit	07/09/2016/ 10:19	VS	321 / Helen Lee Bit Sing	57002	28123035	
Description of Goods / Services					Qty	Unit Price	Amount
A BPILAB						0.10	350.00
"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"							
REFER MID ORDER NO: 3000305413							
S BPNSUB							60.00
SUPPLY 1 PC NUMBER PLATE							
DN : 6134							
A BPILAB							672.00
"REMOVE & REPLACE RADIATOR, COOLING SYSTEM, CONDENSER WITH VACUUM AND RECHARGE OF REFRIGERANT.NETT"							
A BPILAB							672.00
"REMOVE & INSTALL LUGGAGE COMPARTMENT, TRIM, GARNISH AND CARPET FOR NECESSARY REPAIR."							
A BPILAB							96.00
REMOVE REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NET							
A BPILAB							6048.00
REMOVE & REPLACE FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, REAR BUMPER, REAR BOOT, END PANEL, FLR PAN							
A BPRES							4200.00
RESPRAY ON FRONT BUMPER, BONNET, REAR BUMPER, REAR BOOT							
END PANEL, RIGHT FRONT FENDER							
A BPILAB							240.00
DISMANTLE & RE-ADJUST NECKPRO HEADREST TO STANDARD SETTING.							
S BPNTOW							150.00
ACCIDENT TOWING FROM DOVER ROAD BLK 30							
TO PANDAN LOOP USING CAR CARRIER							
WO : 107072							
X MA212 817 00 78	LICENSE PLATE MO	1.00	170.82	10.00			153.83
X MA212 885 04 21	RIGHT GARNISH MO	1.00	78.33	10.00			70.50
X MA212 885 03 21	LEFT GARNISH MOU	1.00	78.33	10.00			70.60
X MA212 885 06 37	RIGHT ENERGY-ABS	1.00	50.54	10.00			45.49
X MA212 885 05 37	LEFT ENERGY-ABS	1.00	50.54	10.00			45.49

14 days

Payment should be made within 14 days by cash, MTO or credit card. Thank you.
Any dispute to the invoice must be made within 14 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - the registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
158 Pandan Loop
Singapore 120376
Tel: 0777 6300
Fax: 6779 5385
www.mercedes-benz.com.sg

13-10-17;17:44



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 108400367W
GST Reg No. M9-8900111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
Ministry Of Defence HQ Maintenance & Engineering Supp 161 Choa Chu Kang Way Blk 822 #02-14 Kranji Camp 3 Singapore 688248/Attn: ME4 Kevin Contact No 63074217 Kevin Ho	Cust No/Name WM000130/Ministry Of Defence Reg No/Reg Date MID18 / 05/05/2010 Date In/Mileage 02/02/2016/ 144570 Chassis No WDD2120482A178290 Engine No 27186030041180 Make/Model MB/E 200 CGI SEDAN (W212) Colour/Trim 021 197 Obsidian Bl/ 042 208 Leather Gr

Account No	Terms	Date/Time Printed	CSP	Operator	WIP No	Invoice/Credit Note No
WM000130	Credit	07/08/2016/ 10:19	VS	321 / Helen Lee Sit Sing	57002	28123035
Description of Goods / Services				Qty	Unit Price	Amount
X	MA212 885 18 37	IMPACT ABSORBER	1.00	101.79	10.00	91.81
X	MA212 885 27 85	CENTRAL BASIC MO	1.00	68.17	10.00	62.25
X	MA212 880 13 40/ 8888	FRONT BUMPER	1.00	1372.78	10.00	1235.48
X	MA212 887 00 88	BONNET FRONT SEA	1.00	19.23	10.00	17.31
X	MA212 880 01 57	BONNET	1.00	2237.97	10.00	2014.17
X	MA212 808 02 32	U-SHAPED STRIKER	1.00	38.84	10.00	34.98
X	MA212 620 15 00	FRONT CROSS MEMB	1.00	494.14	10.00	444.73
X	MA212 620 11 00	FRONT SUPPORT PA	1.00	140.73	10.00	128.86
X	MA212 500 02 55	FRONT SUPPORT PA	1.00	120.84	10.00	108.58
X	MA212 505 14 30	TOP AIR BAFFLE	1.00	63.98	10.00	57.59
X	MA212 880 47 40/ 9999	REAR BUMPER	1.00	1478.90	10.00	1331.01
X	MA212 740 17 95	HANDLE MOLDING	1.00	221.34	10.00	195.21
X	MA212 750 09 75	TRUNK LID	1.00	2052.42	10.00	1847.18
X	MA212 750 01 98	REAR BOOT WEATHE	1.00	165.14	10.00	148.83
X	MA212 840 03 00	REAR END PANEL	1.00	1170.87	10.00	1053.87
X	MA209 817 05 15	TYPE DESIGNATION	1.00	70.98	10.00	63.88
X	MA124 817 54 15	E200 EMBLEM	1.00	70.98	10.00	63.88
X	MA201 997 22 81	GROMMET	3.00	1.68	10.00	4.64
X	MA212 817 02 16	MERCEDES STAR	1.00	44.03	10.00	39.83
X	MA212 743 02 82	REAR BOOT CHROME	1.00	106.84	10.00	96.16
X	MA204 817 49 20	GUIDE SIGN-ABC	1.00	14.11	10.00	12.70
X	MA212 610 20 14	REAR CROSS MEMBE	1.00	751.79	10.00	676.61
X	MA212 885 01 36	RADIATOR GRILLE	1.00	15.19	10.00	13.67
X	MA188 997 13 81	GROMMET	2.00	1.21	10.00	2.18
X	MA212 680 08 83/ 7246	RADIATOR GRILLE	1.00	1108.38	10.00	997.51
X	MA221 670 61 01	GLAZING REPAIR K	1.00	171.01	10.00	154.72
X	MA212 610 00 75	SPARE WHEEL WELL	1.00	260.29	10.00	239.66
X	MA221 817 00 16	BADGE	1.00	40.85	10.00	36.76
X	MA210 890 11 58	RIVETED NUT	4.00	3.43	10.00	12.85
X	MA207 750 01 89	STOP	2.00	9.03	10.00	16.25
X	MA212 750 00 89	STOP	2.00	6.83	10.00	12.28
X	MA212 490 06 35	EXHAUST PIPE	1.00	1748.88	10.00	1573.89
X	MA212 328 02 88	REAR COMP. COVER	1.00	35.83	10.00	32.26

Payment should be made strictly by cash, NETS or credit card. Thank you.
Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Mercedes-Benz Service Center
188 Pandan Loop
Singapore 120379
Tel: 6777 6386
Fax: 6779 6383
www.mercedes-benz.com.sg

13-10-17:17:44



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196800307V
GST Reg No. MFR0500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
Ministry Of Defence HQ Maintenance & Engineering Supp 151 Choa Chu Kang Way Blk 822 #02-14 Kranji Camp 3 Singapore 688248 (Attn: ME4 Kevin) Contact No 63074217 Kevin Ho	Cust No/Name WM000130/Ministry Of Defence Reg No/Reg Date MID18 / 05/05/2010 Date In/Mileage 02/02/2018/ 144570 Chassis No WDD2120482A178280 Engine No 27188030041180 Make/Model MBW 200 CGI SEDAN (W212) Colour/Trim 021 197 Obsidian BV 042 208 Leather Gr

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
WM000130	Credit	07/09/2016/ 10:19	VS	321 / Helen Lee Sit Sing	87002	28123035	
Description of Goods / Services					Qty	Unit Price	Amount
X MA003 990 35 97		RIVET			10.00	2.32	23.20
X MA212 885 20 21		REAR BUMPER CENT			1.00	162.86	162.86
X MA212 885 21 21		LEFT REAR BUMPER			1.00	121.05	121.05
X MA212 885 22 21		RIGHT REAR BUMP			1.00	121.05	121.05
X MA000 991 43 95		CLIP			2.00	2.54	5.08
X MA221 820 04 58		LICENSE PLATE LA			1.00	17.86	17.86
X MA221 820 04 58		LICENSE PLATE LA			1.00	17.86	17.86
X MA212 820 00 28		SUPPORT ABSORBER			2.00	26.77	53.54
X MA204 880 01 27		BONNET HOOK			2.00	27.50	55.00
X MA212 880 00 64		SAFETY HOOK			1.00	66.56	66.56
X MA212 760 00 84/28		(s/s) FASTENER			1.00	434.22	434.22

Parts	14,178.75
Labour	12,308.00
Standard Menu	0.00
Specialist Job	210.00
Diagnostics Job	0.00
Sundry/Others	0.00
Total (w/o GST)	26,696.75

Nett	26,696.75
7% GST on	26,696.75
Total Payable	28,566.52
Paid	0.00
Total Due	28,566.52
Balance B/FWD	13,782.25
Total Payable or C/PWD	42,347.77

Payment should be made strictly by cash, NETS or credit cards. Thank you.
Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 6305
Fax: 6778 5983
www.mercedes-benz.com.sg

SECURITY CLASSIFICATION

Damage Observed on MID 18

MID 18 suffered dents on the front bumper and rear bumper.

Fig. B-1: Close-Up of Damage on MID 18



Fig. B-2: Close-Up of Damage on MID 18



SECURITY CLASSIFICATION

Fig. B-3: Close-Up of Damage on MID 18



Fig. B-4: Front View of MID 18



Fig. B-5: Rear View of MID 18



Fig. B-6: Left Side View of MID 18



Fig. B-7: Right Side View of MID 18



SECURITY CLASSIFICATION

Fig. B-8: Photos of incident Yellow Taxi (SHB 3368P)




Fig. B-9: Photos of incident Grey BMW (SFF 1944S) and Grade 1 Staff Car (MID 18)

