

INS. CASE OWNER:

Kumar, Anilmani

CE 6/AIG1600

2798 ; Aha3 sr

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

15-5-16

Date / Time:

15-5-16

Registered in Merimen:

16-5-16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDV 5785Y

Name of Insured:

Wong Meng Teck

Insured Tel No.:

HP:

86115689

Excess Sec II :SS

D.O.A.:

9-5-16

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

993262060389

Policy No.:

2100409399

Make / Model:

Subaru Forester - 3-0 (A)

Place of Accident:

JIN of Woodlands SF 83/

Woodlands Dr 40 Lane 4

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJL 2763L



INSRS:

WSP:

Tel:

Liability:

RMKS:

* Automobile



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/2/16

VIC

SJL 2763L - X, SDV 5785Y - X

- POTENTIAL RESORT CLAIM

- TO GET OI CCTV FOOTAGE

- TP WOUND AND CLAIM. REQUEST OI CCTV FOOTAGE

IN ORDER TO DENY LIABILITY IN TP CLAIM.

07/04/16 @ 2.34pm

SPOKEN TO OI THE CONFIRMED ACCIDENT, FOOTAGE HAD SEND

TO WORKSHOP AND AIG, AIG REQUESTED FOOTAGE TWO DAYS AGO

OI SEND TO AIG (LINA RAMLI).

04/04/16

- AIG EMAIL IN TO RESORT TP CLAIM.

07/04/16 @ 2pm

MS LINA OF AIG CALLED IN AND CONFIRMED

SHE RECEIVED OI CCTV FOOTAGE. AS PER HER

EMAIL, TO RESORT TP CLAIM. OI IS NOT AT

FAULT.

04/04/16

- EMAIL TO TP RESORT.

- PENDING TP ESTIMATE. TO CLOSE CASE.

16-06-17

TO REJECT TP CLAIM IF CCTV PROVES THAT TP WAS

BEATING TRAFFIC LIGHT AND CAUSED THE COLLISION.

14-09-18

A YEAR HAS PASSED. STILL ESTIMATE IS NOT READY. TO EXPEDITE

PRELIMINAR: 24-11-18

URGENT SURVEYOR TO ISSUE ESTIMATE INSTEAD OF PROLONG

THE CASE FOR NOTHING.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

NO SETTLEMENT
REPAIR COST
"PAR ONLY"
NO ESTIMATE

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

1180.00

COPY SENT
8/1/19

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJL2763L Yr Regn: 2008 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lances c.c. 1584Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 134340 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTCS3A84010850

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 06 mm Rear 06 mmR/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 15/02/16Survey held at S.K.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG16002798/Ahv3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 16-02-2016	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDV 5785Y	Veh. Inspected	SJL 2763L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/02/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/02/2016	Inspection Date	15/02/2016
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR CAR (LH)

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door <i>Re</i>		Re	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door <i>Hinge Chrome Moulding</i> <i>re</i>		✓	
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH <i>Distorted</i>		✓	
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

No of Items:

Assessor:

Vehicle No: *SJL2763L*

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door <i>Distorted</i>		✓	
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door <i>Hinge Chrome Moulding</i> <i>re</i>		✓	
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber <i>lit</i>		✓	
1299	993275	Rear LH Door Outer Handle <i>Damaged</i>		✓	
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock <i>Torn</i>		✓	
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper <i>Distorted</i>		✓	
1147	992976	Rear Bumper <i>Bracket Chips</i> <i>re</i>		✓	
1148	993068	Rear Bumper Side Retainer <i>re</i>		✓	
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender <i>Distorted</i>		✓	
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			
		<i>Rear Windscreen Moulding</i> <i>re</i>		✓	
		<i>Rear Windscreen Sealant</i> <i>re</i>		✓	
		<i>Rear Wheel Rim LH</i> <i>lit</i>		✓	
		<i>Rear Tyre LH - Punctured</i>		✓	
		<i>Rear Lower Arm LH</i> <i>2</i>		✓	
		<i>Rear Knuckle Arm LH</i> <i>2</i>		✓	
		<i>Rear Shock Absorber LH</i>		✓	
		<i>Rear Trailing Arm LH</i>		✓	
		<i>Rear Wheel Hub (w/Brake)</i>		✓	

L/S 15 Days.

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate <i>But</i>	✓		
1002	991887	Frt Number Plate Base <i>But</i>	✓		
1003	991889	Frt Number Plate Garnish <i>But</i>	✓		
1004	991300	Frt Bumper <i>Dist'd</i>	✓		
1005	992341	Frt Bumper Clips <i>m</i>	✓		
1006	991325	Frt Bumper Bracket	✓		
1007	991462	Frt Bumper Side Retainer <i>m</i>	✓		
1008	991433	Frt Bumper Reinforcement <i>But</i>	✓		
1009	991318	Frt Bumper Beam	✓		
1010	991468	Frt Bumper Sponge	✓		
1011	991427	Frt Bumper Protector	✓		
1012	991420	Frt Bumper Pad	✓		
1013	991363	Frt Bumper Grille <i>Dist'd</i>	✓		
1014	991301	Frt Bumper Moulding	✓		
1015	991407	Frt Bumper Lower Spoiler	✓		
1016	991438	Frt Bumper Sensor	✓		
1017	995100	Frt LH Bumper Fog Lamp Cover	✓		
1018	991355	Frt RH Bumper Fog Lamp Cover	✓		
1019	995079	Frt LH Bumper Fog Lamp	✓		
1020	995080	Frt RH Bumper Fog Lamp	✓		
1021	991793	Frt Grille <i>Cracked</i>	✓		
1022	991328	Frt Grille Emblem <i>m</i>	✓		
1023	991799	Frt Grille Chrome Moulding <i>Garnish could</i>	✓		
1024	991222	Frt Apron Panel	✓		
1025	992013	Frt Support Panel <i>But</i>	✓		
1026	992025	Frt Support Panel Top Garnish Cover	✓		
1027	992416	Horn	✓		
1028	991277	Frt Brace Panel <i>But</i>	✓		
1029	995153	Frt LH Headlamp Assy <i>Cracked</i>	✓		
1030	991821	Frt RH Headlamp Assy	✓		
1031	995088	Frt LH Side Lamp	✓		
1032	995089	Frt RH Side Lamp	✓		
1033	990248	Bonnet <i>Dist'd</i>	✓		
1034	991328	Bonnet Emblem	✓		
1035	990287	Bonnet Lock <i>Painted</i>	✓		
1036	990285	Bonnet Insulator	✓		
1037	990273	Bonnet Hinge <i>But</i>	✓		
1038	990261	Bonnet Damper	✓		
1039	990305	Bonnet Rubber	✓		
1040	990252	Bonnet Cable	✓		
1041	990311	Bonnet Stand	✓		
1042	990119	Air Con Condenser <i>But</i>	✓		
1043	990122	Air Con Fan Assy <i>end</i>	✓		
1044	990134	Air Con Suction Pipe (Low Pressure)	✓		
1045	990118	Air Con Suction Hose	✓		
1046	990133	Air Con Discharge Pipe (High Pressure)	✓		
1047	990114	Air Con Discharge Hose	✓		
1048	990149	Air Con Liquid Pipe	✓		
1049	995066	Air Con Receiver Drier	✓		
1050	990111	Air Con Compressor Assy	✓		
1051	995294	Air Con Belt	✓		
1052	995074	Radiator <i>But</i>	✓		
1053	992738	Radiator Cowling	✓		
1054	992742	Radiator Fan Assy <i>But</i>	✓		
1055	992745	Radiator Fan Clutch	✓		
1056	992758	Radiator Hose Top	✓		
1057	992757	Radiator Hose Bottom	✓		
1058	992741	Radiator Expansion Tank	✓		
1059	990151	Air Duct <i>Dist'd</i>	✓		
1060	990070	Air Cleaner Assy <i>But</i>	✓		
1061	990056	Air Cleaner Hose	✓		
1062	990089	Air Cleaner Resonator	✓		
1063	991712	Frt Exhaust Manifold	✓		
1064	991713	Frt Exhaust Manifold Cover	✓		
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)	✓		
1066	991714	Front Exhaust Pipe	✓		
1067	990219	Battery	✓		
1068	990224	Battery Cover	✓		
1069	990223	Battery Bracket	✓		
1070	990229	Battery Tray	✓		

Vehicle No: *SJL 2763L*

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box	✓		
1072	994011	Relay Box	✓		
1073	995053	Wiper Washer Tank	✓		
1074	995052	Wiper Washer Tank Motor	✓		
1075	990159	Alternator Assy	✓		
1076	990160	Alternator Belt	✓		
1077	992688	Power Steering Pump	✓		
1078	992669	Power Steering Belt	✓		
1079	994431	Power Steering Cooler Pipe	✓		
1080	992692	Power Steering Hose	✓		
1081	990010	ABS Pump Control Unit	✓		
1082	990427	Brake Master Pump Assy	✓		
1083	990403	Brake Booster Pump Assy	✓		
1084	991005	Engine Top Cover	✓		
1085	991011	Engine Under Cover	✓		
1086	990946	Engine Mounting	✓		
1087	990949	Engine Mounting Frt	✓		
1088	990950	Engine Mounting LH	✓		
1089	990952	Engine Mounting RH	✓		
1090	990951	Engine Mounting Rear	✓		
1091	992234	Gear Box Mounting	✓		
1092	991520	Frt LH Chassis Member	✓		
1093	991520	Frt RH Chassis Member	✓		
1094	990728	Frt Vertical Cross Member	✓		
1095	991863	Frt Lower Cross Member	✓		
1096	995070	Frt LH Fender <i>Cracked</i>	✓		
1097	995072	Frt LH Fender Inner Panel	✓		
1098	995147	Frt LH Fender Lamp	✓		
1099	995148	Frt LH Fender Protector <i>mostly new</i>	✓		
1100	991740	Frt LH Fender Inner Shield	✓		
1101	995179	Frt LH Mudflap	✓		
1102	995170	Frt LH Wheel Rim	✓		
1103	994025	Frt LH Rim Cover	✓		
1104	995065	Frt LH Tyre	✓		
1105	995071	Frt RH Fender	✓		
1106	991739	Frt RH Fender Inner Panel	✓		
1107	991744	Frt RH Fender Lamp	✓		
1108	991752	Frt RH Fender Protector	✓		
1109	991740	Frt RH Fender Inner Shield	✓		
1110	991884	Frt RH Mudflap	✓		
1111	992087	Frt RH Wheel Rim	✓		
1112	994025	Frt RH Rim Cover	✓		
1113	995065	Frt RH Tyre	✓		
1114	992093	Frt Windscreen Glass	✓		
1115	992117	Frt Windscreen Rubber	✓		
1116	992108	Frt Windscreen Moulding	✓		
1117	992098	Frt Windscreen Sealant	✓		
1118	991019	ERP Bracket	✓		
1119	991020	ERP Unit	✓		
1120	992140	Frt Wiper Arm	✓		
1121	992142	Frt Wiper Blade	✓		
1122	995045	Wiper Panel Garnish	✓		
1123	991126	Firewall Panel	✓		
1124	990753	Dashboard Assy	✓		
1125	992282	Glove Box Cover	✓		
1126	992281	Glove Box Compartment	✓		
1127	994483	Steering Wheel Airbag	✓		
1128	994485	Steering Wheel Airbag Sensor	✓		
1129	990749	Dashboard Airbag	✓		
1130	990750	Dashboard Airbag Sensor	✓		
1131	990029	Airbag Control Unit	✓		
1132	990864	Frt Driver Seat	✓		
1133	991923	Frt RH Seat Belt Assy	✓		
1134	991899	Frt Passenger Seat	✓		
1135	995182	Frt LH Seat Belt Assy	✓		
1136	990247	Sticker	✓		

Addendum Sheet Pg.1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MD51607081 Vehicle Registration No : SDV57854
Name(as shown in NRIC): Wong MangTrek
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : S1804025E
Address : _____
Contact (Tel) : _____ (H/P) : 86115689
(Email) : _____
Date of Accident : 09/02/16 Time of Accident : 1630
Place of Accident : JIN OF Woodlands St 83 / Woodlands Dr to 2 Ave 4
Insurance Company : AIK Asia Pacific Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To amend :

- Was anybody injured in the Accident : YES
- Was any other material or property damaged : YES
- Was there any video captured by Car Owner : YES

F. 

Signature of Vehicle Owner / Driver

Date: 12/02/16

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm

Addendum Sheet Pg.1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MD51607081 Vehicle Registration No : SDV5785Y
Name(as shown in NRIC) : Wong Meng Teck
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : S1804025E
Address : _____
Contact (Tel) : _____ (H/P) : 86115689
(Email) : _____
Date of Accident : 09/02/16 Time of Accident : 1630
Place of Accident : JLN OF woodlands St 83 / Woodlands Dr 40 & Ave 4
Insurance Company : AIG Asia Pacific Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To amend the report to claiming own insurance and
seek recovery from the 3rd party claim after car is
serviced and repair to re-instate all damages claims and
losses

F. (Signature)
Signature of Vehicle Owner / Driver
Date: 15/02/16

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm

Vic

From: Ramli, Lina-Diyanah [Lina-Diyanah.Ramli@aig.com]
Sent: Monday, 4 April, 2016 4:52 PM
To: Vic
Cc: Hsiao Tong; Admin A
Subject: [BOLA] AIG ref : 9932620602SG-003 | Your ref : CC6/AIG16002798/AHV3 | Acc on 09.02.2016 invlg SDV5785Y (AIG) & SJL2763L

Importance: High

AIG ref : 9932620602SG-003
Your ref : CC6/AIG16002798/AHV3

Dear Vic

We refer to the above matter and our telephone conversation today afternoon.

As spoken, TP has reverted to OD. We have received TP BOLA claim from M/s Aviva Ltd, insurer of SJL2763L. Please close file at your end.

We also note that you have requested for Ol's copy of the above Accident Video Footage. Kindly forward us copy of the same on an urgent basis.

Thank you.

Regards
Lina Diyanah Ramli
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1769 | Fax +(65) 6835 7416

lina-diyannah.ramli@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Vic

From: Ramli, Lina-Diyanah <Lina-Diyanah.Ramli@aig.com>
Sent: Monday, 4 April, 2016 4:52 PM
To: Vic
Cc: Hsiao Tong; Admin A
Subject: [BOLA] AIG ref : 9932620602SG-003 | Your ref : CC6/AIG16002798/AHV3 | Acc on 09.02.2016 invlg SDV5785Y (AIG) & SJL2763L

Importance: High

AIG ref : 9932620602SG-003
Your ref : CC6/AIG16002798/AHV3

Dear Vic

We refer to the above matter and our telephone conversation today afternoon.

As spoken, TP has reverted to OD. We have received TP BOLA claim from M/s Aviva Ltd, insurer of SJL2763L. Please close file at your end.

We also note that you have requested for OI's copy of the above Accident Video Footage. Kindly forward us copy of the same on an urgent basis.

Thank you.

Regards
Lina Diyanah Ramli
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1769 | Fax +(65) 6835 7416

lina-diyanah.ramli@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Vic

From: Vic
Sent: Monday, 4 July, 2016 9:06 AM
To: SK Admin
Cc: Julie Johari; Admin A; Vic
Subject: Your Ref: SJL 2763L_ACCIDENT INVOLVING VEHICLES SDV 5785Y AND SJL 2763L ON 09/02/2016
Attachments: SDV 5785Y Statement.pdf

Your Ref: SJL 2763L
Our Ref: CC6/AIG16002798/Aha3

Without Prejudice

Dear Huey Lee,

ACCIDENT INVOLVING VEHICLES SDV 5785Y AND SJL 2763L ON 09/02/2016

We refer to the above matter.

Please be informed that we had further reviewed the matter and based on the available information at hand and CCTV footage, our Principal is in the view that our Insured is not liable of this accident as the Traffic Light was green arrow in our Insured's favour when the accident happened. Kindly refer to the attached report.

A copy of the footage is available upon request.

In view of the above, we regret to inform you and we have our principal's instruction that we are unable to look into your claim.

As such, we will close file in our end.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Feb 2016 17:45 Edit Reg		15 Feb 2016 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Wong Meng Teck , ID: S1804025E		
Main Claimant:	TEOW KOON SIONG , ID: S0214641Z		
Vehicle Reg. No.:	SJL2763L	Date of Loss:	09/02/2016 16:00 - :59 [86 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9932620602SG	Policy/Cover Note No.:	2100409399 (Comprehensive)
Vehicle Reg. No. (Insured):	SDV5785Y	Policy No. (Claimant):	10106688
		Excess:	
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Kumar, Arulmani] arulmanikumar@aig.com		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/02/2016]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL2763L (9932620602SG)**

[SDV5785Y]

TP

TEOW KOON SIONG

Feb 9 2016 4:30PM

[Wong Meng Teck]

SK Automobile Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 16:03	Chassis Number	 Load JPG	
2	30/10/18 16:04	General View	 Load JPG	
3	30/10/18 16:04	General View	 Load JPG	
4	30/10/18 16:04	General View	 Load JPG	
5	30/10/18 16:04	General View	 Load JPG	
6	30/10/18 16:04	General View	 Load JPG	
7	30/10/18 16:04	General View	 Load JPG	
8	30/10/18 16:04	General View	 Load JPG	
9	30/10/18 16:04	General View	 Load JPG	
10	30/10/18 16:04	General View	 Load JPG	
11	30/10/18 16:04	General View	 Load JPG	
12	30/10/18 16:04	General View	 Load JPG	
13	30/10/18 16:04	General View	 Load JPG	
14	30/10/18 16:04	General View	 Load JPG	
15	30/10/18 16:04	General View	 Load JPG	
16	30/10/18 16:04	General View	 Load JPG	
17	30/10/18 16:04	General View	 Load JPG	
18	30/10/18 16:04	General View	 Load JPG	
19	30/10/18 16:04	General View	 Load JPG	
20	30/10/18 16:04	General View	 Load JPG	
21	30/10/18 16:04	General View	 Load JPG	
22	30/10/18 16:04	General View	 Load JPG	
23	30/10/18 16:04	General View	 Load JPG	
24	30/10/18 16:04	General View	 Load JPG	
25	30/10/18 16:04	General View	 Load JPG	
26	30/10/18 16:04	General View	 Load JPG	
27	30/10/18 16:04	General View	 Load JPG	
28	30/10/18 16:04	General View	 Load JPG	
29	30/10/18 16:04	General View	 Load JPG	
30	30/10/18 16:04	General View	 Load JPG	
31	30/10/18 16:04	General View	 Load JPG	
32	30/10/18 16:04	General View	 Load JPG	
33	30/10/18 16:04	General View	 Load JPG	
34	30/10/18 16:04	General View	 Load JPG	
35	30/10/18 16:04	General View	 Load JPG	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	30/10/18 16:04	General View	Load JPG	☒
37	30/10/18 16:04	General View	Load JPG	☒
38	30/10/18 16:04	General View	Load JPG	☒
39	30/10/18 16:04	General View	Load JPG	☒
40	30/10/18 16:04	General View	Load JPG	☒
41	30/10/18 16:04	General View	Load JPG	☒
42	30/10/18 16:04	General View	Load JPG	☒
43	30/10/18 16:04	General View	Load JPG	☒
44	30/10/18 16:04	General View	Load JPG	☒
45	30/10/18 16:04	General View	Load JPG	☒
46	30/10/18 16:04	General View	Load JPG	☒
47	30/10/18 16:04	General View	Load JPG	☒
48	30/10/18 16:04	General View	Load JPG	☒
49	30/10/18 16:04	General View	Load JPG	☒
50	30/10/18 16:04	General View	Load JPG	☒
51	30/10/18 16:04	General View	Load JPG	☒
52	30/10/18 16:04	General View	Load JPG	☒
53	30/10/18 16:04	General View	Load JPG	☒
54	30/10/18 16:04	General View	Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/02/16 17:45	TP GIA REPORT	Load PDF	
2	04/07/16 09:08	EMAIL FROM AIG TO REJECT CLAIM	Load PDF	
3	04/07/16 09:08	EMAIL TO TP REJECT CLAIM	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/02/16 11:11	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG16002798/AHA3S2

Date: 12/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100409399

Claimant Vehicle No: SJL2763L

Insured Vehicle No: SDV5785Y

Date of Loss: 09/02/2016

Nature of Claim: TP

Claim No: 9932620602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL2763L

Make & Model: MITSUBISHI LANCER, 1.6 (A)

Engine No: 4G18JT2913

Reg. Date: 21/11/2008 (Man. Year: 2008)

Chassis No: JMYSTCS3A8U010850

Colour: Silver

Odometer: 134340 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15

Rear Tyre Size: 195/60R15

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/02/2016

SK Automobile Pte Ltd (HQ)

Date Inspected: 15/02/2016 Inspected At:

23 KAKI BUKIT AVE 4 # 03-01 VICOM INSPECTION CENTRE
Singapore 415933

Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Repair	0.00 F	*-F
2	1		*FRT LH DOOR CHROME MOULDING	Necessary	0.00 F	*-F
3	1		*ROCKER PANEL LH	Dented	0.00 F	*-F
4	1		*REAR LH DOOR	Distorted	0.00 F	*-F
5	1		*REAR LH DOOR CHROME MOULDING	Necessary	0.00 F	*-F
6	1		*REAR LH DOOR RUBBER	Cut	0.00 F	*-F
7	1		*REAR LH DOOR OUTER HANDLE	Damaged	0.00 F	*-F
8	1		*REAR LH DOOR LOCK	Jammed	0.00 F	*-F
9	1		*REAR BUMPER	Deformed	0.00 F	*-F
10	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
11	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
12	1		*REAR LH FENDER	Distorted	0.00 F	*-F
13	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*-F
14	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*-F
15	1		*REAR WHEEL RIM LH	Cut	0.00 F	*-F
16	1		*REAR TYRE LH	Punctured	0.00 F	*-F
17	1		*REAR LOWER ARM LH	Bent	0.00 F	*-F
18	1		*REAR KNUCKLE ARM LH	Bent	0.00 F	*-F
19	1		*REAR SHOCK ABSORBER LH	Bent	0.00 F	*-F
20	1		*REAR TRAILING ARM LH	Bent	0.00 F	*-F
21	1		*REAR WHEEL HUB C/W BEARING	Damaged	0.00 F	*-F
22	1		*FRT NUMBER PLATE	Bent	0.00 F	*-F
23	1		*FRT NUMBER PLATE BASE	Deformed	0.00 F	*-F
24	1		*FRT NUMBER PLATE GARNISH	Deformed	0.00 F	*-F
25	1		*FRT BUMPER	Distorted	0.00 F	*-F
26	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
27	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
28	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*-F
29	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*-F
30	1		*FRT GRILLE	Cracked	0.00 F	*-F
31	2		*FRT GRILLE GARNISH	Cracked	0.00 F	*-F
32	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
33	1		*FRT BRACE PANEL	Bent	0.00 F	*-F
34	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*-F
35	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*-F
36	1		*BONNET	Distorted	0.00 F	*-F
37	1		*BONNET LOCK	Jammed	0.00 F	*-F
38	2		*BONNET HINGE	Bent	0.00 F	*-F
39	1		*AIR CON CONDENSER	Bent	0.00 F	*-F
40	1		*AIR CON FAN ASSY	Damaged	0.00 F	*-F
41	1		*RADIATOR	Bent	0.00 F	*-F
42	1		*RADIATOR FAN ASSY	Damaged	0.00 F	*-F
43	1		*AIR DUCT	Deformed	0.00 F	*-F
44	1		*AIR CLEANER ASSY	Cracked	0.00 F	*-F
45	1		*FRT LH FENDER	Buckled	0.00 F	*-F
46	1		*FRT LH FENDER CHROME MOULDING	Necessary	0.00 F	*-F
47	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >