

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5246P - AXA*Not Authoised*
*1.B-1***RIZA**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5246P - RIZA

VF1ABL15AUC276844

RENAULT

LATITUDE

14.02.16

AXA

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>By</i> 852.66 ✓
2	1	BUMPER LOWER REAR	\$	<i>Dis/um</i> 591.41 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 87.29 X
4	1	BUMEPR BRACKET SIDE RH REAR(Taillamp lower)	\$	<i>CM</i> 104.59 ✓
5	1	BUMEPR RETAINER RH REAR	\$	<i>CM</i> 34.61 ✓
6	1	BUMPER REFLECTOR RH	\$	<i>Bo</i> 33.55 ✓
7	1	BUMEPR BRACKET SIDE LH REAR(Taillamp lower)	\$	<i>Sm</i> 104.59 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 34.61 X
9	1	BUMPER BEAM REAR	\$	<i>R</i> 598.09 X
10	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 173.81 X
11	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 173.81 X
12	1	FENDER PANEL REAR LH	\$	<i>R</i> 2,537.80 X
13	1	FENDER PANEL REAR RH	\$	<i>Br</i> 2,537.80 ✓
14	1	FENDER WHEELARCH REAR RH(Linner)	\$	<i>R</i> 418.06 X
15	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	<i>R</i> 2,337.72 X
16	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Return</i> 516.50 ✓
17	1	AIR VENT	\$	<i>ASP</i> 74.83 X
18	1	BOOT REAR	\$	<i>R</i> 2,209.75 X
19	1	BOOT FINISHER (Moulding)	\$	<i>Sm</i> 429.90 X
20	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 248.50 X
21	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 379.50 X
22	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 379.50 X
23	1	BOOT BADGE 'RENAULT'	\$	<i>rr</i> 173.35 X
24	1	BOOT BADGE	\$	<i>rr</i> 173.35 X
25	1	BOOT HINGE LH	\$	<i>R</i> 282.96 X
26	1	BOOT HINGE RH	\$	<i>R</i> 282.96 X
27	1	BOOT LOCK	\$	<i>R</i> 155.90 X
28	1	BOOT LOCK CATCH	\$	<i>R</i> 72.00 X
29	1	TAILLAMP RH	\$	<i>CM</i> 425.04 ✓
30	1	TAILLAMP PANEL RH	\$	<i>Br</i> 759.00 ✓
31	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 1,684.52 X
32	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	<i>Sm</i> 470.93 X
33	1	OUTER PANEL REAR (End Panel)	\$	<i>By</i> 1,132.13 ✓
34	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 308.48 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5246P - AXA**RIZA**

35	1	EXHAUST REAR	\$	<i>B</i> 5,760.00 ✓
36	1	EXHAUST CAP REAR	\$	<i>P</i> 177.30 ✓
37	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 759.61 X
38	1	DOOR PANEL REAR RH	\$	<i>R</i> 2,188.20 X

TOTAL	\$	29,664.61
10%	\$	2,966.46
	\$	26,698.15

Special Nett

1	1SET	PARKING AID	\$	<i>T</i> 600.00 ✓
2	1SET	REAR BUMPER CLIP	\$	<i>M</i> 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>M</i> 33.00 ✓
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	<i>N</i> 10.00 X
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	<i>N</i> 20.00 X
6	1SET	BUMPER LOWER REAR CLIP	\$	<i>M</i> 66.00 ✓
7	1SET	BUMPER BEAM BOLT	\$	<i>S</i> 33.00 X
8	1SET	WHEELARCH CLIP REAR RH	\$	<i>N</i> 45.00 X
9	2	Rear Windscreen Sealant	\$	<i>M</i> 80.00 40sm
10	1	Rear Windscreen Inner Sponge Seal	\$	<i>M</i> 150.00 30sm
11	1	RIM (ROUE 7J 16H 2547)RH RR	\$	<i>S</i> 385.00 X
12	1	TYRE RH RR	\$	<i>S</i> 330.00 X
13	1	CAP HUB RH REAR	\$	<i>S</i> 35.60 X
14	1	DOOR STICKER "6555-3333"	\$	<i>N</i> 80.00 X
15	1	BOOT STICKER "Trans-cab"	\$	<i>N</i> 30.00 X
16	1	BOOT STICKER "6555-3333"	\$	<i>N</i> 30.00 X
17	1	EXHAUST MOUNTING REAR	\$	<i>T</i> 65.50 ✓
18	1	EXHAUST BRACKET REAR	\$	<i>R</i> 22.22 X

TOTAL	\$	2,081.32
TOTAL PARTS	\$	28,779.47

Putty And Spray Painting Of The Affected Portion. \$ 5,400.00 *2800*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 6,000.00 *1200*

To Rust-Proofing Of The Affected Areas. \$ 170.00 *600*

To reinstall rear bumper parking sensor. \$ 170.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD**RIZA**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5246P - AXA

To check steering geometry and computer wheel alignment	\$	220.00 600
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 1000
Towing Fees	\$	120.00 500
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 1200
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00 1000
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	~ 380.00 X

TOTAL	\$	13,460.00
Over All Total	\$	42,239.47

Repair Days*8 days*, **20 Days**
(PARTS BY PARTS)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: