

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3777G

DATE 16/2/2016 16:16

MAKE :

MODEL : HYUNDAI SONATA

LKK-Henry

Ang Azia - LS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>dented</i>			\$ 1,151.80
	Front Bumper Cover <i>gra</i>			\$ 538.80
	Front Bumper Sponge <i>svc</i>			\$ 136.30
	Front Bumper Reinforcement <i>svc</i>			\$ 504.10
	Front Bumper Lip <i>svc</i>			\$ 59.90
	Front Bumper Protector (RH) <i>gra</i>			\$ 29.20
	Front Bumper Bracket (RH) <i>gra</i>			\$ 20.10
	Front Bumper Side Bracket <i>gra</i>			\$ 14.30
	Front Fender (RH) <i>dented</i>			\$ 593.00
	Front Fender Shield (RH) <i>svc</i>			\$ 86.00
	Headlamp RH <i>gra</i>			\$
	SUB TOTAL			\$ 3,133.50
	LESS 20%			\$ 626.70
	DISCOUNTED TOTAL			\$ 2,506.80
	Front Fender Advertisement Logo (RH) <i>net</i>			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 480.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	TOTAL LABOUR			\$ 1,230.00
	ESTIMATE TOTAL			\$ 3,836.80
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			