

15/5/2019

INSURANCE OWNER:

1shale

CC 6/AIG1600

3566, MWG3/S2

LKK:
IDAC:

Surveyor:

Ma.

DOI:

ASSIGNMENT

23/2/16

Date / Time:

23/2/16

Registered in Merimen:

24/2/16

Pre-assign / CCU / FTE

SJP 2772P

Claim No.:

702306035056



Insured Vehicle No.:

Name of Insured:

Basaker Plo Santa

Policy No.:

2100422759

Insured Tel No.:

9694205 HP: 82332027

Make / Model:

Mazda Bionte

Excess Sec II :SS

D.O.A:

18/2/16

Place of Accident:

Holland Road

Is driver the owner?

(YES / NO)

Nature of Accident:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

If NO, Driver Name / Age:

(V/L: YES / NO)

Insured Liability:

%

Final? Yes / No

Driver Tel No.:

SJP 2772

SK 7945S

SJP 6398M



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

KM-1
TP

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
20/2/16	Non-Reporting ltr (1st):	
20/2/16	Non-Reporting ltr (2nd):	
20/2/16	Non-Reporting ltr (Final):	
20/2/16	Notification ltr (if non-pickup):	
20/2/16	Call OI:	
20/2/16	After call ltr to OI:	
20/2/16	Documentation Check List:	Handler Typist
20/2/16	Notification ltr (if non-pickup)	
20/2/16	After call ltr to OI:	
20/2/16	Authorisation To Act:	
20/2/16	Release Voucher:	
20/2/16	Final Repair Bill:	
20/2/16	Car Rental Invoice:	
20/2/16	Towing Invoice	
20/2/16	LTA / GIA:	
20/2/16	Medical Bill:	
20/2/16	PIR:	
20/2/16	Mandate/Reject Instruction:	
20/2/16	LOD	
20/2/16	Payment Breakdown Form:	
20/2/16	Post-Repair Photos:	
20/2/16	Others:	

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Mr Chia

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

27 or 28?

If NO or B 28, Ass. Lia:

100%

Repair Cost:

SS

20865.00

Loss of Rental (LOR):

SS

1400.00

(14 days) X100.00

Loss of Use (LOU):

SS

(\$ x days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

5-3X

Medical:

SS

(e.g. Tow/ Independent)

Disbursement:

SS

Legal Cost

SS

22270.25

Global Sum SS: 22,200.00

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

22200.00

Name 1:

EM-1 Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

(09/11/13)

REF:

C6 / A14 / 16003566 / M / W93

Signature:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s SWI

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK79455 Yr Regn: APR / 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

W Truck / Trailer orMake: MAZDA RX 8 c.c. 1308Colour: Police A/C: Insured / Std / NI / NASp. Reading: 119557 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SE3P 302594Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40/R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 18/10/2016 D.O.I. 23/12/2016

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11/18 Confirm U/S \$19500.00 with 14 working days

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

(Prel. \$24700.24
56.1)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG16003566/M1wg3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 24-02-2016	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJP 2772P	Veh. Inspected	SKT 7945S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/02/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/02/2016	Inspection Date	23/02/2016
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

1,238.00	135.00	40.00	2,100.00
56.20	3,646.00	250.00	2,000.00
52.00	92.00	150.00	150.00
56.20	40.00	15.00	60.00
223.10	846.20	40.00	120.00
279.60	56.00	40.00	120.00
40.00	78.00	450.00	120.00
269.60	50.00		60.00
175.20	219.00		60.00
	226.00	40.00	80.00
	163.50	220.00	120.00
176.20	40.00	80.00	
170.00		80.00	
	580.00		
	211.00	40.00	
982.00	150.00		
72.00	254.00		
50.00	64.00		
302.00	572.00		
868.00			
96.00			
174.00			
50.00			
572.50			
110.00			
145.20	1,529.00		
138.00	129.00		
	60.00		
206.50			
365.00	1,287.00		
326.00			
595.60			
192.00			
30.00			
186.50			
	1,096.00		
495.00			
163.20			
197.50			
68.00	196.00		
1,041.00			
446.00			
60.00	30.00		
296.00			
50.00			
132.00			
116.00			
60.00			
892.50			
144.00			

Total List Price	\$	24,108.30
Discount		20%
List Price (after Discount)	\$	19,286.64
Total Nett Price		
Discount		10%
Nett Price (after Discount)	\$	-
Total Special Nett	\$	1,445.00
Total Labour	\$	4,990.00
Grand Total	\$	25,721.64
Discount 20%		20%
Lump Sum Repair Cost	\$	20,577.31

S\$ 20,550.00

Columns

A	List Price
B	List Price
C	Special Nett
D	Labour

VEHICLE NO.
SKT 79455

DOA :
18.02.2016

MODEL NO.
VOLKSWAGEN JETTA

\$19500 b
14w/day c

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

Page 1 - 7

SK7 79455

Машина КХ-8

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 2-7

Tp/416

ESTIMATE

SKT 79455

Mazda Rx-8

	1pc	Rear Bumper	def ✓	\$868.00
	2pc	Rear Bumper Side Retainer @48	dis ✓	\$96.00
	2pc	Rear Bumper Attachment Retainer @87	dis ✓	\$174.00
	1set	Rear Bumper Clip	in ✓	\$50.00
✓?	1pc	Rear Bumper Reinforcement	dis ✓	\$572.50
	1pc	Rear Bumper No. Plate Lamp	unit ✓	\$110.00
✓?	1pc	Rear Bumper Boot Lid Opener Switch	dis ✓	\$145.20
✓?	2pc	Rear Bumper Reflector @69	dis ✓	\$138.00
	1pc	Rear Bumper Towing Cover	dis ✓	\$41.00
	1pc	Rear Bumper Center Cover	dis ✓	\$206.50
	1pc	Rear Bumper Lower Skirt	dis ✓	\$365.00
	2pc	Rear Bumper Lower Side Arch Garnish @168	dis ✓	\$326.00
	1pc	End Panel	dis ✓	\$545.00
	1pc	End Panel Top Trim	dis ✓	\$192.00
	1set	End Panel Top Trim Clip	in ✓	\$30.00
✓?	1pc	End Panel Inner Lower Garnish	dis ✓	\$186.50
	1pc	Rear Floor Panel	R X	\$412.00
✓?	1pc	Rear Floor Panel Insulator Cloth	dis X	\$495.00
	1pc	Rear Key Antenna Sensor	dis ✓	\$163.20
✓?	1pc	Rear Alarm Speaker	dis ✓	\$197.50
✓?	2pc	Rear Air Vent	dis ✓	\$68.00
				\$
				\$
				\$
				\$

NEC

COMPANY / GST REG. NO: 201316380R

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 4-7

TP/AIG

SKT 79455

ESTIMATE

Mazda Rx-8

✓?	2pc	Head Lamp (HID)	@1823	ova ✓	\$3646.00
	2pc	Head Lamp Bottom Retainer	@46	dis ✓	\$92.00
	2set	Head Lamp Clip	@20	un ✓	\$40.00
	1pc	Front Bumper		dis ✓	\$846.20
	1pc	Front Bumper Budge		un ✓	\$56.00
	2pc	Front Bumper side Retainer	@39	dis ✓	\$78.00
	1set	Front Bumper Clip		un ✓	\$20.00
	1pc	Front Bumper Top Beam		dis ✓	\$219.00
2pc ✓?	1pc	Front Bumper Top Apron Panel		?	\$226.00
	1pc	Front Bumper Top Garnish		dis ✓	\$163.50
	1set	Front Bumper Top Garnish Clip		un ✓	\$40.00
✓?	1pc	Front Bumper Top Rubber		dis ✓	\$68.00
✓?	1pc	Front Bumper Reinforcement		dis ✓	\$580.00
✓?	1pc	Front Bumper Center Sponge		dis ✓	\$211.00
✓?	2pc	Front Bumper side Sponge	@15	dis ✓	\$150.00
	1pc	Front Bumper Lower Grille		dis ✓	\$254.00
	2pc	Front Bumper Towing Cover	@32	dis ✓	\$64.00
✓?	2pc	Front Bumper Fog Lamp	@286	?	\$572.00
X?	2pc	Front Bumper Fog Lamp Cover	@123	?	\$246.00
X?	2pc	Front Bumper Fog Lamp Cover Chrome Moulding	@93	?	\$186.00
	2pc	Front Bumper side Grille	@82	X	\$164.00
	1pc	Front Bumper Lower Skirt		X	\$439.50
	1pc	Engine Under Cover		X	\$213.00
	1set	Engine Under Cover Clip		X	\$30.00
	1pc	Front w/screen		ovl ✓	\$1529.00
	1pc	Front w/screen Moulding		un ✓	\$129.00
	1pc	Front w/screen Inno Seal		un ✓	\$60.00

art

dis
re
one
dis
one
one
one

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

COMPANY / GST REG. NO: 201316380R

Page 5-7

TP/AG

Mazda R48

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 6-7

1P/ALL

ESTIMATE

SKT79455

Special NEM

Mazda RX-8

	1pc	Front w/screen Sealant		\$	60	40 NEC
	1set	Front w/screen Solar Film		\$	380	250 NEC
	1pc	Front w/screen Top solar Film (black)		\$	180	150 NEC
	1pc	ERP Bracket	44 ✓	\$	15	
	1pc	Front No. Plate w/cover	47 ✓	\$	70	40
	1pc	Radiator Coolant	✓	\$	40	NEC
	1pc	Air Cleaner	✓	\$	450	67
	1pc	Air Cleaner Joint Pipe	7	\$	200	NEC
	1pc	Air Cleaner Joint Extent Pipe	7	\$	300	NEC
	1pc	Rear No. Plate w/cover	48	\$	70	40
	1set	Reverse sensor	48	\$	250	220
	1pc	Rear Bumper Center Black sticker		\$	200	80 NEC
	1set	Body Panel Joint sealant		\$	120	80 NEC
	1set	Rear Floor Panel Insulator Pad	NN	\$	150	X
	1pc	Rear w/screen sealant		\$	60	40 NEC
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		
				\$		

✓
✓
✓

FK Auf (Wd)

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

COMPANY / GST REG. NO: 201316380R

Page 7

7th AIG

SK7 79455

Mar 20th Ky 8

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 2-7

Tp/ AIG

ESTIMATE

SKT 79455

Mazda Rx-8

	1pc	Rear Bumper	def ✓	\$
	2pc	Rear Bumper Side Retainer	219 ✓	\$
	2pc	Rear Bumper Attachment Retainer	219 ✓	\$
	1set	Rear Bumper Clip	un ✓	\$
	1pc	Rear Bumper Reinforcement	?	\$
	1pc	Rear Bumper NO. Plate Lamp	unig ✓	\$
	1pc	Rear Bumper Boot Lcd Opener Switch	?	\$
	2pc	Rear Bumper Reflector	?	\$
	1pc	Rear Bumper Towing Cover	MC 219 ✓	\$
	1pc	Rear Bumper Center Cover	219 ✓	\$
	1pc	Rear Bumper Lower Skirt	219 ✓	\$
	2pc	Rear Bumper Lower Side Arch Garnish	219 ✓	\$
	1pc	End Panel	68 ✓	\$
	1pc	End Panel Top Trim	219 ✓	\$
	1set	End Panel Top Trim Clip	un ✓	\$
	1pc	End Panel Inner Lower Garnish	?	\$
	1pc	Rear Floor Panel	R X	\$
	1pc	Rear Floor Panel Insulator Cloth	X	\$
	1pc	Rear Key Antenna Sensor	219 ✓	\$
	1pc	Rear Alarm Speaker	?	\$
	1pc	Rear Air Vent	?	\$
				\$
				\$
				\$
				\$

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 4-7

TP/AIG

ESTIMATE

SKT 79455

Mazda RX-8

	2pc	Head Lamp (HID)	?	\$
	2pc	Head Lamp Bottom Retainer	dis ✓	\$
	2set	Head Lamp Clip	un ✓	\$
	1pc	Front Bumper	dis ✓	\$
	1pc	Front Bumper Badge	un ✓	\$
	2pc	Front Bumper side Retainer	dis ✓	\$
	1set	Front Bumper Clip	un ✓	\$
	1pc	Front Bumper Top Beam	?	\$
	1pc	Front Bumper Top Apron Panel	?	\$
	1pc	Front Bumper Top Garnish	dis ✓	\$
	1set	Front Bumper Top Garnish Clip	un ✓	\$
	1pc	Front Bumper Top Rubber	?	\$
	1pc	Front Bumper Reinforcement	?	\$
	1pc	Front Bumper Center Sponge	?	\$
	2pc	Front Bumper Side Sponge	?	\$
	1pc	Front Bumper Lower Grille	dis ✓	\$
	2pc	Front Bumper Towing Cover	dis ✓	\$
	2pc	Front Bumper Fog Lamp	?	\$
	2pc	Front Bumper Fog Lamp Cover	?	\$
	2pc	Front Bumper Fog Lamp Cover Chrome Moulding	?	\$
	2pc	Front Bumper side Grille	X	\$
	1pc	Front Bumper Lower Skirt	X	\$
	1pc	Engine Under Cover	X	\$
	1set	Engine Under Cover Clip	X	\$
	1pc	Front w/screen	ovl ✓	\$
	1pc	Front w/screen Moulding	un ✓	\$
	1pc	Front w/screen Inner Seal	un ✓	\$

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

Page 5-7

ESTIMATE

5107 79455

Model: RV8

[illegible]

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 6-7

7/16/16

SKT 79455

Special Net

Mazda RX-8

[illegible]

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

COMPANY / GST REG. NO: 201316380R

$$\tau_{\varphi}|_{\text{Alg}}$$

ESTIMATE

Marzola PY-8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

View Received Message

This mail is associated with :

***SKT7945S (7023060350SG)**
[SJP2772P]

TP

DANIEL DAVID CHAN KAI XING

Feb 18 2016 4:20PM

[Baasker S/O Santia]

Em-1 Auto Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 03/12/2018 16:59 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$22270.35) - SKT7945S - Claim Handler: Ishak, Nor Hafizah

Approved:22270.35.

DOCUMENTS SUMMARY

There are no documents.

LETTER OF AUTHORISATION

2

ACCIDENT INVOLVING (any vehicle) SKT7945S and SJP2772P,
ON 18/2/16 ALONG Holland Rd twds Holland Village

I, Daniel David Chan Kai Xing, NRIC No. / Company Reg. No.
_____ of (address) _____

Postal Code _____, the registered owner (or authorised agent) of motor vehicle registration number
SKT7945S hereby authorise your workshop EM-1 Auto Pte Ltd (Company/GST REG.No. : 201316380R)

Blk 8 #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(ies) responsible for the accident.
3. To instruct EM-1 Auto Pte Ltd on my/our behalf to negotiate a settlement with the third party and/ or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto Pte Ltd by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.

I authorise you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorise you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto Pte Ltd, and should I get approval from EM-1 Auto Pte Ltd to bank in the said cheques, I agree to pay EM-1 Auto Pte Ltd the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto Pte Ltd or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto Pte Ltd or the Repairer.

Signature: _____

Company Stamp:
(if applicable)

Name: _____

NRIC No: _____

Contact No: _____

Date: _____

Daniel David Chan Kai Xing
S8528255G
8233 0113
18/2/16

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Feb 2016 17:01 Edit Reg		23 Feb 2016 00:00 Edit Adj Rpt	S\$19,500.00 Edit Estimates	S\$19,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Baasker S/O Santia, ID: S7471557E, Tel: +6582333027		
Main Claimant:	DANIEL DAVID CHAN KAI XING, ID: S8528255G		
Vehicle Reg. No.:	SKT7945S	Date of Loss:	18/02/2016 16:00 - :59 [81 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7023060350SG	Policy/Cover Note No.:	2100422759 (Comprehensive)
Vehicle Reg. No. (Insured):	SJP2772P	Policy No. (Claimant):	GA052230/1
		Excess:	
Repairer:	Em-1 Auto Pte Ltd (HQ) Bk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Ishak, Nor Hafizah] norhafizah.ishak@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 04/03/2016]		
Driver/Custodian (Insured):	Baasker S/O Santia (/ Male), NRIC: S7471557E, Tel: +6582333027		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (03/12/2018): Alert - Adj Mandate Approved (S\$22270.35) - SKT7945S - Claim Handler: Ishak, Nor...
- AIG_SG (19/07/2016): Claim Status

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKT7945S (7023060350SG)**
[SJP2772P]

TP

DANIEL DAVID CHAN KAI XING

Feb 18 2016 4:20PM

[Baasker S/O Santia]

Em-1 Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser ▼	
Letters/Correspondences										1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown						1		Edit	
Assessment Reports										1 per page ▼	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	25/02/16 13:51	Accident Statement From: OD - Reg. No: SJP2772P, Claimant: BAASKER S/O SANTIA						1		Load HTM	
Photos/Images										3 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	26/02/16 12:10	Odometer Reading						1		Load JPG	
2	26/02/16 12:10	Chassis Number						1		Load JPG	
3	26/02/16 12:12	General View						1		Load JPG	
4	26/02/16 12:12	General View						1		Load JPG	
5	26/02/16 12:12	General View						1		Load JPG	
6	26/02/16 12:12	General View						1		Load JPG	
7	26/02/16 12:12	General View						1		Load JPG	
8	26/02/16 12:12	General View						1		Load JPG	
9	26/02/16 12:12	General View						1		Load JPG	
10	26/02/16 12:12	General View						1		Load JPG	
11	26/02/16 12:12	General View						1		Load JPG	
12	26/02/16 12:12	General View						1		Load JPG	
13	26/02/16 12:12	General View						1		Load JPG	
14	26/02/16 12:12	General View						1		Load JPG	
15	26/02/16 12:12	General View						1		Load JPG	
16	26/02/16 12:12	General View						1		Load JPG	
17	26/02/16 12:12	General View						1		Load JPG	
18	26/02/16 12:12	General View						1		Load JPG	
19	26/02/16 12:12	General View						1		Load JPG	
20	26/02/16 12:12	General View						1		Load JPG	
21	26/02/16 12:12	General View						1		Load JPG	
22	26/02/16 12:12	General View						1		Load JPG	
23	26/02/16 12:12	General View						1		Load JPG	
24	26/02/16 12:12	General View						1		Load JPG	
25	26/02/16 12:12	General View						1		Load JPG	
26	26/02/16 12:12	General View						1		Load JPG	
27	26/02/16 12:12	General View						1		Load JPG	
28	26/02/16 12:12	General View						1		Load JPG	

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	26/02/16 12:12	General View	 Load JPG	✓
30	26/02/16 12:12	General View	 Load JPG	✓
31	26/02/16 12:12	General View	 Load JPG	✓
32	26/02/16 12:12	General View	 Load JPG	✓
33	26/02/16 12:12	General View	 Load JPG	✓
34	26/02/16 12:12	General View	 Load JPG	✓
35	26/02/16 12:12	General View	 Load JPG	✓
36	26/02/16 12:12	General View	 Load JPG	✓
37	26/02/16 12:12	General View	 Load JPG	✓
38	26/02/16 12:12	General View	 Load JPG	✓
39	26/02/16 12:12	General View	 Load JPG	✓
40	26/02/16 12:12	General View	 Load JPG	✓
41	26/02/16 12:12	General View	 Load JPG	✓
42	26/02/16 12:12	General View	 Load JPG	✓
43	26/02/16 12:12	General View	 Load JPG	✓
44	26/02/16 12:12	General View	 Load JPG	✓
45	26/02/16 12:12	General View	 Load JPG	✓
46	26/02/16 12:12	General View	 Load JPG	✓
47	26/02/16 12:12	General View	 Load JPG	✓
48	26/02/16 12:12	General View	 Load JPG	✓
49	26/02/16 12:12	General View	 Load JPG	✓
50	26/02/16 12:12	General View	 Load JPG	✓
51	26/02/16 12:12	General View	 Load JPG	✓
52	26/02/16 12:12	General View	 Load JPG	✓
53	26/02/16 12:12	General View	 Load JPG	✓
54	26/02/16 12:12	General View	 Load JPG	✓
55	26/02/16 12:12	General View	 Load JPG	✓
56	26/02/16 12:12	General View	 Load JPG	✓
57	26/02/16 12:12	General View	 Load JPG	✓
58	26/02/16 12:12	General View	 Load JPG	✓
59	26/02/16 12:12	General View	 Load JPG	✓
60	26/02/16 12:12	General View	 Load JPG	✓
61	26/02/16 12:12	General View	 Load JPG	✓
62	26/02/16 12:12	General View	 Load JPG	✓
63	26/02/16 12:12	General View	 Load JPG	✓
64	26/02/16 12:12	General View	 Load JPG	✓
65	26/02/16 12:12	General View	 Load JPG	✓
66	26/02/16 12:12	General View	 Load JPG	✓
67	26/02/16 12:12	General View	 Load JPG	✓
68	26/02/16 12:12	General View	 Load JPG	✓
69	26/02/16 12:12	General View	 Load JPG	✓
70	26/02/16 12:12	General View	 Load JPG	✓
71	26/02/16 12:12	General View	 Load JPG	✓
72	26/02/16 12:12	General View	 Load JPG	✓
73	26/02/16 12:12	General View	 Load JPG	✓
74	26/02/16 12:12	General View	 Load JPG	✓
75	26/02/16 12:12	General View	 Load JPG	✓
76	26/02/16 12:12	General View	Load JPG	✓

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
78	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
79	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
80	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
81	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
82	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
83	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
84	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
85	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
86	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
87	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
88	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
89	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
90	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
91	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
92	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
93	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
94	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
95	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
96	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
97	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
98	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
99	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
100	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
101	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
102	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
103	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
104	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
105	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
106	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
107	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
108	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
109	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
110	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
111	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
112	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
113	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
114	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
115	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
116	23/12/16 16:32	Reinspection Photo	 Load JPG	✓
117	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
118	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
119	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
120	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
121	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
122	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
123	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
124	23/12/16 16:33	Reinspection Photo	 Load JPG	✓

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
125	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
126	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
127	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
128	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
129	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
130	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
131	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
132	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
133	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
134	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
135	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
136	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
137	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
138	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
139	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
140	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
141	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
142	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
143	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
144	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
145	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
146	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
147	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
148	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
149	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
150	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
151	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
152	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
153	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
154	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
155	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
156	23/12/16 16:33	Reinspection Photo	 Load JPG	✓
157	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
158	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
159	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
160	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
161	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
162	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
163	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
164	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
165	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
166	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
167	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
168	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
169	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
170	23/12/16 16:35	Reinspection Photo	Load JPG	✓
171	23/12/16 16:35	Reinspection Photo	Load JPG	✓
172	23/12/16 16:35	Reinspection Photo	Load JPG	✓

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
173	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
174	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
175	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
176	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
177	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
178	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
179	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
180	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
181	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
182	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
183	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
184	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
185	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
186	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
187	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
188	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
189	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
190	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
191	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
192	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
193	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
194	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
195	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
196	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
197	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
198	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
199	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
200	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
201	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
202	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
203	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
204	23/12/16 16:35	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/16 11:17	TP ESTIMATE - MARKED	 Load PDF	
2	25/02/16 11:17	TP GIA REPORT	 Load PDF	
3	26/09/18 17:55	LETTER TO OI	 Load PDF	
4	26/09/18 17:55	LTA SEARCH	 Load PDF	
5	26/09/18 17:55	RENTAL RECEIPT	 Load PDF	
6	09/10/18 18:59	Email to AIG to seek mandate SKT 7945S	 Load PDF	
7	13/12/18 15:57	AUTHORISATION TO ACT	 Load PDF	
8	13/12/18 15:57	RELEASE VOUCHER	 Load PDF	
9	13/12/18 15:57	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SJP2772P (Insd veh)	Model:	MAZDA RX-8 1.3 (A)
	SKT7945S (TP veh)		
Date of Accident:	18/02/2016		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	44,202.24
Final Repair Cost	:	\$	22,200.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	14 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	22,200.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	EM-1 Auto Pte Ltd	:	\$ 22,200.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

13 Dec
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG16003566/M1WB3S2
Date: 13/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100422759
Claimant Vehicle No: SKT7945S Insured Vehicle No: SJP2772P
Date of Loss: 18/02/2016 Nature of Claim: TP Claim No: 7023060350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT7945S**
Make & Model: MAZDA RX-8, 1.3 (A) Engine No: 13B547587
Reg. Date: 29/04/2009 (Man. Year: 2008) Chassis No: SE3P302594
Colour: Blue Odometer: 119557 km
Engine Capacity: 1308 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,680.50	20,411.96	14,268.54	41.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,630.00	4,930.00	1,700.00	25.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,310.50	25,341.96	15,968.54	38.65
Approved Total (Overridden) (S\$)		19,500.00		
(S\$)	41,310.50	19,500.00	21,810.50	52.80
+ GST 7.00/7.00% (S\$)	2,891.74	1,365.00	1,526.74	52.80
Nett Amount (S\$)	44,202.24	20,865.00	23,337.24	52.80
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		22,270.35		
Global Sum Settlement (S\$)		22,200.00		

INSPECTION

Date of Assignment: 23/02/2016
Date Inspected: 23/02/2016 Inspected At: Em-1 Auto Pte Ltd (HQ)
Estimated Period of Repair: 14.0 days Bk 8 Sin Ming Industrial Estate Sector C, #01-68
Singapore 575643

Adjuster: MA CHIN FOOK**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID	Bent	1,238.00 F	*1,238.00 FL
2	1	*BOOT LID BADGE	Necessary	56.20 F	*56.20 FL
3	1	*BOOT LID EMBLEM (MAZDA)	Necessary	52.00 F	*52.00 FL
4	1	*BOOT LID EMBLEM (RX8)	Necessary	56.20 F	*56.20 FL
5	1	*BOOT LID THIRD BRAKE LAMP	Cracked	223.10 F	*223.10 FL
6	1	*BOOT LID INSULATOR	Distorted	279.60 F	*279.60 FL
7	1	*SET BOOT LID INSULATOR CLIP	Necessary	40.00 F	*40.00 FL
8	1	*BOOT LID INNER LOCK	Bent	269.60 F	*269.60 FL
9	1	*BOOT LID AUTO LOCK ACTUATOR	Jammed	175.20 F	*175.20 FL
10	1	*BOOT LID LOCK CATCH	Repair	46.80 F	*- FL
11	1	*BOOT LID LOCK CABLE	Serviceable	113.00 F	*- FL
12	1	*BOOT LID W/STRIP	Distorted	176.20 F	*176.20 FL
13	2	*BOOT LID HINGE	Bent	170.00 F	*170.00 FL
14	2	*BOOT LID ABSORBER	Serviceable	238.00 F	*- FL
15	1	*BOOT LID KEY LOCK	Serviceable	267.00 F	*- FL
16	2	*TAIL LAMP	Cracked	982.00 F	*982.00 FL
17	2	*TAIL LAMP INNER SEALER	Necessary	72.00 F	*72.00 FL
18	2	*TAIL LAMP CLIP	Necessary	50.00 F	*50.00 FL
19	2	*TAIL LAMP PANEL	Bent	302.00 F	*302.00 FL
20	1	*REAR BUMPER	Deformed	868.00 F	*868.00 FL
21	2	*REAR BUMPER SIDE RETAINER	Distorted	96.00 F	*96.00 FL
22	2	*REAR BUMPER ATTACHMENT RETAINER	Distorted	174.00 F	*174.00 FL
23	1	*SET REAR BUMPER CLIP	Necessary	50.00 F	*50.00 FL
24	1	*REAR BUMPER REINFORCEMENT	Bent	572.50 F	*572.50 FL
25	1	*REAR BUMPER NO. PLATE LAMP	Missing	110.00 F	*110.00 FL
26	1	*REAR BUMPER BOOT LID OPENER SWITCH	Shorted	145.20 F	*145.20 FL
27	2	*REAR BUMPER REFLECTOR	Distorted	138.00 F	*138.00 FL
28	1	*REAR BUMPER TOWING COVER	Serviceable	41.00 F	*- FL
29	1	*REAR BUMPER CENTER COVER	Distorted	206.50 F	*206.50 FL
30	1	*REAR BUMPER LOWER SKIRT	Distorted	365.00 F	*365.00 FL
31	2	*REAR BUMPER LOWER SIDE ARCH GARNISH	Distorted	326.00 F	*326.00 FL
32	1	*END PANEL	Bent	595.00 F	*595.00 FL
33	1	*END PANEL TOP TRIM	Distorted	192.00 F	*192.00 FL
34	1	*SET END PANEL TOP TRIM CLIP	Necessary	30.00 F	*30.00 FL
35	1	*END PANEL INNER LOWER GARNISH	Distorted	86.50 F	*86.50 FL
36	1	*REAR FLOOR PANEL	Repair	912.00 F	*- FL
37	1	*REAR FLOOR PANEL INSULATOR CLOTH	Necessary	495.00 F	*495.00 FL
38	1	*REAR KEY ANTENNA SENSOR	Distorted	163.20 F	*163.20 FL
39	1	*REAR ALARM SPEAKER	Distorted	197.50 F	*197.50 FL
40	1	*REAR AIR VENT	Distorted	68.00 F	*68.00 FL
41	1	*REAR FENDER	N/s Bent / O/s Repair	2,082.00 F	*1,041.00 FL
42	2	*REAR FENDER INNER TRIM	Torn	446.00 F	*446.00 FL
43	2	*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 F	*40.00 FL
44	2	*REAR FENDER INNER SHIELD	Distorted	296.00 F	*296.00 FL
45	2	*SET REAR FENDER INNER SHIELD CLIP	Necessary	50.00 F	*50.00 FL
46	1	*REAR W/SCREEN TOP MOULDING	Necessary	132.00 F	*132.00 FL
47	1	*REAR W/SCREEN BOTTOM MOULDING	Necessary	116.00 F	*116.00 FL
48	1	*REAR W/SCREEN INNER SEAL	Necessary	60.00 F	*60.00 FL
49	1	*REAR EXHAUST SILENCER	Bent	892.50 F	*892.50 FL
50	4	*REAR EXHAUST MOUNTING	Serviceable	144.00 F	*- FL
51	1	*REAR EXHAUST GASKET	Not Necessary	46.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*REAR EXHAUST HEAT PLATE	Repair	135.00 F	*- FL
53	2	*HEAD LAMP	Cracked	3,646.00 F	*3,646.00 FL
54	2	*HEAD LAMP BOTTOM RETAINER	Distorted	92.00 F	*92.00 FL
55	2	*SET HEAD LAMP CLIP	Necessary	40.00 F	*40.00 FL
56	1	*FRONT BUMPER	Deformed	846.20 F	*846.20 FL
57	1	*FRONT BUMPER BADGE	Necessary	56.00 F	*56.00 FL
58	2	*FRONT BUMPER SIDE RETAINER	Distorted	78.00 F	*78.00 FL
59	1	*SET FRONT BUMPER CLIP	Necessary	50.00 F	*50.00 FL
60	1	*FRONT BUMPER TOP BEAM	Bent	219.00 F	*219.00 FL
61	1	*FRONT BUMPER TOP APRON PANEL	Cut	226.00 F	*226.00 FL
62	1	*FRONT BUMPER TOP GARNISH	Distorted	163.50 F	*163.50 FL
63	1	*SET FRONT BUMPER TOP GARNISH CLIP	Necessary	40.00 F	*40.00 FL
64	1	*FRONT BUMPER TOP RUBBER	No such part	68.00 F	*- FL
65	1	*FRONT BUMPER REINFORCEMENT	Bent	580.00 F	*580.00 FL
66	1	*FRONT BUMPER FENDER SPONGE	Torn	211.00 F	*211.00 FL
67	2	*FRONT BUMPER SIDE SPONGE	Torn	150.00 F	*150.00 FL
68	1	*FRONT BUMPER LOWER GRILLE	Distorted	254.00 F	*254.00 FL
69	2	*FRONT BUMPER TOWING COVER	Distorted	64.00 F	*64.00 FL
70	2	*FRONT BUMPER FOG LAMP	Distorted	572.00 F	*572.00 FL
71	2	*FRONT BUMPER FOG LAMP COVER	Serviceable	246.00 F	*- FL
72	2	*FRONT BUMPER FOG LAMP COVER CHROME MOULDING	Serviceable	146.00 F	*- FL
73	2	*FRONT BUMPER SIDE GRILLE	Serviceable	164.00 F	*- FL
74	1	*FRONT BUMPER LOWER SKIRT	Serviceable	429.50 F	*- FL
75	1	*ENGINE UNDER COVER	Serviceable	213.00 F	*- FL
76	1	*SET ENGINE UNDER COVER CLIP	Serviceable	30.00 F	*- FL
77	1	*FRONT W/SCREEN	Cracked	1,529.00 F	*1,529.00 FL
78	1	*FRONT W/SCREEN MOULDING	Necessary	129.00 F	*129.00 FL
79	1	*FRONT W/SCREEN INNER SEAL	Necessary	60.00 F	*60.00 FL
80	1	*SUPPORT PANEL	Serviceable	592.50 F	*- FL
81	1	*RADIATOR	Bent	1,287.00 F	*1,287.00 FL
82	2	*RADIATOR TOP MOULDING	Serviceable	72.00 F	*- FL
83	2	*RADIATOR TOP MOUNTING BRACKET	Serviceable	90.00 F	*- FL
84	1	*RADIATOR FAN COWLING }	Serviceable	1,186.00 F	*- FL
85	1	*RADIATOR FAN MOTOR }		0.00 F	*- FL
86	1	*RADIATOR FAN BLADE }		0.00 F	*- FL
87	1	*CONDENSER FAN MOTOR }		0.00 F	*- FL
88	1	*CONDENSER FAN BLADE }		0.00 F	*- FL
89	1	*AIR CON CONDENSER	Bent	1,096.00 F	*1,096.00 FL
90	1	*CONDENSER AIR CON PIPE	Serviceable	188.00 F	*- FL
91	1	*CONDENSER SUCTION PIPE	Bent	196.00 F	*196.00 FL
92	1	*CONDENSER DISCHARGE PIPE	Serviceable	263.00 F	*- FL
93	2	*CONDENSER SIDE GARNISH	Serviceable	106.00 F	*- FL
94	1	*SET CONDENSER GARNISH CLIP	Necessary	30.00 F	*30.00 FL
95	1	*ALTERNATOR BELT	Serviceable	1,629.00 F	*- FL
96	1	*FRONT W/SCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
97	1	*SET FRONT W/SCREEN SOLAR FILM	Necessary	380.00 FS	*250.00 FS
98	1	*FRONT W/SCREEN TOP SOLAR FILM (BLACK)	Necessary	180.00 FS	*150.00 FS
99	1	*ERP BRACKET	Necessary	15.00 FS	*15.00 FS
100	1	*FRONT NO. PLATE W/COVER	Bent	70.00 FS	*40.00 FS
101	1	*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
102	1	*AIR CLEANER	Bent	450.00 FS	*450.00 FS
103	1	*AIR CLEANER JOINT PIPE	Serviceable	200.00 FS	*- FS
104	1	*AIR CLEANER JOINT EXTENT PIPE	Serviceable	300.00 FS	*- FS
105	1	*REAR NO. PLATE W/COVER	Bent	70.00 FS	*40.00 FS
106	1	*SET REVERSE SENSOR	Shorted	250.00 FS	*220.00 FS
107	1	*REAR BUMPER CENTER BLACK STICKER	Necessary	200.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS
109	1		*SET REAR FLOOR PANEL INSULATOR PAD	Not Necessary	150.00 FS	*- FS
110	1		*REAR W/SCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	34,680.50	25,153.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	4,741.74

Total Parts (\$\$)	34,680.50	20,411.96
--------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING.	New	2,800.00	2,100.00
2	SPRAY PAINTING.	New	2,600.00	2,000.00
3	ANTI RUST.	New	180.00	150.00
4	CHECK WIRING.	New	100.00	60.00
5	TOWING FEE (KING ROLLING)	New	150.00	60.00
6	REMOVE AND INSTALL FRONT W/SCREEN.	New	150.00	120.00
7	REMOVE AND INSTALL AIR CON.	New	150.00	120.00
8	REMOVE AND INSTALL CARPET AND SEAT.	New	120.00	60.00
9	REMOVE AND INSTALL REVERSE SENSOR.	New	90.00	60.00
10	REMOVE AND INSTALL REAR EXHAUST.	New	150.00	80.00
11	REMOVE AND INSTALL REAR W/SCREEN.	New	140.00	120.00
Gross Labour Cost (S\$)			6,630.00	4,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >