

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9301G - AXA*Not Authorised*
*1/1/14***Candy***Done - 26/2/14*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9301G - Candy**KL1LA69RJBB055299****CHEVROLET****EPICA 2.0****26.02.16****AXA****PART****LIST**

1	1	Front Bumper	\$	<i>Bu</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	295.25 7
3	1	Front Bumper Lower Absorber	\$	180.00 7
4	1	Front Bumper Lower Grille	\$	<i>su</i> 78.00 X
5	1	Front Bumper Retainer RH	\$	<i>su</i> 102.00 X
6	1	Front Bumper Retainer LH	\$	<i>su</i> 102.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
8	1	Front Headlamp RH	\$	<i>su</i> 816.00 X
9	1	Front Headlamp LH	\$	<i>ngcm</i> 816.00 ✓
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>su</i> 32.40 X
11	1	Front Bumper Fog Lamp Outer Cover RH	\$	<i>su</i> 32.40 X
12	1	Front Support Panel Assy (Panel A-Frt)	\$	<i>R</i> 1,222.32 X
13	1	Bonnet (Panel A-Hood)	\$	<i>Bu</i> 1,250.00 ✓
14	1	Centre 'CHEVROLET' Logo Badge	\$	<i>su</i> 144.30 ✓
15	1	Bonnet Moulding	\$	<i>su</i> 257.00 ✓
16	1	Bonnet Insulator	\$	<i>su</i> 84.63 X
17	1	Bonnet hinge RH	\$	<i>R</i> 36.00 X
18	1	Bonnet hinge LH	\$	<i>R</i> 36.00 X
19	1	Bonnet cable	\$	<i>su</i> 150.00 X
20	1	Bonnet lock	\$	<i>R</i> 200.00 X
21	2	HORN LH	\$	<i>su</i> 320.00 X
22	1	Radiator Grille (Grille A-Rad)	\$	<i>cm</i> 367.00 ✓
23	1	Radiator Assembly (Radiator A)	\$	<i>su</i> 618.00 X
24	1	Aircon Condenser (Conderser A)	\$	600.00 7
25	1	Air Cleaner Assembly	\$	<i>su</i> 112.00 X
26	1	Front Centre Member	\$	<i>R</i> 265.63 X
27	1	Air Intercooler	\$	652.00 7
28	1	Fan Blade (Small)	\$	536.00 7
29	1	Fan Blade (Big)	\$	<i>su</i> 634.00 X
30	1	Front Fender LH	\$	<i>R</i> 837.60 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9301G - AXA**Candy**

31	1	Front Fender RH	\$	R	837.60	X
32	1	Front Fender Liner LH	\$	Sc	47.00	X
33	1	Front Fender Liner RH	\$	Sc	47.00	X
34	1	Front Door RH	\$	R	1,133.00	X
35	1	Front Door LH	\$	R	1,133.00	X
36	1	Rear Bumper	\$	Bt	1,202.00	✓
37	1	Rear Bumper Beam	\$	Bt	239.94	✓
38	1	Rear Bumper Centre Absorber	\$	CM	260.00	✓
39	1	Rear Bumper Side Retainer RH	\$	CM	68.76	✓
40	1	Rear Bumper Side Retainer LH	\$	CM	68.76	✓
41	1	Rear Bumper side support RH	\$	Sn	25.00	X
42	1	Rear Bumper side support LH	\$	Sn	25.00	X
43	1	Rear Bumper Reflectors RH	\$	CM Sn	119.74	X
44	1	Rear Bumper Reflectors LH	\$	Bt	119.74	✓
45	1	Rear Bumper stay RH	\$	Sn	35.00	X
46	1	Rear Bumper stay LH	\$	Sn	35.00	X
47	1	Rear Bumper Tow Hook Cover	\$	Sn	93.00	X
48	1	Rear Luggage Floor Panel	\$	Bt/Bt	973.00	✓
49	1	Rear Luggage Floor Panel Insulator	\$	Sn	63.50	✓
50	1	Rear Luggage Floor Panel Trim Board	\$		378.00	?
51	1	Rear End Panel Inner	\$	Bt	336.84	✓
52	1	Rear End Panel Outer	\$	Bt	623.76	✓
53	1	Rear End Panel Inner Trim	\$	Diy	263.84	✓
54	1	Bootlid	\$	Bt	973.00	✓
55	1	Bootlid inner trim board	\$	Sn	400.00	X
56	1	Bootlid Weatherstrip	\$	Dis/Wt	344.28	50% Sn
57	1	Bootlid Lock - Top	\$	Bt	466.56	✓
58	1	Bootlid lock - bottom	\$	R	39.40	X
59	1	Bootlid 'CHEVROLET' Badge	\$	Sn	120.62	✓
60	1	Bootlid Logo	\$	Sn	138.84	✓
61	1	Bootlid 'EPICA LT' Badge	\$	Sn	119.84	✓
62	1	Bootlid inner handle	\$	Sn	45.55	X
63	1	Bootlid Reflector Centre	\$	Sn	217.97	X
64	1	Bootlid Reflector RH	\$	CM	128.40	✓
65	1	Bootlid Reflector LH	\$	Sn	128.40	X
66	1	Bootlid Hinge RH	\$	R	120.00	X
67	1	Bootlid Hinge LH	\$	R	120.00	X
68	1	Rear Tail Lamp RH	\$	Sn	479.30	X
69	1	Rear Tail Lamp Panel RH	\$	R	359.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9301G - AXA**Candy**

70	1	Rear Tail Lamp LH	\$	<i>CDA</i> 479.30 ✓
71	1	Rear Tail Lamp Panel LH	\$	<i>Bt</i> 359.00 ✓
72	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 X
73	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X
74	1	Rear Fender Inner Cowling RH	\$	<i>Sn</i> 298.00 X
75	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44 X
76	1	Rear Fender LH	\$	<i>Bu</i> 1,145.00 ✓
77	1	Rear Fender Inner Cowling LH	\$	<i>Sn</i> 298.00 X
78	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44 X

TOTAL	\$	30,113.72
10%	\$	3,011.37
	\$	27,102.35

Special Nett

1	1Set	Front Bumper Fastener Clip	\$	<i>Sn</i> 24.00 ✓
2	1Set	Front Licence Plate With Holder	\$	<i>Bro</i> 192.00 455AL
3	1Set	Bonnet Insulator Clip	\$	<i>nn</i> 40.00 X
4	1Set	Radiator Grille Clip	\$	<i>nn</i> 18.00 ✓
5	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 X
6	1Set	Radiator Grille Top Cover Clip	\$	<i>nn</i> 10.00 X
7	1Set	Front Fender Liner Clip	\$	<i>nn</i> 40.00 X
8	1Set	Rear Bumper Parking Sensor	\$	<i>nd</i> 300.00 ✓
9	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 30.00 ✓
10	2Set	Rear Fender inner cowling clip	\$	<i>nn</i> 30.00 X
11	1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00 X
12	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 X
13	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00 X
14	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00 ✓
15	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00 ✓
16	1	Door Sticker " Trans-cab " LH	\$	<i>nn</i> 80.00 X
17	1	Door Sticker " Trans-cab " RH	\$	<i>nn</i> 80.00 X
18	1	Rear Exhaust Mounting	\$	<i>Sn</i> 10.00 X
19	1	Rear Bumper End Sealant	\$	<i>nn</i> 80.00 X
20	1	Spare Tyre Board	\$	<i>Sn</i> 10.00 X
21	1	Spare Tyre	\$	<i>Sn</i> 180.00 X
22	1	Spare Wheel Rim	\$	<i>nn</i> 126.74 X
23	1	Spare Tyre Board	\$	<i>Sn</i> 10.00 X
24	1	Spare tyre fastener bolt	\$	65.00 ?

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9301G - AXA**Candy**

25	2	Rear Windscreen Sealant	\$	<i>Ne</i> 80.00 <i>40SN</i>
26	1	Rear Windscreen Inner Sponge Seal	\$	<i>Ne</i> 100.00 <i>30SN</i>

TOTAL \$ 1,695.74**TOTAL PARTS \$ 28,798.09**

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 28,000.00 *2600*

To Check Electrical Lighting Concerned.

\$ 170.00 *40*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *150*

Putty And Spray Painting Of The Affected
Portion.

\$ 27,000.00 *2000*

To drop rear exhaust box, renew the same, to
repair and realign centre exhaust pipe.

\$ 170.00 } *60*

To repair and realign rear exhaust pipe.

\$ 170.00

To reinstall rear bumper parking sensor.

\$ 170.00 *60*

To supply and re-do rear luggage floor panel
insulation padding.

\$ 380.00 *80*

To transfer of end panel fittings and conduct
water seepage test.

\$ 170.00 } *120*

To transfer of luggage floor panel fittings and
conduct water seepage test.

\$ 170.00

To transfer of boot fittings and conduct water
seepage test.

\$ 170.00 *60*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ *Repair* 380.00 *x*

TRANS-CAB AUTO SERVICES PTE LTD**Candy**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9301G - AXA

To transfer of Fender fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120/
To check ABS brake efficiency, final checking and testing.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 ?
To replace, refix and top up coolant for radiator	\$	170.00 ?
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 ?
Towing Fees.	\$	120.00 50/
	\$	59,070.00
TOTAL	\$	87,868.09

Repair Days**60 Days**

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer**Signature:****Date:**