



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF182G
Ref. No : TAX/03/16/2034
Reg. Date : 13/07/2012
Vehicle Type : TAXI
Make : CHEVROLET EPICA 2.0 VCDI
Model : EPICA-2.0
Name of Driver : TAY KIAU YING
Type of Accident : SIDE SWIPE
Date / Time of Accident : 05/03/2016 02:55:00 AM
Accident Reported Date / Time : 05/03/2016 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024079809
Special Instruction to ARC, if any :
SHD4135C (COMFORT)III
Prepared Date : 05/03/2016 10:12:12 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB136605

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	1,116.00	0.00
Total Material Charges :	439.20	1,696.71
Other Charges :	120.00	0.00
TOTAL :	2,351.20	0.00
Lum Sum Total :	2,350.00	0.00
No. of Repair Days :	4.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	06/03/2016 11:38:04 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/03/2016 11:37:57 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	0.00
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00
TO RESPRAY RIM	180.00	0.00
TO REPSRAY FRONT BUMPER	378.00	0.00
TO RESPRAY BUMPER BEAM	180.00	0.00
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00
Total Other Costs	120.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommend
96636324	FRONT	6504580	PANEL FRT FENDER LH	1	491.00	10.00	441.90	Replace
96633939	FRONT	6504582	LINER FENDER FRT LH (PROTECTOR)	1	40.00	10.00	36.00	Replace
	COMMO N	6504666	TYRE RIM	1	328.99	0.00	328.99	Repair
			BUMPER FRT FASCIA	1	1,004.00	10.00	903.60	Repair
96634054	FRONT	6504593	BEAM FRT BUMPER IMPACT	1	377.00	10.00	339.30	Repair
96634053	FRONT		ABSORBER ENGY FRT BUMPER	1	70.00	10.00	63.00	Replace
96633983			BRACKET FRT BUMPER SIDE LH	1	9.00	10.00	8.10	Replace
TOTAL MATERIALS							549.00	
TOTAL MATERIALS(Discouted)							439.20	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Surveyor Approved	Photos Attached
Replace	No
Replace	No
Replace	No
Replace	No
Replace	No
Replace	No
Replace	No
2,120.89	
1,696.71	