

Maine

CC 4/EQ1600

4853, Mike 3.52

LKK:

IDAC:

ASSIGNMENT

Surveyor: MCI.

DOI: 15/3/16

Date/Time: 15/3/16

Pre-assign / CCU / FTE



Insured Vehicle No. : FBJ 7194B

Claim No. : DMMP15-000429

Name of Insured : Firhan Bin Abdul Rashid

Policy No. :

Insured Tel No. : HP: 81832044

Make / Model : Kawasaki 2100 ABS Manual

Excess Sec II : SS

D.O.A. : 11/5/16

Place of Accident : Junction of middle road & waterloo street

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :


OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(VL: YES / NO)

Insured Liability : %

Final ? Yes / No




INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

PB1

8907195C

Date/ Time	STAGE	DATE / PIC
16/3/16 VIC	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call OI: 03/05/16 - ASHTR	
06/04/16 @ 3:30PM	Documentation Check List: Handler Typist	
03/05/16	Notification Itr (if non-pickup) [] [] After call Itr to OI: [] []	
03/05/16 @ 2:25PM	Authorisation To Act: [] [] Release Voucher: [] [] Final Repair Bill: [] [] Car Rental Invoice: [] [] Towing Invoice: [] []	
08/05/16	LTA / GIA : [] [] Medical Bill: [] []	
21/06/16	PIR: [] [] Mandate/Reject Instruction: [] [] LOD: [] []	
11-1-18 @ 546	Payment Breakdown Form: [] [] Post-Repair Photos: [] []	
09-01-18		
PRELIMINARY 30-05-14		
FINALIZATION 05-8-14		
Repair Cost: L16	SS 1,550.00 (A days) Reduction: 27 %	Email [] Call []
FINAL SETTLEMENT	Date/Time: Confirm with: Email [] Call []	
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost: SS		
Loss of Rental (LOR): SS (days)		
Loss of Use (LOU): SS (\$ x days)		
Loss of Income (LOI): SS (\$ x days)		
LOR only [] LOU only [] LOR + LOU [] LOR + LOI []	[Tick only one]	
GIA/LTA Search: SS		
Medical: SS		
Disbursement: SS (e.g. Tow/ Independent)		
Legal Cost: SS		
Total: SS	Global Sum SS: 35	
FINAL PAYMENT	Date/Time: Confirm with: Email [] Call []	
Payee 1: SS	Name 1: SS	
Payee 2: (Strike if N.A.) SS	Name 2: SS	
Payee 3: (Strike if N.A.) SS	Name 3: SS	

12/1/16

\$160.00

Surveyor:

ASSIGNMENT

From: _____ Date: 15/03/2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S6Q 7195C

at Workshop m/s N/S Trailing

of 314 10 Amk Ind Park JA #02-01

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPI

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S6Q7195C Yr Regn: JAN / 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Vios c.c 1499

Colour: Grey A/C: Insured / Std / NI / NA

Sp.Reading: 125491 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WRO53144204216826

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 175/65/14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 11/03/2016 D.O.I. 15/03/2016

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CR BODY

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	FINISHED COR LIS @ 1,550.00 WITH 4 PAYS
	CRBD. @ 585.28 (27%)

Date/Time, File Pass to?

 : Preli. Report
 : Final Report

Days Of Repair: _____

1) Date/Time, File Return to?

Resurvey No. of Trip: _____

2) _____

Add Fee:

 : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI _____

Photos _____

Others _____

TOTAL _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI16004853/hg3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110		Date : 15-03-2016	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBJ 7194B	Veh. Inspected	SGQ 7195C
Policy No.		Coverage (\$)	0.00
Claim No.	DMMPHQ15-000469	Excess (\$)	0.00
Assign From		Assign Date	15/03/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/03/2016	Inspection Date	
Survey held at	NGS TRADING BLK 10 AMK IND PK 2A #02-01 SINGAPORE 568047		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Sent: Tuesday, 15 March, 2016 11:21 AM
To: assignments
Subject: TP SURVEY - ACCIDENT INVOLVING FBJ7194B (EQ) / SGQ7195C (TP) ON 11.03.16
Attachments: SGQ7195C SAS.pdf; FBJ7194B LTA.pdf; OI - FBJ7194B.PDF

Our ref : SGQ7195C

Policy No. : **DMMPHQ15-000469**

Dear All,

Please proceed to survey the above vehicle.

Liability is clear, please proceed for direct settlement, if possible.

We enclosed the following documents for your reference:

- Our insured, FBJ7194B - GIA report
- Third party, SGQ7195C - GIA report
- TP repair estimate

Regards,

Elaine Cheong
Senior Executive, Claims

EQ Insurance Company Limited

5 Maxwell Road,
#17-00 Tower Block,
MND Complex,
Singapore 069110
DID : 6500 6772
Tel : 6223 9433
Fax: 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Evelyn Ng [mailto:evelynnngstrading@gmail.com]
Sent: Monday, March 14, 2016 5:19 PM
To: Elaine Cheong
Subject: Notification of Accident

Dear Sir/Madam,

RE ACCIDENT ON 11/03/2016 Along Junction of Middle RD to Waterloo Street

*15.03.2016 @ 11.45am
Evelyn: veh in
mca*

INVOLVING SGQ7195C & FBJ7194B

CLAIMS AGAINST VEH FBJ7194B (EQ INSURANCE)

SGQ7195C VEHICLE IS IN WORKSHOP

Kindly be informed that an accident involving my/our vehicle no. **SGB7195C** and vehicle(s) no. **FBJ7194B** had taken place at/along Junction of Middle Rd to Waterloo Street on date **11/03/2016** at time : **22:25 hrs** hours.

Please let us/me know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If I/we did not hear from you within 2 working days, I/we shall proceed to repair the vehicle without further notice and I/we shall claim for the additional loss of use arising from the giving of this notification to you.

Kindly let us have your claims reference, officer in charge of this case and please let us have your clients advice on quantum and liability.

Warmest Regards,

--

NGS TRADING

Evelyn Ng HP96955547

Blk 10 Ang Mo Kio Ind Park 2a

#02-01 AMK AuotPoint

Singapore 568047

Tel: 64815727 Fax: 64815772



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ116004853/M1hg3

Date: 15.03.2016

(TUESDAY)

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD
Attn : Elaine

Dear Elaine,

PRELIMINARY ADVICE OF VEHICLE NO.


SGQ7195C

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.03.2016 at the premises of M/s Ngs Trading - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	<u>2,135.28</u>
Revised Estimate Amount	: S\$	<u>1,955.28</u>
"Check" Items Amount	: S\$	<u>-</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:
The vehicle sustained damages at the
O/S Body



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 4.0 days

Yours faithfully,

MA CHIN FOOK
Licensed Appraiser

NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
 Tel: 64815727 Fax: 64815772 Email: ngstrading@yahoo.com
 Reg No.: 51106300L

QUOTATION

No. : QT-09239

EQ INSURANCE COMPANY LTD
 MOTOR CLAIMS DEPT
 22 GEMMILL LANE
 SINGAPORE 069257

Your Ref. : FBJ7194B
 Our Ref :
 C. C. :
 Date : 14-03-2016
 Page : 1 of 2

TEL : 6223 9433

FAX : 6224 3903

Description	Qty	U/ Price S\$	Amount S\$
ACCIDENT ON 11/03/2016 @22:25HRS ALONG JUNCTION OF MIDDLE RD TO WATERLOO INVOLVING VEHICLE SGQ7195C & FBJ7194B CLAIMS AGAINST FBJ7194B			
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 10px auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company </div>			
REPLACEMENT PARTS:-			
FRT RH DOOR	1	725.46 <i>det</i> ✓	725.46
MIRROR, FRT RH DOOR	1	347.75 <i>ava</i> ✓	347.75
COVER, FRT RH MIRROR	1	17.50 <i>dis</i> ✓	17.50
DOOR PROTECTOR FRT RH	1	63.00 <i>det</i> ✓	63.00
REAR RH DOOR	- REPAIR		
DOOR PILLAR	- REPAIR		
SubTotal			1,153.71
LESS 25%	1	-288.43	-288.43
LABOUR TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHED. STRAIGHTEN CHASSIS MEMBER, REPAIR DENTED BODY PANEL, REPLACE DAMAGED PART. REFIT INTO POSITION. TO REMOVE/TRANSFER DOOR MECHANISM TO FRT DOOR	1	500.00	500.00 <i>450</i>
TO CHECK ALL WIRE HARNESS & PROPPER FUNCTION FOR ALL DOOR & MIRROR	1	120.00	60 120.00 30
PUTTY & SPRAY PAINTING ON FRT & REAR DOOR RH, FENDER, DOOR PILLAR, ROCKER PANEL & ETC	1	50.00	50.00 30
		600.00	600.00 550

Acknowledged by Repairer
 Signature:
 Date:

*\$1550/-
 Hwtdays
 Con*

*Not Authorized.
 HK Repair
 after paint photo
 HK Auto (14)
 15/8/2016 @ 1400
 Hwtdays*

NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: ngstrading@yahoo.com
Reg No.:51106300L

QUOTATION

No. : QT-09239

EQ INSURANCE COMPANY LTD
MOTOR CLAIMS DEPT
22 GEMMILL LANE
SINGAPORE 069257

Your Ref. : FB37194B
Our Ref :
C. C. :
Date : 14-03-2016
Page : 2 of 2

TEL : 6223 9433

FAX : 6224 3903

Description	Qty	U/ Price	Amount
		S\$	S\$

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total **2,135.28**

Yours faithfully,



Administrator



Subject: YOUR REF: FBJ 7194B_ACCIDENT INVOLVING FBJ 7194B AND SGQ 7195C ALONG MIDDLE ROAD ON 11.03.2016

TO Mr Firhan Bin Abdul Rashed

Dear Sir,

OUR REF : CC4/EQ116004853/M1hb3

YOUR REF : FBJ 7194B

ACCIDENT INVOLVING FBJ 7194B AND SGQ 7195C ALONG MIDDLE ROAD ON 11.03.2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

As discussed previously with between your good self and our Ms Asher, we would like to request the below documents for our further review on this matter.

- **Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)**
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- **Video footage of accident (if any)**
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ116004853/M1wb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 13-09-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBJ 7194B	Veh. Inspected	SGQ 7195C
Policy No.		Coverage (\$)	0.00
Claim No.	DMMPHQ15-000469	Excess (\$)	0.00
Assign From		Assign Date	15/03/2016

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053HY4204216826	Colour	GREY
Odometer	125491	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R14	MICHELIN	8 mm
L/H Front Tyre	175/65 R14	MICHELIN	8 mm
R/H Rear Tyre	175/65 R14	MICHELIN	8 mm
L/H Rear Tyre	175/65 R14	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/03/2016	Inspection Date	15/03/2016
Survey held at	NGS TRADING BLK 10 AMK IND PK 2A #02-01 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGQ 7195C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT RH DOOR	DENTED	725.46	725.46
1	MIRROR, FRT RH DOOR	CRACKED	347.75	347.75
1	COVER, FRT RH MIRROR	DISTORTED	17.50	17.50
1	DOOR PROTECTOR FRT RH	DEFORMED	63.00	63.00
1	REAR RH DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
1	DOOR PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-288.43	-288.43
			865.28	865.28
	LABOUR			
	LABOUR TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT / ATTACHED. STRAIGHTEN CHASSIS MEMBER, REPAIR DENTED BODY PANEL, REPLACE DAMAGED PART. REFIT INTO POSITION. INCLUSIVE OF THE REPAIR OF REAR RH DOOR AND DOOR PILLAR.		500.00	450.00
	TO REMOVE / TRANSFER DOOR MECHANISM TO FRT DOOR.		120.00	60.00
	TO CHECK ALL WIRE HARNESS & PROPER FUNCTION FOR ALL DOORS & MIRROR.		50.00	30.00
	PUTTY & SPRAY PAINTING ON FRT & REAR DOOR RH, FENDER, DOOR PILLAR, ROCKER PANEL & ETC.		600.00	550.00
			1,270.00	1,090.00
GRAND TOTAL			2,135.28	1,955.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,550.00

Report Ref No. CC4/EQ116004853/M1wb3s2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.