

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GV 5563K
Vehicle Model : NISSAN URVAN
Accident Date : 24.03.2016
Original Reg Date : 01.08.2002

Date : 24.03.2016
Chassis : JN1MGE25Z0700583
TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate	dt	✓	2,101.40	L
2	1 pc	Tailgate Outer Garnish		?	463.50	L
3	1 pc	Tailgate Inner Trim Board		?	298.20	L
4	1 pc	Tailgate Windscreen Glass	eva	✓	963.00	L
5	1 pc	Rear Bumper	claf	✓	672.50	L
6	1 pc	End Panel (Outer)	bt	✓	423.90	L
7	1 pc	End Panel (Inner)	bt	✓	512.50	L
8	1 pc	Rear Floor Panel	R	✗	1,411.70	L
9	1 pc	Rear Fender LH	Buc	✓	2,101.30	L
					8,948.00	
					Less 30%	2,684.40
						6,263.60

1	1 pc	Tailgate Wiper Motor		?	495.10	N
2	1 pc	Tailgate Wiper Arm	bt	✓	82.40	N
3	1 pc	Tailgate Wiper Arm Cover	eva	✗	35.00	N
4	1 pc	Tailgate Wiper Blade	eva	✓	54.00	N
5	1 pc	Tailgate Outer Garnish Clips	ne	✓	30.00	N
6	2 pcs	Tailgate Number Plate Lamps	65.50	✗	131.00	N
7	1 pc	Tailgate Opener Handle		✗	88.50	N
8	1 pc	Tailgate Inner Lock	bt	✓	295.20	N
9	1 pc	Tailgate Lock Cover	dig	✓	49.20	N
10	1 pc	Tailgate Lock Catch	bt	✓	46.20	N
11	1 pc	Tailgate Auto Lock Actuator		?	175.00	N
12	1 pc	Tailgate Lock Mechanism		?	329.50	N
13	1 pc	Tailgate Weatherstrip	dig	✓	195.20	N
14	2 pcs	Tailgate Stopper (Male)	bt	✓	72.00	N
15	2 pcs	Tailgate Stopper (Female)	bt	✓	64.00	N
16	1 set	Tailgate Inner Trim Board Clips	eva	✓	40.00	N ²⁰
17	1 pc	Tailgate Inner Cover Plate	R	✗	65.30	N
18	2 pcs	Tailgate Hinges	R	✗	136.40	N
19	2 pcs	Tailgate Absorber	bt as per	✓	262.80	N

C/F

9,173.20

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GV 5563K

B/F

9,173.20

1	1 pc	Tailgate Windscreen Inner Seal		na 50.00	N	✓
2	2 pcs	Rear Bumper Side Retainers	36.00	dis 72.00	N	✓
3	1 set	Rear Bumper Clips		na 50.00	N	✓
4	1 pc	Rear Bumper Step Panel		bot 223.60	N	✓
5	1 pc	End Panel Top Plate		bot 109.60	N	✓
6	1 pc	Sliding Door Railing LH		gvc 236.00	N	✓
7	1 pc	Sliding Door Railing Joint LH		gvc 42.30	N	✓
8	2 pcs	Taillamps	223.50	cvr 447.00	N	✓
9	2 pcs	Taillamps Inner Sealer	30.00	co 60.00	N	✓
10	2 set	Taillamp Clips	25.00	50.00	N	✓
11	2 pcs	Taillamp Panel (Outer)	NS RT OSR ✓ 353.10	Y 706.20	N	
12	2 pcs	Taillamp Panel (Inner)	NS RT OSR ✓ 484.70	X 969.40	N	
13	1 pc	Rear Floor Panel Insulator Cloth	7	589.60	N	
14	2 pcs	Rear Fender Inner Trims Board	X 198.50	397.00	N	
15	2 pcs	Rear Fender Inner Trims Board Clips	na 30.00	26 60.00	N	
16	1 pc	Rear Exhaust Pipe	7	771.90	N	
17	2 pcs	Rear Exhasut Mountings	X 38.00	76.00	N	
18	1 pc	Rear Exhaust Gasket	7	46.20	N	
19	1 pc	Spare Tyre Carrier	7	195.50	N	

8,061.90

Less 10% 806.19

7,255.71

Special Nett

1	1 pc	Rear Windscreen Sealant		60.00	✓
2	1 pc	Rear Number Plate		Bot. 50.00	✓
4	1 pc	Tailgate Sticker 70km/h		na 15.00	
5	1 pc	Tailgate Sticker 5 pax		na 15.00	
6	1 set	Reverse Sensor		SWA 250.00	220
7	1 set	Body Panel Joint Sealant		80 120.00	
8	1 pc	Rear Floor Panel Insulator Pad		7 150.00	
9	1 set	Rear Floor Panel Top Wooden Board		380.00	200

C/F

8,295.71

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GV 5563K

B/F

8,295.71

Labour charge

Panel Beating		2,000.00	1400
Spray painting		1,600.00	1200
Check Wiring		50.00	80
Anti rust		100.00	80
Remove and install rear winscreen.		140.00	120
Remove and install tailgate parts.		90.00	60
Remove and install carpet and wooden.		150.00	80
Remove and install reverse sensor		90.00	60
Remove and install rear exhaust silencer.		120.00	80
		\$ 18,899.31	

Not Authorised
WSRajm.
After repair photo
take and (un)
11 wks days.
28/3/2016 @ 1210