

ATTN: RASUL

VIC

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 01 April 2016

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : FD 8432S

ACCIDENT DATE: 15 March 2016

Vespa PX 150

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Vespa Emblem	1	80.00 <i>Ne /</i>
2 Handle Bar	1	250.00 <i>X</i>
3 Front Mudguard	1	170.00 <i>PA /</i>
4 Front Shock Absorber	1	450.00 <i>scr /</i>
5 Absorber Spring	1	180.00 <i>scr /</i>
6 Front Rim	1	380.00 <i>R</i>
7 Brake Lever	1	78.00 <i>X</i>
8 Brake Hub	1	250.00 <i>scr /</i>
9 Brake Cable	1	168.00 <i>X</i>
10 Body Beading	1	268.00 <i>scr /</i>
11 Rear Box Rack	1	150.00 <i>scr /</i>
12 Rear Mudflap	1	160.00 <i>X</i>
Sub-Total		2,584.00 <i>1548</i>
Less 10%		258.40 <i>10%</i>
Sub-Total		2,325.60 <i>13'93720</i>

VEHICLE NO : FD 8432S

Vespa PX 150

Nett items

1	Front Number Plate	20.00	41
2	Rear RH Side Box	350.00	scr
3	Towing Fee	50.00	35
4	Remove & replace necessary damaged parts, align & reshape body dents, welding & etc.	520.00	450
5	Putty & respray paint - whole bike	650.00	400
4	Replace front fork/absorber assy, brakes & alignment	150.00	100

Sub-Total 1,740.00

Nett Total 4,065.60

NB: This estimate was made from a visual inspection only. Any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

10

Rasul
Hp 90010068

4 days

4/1

24/03/16 @ 1600

1353.20

1355.00

2748.20

20%

2198.56

41 - 2,200.00

4 days

(2)