

AUTOWORX HOUSE

C/O176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL : 6452 8211

FAX : 64517420

ESTIMATE

PANG KONG YON

c/o 46 Lentor Plain

Singapore 786548

Date: 1/4/2016

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE : PROTON WIRA / JHV6791</u>	
1 pc	rear bumper nett	576.00
1 pc	rear bumper beam nett	344.80
2 pcs	rear bumper bracket nett @ 125.00	250.00
2 pcs	rear number plate lamp nett @ 165.00	330.00
1 pc	rear boot lid nett	796.40
1 pc	rear boot lid lock nett	230.00
1 pc	rear boot lid lock catch nett	78.00
1 pc	rear boot lid weatherstrip nett	276.00
1 pc	rear boot lid number plate garnish nett	346.00
1 pc	rear boot lid reflector nett	315.00
1 pc	rear tail lamp apron panel nett	117.00
1 pc	rear tail lamp assy nett	456.00
1 pc	rear end panel nett	567.00
1 pc	rear end panel garnish nett	340.00
1 pc	rear fender nett	786.00
1 pc	rear fender inner garnish nett	450.00
1 pc	rear spare tyre panel nett	765.00
1 pc	rear spare tyre top board nett	345.00
1 pc	rear door lock nett	215.00
1 pc	rear door lock catch nett	65.00
1 pc	rear door nett	657.00
	sub-total	8,305.20
	less 10%	830.52
	sub-total	7,474.68
1 set	rear bumper lower kit s.nett	560.00
1 pc	number plate s.nett	35.00
1 tube	rear windscreen glass sealant s.nett	60.00
	sub-total	8,129.68

	balance brought forward.	8,129.68
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	1,600.00
	To remove and refit fuel tank to enable repair.	120.00
	To spray painting on affected areas.	1,000.00
	To check wiring system.	50.00
	To apply rust proofing on affected areas.	150.00
	To apply waterproof sealant on affected areas.	150.00
	To remove and refit rear windscreen glass to enable repair.	140.00
	total	<u>11,339.68</u>