

Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Cer
2K Oven Spray Pi

Power-M Autom
Specialise In Car
Car Audio & Hi-Fi

Hilton Car Rent
Hilton Auto Trad
Dealing In New/U

TP INSURER: AXA Insurance Singapore Pte Ltd (HQ)
UNKNOWN
0
Singapore 0

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	0	Date of Loss:	03/04/2016
Vehicle Reg. No.:	SKV9288G	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAN HEE MENG	Driver (Insured):	UNKNOWN
Make/Model:	AUDI A6, 1.8 TMU (A)	Vehicle Reg. Date:	28/02/2014
Vehicle Colour:	BLACK		
Engine No:	CDN385068	Chassis No:	WAUZZZ4GXEN067656
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration 7
of Repair
(day)

Description of REFER TO GIA RPT
Accident/Loss

Remarks: VEHICLE NOT IN WORKSHOP

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS	Amount
Parts	20,273.30
Miscellaneous Items	0.00
Labour	2,210.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	22,483.30
+ GST 7.00% (\$\$)	1,573.83

Estimate Report

Nett Amount (S\$)

24,057.13**This claim is handled by: KEONG***Generated using Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 04 Apr 2016)

Parts: 143

AUDI A6 1.8 TMU (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV9288G)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET / BI	0.00	0.00	*4,180.00 F
2	1		*BONNET CATCH ?	0.00	0.00	*116.00 F
3	1		*FRONT GRILLE / CRA	0.00	0.00	*1,059.00 F
4	1		*FRONT GRILLE LOGO / nec	0.00	0.00	*97.00 F
5	1		*FRONT GRILLE TOP COVER / PL	0.00	0.00	*189.00 F
6	1		*FRONT GRILLE TOP COVER CLIP / nec	0.00	0.00	*119.00 F
7	2		*HEAD LAMP LH & RH / CRA	0.00	0.00	*8,525.00 F
8	2		*HEAD LAMP LOWER BRACKET LH & RH / nec	0.00	0.00	*75.00 F
9	2		*HEAD LAMP SIDE BRACKET LH & RH ?	0.00	0.00	*178.40 F
10	2		*HEAD LAMP CLIP / nec	0.00	0.00	*10.60 F
11	1		*SUPPORT PANEL ?	0.00	0.00	*955.00 F
12	2		*SUPPORT PANEL SIDE GARNISH LH & RH ?	0.00	0.00	*61.50 F
13	1		*FRONT BUMPER / Deforme	0.00	0.00	*1,991.30 F
14	1		*FRONT BUMPER FOG LIGHT COVER LH / PL	0.00	0.00	*143.00 F
15	1		*FRONT BUMPER WASHER JET LH ?	0.00	0.00	*216.00 F
16	1		*FRONT BUMPER WASHER COVER LH ?	0.00	0.00	*41.80 F
17	1		*FRONT BUMPER WASHER PIPE ?	0.00	0.00	*37.25 F
18	1		*FRONT BUMPER SPONGE ?	0.00	0.00	*72.00 F
19	1		*FRONT BUMPER REINFORCEMENT ?	0.00	0.00	*581.70 F
20	2		*FRONT BUMPER BRACKET LH & RH ?	0.00	0.00	*368.00 F
21	2		*FRONT BUMPER SIDE BRACKET LH & RH ?	0.00	0.00	*53.50 F
22	1		*FRONT BUMPER CLIP / nec	0.00	0.00	*158.25 F
			(SET)			
23	1		*FRONT FENDER RH / BI	0.00	0.00	*1,045.00 F
24	2		*FRONT CHASSIS MEMBER LH & RH	0.00	0.00	-
			(REPAIR)			

F=Franchise part.

Total Parts (S\$)

20,273.30

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimate Report

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR FRONT CHASSIS MEMBER LH & RH & FRONT INNER PANEL LH & RH. TO REMOVE & RE-FIX DAMAGED PARTS, STRAIGHTEN & RE-ALIGN AFFECTED AREAS	New	900 980.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	800 850.00
3	TO REMOVE & RE-FIX A/C CONDENSER, ELECTRIC FAN, HOSE & PIPE. VACUUM & REFILLING OF GAS	New	150.00 ?
4	TO CHECK WIRING & PROGRAMMING OF HEAD LAMP SYSTEM	New	150.00 120
5	TO RUST PROOF AFFECTED AREAS	New	80.00 60
Gross Labour Cost (S\$)			2,210.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

11/4/16 w/p, not authorise

L/S, Repair days 6

#A-

Stevenfoong@kkant.com

81117723