

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7921R - III

Not Authorised
CL/Eng B

ROEL

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 7921R - ROEL
 KL1LA69RJB109260
 CHEVROLET
 EPICA 2.0
 03.04.16
III

PART		LIST	
1	1 Front Bumper	\$	CM 1,202.00 ✓
2	1 Front Bumper Lower Absorber	\$	Mis 180.00 ✓
3	1 Front Bumper Reinforcement	\$	Bu 356.00 ✓
4	1 Front Bumper Retainer RH	\$	CM 102.00 ✓
5	1 Front Bumper Retainer LH	\$	CM 102.00 ✓
6	1 Front Bumper Lower Grille	\$	Mis 78.00 ✓
7	1 Front Bumper Lower Stiffener	\$	Bu 134.37 ✓
8	1 Front Bumper Bracket LH	\$	Bu 10.00 ✓
9	1 Front Bumper Bracket RH	\$	R 10.00 X
10	1 Bumper Fog Lamp Cover RH	\$	Sm 32.40 X
11	1 Bumper Fog Lamp Cover LH	\$	Mis 32.40 ✓
12	1 Front Fender RH	\$	Bu 837.60 ✓
13	1 Front Fender LH	\$	Bu 837.60 ✓
14	1 Front Fender Liner RH	\$	Sm 47.00 X
15	1 Fender Insulation RH	\$	R 39.00 X
16	1 Front Fender RR Bracket RH	\$	R 7.10 X
17	1 Front Fender Inner Wheel House Panel RH	\$	R 1,437.00 X
18	1 Front Fender Liner LH	\$	Mis 47.00 ✓
19	1 Fender Insulation LH	\$	Sm 39.00 X
20	1 Front Fender RR Bracket LH	\$	R 7.10 X
21	1 Front Fender Inner Wheel House Panel LH	\$	R 1,437.00 X
22	1 Resonator (B/S Fender LH) AIR BOX	\$	Bu 134.67 ✓
23	1 Resonator Hose	\$	Sm 37.00 X
24	1 Bonnet	\$	Bu 1,250.00 ✓
25	1 Bonnet under weatherstrip seal	\$	Sm 105.00 X
26	1 Bonnet hinge RH	\$	R 36.00 X
27	1 Bonnet hinge LH	\$	R 36.00 X
28	1 Bonnet Moulding	\$	NC 161.97 ✓

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7921R - III

ROEL

29	1	Bonnet Lock
30	1	Bonnet cable
31	1	Bonnet damper stay RH
32	1	Bonnet damper stay LH
33	1	Bonnet insulator
34	1	Centr' logo badge
35	1	Bonnet Gas T/Gate Spring RH
36	1	Bonnet Gas T/Gate Spring LH
37	1	Front Support Panel Assy
38	1	Front brace panel
39	1	Headlamp RH
40	1	Headlamp LH
41	1	Front Windscreen
42	1	Front Windscreen Moulding
43	1	Front Wiper Garnish / Wiper Grille (Cowl A)
44	1	Windscreen Washer Tank - Filler Neck
45	1	Windscreen Washer Tank
46	1	Windscreen Washer Tank Motor
47	1	TANK, WIPER HOSE
48	1	Radiator Assembly
49	1	Radiator expansion tank
50	1	Radiator upper hose
51	1	Radiator lower hose
52	1	Radiator Grille (Grille A-Rad)
53	1	Radiator Grille Top Cover
54	1	Fan Blade(A/C)
55	1	Fan Blade(Radiator)
56	1	Aircon Condenser
57	1	Aircon compressor - pump
58	1	Aircon compressor bracket
59	1	Aircon condensor bottom bushing
60	1	Aircon hose - condenser to compressor
61	1	Aircon hose - compressor to evaporator
62	1	Aircon hose - condenser to evaporator
63	1	Air Cleaner Assembly (Cleaner A-Air)
64	1	Alternator assembly
65	1	W/HARNESS-ENG

\$	Dir	60.00 ✓
\$	Sn	125.00 X
\$	Sn	125.00 X
\$	Sn	125.00 X
\$	Defam	400.00 508mm
\$	na	60.00 ✓
\$	Sn	286.90 X
\$	Sn	286.90 X
\$	Bt	1,222.32 ✓
\$	Bt	134.37 ✓
\$	ngcmt	816.00 —
\$	ngcmt	816.00 —
\$	cm	1,304.00 ✓
\$	na	196.00 —
\$	Sn	184.50 X
\$	Sn	4.80 X
\$	Sn	62.00 X
\$	Sn	51.00 X
\$	Sn	21.00 X
\$	1 hour cm	618.00 ✓
\$	Sn	45.00 X
\$	Sn	30.00 X
\$	Sn	120.00 X
\$	cm	367.00 ✓
\$	mt	45.02 —
\$	cm	536.00 —
\$	cm	634.00 ✓
\$	Pz	600.00 —
\$	Sn	1,847.95 X
\$	A	245.30 X
\$	Sn	119.00 X
\$	Sn	450.00 X
\$	Sn	624.00 X
\$	Sn	580.00 X
\$	Sn	112.00 X
\$	Sn	1,040.00 X
\$	Sn	1,500.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7921R - III

ROEL

66	1	Engine block	\$	28,895.40 X
67	1	Gear box assy	\$	20,800.00 X
68	1	Cross member	\$	1,030.71 ?
69	1	Front Centre Member	\$	265.63 ?
70	1	Engine Splash Cover RH	\$	168.00 X
71	1	Engine Splash Cover LH	\$	168.00 X
72	1	Horn Unit (High Tone)	\$	53.46 X
73	1	Air Intercooler	\$	652.00
74	1	Air Intercooler Hose (FILTER FUEL)	\$	34.67 X
75	1	Gear Box Mounting RH	\$	249.00 ?
76	1	Engine Mounting LH	\$	228.00 ?
77	1	Front Engine Mounting	\$	100.14 ?
78	1	Rear Engine Mounting	\$	134.00 ?
79	1	Power steering hose	\$	312.11 ?
80	1	Engine suspension cross member	\$	344.07 ?
81	1	Engine oil sump	\$	500.00 X
82	1	Front Shock Absorber Assy RH	\$	216.17 X
83	1	Front Lower Arm RH	\$	283.00 X
84	1	Front Knuckle Arm RH	\$	230.00 X
85	1	Front Shock Absorber Assy LH	\$	216.17 X
86	1	Front Lower Arm LH	\$	283.00 X
87	1	Front Knuckle Arm LH	\$	230.00 X
88	1	Front Disc Brake RH	\$	157.55 X
89	1	Front Strut Bar Bracket LH	\$	235.01 X
90	1	Front Stabilizer Bar	\$	234.00 X
91	1	Front Stabilizer Bar Link RH	\$	51.79 X
92	1	Front Stabilizer Bar Bracket RH	\$	105.75 X
93	1	Front Stabilizer Bar Bush RH	\$	66.00 X
94	1	Front Stabilizer Bar Link LH	\$	51.79 X
95	1	Front Stabilizer Bar Bracket LH	\$	105.75 X
96	1	Front Stabilizer Bar Bush LH	\$	66.00 X
97	1	Drive Shaft RH	\$	900.00 X
98	1	Drive Shaft LH	\$	900.00 X
99	1	Front Beam A - Impact RH	\$	214.00 ?
100	1	Front Beam A - Impact LH	\$	214.00 ?
101	1	Front Fuse Box	\$	715.00 X
102	1	Dash Board	\$	1,420.63

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7921R - III

103	1	Dash Board Air Bag
104	1	Dash Board Air Bag Sensor
105	1	Dash Board air bag control unit
106	1	Steering Wheel Air Bag
107	1	Steering Wheel Air Bag Sensor
108	1	Steering air bag control unit
109	1	Front Seat Belt RH
110	1	Front Seat Belt LH
111	1	Front Door LH
112	1	Front Door RH

\$	Bury	1,792.96	✓
\$	na	965.33	✓
\$	na	1,543.22	✓
\$	Bury	1,681.48	✓
\$	na	680.00	✓
\$	na	1,333.22	✓
\$	Tr	402.50	✓
\$	Tr	402.50	✓
\$	R	1,133.00	X
\$	R	1,133.00	X

TOTAL	\$	96,427.28
10%	\$	9,642.73
	\$	86,784.55

Special Nett

1	1 Set	Front Bumper Fastener Clip
2	1 Set	Radiator Grille Top Cover Clip
3	1 Set	Front licence plate with holder
4	2	Front windscreen sealant
5	1	Front windscreen inner sponge seal
6	2	Front ERP Sticker
7	1 Set	Front Wiper Garnish Clip
8	1 Set	Radiator Coolant
9	1 Set	Radiator Grille clip
10	1 Set	Engine Splash Cover Clip RH
11	1 Set	Engine Splash Cover Clip LH
12	1	Engine oil sump Strainer
13	1	Engine oil sump sealant
14	1 Set	Front Fender Liner clip
15	1 Set	Louver Cowl Top clip
16	2	Bonnet stopper
17	1	Door Sticker "Trans-cab" LH
18	1	Door Sticker "Trans-cab" RH
19	1	Front Wheel Rim Hub Cap LH
20	1	Front Wheel Rim Hub Cap RH

\$	na	24.00	✓
\$	na	10.00	✓
\$	B	192.00	25na
\$	na	80.00	40na
\$	na	100.00	30na
\$	na	40.00	26na
\$	na	18.00	X
\$	na	60.00	20na
\$	na	35.00	✓
\$	na	12.00	X
\$	na	12.00	X
\$	su	125.60	X
\$	na	45.00	X
\$	na	30.00	✓
\$	na	30.00	X
\$	su	15.00	X
\$	na	80.00	X
\$	na	80.00	X
\$	su	166.30	X
\$	su	166.30	X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7921R - III

21	1	Front Tyre RH	\$	180.00 X
22	1	Front Tyre Rim RH	\$	126.00 X
23	1	Front Tyre LH	\$	180.00 X
24	1	Front Tyre Rim LH	\$	126.00 X

TOTAL	\$	1,933.20
TOTAL PARTS	\$	88,717.75

To Check Electrical Lighting Concerned.	\$	170.00 300
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	16,800.00 800
Putty and spray painting of the affected portion.	\$	16,200.00 1000
Towing Fees.	\$	120.00 50
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 7
To dismantle and refit rear seat, backrest, trimings, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$	nn 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00 X
To remove and renew engine and gear box mounting.	\$	nn 380.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7921R - III

ROEL

To dismantle and refit engine cross-member and engine mounting.	\$	nn 380.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 60d
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To replace, refix and top up coolant for radiator	\$	170.00 50d
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00 100d
To rust-proofing of the affected areas.	\$	170.00 120d

TOTAL \$ 37,670.00

Over All Total \$ 126,387.75

Repair Days

60 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: