

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHC 274K - AXA

Not Authored
1.13.1

Candy

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 274K - Candy
 VF1ABL15AUC282629
 RENAULT
 LATITUDE
 09.04.16
AXA

PART			LIST
1	1	BUMPER COVER FRT	\$ Tu 968.79 ✓
2	1	BUMPER SPOILER FRT	\$ Mis 139.81 ✓
3	1	BUMPER ABSORBER FRT	\$ Bro 303.60 ✓
4	1	BUMPER BRACKET FRT LH	\$ R 116.47 ✓
5	1	BUMPER RETAINER FRT LH	\$ CRA 18.37 ✓
6	1	BUMPER BRACKET FRT RH	\$ Su 115.98 X
7	1	BUMPER REPAIRER FRT RH	\$ Su 18.37 X
8	1	BUMPER UNDERTRAY FRT	\$ CRA 363.71 ✓
9	1	BUMPER GRILLE LOWER FRT	\$ CRA 205.23 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$ Mis 159.39 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$ Su 159.39 X
12	1	BUMPER BEAM FRT	\$ R 703.14 ✓
13	1	RADIATOR GRILLE	\$ CRA 1,313.68 ✓
14	1	RADIATOR GRILLE BADGE 'RENAULT'	\$ Nu 173.36 ✓
15	1	RADIATOR GRILLE FRAME	\$ Bro 1,041.35 ✓
16	1	FRAME FULL SUPPORT PANEL	\$ CRA 473.77 ✓
17	1	FRAME FULL SUPPORT BRACKET	\$ R 69.07 ✓
18	1	FRONT BRACE PANEL	\$ R 136.32 ✓
19	1	SUBFRAME OUTER FRT	\$ 2,040.34 ?
20	1	SUBFRAME INNER FRT (crossmember)	\$ 1,757.54 ?
21	1	SUBFRAME SUPPORT INNER	\$ R 71.04 X
22	1	SUBFRAME BRACKET OUTER LH	\$ R 71.04 X
23	1	SUBFRAME BRACKET OUTER RH	\$ R 71.04 X
24	1	SUBFRAME BRACKET INNER LH	\$ R 138.44 X
25	1	SUBFRAME BRACKET INNER RH	\$ R 138.44 X
26	1	LOWER ARM RH	\$ Su 527.51 X
27	1	BRAKE DISC FRT	\$ Su 211.91 X
28	1	KUNCKLE ARM RH	\$ Su 651.53 X
29	1	KUNCKLE HUB+BEARING RH	\$ Nu 382.84 X
30	1	KUNCKLE ARM SHIELD RH	\$ Su 101.10 X
31	1	KUNCKLE ARM PLATE RH	\$ Su 133.89 X
32	1	BRAKE DISC FRT	\$ Su 211.91 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

33	1	ABSORBER FRT RH	\$	277.34 X
34	1	ABSORBER MOUNTING KIT RH	\$	338.97 X
35	1	ABSORBER DUST COVER	\$	175.94 X
36	1	STABILIZER BAR FRT	\$	465.12 ?
37	1	STABILIZER LINK FRT	\$	90.17 X
38	1	BRAKE CALIPER FRT RH	\$	505.34 X
39	1	BRAKE CALIPER BRACKET FRT RH	\$	427.01 X
40	1	ABS SENSOR FRT RH	\$	196.73 X
41	1	BRAKE HOSE FRT RH	\$	96.70 X
42	1	DRIVESHAFT RH	\$	R 1,344.19 X
43	1	LOWER ARM LH	\$	527.51 ?
44	1	BRAKE DISC FRT	\$	211.91 X
45	1	KUNCKLE ARM LH	\$	651.53 X
46	1	KUNCKLE HUB+BEARING LH	\$	382.84 X
47	1	KUNCKLE ARM SHIELD LH	\$	101.10 X
48	1	KUNCKLE ARM PLATE LH	\$	133.89 X
49	1	BRAKE DISC FRT	\$	211.91 X
50	1	ABSORBER FRT LH	\$	277.34 ?
51	1	ABSORBER MOUNTING KIT LH	\$	338.97 ?
52	1	ABSORBER DUST COVER	\$	175.94 X
53	1	STABILIZER BAR FRT	\$	465.12 X
54	1	STABILIZER LINK FRT	\$	90.17 X
55	1	BRAKE CALIPER FRT LH	\$	505.34 X
56	1	BRAKE CALIPER BRACKET FRT LH	\$	427.01 X
57	1	ABS SENSOR FRT LH	\$	196.73 X
58	1	BRAKE HOSE FRT LH	\$	96.70 X
59	1	DRIVESHAFT LH	\$	R 1,344.19 X
60	1	SEATBELT BUCKLE RH	\$	730.61 ?
61	1	SEATBELT RH	\$	2,250.28 ✓
62	1	SEATBELT BUCKLE LH	\$	730.61 ?
63	1	SEATBELT LH	\$	2,250.28 ✓
64	1	PASSENGER AIRBAG	\$	2,624.93 ✓
65	1	PASSENGER AIRBAG COMPUTER	\$	969.09 ✓
66	1	PASSENGER AIRBAG SENSOR	\$	557.41 ✓
67	1	STEERING AIRBAG	\$	1,942.89 ✓
68	1	STEERING AIRBAG SENSOR	\$	222.54 ✓
69	1	STEERING AIRBAG COMPUTER	\$	969.09 X
70	1	ROTARY SWITCH	\$	963.93 ✓
71	1	DASHBOARD	\$	3,769.65 ✓
72	1	GLOVE BOX	\$	799.83 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

Item No	Qty	Description	Unit Price (\$)	Total (\$)	Remarks
73	1	GLOVE BOX FLAP	\$	983.82	X ✓
74	1	HEADLAMP LH	\$	911.10	✓
75	1	HEADLAMP RH	\$	911.10	✓
76	1	HEADLAMP HARNESS RH	\$	714.07	X
77	1	HEADLAMP HARNESS LH	\$	714.07	?
78	1	HEADLAMP PANEL FRT RH	\$	134.59	X
79	1	HEADLAMP PANEL FRT LH	\$	134.59	✓
80	1	BONNET	\$	1,493.56	✓
81	1	BONNET INSULATOR	\$	312.10	✓
82	1	BONNET STRUT LH	\$	166.29	X
83	1	BONNET STRUT RH	\$	166.29	X
84	1	BONNET HINGE LH	\$	267.93	✓
85	1	BONNET HINGE RH	\$	267.93	X
86	2	BAL HOOD	\$	75.60	X
87	1	BONNET LOCK	\$	234.99	✓
88	1	BONNET CABLE	\$	91.69	X
89	1	BONNET CABLE COVER	\$	123.87	X
90	1	BONNET SEAL OUTER	\$	71.04	X
91	1	FENDER PANEL FRT LH	\$	602.95	✓
92	1	FENDER PANEL FRT RH	\$	602.95	✓
93	1	FENDER WHEELARCH FRT LH (Linner)	\$	107.32	✓
94	1	FENDER WHEELARCH FRT RH (Linner)	\$	214.49	✓
95	1	FENDER INSULATOR RH	\$	100.64	X
96	1	FENDER INSULATOR LH	\$	100.64	X
97	1	FENDER PANEL BRACKET FRT RH	\$	161.52	X
98	1	FENDER PANEL BRACKET FRT LH	\$	161.52	✓
99	1	WHEEL HOUSING PANEL FRT RH	\$	3,601.61	X
100	1	WHEEL HOUSING PANEL FRT LH	\$	3,601.61	X
101	1	FENDERCHASSIS REINFORCEMENT FRT LH	\$	765.90	X
102	1	FENDERCHASSIS REINFORCEMENT FRT RH	\$	765.90	✓
103	1	RADIATOR	\$	924.77	?
104	1	RADIATOR FAN COWLING	\$	573.80	?
105	1	RADIATOR FAN MOTOR LH	\$	676.48	?
106	1	RADIATOR FAN MOTOR RH	\$	676.48	?
107	1	RADIATOR HOSE UPPER	\$	168.22	?
108	1	RADIATOR HOSE LOWER	\$	343.48	?
109	1	AIR CLEANER HOSE	\$	58.57	?
110	1	AIR CLEANER LOWER	\$	311.95	?
111	1	ENGINE UNDERTRAY	\$	434.60	?
112	1	A/C CONDENSER	\$	1,554.13	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

113	1	A/C CONDENSER GARNISH LH UPPER	\$	CMA	27.74	✓
114	1	A/C CONDENSER GARNISH RH UPPER	\$	Sm	27.74	X
115	1	A/C CONDENSER GARNISH LH	\$	CMA	41.12	✓
116	1	A/C CONDENSER GARNISH RH	\$	Sm	41.68	X
117	1	A/C PIPE CONDENSER TO COMPRESSOR	\$		145.73	?
118	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$		460.64	?
119	1	A/C PIPE COMPRESSOR	\$		233.77	?
120	1	A/C PIPE	\$		460.64	?
121	1	TRANSMISSION COOLER	\$	Both	852.66	✓
122	1	AIR INTERCOOLER HOSE (LONG)	\$		709.18	?
123	1	AIR INTERCOOLER HOSE (Short)	\$		262.34	?
124	1	STEERING PUMP ELECTRIC	\$	Reservoir CMA	1,543.08	✓
125	1	STERING HOSE LOW PRESSURE LONG	\$		442.50	?
126	1	STERING HOSE LOW PRESSURE	\$		247.18	?
127		WINDSCREEN FRT	\$	Sm	1,005.56	X
128	1	WIPER RESERVOIR	\$	Sm	190.96	X
129	1	WIPER RESERVOIR NECK	\$	Sm	27.78	X
130	1	WIPER RESERVOIR MOTOR	\$	Sm	100.95	X
131	1	DOOR PANEL FRT LH	\$	R	2,188.20	X
132	1	DOOR MIRROR LH	\$	Sm	1,141.08	X
133	1	DOOR SEAL FRT LH	\$	Sm	50.92	X
134	1	DOOR PANEL FRT RH	\$	R	2,188.20	X
135	1	DOOR MIRROR RH	\$	Sm	1,141.08	X
136	1	DOOR SEAL FRT RH	\$	Sm	50.92	X

TOTAL	\$	79,690.98
10%	\$	7,969.10
	\$	71,721.88

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	Net	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	Net	66.00	✓
3	1	TOW COVER FRT	\$	Net	14.50	✓
4	1SET	RADIATOR GRILLE SCREW	\$	Net	16.00	✓
5	1SET	BUMPER GRILLE LOWER CLIP	\$	Net	69.00	✓
6	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Net	70.00	✓
7	2	FRAME FULL SUPPORT PANEL NUT	\$	Net	20.00	X
8	2	FRAME FULL SUPPORT PANEL STUD	\$	Net	30.00	X
9	2	BONNET CABLE CLIP	\$	Net	6.40	X
10	1SET	WHEELARCH CLIP LH	\$	Net	30.50	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

11	1SET	WHEELARCH CLIP RH	\$	<i>NN</i>	29.40	X
12	2	Front windscreen sealant	\$	<i>NN</i>	80.00	X
13	2	Front windscreen moulding	\$	<i>NN</i>	100.00	X
14	2	"E.R.P "Sticker	\$	<i>NN</i>	65.00	X
15	1	DOOR STICKER "Trans-cab"	\$	<i>NN</i>	80.00	X
16	1	DOOR STICKER "Classic"	\$	<i>NN</i>	30.00	X
17	1	DOOR STICKER "6555-3333"	\$	<i>NN</i>	80.00	X
18	1SET	NUMBER PLATE WITH HOLDER	\$	<i>Bn</i>	140.00	<i>455m</i>
19	1	DASHBOARD SCREW	\$	<i>NN</i>	55.55	X
20	1	CAP HUB RH FRT	\$	<i>sm</i>	35.00	X
21	1	RIM RH FRT	\$	<i>sm</i>	385.00	X
22	1	TYRE RH FRT	\$	<i>sm</i>	330.00	X
23	1	CAP HUB LH FRT	\$	<i>sm</i>	35.00	X
24	1	RIM LH FRT	\$	<i>sm</i>	385.00	X
25	1	TYRE LH FRT	\$	<i>sl</i>	330.00	X
26	1	CAP HUB LH RR	\$	<i>sm</i>	35.00	X
27	1	RIM LH RR	\$	<i>sm</i>	385.00	X
28	1	TYRE LH RR	\$	<i>sm</i>	330.00	X

TOTAL	\$	3,284.35
TOTAL PARTS	\$	75,006.23

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	8,400.00	<i>900</i>
Putty and spray painting of the affected portion.	\$	9,000.00	<i>1100</i>
To rust-proofing of the affected areas.	\$	170.00	<i>90</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>NN</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	<i>60</i>
Towing Fees.	\$	120.00	<i>50</i>

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHC 274K - AXA

Candy

To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 7
To remove and renew engine and gear box mounting.	\$	380.00 7
To lift-up engine with gear box and refit.	\$	<i>Renew</i> 440.00 X
To dismantle and refit engine cross-member and engine mounting.	\$	380.00 7
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 <i>601</i>
To remove and refit air bag system and reset.	\$	480.00 <i>2501</i>
To check ABS brake efficiency, final checking and testing.	\$	<i>na</i> 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 } <i>2501</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 }
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>301</i>

TOTAL	\$	22,440.00
Over All Total	\$	97,446.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on 5 working days
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

< parts by parts > Repair Days

30 DAYS
9 days