

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Not Authen
1vB.1

Candy

9 57, 493.78

Fl. 940, 107.64

1606-360

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 274K - Candy
VF1ABL15AUC282629
RENAULT
LATITUDE
09.04.16
AXA

PART		LIST
1	1 BUMPER COVER FRT	\$ Tu 968.79 ✓✓
2	1 BUMPER SPOILER FRT	\$ mi 139.81 ✓
3	1 BUMPER ABSORBER FRT	\$ Br 303.60 ✓✓
4	1 BUMPER BRACKET FRT LH	\$ R 116.47 ✓✓
5	1 BUMPER RETAINER FRT LH	\$ CRA 18.37 ✓✓
6	1 BUMPER BRACKET FRT RH	\$ Su 115.98 X
7	1 BUMPER REPAIRER FRT RH	\$ Su 18.37 X
8	1 BUMPER UNDERTRAY FRT	\$ CRA 363.71 ✓
9	1 BUMPER GRILLE LOWER FRT	\$ CRA 205.23 ✓✓
10	1 BUMPER FOG LAMP GRILLE LH	\$ mi 159.39 ✓✓
11	1 BUMPER FOG LAMP GRILLE RH	\$ Su 159.39 X
12	1 BUMPER BEAM FRT	\$ R 703.14 ✓✓
13	1 RADIATOR GRILLE	\$ CRA 1,313.68 ✓✓
14	1 RADIATOR GRILLE BADGE 'RENAULT'	\$ Su 173.36 ✓✓
15	1 RADIATOR GRILLE FRAME	\$ Br 1,041.35 ✓✓
16	1 FRAME FULL SUPPORT PANEL	\$ CRA 473.77 ✓✓
17	1 FRAME FULL SUPPORT BRACKET	\$ R 69.07 ✓✓
18	1 FRONT BRACE PANEL	\$ R 136.32 ✓✓
19	1 SUBFRAME OUTER FRT →	\$ Su 2,040.34 7#X
20	1 SUBFRAME INNER FRT (crossmember) →	\$ Su 1,757.54 7#X
21	1 SUBFRAME SUPPORT INNER	\$ R 71.04 X
22	1 SUBFRAME BRACKET OUTER LH	\$ R 71.04 X
23	1 SUBFRAME BRACKET OUTER RH	\$ R 71.04 X
24	1 SUBFRAME BRACKET INNER LH	\$ R 138.44 X
25	1 SUBFRAME BRACKET INNER RH	\$ R 138.44 X
26	1 LOWER ARM RH	\$ Su 527.51 X
27	1 BRAKE DISC FRT	\$ Su 211.91 X
28	1 KUNCKLE ARM RH	\$ Su 651.53 X
29	1 KUNCKLE HUB+BEARING RH	\$ RR 382.84 X
30	1 KUNCKLE ARM SHIELD RH	\$ Su 101.10 X
31	1 KUNCKLE ARM PLATE RH	\$ Su 133.89 X
32	1 BRAKE DISC FRT	\$ Su 211.91 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

33	1	ABSORBER FRT RH	\$	277.34 X
34	1	ABSORBER MOUNTING KIT RH	\$	338.97 X
35	1	ABSORBER DUST COVER	\$	175.94 X
36	1	STABILIZER BAR FRT	\$	465.12 X
37	1	STABILIZER LINK FRT	\$	90.17 X
38	1	BRAKE CALIPER FRT RH	\$	505.34 X
39	1	BRAKE CALIPER BRACKET FRT RH	\$	427.01 X
40	1	ABS SENSOR FRT RH	\$	196.73 X
41	1	BRAKE HOSE FRT RH	\$	96.70 X
42	1	DRIVESHAFT RH	\$	1,344.19 X
43	1	LOWER ARM LH	\$	527.51 X
44	1	BRAKE DISC FRT	\$	211.91 X
45	1	KUNCKLE ARM LH	\$	651.53 X
46	1	KUNCKLE HUB+BEARING LH	\$	382.84 X
47	1	KUNCKLE ARM SHIELD LH	\$	101.10 X
48	1	KUNCKLE ARM PLATE LH	\$	133.89 X
49	1	BRAKE DISC FRT	\$	211.91 X
50	1	ABSORBER FRT LH	\$	277.34 X
51	1	ABSORBER MOUNTING KIT LH	\$	338.97 X
52	1	ABSORBER DUST COVER	\$	175.94 X
53	1	STABILIZER BAR FRT	\$	465.12 X
54	1	STABILIZER LINK FRT	\$	90.17 X
55	1	BRAKE CALIPER FRT LH	\$	505.34 X
56	1	BRAKE CALIPER BRACKET FRT LH	\$	427.01 X
57	1	ABS SENSOR FRT LH	\$	196.73 X
58	1	BRAKE HOSE FRT LH	\$	96.70 X
59	1	DRIVESHAFT LH	\$	1,344.19 X
60	1	SEATBELT BUCKLE RH	\$	730.61 X
61	1	SEATBELT RH	\$	2,250.28 ✓
62	1	SEATBELT BUCKLE LH	\$	730.61 X
63	1	SEATBELT LH	\$	2,250.28 ✓
64	1	PASSENGER AIRBAG	\$	2,624.93 ✓
65	1	PASSENGER AIRBAG COMPUTER	\$	969.09 ✓
66	1	PASSENGER AIRBAG SENSOR	\$	557.41 ✓
67	1	STEERING AIRBAG	\$	1,942.89 ✓
68	1	STEERING AIRBAG SENSOR	\$	222.54 ✓
69	1	STEERING AIRBAG COMPUTER	\$	969.09 X
70	1	ROTARY SWITCH	\$	963.93 ✓
71	1	DASHBOARD	\$	3,769.65 ✓
72	1	GLOVE BOX	\$	799.83 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
73	GLOVE BOX FLAP		\$	983.82	Sm X
74	HEADLAMP LH		\$	911.10	Bro ✓
75	HEADLAMP RH		\$	911.10	my car ✓
76	HEADLAMP HARNESS RH		\$	714.07	Sm X
77	HEADLAMP HARNESS LH		\$	714.07	Sm X
78	HEADLAMP PANEL FRT RH		\$	134.59	R X
79	HEADLAMP PANEL FRT LH		\$	134.59	R ✓
80	BONNET		\$	1,493.56	Bro ✓
81	BONNET INSULATOR		\$	312.10	Deform ✓
82	BONNET STRUT LH		\$	166.29	Sm X
83	BONNET STRUT RH		\$	166.29	Sm X
84	BONNET HINGE LH		\$	267.93	Dis ✓
85	BONNET HINGE RH		\$	267.93	R X
86	BAL HOOD	2	\$	75.60	Sm X
87	BONNET LOCK		\$	234.99	Dis ✓
88	BONNET CABLE		\$	91.69	Sm X
89	BONNET CABLE COVER		\$	123.87	Sm X
90	BONNET SEAL OUTER		\$	71.04	Sm X
91	FENDER PANEL FRT LH		\$	602.95	Br ✓
92	FENDER PANEL FRT RH		\$	602.95	R Bro X
93	FENDER WHEELARCH FRT LH (Linner)		\$	107.32	CM ✓
94	FENDER WHEELARCH FRT RH (Linner)		\$	214.49	Sm X
95	FENDER INSULATOR RH		\$	100.64	Sm X
96	FENDER INSULATOR LH		\$	100.64	Sm X
97	FENDER PANEL BRACKET FRT RH		\$	161.52	R X
98	FENDER PANEL BRACKET FRT LH		\$	161.52	Br ✓
99	WHEEL HOUSING PANEL FRT RH		\$	3,601.61	R X
100	WHEEL HOUSING PANEL FRT LH		\$	3,601.61	R X
101	FENDERCHASSIS REINFORCEMENT FRT LH		\$	765.90	R X
102	FENDERCHASSIS REINFORCEMENT FRT RH		\$	765.90	R X
103	RADIATOR → ✓		\$	924.77	Pr 7#
104	RADIATOR FAN COWLING → ✓		\$	573.80	CM 7#
105	RADIATOR FAN MOTOR LH → ✓		\$	676.48	Jm 7#
106	RADIATOR FAN MOTOR RH → ✓		\$	676.48	Jm 7#
107	RADIATOR HOSE UPPER		\$	168.22	Sm 7#
108	RADIATOR HOSE LOWER		\$	343.48	Sm 7#
109	AIR CLEANER HOSE		\$	58.57	Sm 7#
110	AIR CLEANER LOWER		\$	311.95	Sm 7#
111	ENGINE UNDERTRAY		\$	434.60	Sm 7#
112	A/C CONDENSER		\$	1,554.13	Pr ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

113	1	A/C CONDENSER GARNISH LH UPPER	\$	CMA	27.74	✓
114	1	A/C CONDENSER GARNISH RH UPPER	\$	Sm	27.74	X ✓
115	1	A/C CONDENSER GARNISH LH	\$	CMA	41.12	✓ ✓
116	1	A/C CONDENSER GARNISH RH	\$	Sm	41.68	X
117	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sm	145.73	X
118	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sm	460.64	Z
119	1	A/C PIPE COMPRESSOR	\$	Sm	233.77	Z
120	1	A/C PIPE	\$	Sm	460.64	X
121	1	TRANSMISSION COOLER	\$	BTL Sm	852.66	✓ ✓
122	1	AIR INTERCOOLER HOSE (LONG)	\$	Sm	709.18	X
123	1	AIR INTERCOOLER HOSE (Short)	\$	Sm	262.34	X
124	1	STEERING PUMP ELECTRIC	\$	Reservoir CMA	1,543.08	✓ ✓
125	1	STERING HOSE LOW PRESSURE LONG	\$	Sm	442.50	X
126	1	STERING HOSE LOW PRESSURE	\$	Sm	247.18	X
127		WINDSCREEN FRT	\$	Sm	1,005.56	X
128	1	WIPER RESERVOIR	\$	Sm	190.96	X
129	1	WIPER RESERVOIR NECK	\$	Sm	27.78	X
130	1	WIPER RESERVOIR MOTOR	\$	Sm	100.95	X
131	1	DOOR PANEL FRT LH	\$	R	2,188.20	X
132	1	DOOR MIRROR LH	\$	Sm	1,141.08	X
133	1	DOOR SEAL FRT LH	\$	Sm	50.92	X
134	1	DOOR PANEL FRT RH	\$	R	2,188.20	X
135	1	DOOR MIRROR RH	\$	Sm	1,141.08	X
136	1	DOOR SEAL FRT RH	\$	Sm	50.92	X

TOTAL	\$	79,690.98
10%	\$	7,969.10
	\$	71,721.88

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	Sm	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	Sm	66.00	✓
3	1	TOW COVER FRT	\$	Sm	14.50	✓
4	1SET	RADIATOR GRILLE SCREW	\$	Sm	16.00	✓
5	1SET	BUMPER GRILLE LOWER CLIP	\$	Sm	69.00	✓
6	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Sm	70.00	✓
7	2	FRAME FULL SUPPORT PANEL NUT	\$	Sm	20.00	X
8	2	FRAME FULL SUPPORT PANEL STUD	\$	Sm	30.00	X
9	2	BONNET CABLE CLIP	\$	Sm	6.40	X
10	1SET	WHEELARCH CLIP LH	\$	Sm	30.50	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

11	1SET	WHEELARCH CLIP RH	\$	<i>nn</i>	29.40 X
12	2	Front windscreen sealant	\$	<i>nn</i>	80.00 X
13	2	Front windscreen moulding	\$	<i>nn</i>	100.00 X
14	2	"E.R.P "Sticker	\$	<i>nn</i>	65.00 X
15	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i>	80.00 X
16	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00 X
17	1	DOOR STICKER "6555-3333"	\$	<i>nn</i>	80.00 X
18	1SET	NUMBER PLATE WITH HOLDER	\$	<i>Bu</i>	140.00 <i>455</i>
19	1	DASHBOARD SCREW	\$	<i>nn</i>	55.55 X
20	1	CAP HUB RH FRT	\$	<i>su</i>	35.00 X
21	1	RIM RH FRT	\$	<i>su</i>	385.00 X
22	1	TYRE RH FRT	\$	<i>su</i>	330.00 X
23	1	CAP HUB LH FRT	\$	<i>su</i>	35.00 X
24	1	RIM LH FRT	\$	<i>su</i>	385.00 X
25	1	TYRE LH FRT	\$	<i>su</i>	330.00 X
26	1	CAP HUB LH RR	\$	<i>su</i>	35.00 X
27	1	RIM LH RR	\$	<i>su</i>	385.00 X
28	1	TYRE LH RR	\$	<i>su</i>	330.00 X

TOTAL	\$	3,284.35
TOTAL PARTS	\$	75,006.23

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	8,400.00	<i>900</i>
Putty and spray painting of the affected portion.	\$	9,000.00	<i>1100</i>
To rust-proofing of the affected areas.	\$	170.00	<i>90</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	<i>60</i>
Towing Fees.	\$	120.00	<i>50</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 274K - AXA

Candy

To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na 380.00 X
To remove and renew engine and gear box mounting.	\$	na 380.00 X
To lift-up engine with gear box and refit.	\$	Proposed 440.00 X
To dismantle and refit engine cross-member and engine mounting.	\$	na 380.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 601 ✓
To remove and refit air bag system and reset.	\$	480.00 2501 ✓
To check ABS brake efficiency, final checking and testing.	\$	na 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 } 2501 ✓
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 }
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 301 ✓

TOTAL	\$	22,440.00
Over All Total	\$	97,446.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a written report
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Parts by parts Repair Days

Acknowledged by Repairer
Signature:
Date:

~~30 DAYS~~
9 days