

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB229C
 Ref. No : TAX/04/16/2198
 Reg. Date : 20/02/2013
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : MICKEL ANG KIM HUAT
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 20/04/2016 08:20:00 AM
 Accident Reported Date / Time : 20/04/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024081156
 Special Instruction to ARC, if any :
 GBA1054J - CHINA TAIPING - LKK
 Prepared Date : 20/04/2016 01:52:23 PM



*After Repair photo
 Loo Pooon Kyaw*

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB137799

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 2,070.00	0.00
Total Material Charges	: 6,204.07	6,204.07
Other Charges	: 880.00	0.00
TOTAL	: 10,337.07	0.00
Lum Sum Total	: 10,350.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	0.00 <i>4 Pags.</i>
Arc / Surveyor Sign Off Date	: 20/04/2016 05:49:07 PM	01/01/1900 12:00:00 AM

F

Prepared / Adjusted Date

Remarks :

Prepared Date : 20/04/2016 05:48:43 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 4/20/2016 5:50:01 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	0.00
Total Labour	1,183.00	0.00 600

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 X
TO RESPRAY FRONT DOOR LH	378.00	0.00
TO RESPRAY VIEW MIRROR	180.00	0.00
TO RESPRAY REAR DOOR LH	378.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
TO REPSRAY REAR BUMPER	378.00	0.00
Total Spray Painting & Panel Beating	2,070.00	0.00 850

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	300.00	0.00 80
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 1X0
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 20
Total Other Costs	880.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96636324	FRONT	6504580	PANEL FRT FENDER LH	1	606.00	10.00	545.40	Replace	Replace X	No
96635577	DOOR	6504596	PANEL LH FRONT DOOR	1	2,020.00	10.00	1,818.00	Replace	Replace X	No
	DOOR		SMRT LOGO DOOR	1	60.00	0.00	60.00	Replace	Replace ✓	No
96635885	DOOR		HANDLE DOOR INNER LH	1	105.00	10.00	94.50	Replace	Replace ✓	No
			HANDLE DOOR OUTER LH	1	60.00	10.00	54.00	Replace	Replace X	No
	DOOR		REGULATOR W/GLASS FRT LH	1	84.58	10.00	76.12	Replace	Replace X	No
			MOTOR POWER WINDOW LH	1	284.97	10.00	256.47	Replace	Replace X	No
	DOOR		LATCH FRT DOOR LH	1	212.00	10.00	190.80	Replace	Replace X	No
96635655	DOOR	6504603	PANEL LH REAR DOOR	1	1,863.00	10.00	1,676.70	Replace	Replace X	No
	COMMON		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00	Replace	Replace X	No
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace X	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace X	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No
			BUMPER REAR FASCIA	1	1,004.00	10.00	903.60	Replace	Replace ✓	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace X	No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace X	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace X	No
	COMMON	6505044	MIRROR LH	1	844.00	10.00	759.60	Replace	Replace X	No
TOTAL MATERIALS							7,755.10	7,755.09		
TOTAL MATERIALS(Discounted)							6,204.07	6,204.07		
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Kaluz 10/16/16
M 21/4/16