

INS CASE OWNER:

CC 4/EQ1600

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/ NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: 8/8

Repair Cost:

R/S S\$220,000.00

(25 days)

Reduction:

39 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 335,400.00

DID NOT NEED TO

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 1211.00

(\$350 x 3.5 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 5.55

Medical:

S\$ -

Disbursement:

S\$ 4,106.66

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 25,412.01

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

S\$ 300.00

(up)

08/11/13

REF: EV1

Surveyor:

ASSIGNMENT

From: _____ Date: 25/4/2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 2127M

at Workshop n/s CT 04/0

of Bk 16 Sin Mary Ind Est #0191

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 25 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "WP"

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XE 2127M Yr Regn: JUL 14.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MIT FUSO c.c 11967

Colour: GREY / GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 79193 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FVST 3JA 10011

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: N150 225/80R22.5

R: 295/80R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. D.O.I. 25/4/2016

Survey held at 16.30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/4/16 No GIA, estimate upon survey.

R/S: +220.000

P/P: +141,719.93 39%

P/P # 6317.92 (Red # 299412/4874)

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: _____

1)

☐: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Add Fee: ☐: Site Insp (\$ _____)

S + RS, SI

☐: Interview (\$ _____)

Photos

☐: Tech. Invs (\$ _____)

Others

☐: Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ116007503/M1jb3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 25-04-2016



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 8630J	Veh. Inspected	XE 2727M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	25/04/2016

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/04/2016	Inspection Date	25/04/2016
Survey held at	CT AUTO PTE LTD BLK 16 SIN MING IND ESTATE #01-91 SINGAPORE 575674		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

CT AUTO PTE LTD

16 Sin Ming Industrial Estate Sector A, #01-83, Singapore 575674

Tel: 64563008 Fax: 64599942 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

ESTIMATE

Date: 26/4/2016

DOA: 20/4/2016

Vehicle No: XE2727M

Make & Model: Mitsubishi FV5ISJD2DEA

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear R/H Tail Lamp <i>CRA</i>	\$ 455.00	✓
2	1	Rear R/H Tail Lamp Bracket <i>BT</i>	\$ 142.40	✓
5	1	Rear R/H MudGuard <i>BT</i>	\$ 1,768.80	✓
6	1	Rear R/H MudGuard MudFlap <i>Distorted</i>	\$ 177.70	✓
			\$ 2,543.90	
		Less 25%	\$ 635.98	
			\$ 1,907.93	
		<u>Special Neft Items</u>		
1		Sundries <i>R</i>	\$ 300.00	✓
2	1	Rear Tail Gate <i>BT</i>	\$ 8,000.00	✓ <i>7200.00</i>
3	4	Rear Lock Catch <i>BT</i>	\$ 800.00	✓
4	1	Rear Water Tank Complete (with LTA Cert) <i>Rear Water Tank</i>	\$ 180,000.00	✓ <i>42000.00</i>
5	1	Rear Engine Pump with Bracket and Water Pump (with LTA Cert) <i>CPA</i>	\$ 80,000.00	✓
6	2	Rear Engine Pump Bracket Tail Lamp <i>BT</i>	\$ 672.00	✓
7	1	Rear Trunk <i>R</i>	\$ 15,000.00	✓
8	2	Rear Trunk Absorber <i>R</i>	\$ 24,000.00	✓
9	1	Rear No. Plate <i>BT</i>	\$ 50.00	✓ <i>30.00</i>
			\$ 308,822.00	
		Total parts	\$ 310,729.93	
S/N	Labour Description		Amount	Amount
	Labour for panel beating, cut, weld, straighten and replace rear			
1	damaged parts.		\$ 5,000.00	✓ <i>4500.00</i>
2	To putty and spray painting rear portion. (Inclusive of Tank)		\$ 10,000.00	✓ <i>6000.00</i>
3	To remove and install rear water tank to facilitate the repairs		\$ 8,000.00	✓ <i>X m</i>
4	(Including Welding & Cranks).		\$ 1,000.00	✓ <i>500.00</i>
	To apply anti rust proofing to affected area.		\$ 1,000.00	
	Total labour :		\$ 24,000.00	
	Total parts :		\$ 310,729.93	
	Total labour :		\$ 24,000.00	
	Total repair cost : (Before GST)		\$ 334,729.93	

* Less Depreciation 10% of \$ 42000.00
Cost Parts 10% 20% \$ 7200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2727M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS					
1	REAR R/H TAIL LAMP	CRACKED	455.00	-	455.00
1	REAR R/H TAIL LAMP BRACKET	BENT	142.40	-	142.40
1	REAR R/H MUDGUARD	BENT	1,768.80	-	1,768.80
1	REAR R/H MUDGUARD MUDFLAP	DISTORTED	177.70	-	177.70
	LESS 25% DISCOUNT		-635.98	-	-635.98
			1,907.92	-	1,907.92
SPECIAL NETT ITEMS					
1	SUNDRIES (SN)	TO REPAIR SEE LABOUR	300.00	-	-
1	REAR TAIL GATE (SN)	BENT	8,000.00	-	7,000.00
4	REAR LOCK CATCH (SN)	BENT	800.00	-	800.00
1	REAR TRUNK (SN)	TO REPAIR SEE LABOUR	15,000.00	-	-
2	REAR TRUNK ABSORBER (SN)	TO REPAIR SEE LABOUR	24,000.00	-	-
1	REAR NO.PLATE (SN)	BENT	50.00	-	30.00
			48,150.00	-	7,830.00
1	REAR WATER TANK COMPLETE (WITH LTA CERT) (WCP))	BENT / CRACKED	180,000.00	-	42,000.00
1	REAR ENGINE PUMP WITH BRACKET AND WATER PUMP (WITH LTA CERT) (WCP))	CRACKED	80,000.00	-	-
2	REAR ENGINE PUMP BRACKET TAIL LAMP (WCP))	BENT	672.00	-	-
	LESS DEPRECIATION 10% OF \$42,000.00		-	-	-4,200.00
	COST PLUS 10% ON \$37,800.00		-	-	3,780.00
			260,672.00	-	41,580.00
LABOUR					
	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN AND REPLACE REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF SUNDRIES,REAR TRUNK AND REAR TRUNK ABSORBER .		5,000.00	-	4,500.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION (INCLUSIVE OF TANK).		10,000.00	-	6,000.00

Report Ref No. CC4/EQI16007503/M1eb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR WATER TANK TO FACILITATE THE REPAIRS (INCLUDING WELDING & CRANKS).	NOT NECESSARY	35,000.00	-	-
	TO APPLY ANTI RUST PROOFING TO AFFECTED AREA.		1,000.00	-	500.00
			51,000.00	-	11,000.00
GRAND TOTAL			361,729.92	-	62,317.92
RECOMMENDED COST OF REPAIR SUM					62,317.92

Report Ref No. CC4/EQI16007503/M1eb3q2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

CT AUTO PTE LTD

16 Sin Ming Industrial Estate Sector A, #01-83, Singapore 575674

Tel: 64563008 Fax: 64599942 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

ESTIMATE

Date: 26/4/2016

DOA: 20/4/2016

Vehicle No: XE2727M

Make & Model: Mitsubishi FV5ISJD2DEA

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear R/H Tail Lamp	\$ 455.00	✓ CVA
2	1	Rear R/H Tail Lamp Bracket	\$ 142.40	✓ bt
5	1	Rear R/H MudGuard	\$ 1,768.80	✓ bt
6	1	Rear R/H MudGuard MudFlap	\$ 177.70	✓ dig
			\$ 2,543.90	
		Less 25%	\$ 635.98	
			\$ 1,907.93	
		<u>Special Nett Items</u>		
1		Sundries	\$ 300.00	X 12
2	1	Rear Tail Gate	\$ 8,000.00	7000. ✓ bt
3	4	Rear Lock Catch	\$ 800.00	120K. ✓ bt
4	1	Rear Water Tank Complete (with LTA Cert)	\$ 180,000.00	120K. ✓ bt / CVA
5	1	Rear Engine Pump with Bracket and Water Pump (with LTA Cert)	\$ 80,000.00	50K. CVA
6	2	Rear Engine Pump Bracket Tail Lamp	\$ 672.00	✓ bt
7	1	Rear Trunk	\$ 15,000.00	✓ R.
8	2	Rear Trunk Absorber	\$ 24,000.00	✓ R.
9	1	Rear No. Plate	\$ 50.00	20 ✓ bt
			\$ 308,822.00	
		Total parts	\$ 310,729.93	.
S/N	Labour Description		Amount	Amount
1	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.		\$ 5,000.00	4200. ✓
2	To putty and spray painting rear portion. (Inclusive of Tank)		\$ 10,000.00	6000. ✓
3	To remove and install rear water tank to facilitate the repairs (Including Welding & Cranks).		\$ 35,000.00	3000. ✓
4	To apply anti rust proofing to affected area.		\$ 1,000.00	500. ✓
	Total labour :		\$ 51,000.00	
	Total parts :		\$ 310,729.93	
	Total labour :		\$ 51,000.00	
	Total repair cost : (Before GST)		\$ 361,729.93	

A/S \$ 22000.
25 w/ days

Catherine Chong (LKK Auto)

From: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Sent: Friday, 22 April, 2016 5:22 PM
To: assignments
Subject: FW: Request for Pre-Repair Inspection – XE2727M

Our ref : XB8630J
TP veh : XE2727M
Policy No. : DMCPHQ16-000703

Dear All,

Please proceed to survey the TP vehicle.
Our insured has yet to report the accident.

Regards,

Elaine Cheong
Senior Executive, Claims

EQ Insurance Company Limited

5 Maxwell Road,
#17-00 Tower Block,
MND Complex,
Singapore 069110
DID : 6500 6772
Tel : 6223 9433
Fax: 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Emellene Teng [mailto:admin@ctauto.com.sg]
Sent: Friday, April 22, 2016 12:17 PM
To: Elaine Cheong
Subject: Request for Pre-Repair Inspection – XE2727M

Our Ref: XE2727M

To: The owner and/or driver of XB8630J 3rd party
c/o EQ Insurance

cc: EQ Insurance

Shu Pei (LKK Auto)

From: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Sent: Friday, 6 May, 2016 1:20 PM
To: Shu Pei (LKK Auto)
Cc: Admin A; Joy Irene (LKK Auto); Thin Thin
Subject: RE: Request for Pre-Repair Inspection – XE2727M ***LKK REF:CC4/EQI16007503/M1jb3 (EQ VEH: XB8630J) / CLAIM REF: DM16/887-EC)
Attachments: OI - XB8630J.PDF

Dear Shu Pei,

As requested, attached a copy of our insured's GIA report for your perusal.

Regards,

Elaine Cheong
Senior Executive, Claims

EQ Insurance Company Limited

5 Maxwell Road,
#17-00 Tower Block,
MND Complex,
Singapore 069110
DID : 6500 6772
Tel : 6223 9433
Fax: 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Shu Pei (LKK Auto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, May 05, 2016 4:30 PM
To: Elaine Cheong
Cc: Admin A; Joy Irene (LKK Auto); Thin Thin
Subject: RE: Request for Pre-Repair Inspection – XE2727M ***LKK REF:CC4/EQI16007503/M1jb3

WITHOUT PREJUDICE

Dear Elaine,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle XE 2727M at M/s CT Auto Pte Ltd.

Enclosed for your perusal is:

- TP's GIA report
- TP's Police report Addendum

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Joy and she can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKK Auto)

Sent: Monday, 25 April, 2016 9:06 AM

To: 'Elaine Cheong' <elaine.cheong@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Request for Pre-Repair Inspection – XE2727M

Dear Elaine,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elaine Cheong [<mailto:elaine.cheong@eqinsurance.com.sg>]

Sent: Friday, 22 April, 2016 5:22 PM

To: assignments <assignments@lkkauto.com>

Subject: FW: Request for Pre-Repair Inspection – XE2727M

Our ref : XB8630J

TP veh : XE2727M

Policy No. : DMCPHQ16-000703

Dear All,

Please proceed to survey the TP vehicle.

Our insured has yet to report the accident.

Regards,

Elaine Cheong
Senior Executive, Claims

EQ Insurance Company Limited

5 Maxwell Road,
#17-00 Tower Block,
MND Complex,
Singapore 069110
DID : 6500 6772
Tel : 6223 9433
Fax: 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Emellene Teng [<mailto:admin@ctauto.com.sg>]
Sent: Friday, April 22, 2016 12:17 PM
To: Elaine Cheong
Subject: Request for Pre-Repair Inspection – XE2727M

Our Ref: XE2727M

To: The owner and/or driver of XB8630J 3rd party
c/o EQ Insurance

cc: EQ Insurance

Dear Sir/Madam,

Accident Involving XE2727M & XB8630J on 14/4/2016 along Sims Way towards PIE (Tuas)

With reference to the above, we hereby give EQ Insurance 2 days' notice to conduct a pre-repair inspection notice of vehicle XE2727M at our premise.

Please arrange for your surveyor to inspect the vehicle at:

Block 16 Sin Ming Industrial Estate Sector A #01-91

Singapore 575674

Mobile No.: 9737 0733

If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Please let us know which surveyor will be attending this survey so that we can arrange the exact location (as the location is off limits to outsiders).

Please advise on liability for this case.

Best Regards,
Emellene Teng
CT Auto PTE LTD
Office: 6456-3008 Fax: 6459-9942

Please like our Facebook page at: <https://www.facebook.com/leongautogroup>

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 22 November, 2017 5:12 PM
To: 'Annabel Tan'; Janet Tan
Cc: Vic (LKKAUTO)
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016
Attachments: LKK Resurvey Photo.pdf; LKK Survey Photo.pdf; XE2727M - Vicom Inspection.pdf; XE2727M - Chemical Liquid Invoice.pdf; XE2727M - Rental Agreement.pdf; XE2727M - Time Card.pdf; LKK Adjustment.pdf; LKK Inspection.pdf; XE2727M - LOD.PDF

Your ref : DM16HO00887
Our ref : CC4/EQI16007503/M1eb3

Dear Sirs,

We refer to the above matter.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " CT AUTO PTE LTD" at \$251,912.01 (all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 387,051.01	\$ 235,400.00
2. Loss of Use (31days x \$450)	\$ 13,950.00	\$ 12,400.00 (31days x \$400)
3. LTA Search Fee	\$ 5.35	\$ 5.35
4. Disbursement	\$ 4,106.66	\$ 4,106.66
Total	\$ 405,113.02	\$ 251,912.01

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annabel Tan [mailto:annabel.tan@eqinsurance.com.sg]

Sent: Friday, 14 July, 2017 4:27 PM

To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>

Hsiao Tong (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 30 August 2019 4:54 PM
To: Hsiao Tong (LKKAUTO)
Cc: Olivia Lau (LKKAUTO); KKLau; Bryan Ang (LKKAUTO)
Subject: RE: Our ref: DM16HO00887/JT- [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Okay. Thank you.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Friday, August 30, 2019 4:50 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; KKLau <kklau@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>
Subject: RE: Our ref: DM16HO00887/JT- [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Janet,

We refer to the above matter.

We are presently doing file review. We will proceed to submit our WP report to your good office since the matter is now handled by EQ's lawyer United Legal Alliance.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan <janet.tan@eqinsurance.com.sg>

Sent: Tuesday, 27 March 2018 4:13 PM

To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Cc: Ronald Cheng <ronald.cheng@eqinsurance.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; KKLau <kklau@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: Our ref: DM16HO00887/JT- [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Dear Oliver,

Please proceed to negotiate settlement up to \$85,000.00 (all-in).

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Olivia Lau (LKKAuto) [<mailto:olivialau@lkkauto.com>]

Sent: Tuesday, February 6, 2018 5:48 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Ronald Cheng <ronald.cheng@eqinsurance.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; KKLau <kklau@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: RE: [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

MANDATE – REMINDER

Dear Janet,

We are following up on our mandate request below of 23 January.

Please advise if we can proceed to offer as per our recommendation.

Thank you.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Olivia Lau (LKKAuto)

Sent: Tuesday, 23 January, 2018 3:13 PM

To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>

Cc: 'ronald.cheng@eqinsurance.com.sg' <ronald.cheng@eqinsurance.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; KKLau <kklau@lkkauto.com>

Subject: [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

MANDATE

Your ref : DM16HO00887

Our ref : CC4/EQ116007503/M1eb3

Dear Janet,

We refer to the above matter.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability. We have clarified with insured BLL'S HOLDINGS PTE LTD the nature of the accident and it is aware that its NCD (if any) would be affected. Insured had also provided PIR where Traffic Police had initiated action against the insured's employee driver for "Careless Driving under Rule 29 RTR". (PIR is enclosed)

A. The breakdown of TP's claim is as follows:-

	Amount Claimed
1. Cost of Repairs (with GST)	\$ 387,051.01
2. Loss of Use (31days x \$450)	\$ 13,950.00
3. LTA Search Fee	\$ 5.35
4. Disbursement	\$ 4,106.66
Total	\$ 405,113.02

As TP's damages involved a 20,000L water tank, we had obtained a direct quotation from a local supplier of such water tanks (email with tank supplier 'Wong Fong Engineering Works' is enclosed).

The water pump and the installation cost of water tank were also covered in the supplier's quotation. In our opinion, based on our research, we suggest to offer as follows, factoring in a reasonable 10% depreciation of the amount and reasonable 10% mark up on the cost.

B. Our computation summary is as follows: -

	Amount Revised
1. Cost of Repairs (with GST)	\$ 66,680.17
2. Loss of Use (31days x \$450)	\$ 12,400.00 (31days x <u>\$400</u>) (No Benchmark)
3. LTA Search Fee	\$ 5.35
4. Disbursement	\$ 4,106.66
Total	\$ 83,192.18

For your information, claimant did not provide any reasonable documents to support the justification of their amount claimed, in particular, amounts for the water tank and the various related job/work relating to the restoration of the TP vehicle to its pre-accident condition.

Enclosed here with all the relevant documents for your perusal.

Based on the above, please advise if we can proceed to offer TP repairer " CT AUTO PTE LTD" at **\$83,192.18** (all-in).

Thank you.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Asher Sng (LKKAuto)

Sent: Wednesday, 6 December 2017 4:40 PM

To: Annabel Tan <annabel.tan@eqinsurance.com.sg>

Cc: Janet Tan <janet.tan@eqinsurance.com.sg>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Annabel,

We refer to the above matter.

Enclosed a copy of the Preliminary Advice for your perusal.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]
Sent: Friday, 14 July, 2017 4:27 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>
Cc: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Ma C.F (LKKAUTO) <MaCF@lkkauto.com>
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Asher,


Please follow up with TP repairer and request them to expedite.
Many thanks.

Regards,

Annabel Tan
Assistant Manager | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Asher Sng (LKKAUTO) [<mailto:AsherSng@lkkauto.com>]
Sent: Friday, July 14, 2017 4:23 PM
To: Annabel Tan; Shu Pei (LKKAUTO)
Cc: Thin Thin (LKKAUTO); Ma C.F (LKKAUTO)
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Annabel,

We refer to the email below.

We still pending finalize from third party repairer.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]

Sent: Friday, 14 July, 2017 4:24 PM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Shu Pei (LKKAuto) <shupe@lkkauto.com>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Ma C.F (LKKAuto) <MaCF@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

OUR REF : DM16HO00887 (FILE REVIEW)

YOUR REF : CC4/EQ16007503/M1JB3

Dear Asher,

It has been 07 months since our last chaser, please revert on status and advise the delay, thank you.

Regards,

Annabel Tan

Assistant Manager | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Asher Sng (LKKAuto) [<mailto:AsherSng@lkkauto.com>]

Sent: Wednesday, December 28, 2016 2:29 PM

To: Shu Pei (LKKAuto); Annabel Tan

Cc: Thin Thin (LKKAuto); Ma C.F (LKKAuto); Hsiao Tong (LKKAuto)

Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Annabel,

We refer to the email below.

We still pending finalize from third party repairer.

Thank You.

"Wishes you a Happy New Year 2017"

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

From: Shu Pei (LKKAuto)
Sent: Wednesday, 28 December, 2016 12:33 PM
To: Annabel Tan <annabel.tan@eqinsurance.com.sg>
Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Dear Annabel,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Asher,

For your information and necessary action please.

Thank you.

To check availability of the case handler , you may contact the undersigned.

"Wishes you a Happy New Year 2017"

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]
Sent: Wednesday, 28 December, 2016 11:20 AM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Subject: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

OUR REF : DM16HO00887 (FILE REVIEW)
YOUR REF : CC4/EQI16007503/M1JB3

Dear Shu Pei,

We refer to the above mentioned matter.

As we are conducting our file review, please let us have the status of the TP Direct Settlement with CT Auto.
Thank you.

Regards,

Annabel Tan
Assistant Manager, Claims

EQ Insurance Company Limited

5 Maxwell Road,
#17-00 Tower Block,
MND Complex,
Singapore 069110

DID: 6496 9115

Tel: 6223 9433

Fax: 6223 4190

www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 30 August 2019 4:50 PM
To: Janet Tan
Cc: Olivia Lau (LKKAuto); KKLau; Bryan Ang (LKKAuto)
Subject: RE: Our ref: DM16HO00887/JT- [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Janet,

We refer to the above matter.

We are presently doing file review. We will proceed to submit our WP report to your good office since the matter is now handled by EQ's lawyer United Legal Alliance.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan <janet.tan@eqinsurance.com.sg>

Sent: Tuesday, 27 March 2018 4:13 PM

To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Cc: Ronald Cheng <ronald.cheng@eqinsurance.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; KKLau <kklau@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: Our ref: DM16HO00887/JT- [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Dear Oliver,

Please proceed to negotiate settlement up to \$85,000.00 (all-in).

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: Olivia Lau (LKKAUTO) [<mailto:olivialau@lkkauto.com>]
Sent: Tuesday, February 6, 2018 5:48 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Ronald Cheng <ronald.cheng@eqinsurance.com.sg>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; KKLau <kklau@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>
Subject: RE: [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

MANDATE – REMINDER

Dear Janet,

We are following up on our mandate request below of 23 January.

Please advise if we can proceed to offer as per our recommendation.

Thank you.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Olivia Lau (LKKAUTO)
Sent: Tuesday, 23 January, 2018 3:13 PM
To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>
Cc: 'ronald.cheng@eqinsurance.com.sg' <ronald.cheng@eqinsurance.com.sg>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; KKLau <kklau@lkkauto.com>
Subject: [MANDATE]: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

MANDATE

Your ref : DM16HO00887

Our ref : CC4/EQI16007503/M1eb3

Dear Janet,

We refer to the above matter.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability. We have clarified with insured BLL'S HOLDINGS PTE LTD the nature of the accident and it is aware that its NCD (if any) would be affected. Insured had also provided PIR where Traffic Police had initiated action against the insured's employee driver for "Careless Driving under Rule 29 RTR". (PIR is enclosed)

A. The breakdown of TP's claim is as follows:-

	Amount Claimed
1. Cost of Repairs (with GST)	\$ 387,051.01
2. Loss of Use (31days x \$450)	\$ 13,950.00
3. LTA Search Fee	\$ 5.35
4. Disbursement	\$ 4,106.66
Total	\$ 405,113.02

As TP's damages involved a 20,000L water tank, we had obtained a direct quotation from a local supplier of such water tanks (email with tank supplier 'Wong Fong Engineering Works' is enclosed).

The water pump and the installation cost of water tank were also covered in the supplier's quotation. In our opinion, based on our research, we suggest to offer as follows, factoring in a reasonable 10% depreciation of the amount and reasonable 10% mark up on the cost.

B. Our computation summary is as follows: -

	Amount Revised
1. Cost of Repairs (with GST)	\$ 66,680.17
2. Loss of Use (31days x \$450)	\$ 12,400.00 (31days x <u>\$400</u>) (No Benchmark)
3. LTA Search Fee	\$ 5.35
4. Disbursement	\$ 4,106.66
Total	\$ 83,192.18

For your information, claimant did not provide any reasonable documents to support the justification of their amount claimed, in particular, amounts for the water tank and the various related job/work relating to the restoration of the TP vehicle to its pre-accident condition.

Enclosed here with all the relevant documents for your perusal.

Based on the above, please advise if we can proceed to offer TP repairer " **CT AUTO PTE LTD**" at **\$83,192.18** (all-in).

Thank you.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Asher Sng (LKKAUTO)

Sent: Wednesday, 6 December 2017 4:40 PM

To: Annabel Tan <annabel.tan@eqinsurance.com.sg>

Cc: Janet Tan <janet.tan@eqinsurance.com.sg>; Vic (LKKAUTO) <yicalpeh@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>

Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Annabel,

We refer to the above matter.

Enclosed a copy of the Preliminary Advice for your perusal.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]

Sent: Friday, 14 July, 2017 4:27 PM

To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>

Cc: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Ma C.F (LKKAUTO) <MaCF@lkkauto.com>

Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Asher,

Please follow up with TP repairer and request them to expedite.
Many thanks.

Regards,

Annabel Tan

Assistant Manager | Claims

eqinsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Asher Sng (LKKAUTO) [<mailto:AsherSng@lkkauto.com>]
Sent: Friday, July 14, 2017 4:23 PM
To: Annabel Tan; Shu Pei (LKKAUTO)
Cc: Thin Thin (LKKAUTO); Ma C.F (LKKAUTO)
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Annabel,

We refer to the email below.

We still pending finalize from third party repairer.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]
Sent: Friday, 14 July, 2017 4:24 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Cc: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Ma C.F (LKKAUTO) <MaCF@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

OUR REF : DM16HO00887 (FILE REVIEW)
YOUR REF : CC4/EQI16007503/M1JB3

Dear Asher,

It has been 07 months since our last chaser, please revert on status and advise the delay, thank you.

Regards,

Annabel Tan

Assistant Manager | Claims

eqinsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Asher Sng (LKKAuto) [<mailto:AsherSng@lkkauto.com>]
Sent: Wednesday, December 28, 2016 2:29 PM
To: Shu Pei (LKKAuto); Annabel Tan
Cc: Thin Thin (LKKAuto); Ma C.F (LKKAuto); Hsiao Tong (LKKAuto)
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Hi Annabel,

We refer to the email below.

We still pending finalize from third party repairer.

Thank You.

"Wishes you a Happy New Year 2017"

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Wednesday, 28 December, 2016 12:33 PM
To: Annabel Tan <annabel.tan@eqinsurance.com.sg>
Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

Dear Annabel,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Asher,

For your information and necessary action please.

Thank you.

To check availability of the case handler , you may contact the undersigned.

"Wishes you a Happy New Year 2017"

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

From: Annabel Tan [<mailto:annabel.tan@eqinsurance.com.sg>]
Sent: Wednesday, 28 December, 2016 11:20 AM
To: Shu Pei (LKKAUTO) <shupe@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>
Subject: Accident involving XB8630J (EQ) & XE2727M on 20 April 2016

OUR REF : DM16HO00887 (FILE REVIEW)
YOUR REF : CC4/EQI16007503/M1JB3

Dear Shu Pei,

We refer to the above mentioned matter.

As we are conducting our file review, please let us have the status of the TP Direct Settlement with CT Auto.
Thank you.

Regards,

Annabel Tan
Assistant Manager, Claims

EQ Insurance Company Limited
5 Maxwell Road,
#17-00 Tower Block,
MND Complex,
Singapore 069110

DID: 6496 9115
Tel: 6223 9433
Fax: 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ116007503/M1pb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 18-09-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 8630J	Veh. Inspected	XE 2727M
Policy No.	DMCPHQ16-000703	Coverage (\$)	0.00
Claim No.	DM16HO00887/JT	Excess (\$)	0.00
Assign From	ELAINE	Assign Date	25/04/2016

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FUSO	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	FV51SJA10011	Colour	GREY/GRREN
Odometer	79193	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	INDFORCE	8 mm
L/H Front Tyre	315/80 R22.5	INDFORCE	8 mm
R/H Rear Tyre	295/80 R22.5	INDFORCE	8 mm
L/H Rear Tyre	295/80 R22.5	INDFORCE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/04/2016	Inspection Date	25/04/2016
Survey held at	CT AUTO PTE LTD BLK 16 SIN MING IND ESTATE #01-91 SINGAPORE 575674		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	25 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 2727M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR R/H TAIL LAMP	CRACKED	455.00	455.00
1	REAR R/H TAIL LAMP BRACKET	BENT	142.40	142.40
1	REAR R/H MUDGUARD	BENT	1,768.80	1,768.80
1	REAR R/H MUDGUARD MUDFLAP	DISTORTED	177.70	177.70
	LESS 25% DISCOUNT		-635.98	-635.98
			1,907.92	1,907.92
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	TO REPAIR SEE LABOUR	300.00	-
1	REAR TAIL GATE (SN)	BENT	8,000.00	7,000.00
4	REAR LOCK CATCH (SN)	BENT	800.00	800.00
1	REAR TRUNK (SN)	TO REPAIR SEE LABOUR	15,000.00	-
2	REAR TRUNK ABSORBER (SN)	TO REPAIR SEE LABOUR	24,000.00	-
1	REAR NO.PLATE (SN)	BENT	50.00	30.00
			48,150.00	7,830.00
1	REAR WATER TANK COMPLETE (WITH LTA CERT) (WCP) }	BENT / CRACKED	180,000.00	42,000.00
1	REAR ENGINE PUMP WITH BRACKET AND WATER PUMP (WITH LTA CERT) (WCP) }	CRACKED	80,000.00	-
2	REAR ENGINE PUMP BRACKET TAIL LAMP (WCP) }	BENT	672.00	-
	LESS DEPRECIATION 10% OF \$42,000.00		-	-4,200.00
	COST PLUS 10% ON \$37,800.00		-	3,780.00
			260,672.00	41,580.00
<u>LABOUR</u>				
	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN AND REPLACE REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF SUNDRIES,REAR TRUNK AND REAR TRUNK ABSORBER .		5,000.00	4,500.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION (INCLUSIVE OF TANK).		10,000.00	6,000.00

Report Ref No. CC4/EQ116007503/M1pb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR WATER TANK TO FACILITATE THE REPAIRS (INCLUDING WELDING & CRANKS).	NOT NECESSARY	35,000.00	-
	TO APPLY ANTI RUST PROOFING TO AFFECTED AREA.		1,000.00	500.00
			51,000.00	11,000.00
GRAND TOTAL			361,729.92	62,317.92
RECOMMENDED COST OF REPAIRS				62,317.92

Report Ref No. CC4/EQ16007503/M1pb3q2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.