

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6247A
 Ref. No : TAX/04/16/2283
 Reg. Date : 05/08/2011
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TAN LIP SENG @ MUHAMMAD RAMZI TAN
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 28/04/2016 06:30:00 PM
 Accident Reported Date / Time : 29/04/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024081392
 Special Instruction to ARC, if any :
 SKF3988T - CHINA TAIPING - LKK
 Prepared Date : 29/04/2016 03:23:29 PM



*for repair
 Complete Repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB070880

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	676.00	0.00
Total Spray Painting Charges	1,494.00	0.00
Total Material Charges	3,880.32	4,143.51
Other Charges	420.00	0.00
TOTAL	6,470.32	0.00
Lum Sum Total	6,450.00	0.00
No. of Repair Days	4.00	0.00
Prepared / Adjusted By		<i>3 Pgs.</i>
Arc / Surveyor Sign Off Date	03/05/2016 10:09:47 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/05/2016 10:09:47 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	676.00	0.00
Total Labour	676.00	0.00 400

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00
TO RESPRAY RIM	180.00	0.00 X
TO REPSRAY REAR BUMPER	378.00	0.00 50
Total Spray Painting & Panel Beating	1,494.00	0.00 X 450

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 50
Total Other Costs	420.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96635655	DOOR	6504603	PANEL LH REAR DOOR	1	1,863.00	10.00	1,676.70	Replace	Replace ✓	No
	COMMON		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓	No
96634087	LEFT	6504608	MOLDING PANEL LH ROCKER	1	304.00	10.00	273.60	Replace	Replace ✓	No
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace X	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace X	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No
	COMMON	6504666	TYRE RIM	1	328.99	0.00	328.99	Repair	Replace ✓	No
			BUMPER REAR FASCIA	1	1,004.00	10.00	903.60	Replace	Replace X	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace X	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace X	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace X	No
TOTAL MATERIALS								4,476.90	4,805.89	
TOTAL MATERIALS(Discounted)								3,880.32	4,143.51	
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Kalvin / (K)

3/5/16