

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III16008133/T1PA3Q2**Date:** 19/12/2018REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MC0M0016
Claimant Vehicle No :	SJF3110X	Insured Vehicle No :	SH9823R
Date of Loss:	23/04/2016	Nature of Claim:	TP
		Claim No:	MCT16040929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF3110X	Engine No:	72014241N52B25AE
Make & Model:	BMW 523i, 2.5 XL (A)	Chassis No:	WBANU12070CW25293
Reg. Date:	27/05/2008 (Man. Year: 2008)	Odometer:	138900 km
Colour:	Grey		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,633.00	2,689.45	2,943.55	52.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,260.00	880.00	41.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,773.00	3,949.45	3,823.55	49.19
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	7,773.00	3,100.00	4,673.00	60.12
+ GST 7.00/7.00% (S\$)	544.11	217.00	327.11	60.12
Nett Amount (S\$)	8,317.11	3,317.00	5,000.11	60.12
+ Car Rental (6.0 x S\$180.00/day + 7.00% GST) (S\$)		1,155.60		
Nett Liability (S\$)		4,472.60		

INSPECTION

Date of Assignment:	03/05/2016	
Date Inspected:	03/05/2016 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2018)
Parts:	143	BMW 523I 2.5 XL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF3110X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,271.00 F	*1,271.00 FL
2	2		*REAR BUMPER RETAINER	Necessary	142.00 F	*142.00 FL
3	1		*REAR BUMPER REFLECTOR O/S	Missing	43.75 F	*43.75 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	480.00 F	*480.00 FL
5	1		*REAR END PANEL	Dented	717.00 F	*717.00 FL
6	1		*SPARE TYRE PANEL	Repair	2,100.00 F	*- FL
7	1		*REAR BUMPER GUIDE	Deformed	42.00 F	*42.00 FL
8	1		*REAR BUMPER LOWER COVER	Deformed	135.25 F	*135.25 FL
9	2		*REAR SENSOR	Serviceable	702.00 F	*- FL
					Sub Total (\$\$)	5,633.00 2,831.00
					- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00 141.55
					Total Parts (\$\$)	5,633.00 2,689.45

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR,REPLACE & INSTALL DAMAGED	New	1,000.00	600.00
2	TO R&R WIRING	New	60.00	30.00
3	TO TUFF COAT	New	80.00	30.00
4	TO PUTTY & SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,140.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >