

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ001816

AXA INSURANCE (SINGAPORE) PTE LTD

8 SHENTON WAY AXA TOWER #B1-01
SINGAPORE 068811

ATTENTION:

CONTACT: 63387288

FAX NO: 63370677

DATE: 22/06/2016
ACCIDENT DATE: 04/05/2016
VEHICLE NO: SGX8226D
CHASSIS/ENG.NO:
VEHICLE MODEL: HONDA STREAM
CLAIM NO:
POLICY NO:
REMARK: 8226AXA TP AGST
SJF1720Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR DOOR (LH)	870.40	20	696.32	696.32
2	1	PC	REAR DOOR HINGE LOWER	58.60	20	46.88	46.88
3	1	PC	REAR DOOR REGULATOR AND MOTOR	363.40	20	290.72	290.72
4	1	PC	REAR DOOR BLACK TAPE	37.70	20	30.16	30.16
5	1	PC	REAR DOOR OUTER MOULDING	70.55	20	56.44	56.44
6	1	PC	FRT DOOR (LH)	860.80	20	688.64	688.64
7	1	PC	FRT DOOR BLACK TAPE	48.60	20	38.88	38.88
8	1	PC	FRT DOOR OUTER MOULDING	69.60	20	55.68	55.68
9	1	PC	REAR FENDER (LH)	858.30	20	686.64	686.64
10	1	PC	REAR BUMPER	588.90	20	471.12	471.12
11	6	PC	REAR BUMPER CLIPS	3.90	20	3.12	18.72
12	1	PC	REAR BUMPER RETAINER(LH)	19.50	20	15.60	15.60

SUB-TOTAL: 3,095.80

** SPECIAL NETT PRICE **							
1	1	PC	REAR FENDER GLASS SEALANT (LH)	40.00		40.00	40.00
2	1	PC	REAR TYRE (LH)	380.00		380.00	380.00
3	1	PC	REAR TYRE RIM(LH)	400.00		400.00	400.00
SUB-TOTAL							820.00

** WORK LABOUR **

TO KNOCK ROCKER GARNISH, WELD, REMOVE AND FIX ON ABOVE PARTS	1000.00	700	1,000.00
TO REMOVE AND REFIX 2 DOOR GLASS	120.00	60	120.00

JANICE

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ001816

AXA INSURANCE (SINGAPORE) PTE LTD

8 SHENTON WAY AXA TOWER #B1-01
SINGAPORE 068811

ATTENTION:

CONTACT: 63387288

FAX NO: 63370677

DATE: 22/06/2016
ACCIDENT DATE: 04/05/2016
VEHICLE NO: SGX8226D
CHASSIS/ENG.NO:
VEHICLE MODEL: HONDA STREAM
CLAIM NO:
POLICY NO:
REMARK: 8226AXA TP AGST
SJF1720Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	ISC/MARKUP	TOTAL AMT
			TO REMOVE AND REFIX TRIMS AND UPHOLSTERY	180.00		80	180.00
			TO APPLY ANTI RUST COATING	150.00		80	150.00
			TO DO WHEEL ALIGNMENT	60.00		/	60.00
			TO SPRAY PAINTING ON RR DOOR (LH), FRT DOOR (LH), RR FENDER (LH)	0.00			0.00
			RR BUMPER, ROCKER GARNISH AND AFFECTED AREAS	1200.00		900	1,200.00
			TO REMOVE AND FIX FENDER GLASS	60.00		X	60.00
SUB-TOTAL							2,770.00

Rasul

Hp 90010068

6 days

4/5

18/08/16 @ 1635

email: rasul@lkkauto.com

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JANICE

PAGE: 2 of 2

SUB-TOTAL : S\$ 6,685.80
ADD 7% GST. S\$ 468.01
GRAND TOTAL : S\$ 7,153.81