

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5514K - AXA*Not Authorized
11 Sep 8 1900h***Candy***Done*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 5514K - Candy

JTDGJ20W405002462

TOYOTA

WISH 2.0 BI-FUEL

29.04.16

AXA

		PART		LIST
1	1	Rear Bumper	\$	<i>Per</i> 585.36 ✓
2	1	Rear Bumper Side Retainer RH	\$	<i>Per</i> 68.76 X
3	1	Rear Bumper Side Support RH	\$	<i>Per</i> 104.76 X
4	1	Rear Bumper Reflectors RH	\$	<i>Per</i> 66.00 X
5	1	Rear Bumper Side Retainer LH	\$	<i>Per</i> 68.76 X
6	1	Rear Bumper Side Support LH	\$	<i>Per</i> 104.76 X
7	1	Rear Bumper Reflectors LH	\$	<i>Per</i> 66.00 X
8	1	Rear End Panel Outer	\$	<i>Per</i> 623.76 ✓
9	1	Rear End Panel Inner Trim	\$	<i>Per</i> 263.84 X
10	1	Tailgate lid	\$	<i>R</i> 1,480.44 X
11	1	Tailgate lid lock - top	\$	<i>R</i> 466.56 X
12	1	Tailgate lid inner trim board	\$	<i>Per</i> 189.94 X
13	1	Tailgate lid inner garnish top	\$	<i>Per</i> 245.52 X
14	1	Tailgate lid outer chrome garnish	\$	<i>Per</i> 214.48 X
15	1	Tailgate lid centre 'TOYOTA' logo badge	\$	<i>Per</i> 66.82 ✓
16	1	Tailgate lid weatherstrip	\$	<i>Per</i> 344.28 X
17	1	Tailgate lid switcher opener	\$	<i>Per</i> 115.20 X
18	1	Tailgate reflector RH	\$	<i>Per</i> 128.40 X
19	1	Tailgate reflector LH	\$	<i>Per</i> 128.40 X
20	1	Tail lamp RH	\$	<i>Per</i> 595.72 X
21	1	Tail lamp LH	\$	<i>Per</i> 595.72 X

TOTAL	\$	6,523.48
25%	\$	1,630.87
	\$	4,892.61

Special Nett

1	1 Set	Rear Bumper Parking Sensor	\$	<i>Per</i> 300.00 X
2	1 Set	Rear Bumper Fastener Clip	\$	<i>Per</i> 30.00 ✓
3	1 Set	Rear end panel inner trim clip	\$	<i>Per</i> 36.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5514K - AXA**Candy**

4	1	CNG Sticker	\$	15.00 ✓
5	2	Rear Windscreen Sealant	\$	80.00 40 X
6	1	Rear Windscreen Inner Sponge Seal	\$	60.00 X
7	1	Tailgate Lid Inner handle	\$	20.96 X
8	1	Rear windscreen weatherstrip seal	\$	82.51 X
9	1	Tailgate Sticker "TRANS-CAB"	\$	30.00 —
10	1	Tailgate Sticker "TRANS-LINK"	\$	30.00 —
11	1	Tailgate Sticker "6555-3333"	\$	30.00 —

TOTAL	\$	714.47
TOTAL PARTS	\$	5,607.08

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 600

To Rust-Proofing Of The Affected Areas.

\$ 170.00 300

To Check Electrical Lighting Concerned.

\$ 120.00 200

Putty And Spray Painting Of The Affected
Portion.

\$ 2,700.00 600

To Remove And Refit Rear W/Screen Glass And
To Facilitate Bodywork Repair.

\$ 380.00 X

To Transfer Of Tailgate Fittings, Attachments
And Perform Water Seepage Test.

\$ 170.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 500

TOTAL	\$	6,510.00
	\$	12,117.08

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

REPAIR DAYS

10 DAYS
4 days

Acknowledged by Repairer

Signature:

Date: