




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG16009074/Ahg3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-05-2016	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKX 8789Z	Veh. Inspected	SKF 3645H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/05/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/05/2016	Inspection Date	17/05/2016
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

BETTY ONG BEE SENG
BLK 127 BISHAN ST 12 #08-135
SINGAPORE 570127

TP A19

Vic.

Contact : 96461891, 96461890

ESTIMATE

Repair Code : CLM13532

Date in : 16/05/2016

Vehicle Num. : SKF3645H

Model : VOLKSWAGEN SCIROCCO 1.4L AT TSI 1372Q5

Chassis/Eng# : WVVZZZ13ZCV031791/CAV400192

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehnd.</i>	1	1116.70	1,116.70 ✓
REAR BUMPER NUMBER PLATE LAMP L/R <i>He m</i>	2	37.70	75.40 ✓
REAR BUMPER REINFORCEMENT <i>Best</i>	1	577.13	577.13 ✓
REAR BUMPER SIDE GARNISH L/R <i>He m</i>	2	40.99	81.98 ✓
REAR BUMPER SIDE RETAINER L/R <i>He m</i>	2	50.17	100.34 ✓
REAR BUMPER TOP BEAM <i>Canhd</i>	1	200.31	200.31 ✓
REAR BUMPER TOW HOOK COVER <i>He m</i>	1	40.97	40.97 ✓
REAR END PANEL <i>Rys</i>	1	970.75	970.75 ✓
REAR END PANEL INNER TOP GARNISH <i>He m</i>	1	200.33	200.33 ✓
REAR END PANEL INNER TOP GARNISH CLIPS <i>He m</i>	4	6.50	26.00 ✓
REAR END PANEL LOCK STRIKER <i>He m</i>	1	49.97	49.97 ✓
REAR END PANEL LOCK STRIKER COVER <i>He m</i>	1	20.30	20.30 ✓
REAR EXHAUST ALUMINIUM HEAT SHIELD <i>He m</i>	1	211.97	211.97 ✓
REAR EXHAUST GASKET <i>He m</i>	1	27.77	27.77 ✓
REAR EXHAUST RUBBER MOUNTING <i>He m</i>	4	39.75	159.00 ✓
REAR EXHAUST SILENCER BOX <i>He m</i>	1	970.73	970.73 ✓
REAR TAILGATE 'LOGO' EMBLEM <i>He m</i>	1	90.77	90.77 ✓
REAR TAILGATE 'SCIROCCO' EMBLEM <i>He m</i>	1	80.99	80.99 ✓



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

BETTY ONG BEE SENG
BLK 127 BISHAN ST 12 #08-135
SINGAPORE 570127

Contact : 96461891, 96461890

ESTIMATE

Repair Code : CLM13532

Date in : 16/05/2016

Vehicle Num. : SKF3645H

Model : VOLKSWAGEN SCIROCCO 1.4L AT TSI 1372Q5

Chassis/Eng# : WVWZZZ13ZCV031791/CAV400192

REAR TAILGATE 'TSI' EMBLEM <i>not here</i>	1	80.99	80.99	X
REAR TAILGATE MECHANISM LOCK	1	200.93	200.93	X
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>2</i>	2	20.77	41.54	X
REAR TAILGATE WEATHER STRIP	1	290.40	290.40	X
REAR TAILLAMP CLIPS L/R <i>per</i>	2	6.50	13.00	✓
REAR TAILLAMP INNER PANEL L/R <i>near</i>	2	211.70	423.40	✓
REAR TAILLAMP L/R <i>L.H. can't do</i>	2	347.70	695.40	✓
Subtotal before discount			6,747.07	
Percentage discount 0%			0.00	
Sub-total 1			6,747.07	
REAR BUMPER CLIPS - SET <i>per</i>	1	30.00	30.00	✓
REAR BUMPER NUMBER PLATE <i>sent</i>	1	25.00	25.00	✓
REAR BUMPER NUMBER PLATE HOLDER <i>del</i>	1	50.00	50.00	✓
REAR BUMPER REVERSE SENSOR - SET <i>used</i>	1	350.00	350.00	✓
Subtotal before discount			455.00	
Percentage discount 0%			0.00	
Sub-total 2			455.00	
Parts-total			7,202.07	

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

BETTY ONG BEE SENG

BLK 127 BISHAN ST 12 #08-135

SINGAPORE 570127

Contact : 96461891, 96461890

ESTIMATE

Repair Code : CLM13532

Date in : 16/05/2016

Vehicle Num. : SKF3645H

Model : VOLKSWAGEN SCIROCCO 1.4L AT TSI 1372Q5

Chassis/Eng# : WVVZZZ13ZCV031791/CAV400192

LABOUR

To reset system after repair works

500.00 ~~+~~

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

180.00 ~~100~~

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00 ~~40~~

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1,500.00 ~~400~~

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

970

160.00 ~~X~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,500.00 ~~400~~

To apply anti-rust chemical on repaired and replaced panel.

120.00 ~~30~~

Labour Total

4,100.00

Parts & Labour Total

11,302.07

LKK Auto Consultants hereby notify the Repairer of the following:

• To resurvey before and after spray painting

• To display damaged parts for resurvey *** This is a computer-generated document which requires no signature.***

• Parts prices are subject to confirmation

page 3

• Third party survey is on a "Without Prejudice" basis

• No final modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

total: 3572.46

03 days

Acknowledged by Repairer

Signature:

Date:

L/S: 2850

2850



Logout

- Pre repair inspection request - SKF3645H VS SKX8789Z(OI) DOA 14/05/2016

From: MingYao.Lee@aig.com
To: assignments@lkkauto.com, admin-ag@lkkauto.com
Cc: Kristelli.Lopez@chartisinsurance.com, Andy-SY.Fong@aig.com, Lily.Tan@aig.com, KahYin.Leong@aig.com, Kunaseelan.Deivaseelan@aig.com, Bernard.JiQian.Ler@aig.com, 1
Sent: Monday, 16 May, 2016 5:38:59 PM
Attachments: 16052016170754.pdf 16052016120650-0001.pdf

Hi,

Please refer to the enclosed request from **N-51 AUTOMOTIVE PTE LTD.**Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know
Kindly assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Best Regards,
Lee Ming Yao @ George
AIG
Express Claims Adjuster II
Claims Operations | AIG Shared Services

Level 7, Mahara Worldwilde, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia.

MingYao.Lee@aig.com / www.AIG.com

16.05.2016 @ 5:54pm

Mr Neo ven in

Adrian

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **SKF 3645 H**
Your ref: **SKX 8789 Z**

16 May 2016

AIG ASIA PACIFIC INSURANCE PTE. LTD.
NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

BY FAX 6835-7416 & EMAIL :
MingYao.Lee@AIG.com

Dear Sir/Madam,

NAME OF CLAIMANT : ONG BEE SENG, BETTY
VEHICLE NUMBER : SKF 3645 H
YOUR INSURED VEHICLE NUMBER : SKX 8789 Z
ACCIDENT ON 14 May 2016 ALONG BISHAN ST 13 JUST INFRONT OF BISHAN
BUS INTERCHARGE AT ABOUT 14:30 HOURS

We refer to your email dated 16 May 2016 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **ADRIAN LING of LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921
8482 0051 (Mr. Winson Ng)
9857 5300 (Mr. Neo)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....
N-51 AUTOMOTIVE PTE LTD

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

Print Received Message

This mail is associated with :

*SKF3645H (9835656351SG)
[SKX8789Z]

TP
ONG BEE SENG BETTY
May 14 2016 12:00AM
[Tang Chee Yin]
N-51 Automotive Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/05/2016 09:55 AM.
To LKK_HQ
Subject SKF3645H vs SKX8789Z (OI Detailed)

Hi

Kindly be adviced OI not yet reporting

Please find OI detailed for your perusal

Tang Chee Yin

170 Bishan St 13 No. #06-65 Singapore 570170

96617997

Regards

Mohd Fitri Bin Hassim
AIG

Express Claims Adjuster II
FNOL-Singapore Windscreen | AIG Shared Services

Level 14, Menara Worldwide, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel 80012065561 ext: 1012117

MohdFitri.Hassim@aig.com | www.aig.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG16009074/Ahg3

18th May 2016

Tang Chee Yin

170 Bishan St 13 No. #06-65
Singapore 570170

Dear Sirs,

**ACCIDENT INVOLVING SKX 8789Z AND SKF 3645H ON 14.05.2016 ALONG
BISHAN STREET 13 JUNCTION INFRONT OF BISHAN BUS INTERCHANGE**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan

Claims

Tel : 6841 2096

Fax: 6741 4108

Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2016 12:41
Date Of Accident	14/05/2016 16:00 ✓
Exact Location Of Accident	T-Junction of Bishan St 13 & Bishan Place ✓
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX8789Z
Insured/Policyholder	
Name Of Registered Owner	TANG CHEE YIN
NRIC No	S2512526F
Email Address	tepg.grace@gmail.com
Mobile Phone No	(LOCAL) +65-96617997
Alternative Phone No	Others-96617997

170 BISHAN ST 13
H06-65
(S) 570170

Vehicle Particulars

Manufacturer	NISSAN
Model	SLYPHY 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Reporting Only
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100444169-00000
Cover Note Number	30/012/15 - 29/12/16

Driver

Name of Driver	TANG ENPING GRACE
NRIC No	S9100092Z
Date Of Birth	05/01/1991 (25YRS)
Occupation	Indoor
Date Of Driving Pass	08/09/2009
Driving Experience	6 Years And 8 Months
Gender	Female
Mobile Number	(Local) +65-98636862
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company No

If No, Relationship of the Driver with the Insured Children

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident Collision- Head to Rear (Insured Hit TP)

Weather Conditions Raining

Road Surface Wet

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

Was there any video captured by Car Camera? No

Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

Refer to attached sketch plan.

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKF3645H ✓
Vehicle Make/Model/Colour VOLKSWAGEN SCIROCCO WHITE
Details Of Properties
Name of Driver GOH DUO YUN, SHAUN (WU DUOYUN)
NRIC/Passport Number S8222173E
Contact Number 96461890

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

PP Stopped down the vehicle and pushed the brakes but as it
was raining heavily the car skidded and scratched the
car in front.

No injuries for both parties.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Authorization Letter

I, Tany Chee Yin, S 2512526F authorize

Tany Seng Guan, S 91000922 to file a report on my

behalf.

Vic

From: Vic
Sent: Tuesday, 14 June, 2016 9:13 AM
To: sales@n51.com.sg
Cc: Admin A; Vic
Subject: Your Ref: SKF 3645H_ACCIDENT INVOLVING VEHICLES SKX 8789Z AND SKF 3645H ON 14/05/2015

Your Ref: SKF 3645H
Our Ref: CC4/AIG16009074/Ahg3

"WITHOUT PREJUDICE"

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES SKX 8789Z AND SKF 3645H ON 14/05/2015

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us (LKK) if available to proceed with the settlement.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510
Email: sales@n51.com.sg
Company Reg. No.: 200714616M
GST Registration No.: 200714616M

18-Aug-2016

Our Ref: CLM13532 / May-14 (2016)

AIG ASIA PACIFIC INSURANCE PTE LTD
NO. 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120

ATTN: MOTOR CLAIMS DEPARTMENT

Dear Sir @ Mdm,

Re: Accident involving SKF 3645 H & SKX 8789 Z on 14/05/2016.

We refer to the above accident which was caused due to the negligence of your insured driver of vehicle No: SKX 8789 Z whose vehicle was insured with you at the material date of the accident.

We are proposing for a direct settlement on the claims as following exclude personal injury in respect of claim arising out of the abovementioned accident.

Cost of Repairs	\$ 3,049.50 (Include 7% GST)
Car Rental	\$ 480.00
Towing Fee	\$ 100.00
LTA Search	\$ 5.35
	<u>S \$ 3,634.85</u>

We enclosed herein the following documents for your necessary attention.

- 1) Our Final Repair Bill No: CLM13532
- 2) Hock Chuan Heng Car Rental & Trading Pte Ltd. - Invoice No: H 14058
- 3) Autobay Towing - SKF 3645 H (receipt attached)
- 4) LTA Search Fee
- 5) Letter of Authorisation
- 6) Release Voucher (AIG Express Third Party Claim)

We look forward to your prompt reply.

Yours faithfully,



N-51 Automotive Pte Ltd
S.Y. NEO
Managing Director

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 May 2016 Edit Reg		16 May 2016 00:00 Edit Adj Rpt	S\$2,850.00 Edit Estimates	S\$2,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	Tang Chee Yin, ID: S2512526F		
Main Claimant:	ONG BEE SENG BETTY, Co. Reg. No.: S1290735D		
Vehicle Reg. No.:	SKF3645H	Date of Loss:	14/05/2016 00:00 - :59 [47 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9835656351SG	Policy/Cover Note No.:	2100444169
Vehicle Reg. No. (Insured):	SKX8789Z	Policy No. (Claimant):	Z/15/VP00/093174
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Sivaguru Raja, Jeevan Raj] jeevansivagum@aig.com		
Claimant's Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/05/2016]		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (18/05/2016): Request to Upload TP GIA Report AIG_SG (18/05/2016): SKF3645H vs SKX8789Z (OI Detailed) 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKF3645H (9835656351SG)**
[SKX8789Z]

TP















































ONG BEE SENG BETTY

May 14 2016 12:00AM

[Tang Chee Yin]

N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	08/06/16 12:37		Accident Statement From:SC - Reg. No: SKX8789Z, Claimant: TANG CHEE YIN															Load HTM		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	18/05/16 14:34		Odometer Reading															Load JPG		
2	18/05/16 14:34		Chassis Number															Load JPG		
3	18/05/16 14:35		General View															Load JPG		
4	18/05/16 14:35		General View															Load JPG		
5	18/05/16 14:35		General View															Load JPG		
6	18/05/16 14:35		General View															Load JPG		
7	18/05/16 14:35		General View															Load JPG		
8	18/05/16 14:35		General View															Load JPG		
9	18/05/16 14:35		General View															Load JPG		
10	18/05/16 14:35		General View															Load JPG		
11	18/05/16 14:35		General View															Load JPG		
12	18/05/16 14:35		General View															Load JPG		
13	18/05/16 14:35		General View															Load JPG		
14	18/05/16 14:35		General View															Load JPG		
15	18/05/16 14:35		General View															Load JPG		
16	18/05/16 14:35		General View															Load JPG		
17	18/05/16 14:35		General View															Load JPG		
18	18/05/16 14:35		General View															Load JPG		
19	18/05/16 14:35		General View															Load JPG		
20	18/05/16 14:35		General View															Load JPG		
21	18/05/16 14:35		General View															Load JPG		
22	18/05/16 14:35		General View															Load JPG		
23	18/05/16 14:35		General View															Load JPG		
24	18/05/16 14:35		General View															Load JPG		
25	18/05/16 14:35		General View															Load JPG		
26	18/05/16 14:35		General View															Load JPG		
27	18/05/16 14:35		General View															Load JPG		
28	18/05/16 14:35		General View															Load JPG		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	18/05/16 14:35	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/05/16 14:35	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/05/16 14:35	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/05/16 14:35	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/05/16 14:35	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/05/16 14:35	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/19 10:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/16 09:37	EMAIL FROM AIG DD 16052016	 Load PDF	

Letters/Correspondences			1 per page ▼	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
2	18/05/16 09:37	NOTIFICATION FROM WORKSHOP + TP GIA REPORT		Load PDF
3	18/05/16 09:37	NOTIFICATION FROM WORKSHOP		Load PDF
4	19/05/16 09:23	NON REPORTING LETTER		Load PDF
5	19/05/16 17:36	TP GIA REPORT		Load PDF
6	13/06/16 16:57	LETTER TO OI		Load PDF
7	15/04/19 17:48	TP ESTIMATE - MARKED		Load PDF
8	23/05/19 09:42	AUTHORISATION TO ACT		Load PDF
9	23/05/19 09:42	LTA SEARCH		Load PDF
10	23/05/19 09:42	RELEASE VOUCHER		Load PDF
11	23/05/19 09:42	RENTAL RECEIPT		Load PDF
12	23/05/19 09:42	TOWING FEE		Load PDF
13	23/05/19 09:42	WORKSHOP INVOICE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKX8789Z (Insd veh)	Model:	VOLKSWAGEN SCIROCCO 1.4
	SKF3645H (TP veh)		TSI (A)
Date of Accident:	14/05/2016		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		12,093.21
Final Repair Cost	:	\$		3,500.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		4 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		3,500.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> [] YES <input checked="" type="checkbox"/> [X] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	N-51 Automotive Pte Ltd	:	\$	3,500.00
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

23 May
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG16009074/AHB3S2

Date: 23/05/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100444169
Claimant Vehicle No :	SKF3645H	Insured Vehicle No :	SKX8789Z
Date of Loss:	14/05/2016	Nature of Claim:	TP
		Claim No:	9835656351SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF3645H	Engine No:	CAV400192
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13ZCV031791
Reg. Date:	24/05/2012 (Man. Year: 2012)	Odometer:	69528 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40R18	Rear Tyre Size:	235/40R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,202.07	2,542.42	4,659.65	64.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	970.00	3,130.00	76.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,302.07	3,512.42	7,789.65	68.92
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	11,302.07	2,850.00	8,452.07	74.78
+ GST 7.00/7.00% (S\$)	791.14	199.50	591.64	74.78
Nett Amount (S\$)	12,093.21	3,049.50	9,043.71	74.78
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		5.35		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		3,554.85		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment: 16/05/2016

Date Inspected: 17/05/2016 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,116.70 F	*1,116.70 FL
2	2		*REAR BUMPER NUMBER PLATE LAMP L/R	Not Necessary	75.40 F	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	577.13 F	*577.13 FL
4	2		*REAR BUMPER SIDE GARNISH L/R	Not Necessary	81.98 F	*- FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	100.34 F	*100.34 FL
6	1		*REAR BUMPER TOP BEAM	Cracked	200.31 F	*200.31 FL
7	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	40.97 F	*- FL
8	1		*REAR END PANEL	Repair	970.75 F	*- FL
9	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	200.33 F	*- FL
10	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	26.00 F	*- FL
11	1		*REAR END PANEL LOCK STRIKER	Not Necessary	49.97 F	*- FL
12	1		*REAR END PANEL LOCK STRIKER COVER	Not Necessary	20.30 F	*- FL
13	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Not Necessary	211.97 F	*- FL
14	1		*REAR EXHAUST GASKET	Not Necessary	27.77 F	*- FL
15	4		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	159.00 F	*- FL
16	1		*REAR EXHAUST SILENCER BOX	Not Necessary	970.73 F	*- FL
17	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	90.77 F	*- FL
18	1		*REAR TAILGATE SCIROCCO EMBLEM	Not Necessary	80.99 F	*- FL
19	1		*REAR TAILGATE TSI EMBLEM	Not Necessary	80.99 F	*- FL
20	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	200.93 F	*- FL
21	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	41.54 F	*- FL
22	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	290.40 F	*- FL
23	2		*REAR TAILLAMP CLIPS L/R	Necessary	13.00 F	*13.00 FL
24	2		*REAR TAILLAMP INNER PANEL L/R	Not Necessary	423.40 F	*- FL
25	1		*REAR TAILLAMP L/R	N/s Cracked	695.40 F	*347.70 FL
26	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
27	1		*REAR BUMPER NUMBER PLATE	Bent	25.00 FS	*25.00 FS
28	1		*REAR BUMPER NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,202.07	2,660.18
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	117.76
Total Parts (\$\$)	7,202.07	2,542.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS.	New	500.00	0.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	180.00	100.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	140.00	40.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.	New	1,500.00	400.00
5	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	New	160.00	0.00
6	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,500.00	400.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	120.00	30.00
Gross Labour Cost (S\$)			4,100.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >