

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ASOKARAJAN S/O ANAMALAI
BLK 225 BUKIT BATOK CENTRAL #09-73
SINGAPORE 650225

Contact : 81807635

TP ALG.
Thin Thin
Xiao Tony

ESTIMATE

Repair Code : CLM13298

Date in : 18/05/2016

Vehicle Num. : SKR5263A

Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Chassis/Eng# : KMHDH41CMFU432929/G4FGFU178809

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>selid</i>	1	459.00	459.00 ✓
REAR BUMPER LOWER DIFFUSER <i>new</i>	1	250.00	250.00 ✓
REAR BUMPER REFLECTOR L/R <i>new</i>	2	35.00	70.00 ✓
REAR BUMPER RH INNER SHIELD 'VERTICAL' <i>3 new</i>	1	57.00	57.00 ✓
REAR BUMPER RH INNER SHIELD 'VERTICAL' CLIPS <i>3 new</i>	3	6.50	19.50 ✓
REAR BUMPER RH INNER SIDE SHIELD <i>torn</i>	1	55.00	55.00 ✓
REAR BUMPER RH INNER SIDE SHIELD CLIPS <i>new</i>	8	6.50	52.00 ✓
REAR BUMPER RH MUDFLAP <i>new</i>	1	24.00	24.00 ✓
REAR BUMPER SIDE RETAINER L/R <i>RH new</i>	2	26.00	52.00 ✓
REAR RH FENDER <i>Distorted</i>	1	1768.00	1,768.00 ✓
REAR RH FENDER INNER AIR VENT <i>cracked</i>	1	32.00	32.00 ✓
REAR RH FENDER INNER PANEL <i>Repis</i>	1	1406.00	1,406.00 ✓
REAR RH FENDER INNER SHIELD <i>new</i>	1	57.00	57.00 ✓
REAR RH FENDER INNER UPHOLSTERY TRIM <i>new</i>	1	167.00	167.00 ✓
REAR RH FENDER QUARTER GARNISH <i>3 new</i>	1	79.00	79.00 ✓
REAR RH FENDER QUARTER GARNISH CLIPS <i>3 new</i>	2	6.50	13.00 ✓
REAR RH TAILLAMP <i>cracked</i>	1	362.00	362.00 ✓
REAR RH TAILLAMP CLIPS <i>new</i>	2	6.50	13.00 ✓

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASOKARAJAN S/O ANAMALAI

BLK 225 BUKIT BATOK CENTRAL #09-73

SINGAPORE 650225

Contact : 81807635

ESTIMATE

Repair Code : CLM13298

Date in : 18/05/2016

Vehicle Num. : SKR5263A

Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Chassis/Eng# : KMHDH41CMFU432929/G4FGFU178809

REAR RH TAILLAMP INNER PANEL	1	171.00	171.00 ✓
REAR RH WHEEL 16" SPORT RIM CAP	1	114.00	114.00 ✓
REAR SUSPENSION AXLE	1	1188.00	1,188.00 ✓
REAR SUSPENSION RH COIL SPRING	1	216.00	216.00 ✓
REAR SUSPENSION RH SHOCK ABSORBER	1	239.00	239.00 ✓
REAR SUSPENSION RH WHEEL BEARING	1	352.00	352.00 ✓
REAR WHEEL RH 16" SPORT RIM 'ORIGINAL'	1	891.00	891.00 ✓
REAR WINDSCREEN MOULDING	1	128	128 ✓
Subtotal before discount			8,148.50
Percentage discount 20%			1,629.70
Sub-total 1			6,518.80
REAR BUMPER CLIPS - SET	1	30.00	30.00 ✓
REAR RH FENDER INNER SHIELD CLIPS - SET	1	30.00	30.00 ✓
REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET	1	30.00	30.00 ✓
REAR WHEEL RH 205/55R16 91H TYRE	1	480.00	480.00 ✓
REAR WINDSCREEN SEALANT	1	100.00	100.00 ✓

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

ASOKARAJAN S/O ANAMALAI

BLK 225 BUKIT BATOK CENTRAL #09-73

SINGAPORE 650225

Contact : 81807635

ESTIMATE

Repair Code : CLM13298

Date in : 18/05/2016

Vehicle Num. : SKR5263A

Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Chassis/Eng# : KMHDH41CMFU432929/G4FGFU178809

Subtotal before discount	670.00
Percentage discount 0%	0.00
Sub-total 2	670.00
Parts-total	7,188.80

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove and refit rear windscreen(to FR)

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total 3,540.00

Parts & Labour Total 10,728.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 3

Total: 5624.8
H/s: A.Sic
06 Pump.

A.Sic

06hys