

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9781D - CHINA**Candy**

Not Authorised
1.3.1
85715.43
Resurvey By point

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9781D - CANDY

VF1ABL15AUC282201

RENAULT

LATITUDE

17.05.2016

CHINA

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>852.66</i> ✓
2	1	BUMPER LOWER REAR	\$	<i>591.41</i> X
3	1	BUMPER BRACKET CTR REAR	\$	<i>87.29</i> X
4	1	BUMEP R BRACKET SIDE RH REAR(Taillamp lower)	\$	<i>104.59</i> ✓
5	1	BUMEP R RETAINER RH REAR	\$	<i>34.61</i> ✓
6	1	BUMPER REFLECTOR RH	\$	<i>33.55</i> ✓
7	1	FENDER PANEL REAR RH	\$	<i>2,537.80</i> ✓
8	1	FENDER WHEELARCH REAR RH(Linner)	\$	<i>418.06</i> X
9	1	AIR VENT	\$	<i>74.83</i> X
10	1	TAILLAMP RH	\$	<i>425.04</i> ✓
11	1	KUCKLE ARM REAR RH	\$	<i>566.67</i> X
12	1	AXLE SPRING ARM RH	\$	<i>289.94</i> X
13	1	LOWER ARM REAR RH	\$	<i>696.91</i> X
14	1	LOWER ARM BALANCER REAR RH	\$	<i>26.26</i> X
15	1	ABSORBER REAR RH	\$	<i>299.81</i> X
16	1	STABILIZER BAR REAR	\$	<i>465.12</i> X
17	1	ROCKER PANEL OUTER RH	\$	<i>759.61</i> X
18	1	DOOR PANEL REAR RH	\$	<i>2,188.20</i> X

TOTAL	\$	10,452.35
10%	\$	1,045.24
	\$	9,407.12

Specical Nett

1	1SET	PARKING AID	\$	<i>600.00</i> X
2	1SET	REAR BUMPER CLIP	\$	<i>66.00</i> ✓
3	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	<i>10.00</i> X
4	1SET	BUMEP R RETAINER RH CLIP RR	\$	<i>20.00</i> X
5	1SET	BUMPER LOWER REAR CLIP	\$	<i>66.00</i> X
6	1SET	WHEELARCH CLIP REAR RH	\$	<i>45.00</i> X
7	2	Rear Windscreen Sealant	\$	<i>80.00</i> 40SA ✓
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>150.00</i> 30SA ✓
9	1	RIM (ROUE 7J 16H 2547)RH RR (Spare change)	\$	<i>385.00</i> X
10	1	TYRE RH RR (Spare change)	\$	<i>330.00</i> X

TRANS-CAB AUTO SERVICES PTE LTD

Candy

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 9781D - CHINA

11	1	CAP HUB RH REAR	\$	<i>in</i> 35.60 <i>X</i>
12	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 <i>X</i>

TOTAL	\$	1,867.60
TOTAL PARTS	\$	11,274.72

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>800</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 <i>800</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>300</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 <i>1000</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 <i>1200</i>

TOTAL	\$	7,080.00
Over All Total	\$	18,354.72

Repair Days**10 Days**
(PARTS BY PARTS)