

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5441Y
 Ref. No : TAX/05/16/2140
 Reg. Date : 22/11/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TAN KAH HUAT
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 17/05/2016 07:30:00 PM
 Accident Reported Date / Time : 18/05/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024081955
 Special Instruction to ARC,if any :
 DROVE IN / SFW708Y
 Prepared Date : 18/05/2016 12:24:24 PM



Alvin Rajapala
Lin Angchen Rajapala

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB134594

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 1,314.00	0.00
Total Material Charges	: 3,439.84	5,044.39
Other Charges	: 820.00	0.00
TOTAL	: 6,756.84	0.00
Lum Sum Total	: 6,750.00	0.00
No. of Repair Days	: 7.00	0.00 <i>4.00</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 18/05/2016 04:42:25 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/05/2016 04:42:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,183.00	0.00
Total Labour	1,183.00	0.00 600

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
TO RESRAY REAR DOOR LH	378.00	0.00
TO RESPRAY RIM	180.00	0.00
Total Spray Painting & Panel Beating	1,314.00	0.00 650

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 20
TO APPLY RUST-PROOFING ON AFFECTED AREA	150.00	0.00 40
TO REMOVE / REFIT WINDSCREEN	120.00	0.00 100
TO REMOVE / REFIT SEAT	200.00	0.00 50
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 140
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 20
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
Total Other Costs	930.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
			BUMPER REAR FASCIA	1	1,004.00	10.00	903.60	Replace	Replace ✓	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace X	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace X	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace X	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace X	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ✓	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace ✓	No
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace X	No
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace ✓	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No
96633557	REAR	6504575	LINER LH REAR FENDER (PROTECTOR)	1	201.00	10.00	180.90	Replace	Replace X	No
	COMMON	6504666	TYRE RIM	1	328.99	0.00	328.99	Repair	Replace X	No repair
96635655	DOOR	6504603	PANEL LH REAR DOOR	1	1,863.00	10.00	1,676.70	Repair	Replace X	No repair
	COMMON		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓	No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace X	No X
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace ✓	No
TOTAL MATERIALS								4,299.80	6,305.49	
TOTAL MATERIALS(Discounted)								3,439.84	5,044.39	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Kalvin K. King
U 12/15/16
 10,456.72