

INS. CASE OWNER:

CC4 / AXA1600 9377

LKK:

IDAC:

Surveyor:

Tan Hui

DOI:

20/08/16

Date / Time:

20/08/16

Registered in Merimen:

20/08/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

YNS161R

Name of Insured:

DECOCEL PLASTER P/L

Insured Tel No.:

HP:

Excess Sec II : SS

D.O.A.:

18.08.16

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

FOYSA MOHAMMAD

Driver Tel No.:

98748672

(V/L: YES / NO)

Claim No.:

C0384414

Policy No.:

P1487242

Make / Model:

M.T. CANTER

Place of Accident:

BRICKLAND RD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

6BB 4963K



INSRS:

WSP: Woon Meng

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
20/08/16	Non-Reporting ltr (1st):	
20/08/16	Non-Reporting ltr (2nd):	
20/08/16	Non-Reporting ltr (Final):	
04/08/16 @ 11:45AM	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
11/08/16	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR: AGAINST OUI	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: H9	SS \$10,300.00	Confirm with: 10 days
Reduction: 10	days	Reduction: 10 %
FINAL SETTLEMENT	Date/Time: 27/08/16	Confirm with: H9 HONG
Final Liability: %	100 (Agreed / Assessed)	BOLA S/N No.:
Repair Cost: (w/ass)	SS \$11,021.00	(CONFLICTING VERSION)
Loss of Rental (LOR):	SS \$960.00	x 12 days
Loss of Use (LOU):	SS \$960.00	x 12 days
Loss of Income (LOI):	SS \$	x days
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	SS \$2.00	
Medical:	SS	
Disbursement:	SS	(e.g. Tow/ Independent)
Legal Cost	SS	
Total:	SS \$11,983.00	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS \$11,983.00	Name 1: WOON MENG MOTOR PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

Surveyor: Taufik

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 418,800.00

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 9684963K Yr Regn: 2009, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c. 2982Colour: S/ma A/C: Insured / Std / NI / NASp. Reading: 275805 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5TFA135480K 2008B3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/R15R: 135/R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Max truck

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5/5 mmL/Bal. 5 mm L/Bal. 5/5 mmD.O.A. _____ D.O.I. 20/5/16 @ 1730Survey held at Woon Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fr t n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>1/5 will pass estimate later.</u>
	<u>45 @ 10,300, 10 days.</u>
	<u>(CRAB: \$10,164.22 / 49%)</u>
	<u>LIV: \$18,800.00 (Cost)</u>
	<u>GIA: \$ 278.00 (Cost)</u>
	<u>Note: \$ 18,972.00 (Cost)</u>

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16009377/T1ha3		
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 20-05-2016		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 5161R	Veh. Inspected	GBB 4963K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/05/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/05/2016	Inspection Date		
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

BI Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 May 2016		20 May 2016 14:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	DECOCEIL PLASTER PTE LTD, NRIC: 198701473Z, Tel: +6596746086, Email: decocellpl@gmail.com		
Main Claimant:	QUEK & TAN BUILDING CONSTRUCTION PTE LTD, NRIC: 199304548K		
Vehicle Reg. No.:	GBB4963K	Date of Loss:	18/05/2016 16:00 - :59
Claim Type:	TP / C0384414	Policy/Cover Note No.:	P1487242 (Comprehensive)
Vehicle Reg. No. (Insured):	YN5161R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131		
Handling Insurer:	AXA Insurance Singapore Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/05/2016]		
Driver/Custodian (Insured):	FOYSAL MOHAMAD (), NRIC: G8206290X, Tel: +6598748672		
Adj Asg. Remarks:	XS NIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (20/05/2016): New TP Assignment - C0384414/P1487242

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

20/5/2016 @ 2:20pm
ms heng
vehicle in
Tanjong

Ref NO: CC4/AXA16009377/T1m3.

email taufik on
7/9/16

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

TP claims

Estimate

TP Claim

To : AXA Insurance Singapore Pte Ltd
Motor Claims Dept

Date : 20 May 2016

Dear Sirs :

Fax : 68804838

RE : ESTIMATE COST FOR TOYOTA DYNA 150 - GBB4963K
ACCIDENT INVOLVING GBB4963K & YN5161R ON 18.05.2016

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front windscreen glass.	1pc	\$ 1,484.20 <i>na</i>
2	Front windscreen rubber.	1pc	\$ 305.00 <i>na</i>
3	Front upper panel.	1pc	\$ 275.00 <i>bt</i>
4	Front upper panel moulding.	1pc	\$ 275.00 <i>de</i>
5	Front upper panel lower garnish.	1pc	\$ 275.00 <i>de</i>
6	Front wiper side garnish @\$131ea.	2pcs	\$ 131 262.00 <i>LH-de, RH-xm</i>
7	Front upper side panel lower garnish @130ea.	2pcs	\$ 130 260.00 <i>LH-de, RH-xm</i>
8	Nozzle.	1pc	\$ 47.00 <i>xm</i>
9	Front wiper arm @\$122.3ea.	2pcs	\$ 122.33 244.60 <i>LH-bt, RH-xm</i>
10	Front wiper arm cover @\$11.8ea.	2pcs	\$ 11.80 23.60 <i>LH-cut, RH-xm</i>
11	Front wiper link @\$345ea.	2pcs	\$ 690.00 <i>xm</i>
12	Front wiper blade @\$85ea.	2pcs	\$ 85 170.00 <i>LH-cut, RH-xm</i>
13	Front wiper motor.	1pc	\$ 715.00 <i>xm</i>
14	Front corner panel n/s.	1pc	\$ 285.00 <i>bt</i>
15	Front panel.	1pc	\$ 1,100.00 <i>bt</i>
16	Dyna.	1pc	\$ 145.00 <i>na</i>
17	Front center grille.	1pc	\$ 510.00 <i>cut</i>
Sum Carried Forward			\$ 7,066.40

Sum Carried Forward

\$ 7,066.40

18	Front center grille moulding.	1pc	\$	31.55	wt ✓
19	Emblem.	1pc	\$	165.00	nee ✓
20	Front headlamp n/s.	1pc	\$	725.00	coe ✓
21	Front headlamp lower seal.	1pc	\$	30.00	nh ✓
22	Front bumper.	1pc	\$	475.00	bt ✓
23	Front bumper bracket @\$155ea.	2pcs	\$	310.00	175 LH-bt RH-Xon
24	Front bumper reinforcement.	1pc	\$	219.00	X n ✓
25	Front side mirror stay n/s.	1pc	\$	450.00	bt ✓
26	Front door n/s.	1pc	\$	1,600.00	bt ✓
27	Front door hinge @\$85.5ea.	2pcs	\$	171.00	bt ✓
28	Front door chek n/s.	1pc	\$	125.00	bt ✓
29	Front power window motor n/s.	1pc	\$	580.00	X n ✓
30	Front door regulator n/s.	1pc	\$	321.00	bt ✓
31	Front door outer moulding n/s.	1pc	\$	155.00	de ✓
32	D4D.	1pc	\$	165.00	ne ✓
33	Logo.	1pc	\$	165.00	ne ✓
34	Front door inner trim n/s.	1pc	\$	565.00	de ✓
35	Front door rubber n/s.	1pc	\$	195.00	ne ✓
36	Front door pillar inner protector n/s.	1pc	\$	211.00	X } X
37	Front door step garnish n/s.	1pc	\$	300.00	X } X
38	Spare tank.	1pc	\$	180.00	X } X
39	Wiper tank.	1pc	\$	170.00	X } X
40	Front wheel panel n/s.	1pc	\$	410.00	R n ✓
41	Front wheel panel outer moulding n/s.	1pc	\$	85.00	X n ✓
42	Front dashboard.	1pc	\$	950.00	de ✓
43	Air con heater.	1pc	\$	1,100.00	coe ✓
44	Air con blower.	1pc	\$	880.00	coe ✓
45	Suction hose.	1pc	\$	230.00	X } X
46	Discharge hose.	1pc	\$	250.00	X } X
47	Front radiator.	1pc	\$	2,415.00	X } X
48	Front pillar n/s.	1pc	\$	388.10	R n ✓
49	Front inner pillar n/s.	1pc	\$	375.91	R n ✓
				\$	21,458.96
				\$	(5,364.74)
				\$	16,094.22
					13,530.85
					10148.14

Sum Carried Forward

Less 25%

Sum Carried Forward**\$ 16,094.22**

50	Front ERP bracket.	1pc	\$	15.00	121
51	Front number plate.	1pc	\$	25.00	221
52	Coolant.		\$	30.00	X 11 40

Labour Charge & Misc

Towing fee. \$ 70.00 ✓

To remove, replace & install damaged parts. } \$ 2,200.00 1200 }

To R & R front windscreen glass. \$ 120.00 ✓

To remove & install door mechansim & check for function. } \$ 180.00 60. }

To R & R front dashboard. \$ 250.00 180.

To R & R air con system. } \$ 180.00 100. }

To refill & top up air con gas.

To R & R front radiator. \$ 150.00 X 11.

To R & R wiring. \$ 150.00 40.

To putty & spray painting. \$ 1,000.00 900.

Total**\$ 20,464.22**

2670.

All prices quoted are subjected to 7% GST.

This is a computer generated document.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts pending resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12858-14

2/5/10,300

10 days

Print Sent Message

This mail is associated with :

***GBB4963K (C0384414)**

[YN5161R]

TP

QUEK & TAN BUILDING CONSTRUCTION PTE LTD

May 18 2016 4:00PM

[DECOCEIL PLASTER PTE LTD]

Woon Meng Motor Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 11/08/2016 19:35 PM.
To AXA_SG; cynthia.loh@axa.com.sg
CC vicalpeh@lkkauto.com; jaskhine@lkkauto.com; admin-a@lkkauto.com
Subject Re: Direct Settlement - Accident Involving YN5161R (OI : AXA - C0384414) and GBB4963K (TP : LKK REF - CC4/AXA16009377/T1ha3) on 18.05.2016

Dear Cynthia,

We refer to your below

Cynthia

<-- Original Message -->

From: LKK_HQ

To: cynthia.loh@axa.com.sg

CC: AXA_SG; vicalpeh@lkkauto.com; jaskhine@lkkauto.com; admin-a@lkkauto.com

Sent On: 23/05/2016 04:20 PM

Subject: Direct Settlement - Accident Involving YN5161R (OI : AXA - C0384414) and GBB4963K (TP : LKK REF - CC4/AXA16009377/T1ha3) on 18.05.2016

Dear Cynthia

We refer to the above matter.

As per instruction, we will proceed direct settlement for this case.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408065
Tel +65 65476390
Fax +65 65476250
www.police.gov.sg

Our Ref : TP/IP/26059/2016(Wayzik)
Your Ref :

Date : 4 August 2016

Chowdhury Mofij
c/o 57 Ubi Avenue 1
#05-01
Singapore 408936

Dear Sir/Mdm,

ROAD TRAFFIC ACCIDENT INVOLVING GBB 4963 K AND YN 5161 R ALONG BRICKLAND ROAD ON 18 MAY 2016 AT ABOUT 5.20 PM

I refer to the above road traffic accident

2. Investigation into the case has been completed. Please be informed that action has been taken against the driver of YN 5161 R for Inconsiderate Driving under Section 65(b) of the Road Traffic Act, Chapter 276

3. Should you need any clarification please contact the Investigation Officer Wayzik Khoo at Tel 6547 6187

Yours faithfully


PECK TIAN SENG
TEAM 1 PROCESS

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 16 August, 2016 4:20 PM
To: woonmeng2
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Police Report_Your Ref: GBB 4963K_ACCIDENT INVOLVING VEHICLES YN 5161R AND GBB 4963K ON 18/05/2016
Attachments: 201608081606.pdf

Your Ref: GBB 4963K
Our Ref: CC4/AXA16009377/T1ha3

"WITHOUT PREJUDICE"

Dear Ms Heng,

ACCIDENT INVOLVING VEHICLES YN 5161R AND GBB 4963K ON 18/05/2016

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.</

View Received Message

This mail is associated with :

***GBB4963K (C0384414)**

[YN5161R]

TP

QUEK & TAN BUILDING CONSTRUCTION PTE LTD

May 18 2016 4:00PM

[DECOCEIL PLASTER PTE LTD]

Woon Meng Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 26/06/2019 11:23 AM.



Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578
Tel: +6563161131 / +6563161151 FAX: +6563167050
Workshop 42, Sungei Kadut Ave Singapore 729666 Tel: +6563628523
Email: woonmeng@singnet.com.sg
Co Reg No 200603678M GST Reg No. 20-0603678M

AXA Insurance Singapore Pte Ltd
8 Shenton Way # 27 - 01
27- 01 AXA Tower
Singapore 068811

19 Dec 2018

Attn: Motor Claim Dept.

Dear Sirs

DIRECT SETTLEMENT FOR REPAIR OF TOYOTA DYNA 150 - GBB4963K

RE : ACCIDENT INVOLVING GBB4963K & YN5161R
ALONG BRICKLAND ROAD TOWARDS BUKIT BATOK ROAD ON 18.05.16

We have been given the full authority to act on behalf of Quek & Tan Bldg Constrn Pte Ltd, registered owner of motor vehicle no: GBB4963K, which was involved and damaged in the above accident.

...CLAIM SUBFOLDER...(Pending for Survey Report)

B1 Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 May 2016		20 May 2016 14:18 Edit Adj Rpt	S\$10,300.00 Edit Estimates	S\$10,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	DECOCEIL PLASTER PTE LTD , Co. Reg. No.: 198701473Z, Tel: +6596746086, Email: decocellpl@gmail.com		
Main Claimant:	QUEK & TAN BUILDING CONSTRUCTION PTE LTD , Co. Reg. No.: 199304548K		
Vehicle Reg. No.:	GBB4963K	Date of Loss:	18/05/2016 16:00 - :59 [84 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0384414	Policy/Cover Note No.:	P1487242 (Comprehensive)
Vehicle Reg. No. (Insured):	YN5161R	Policy No. (Claimant):	16-MB004804-R06
		Excess:	S\$0.00
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by SASHE Go Mui Sang]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 31/05/2016]		
Driver/Custodian (Insured):	FOYSAL MOHAMAD (), NRIC: G8206290X, Tel: +6598748672 Email:		
Adj Asg. Remarks:	XS NIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (26/06/2019): **Alert - Adj Mandate Approved (S\$11983.00) - GBB4963K - Claim Handler: SASHE Go M...**
- AXA_SG (26/06/2019): **Alert - Adj Mandate Maintained - GBB4963K - Claim Handler: SASHE Go Mui Sang**
- AXA_SG (29/05/2018): **Re: Direct Settlement - Accident Involving YN5161R (OI : AXA - C0384414) and GBB...**
- AXA_SG (12/08/2016): **Re: Direct Settlement - Accident Involving YN5161R (OI : AXA - C0384414) and GBB...**
- AXA_SG (13/06/2016): **Re: Direct Settlement - Accident Involving YN5161R (OI : AXA - C0384414) and GBB...**
- AXA_SG (20/05/2016): **New TP Assignment - C0384414/P1487242**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBB4963K (C0384414)

[YN5161R]

TP

QUEK & TAN BUILDING CONSTRUCTION PTE LTD

May 18 2016 4:00PM

[DECOCEIL PLASTER PTE LTD]

Woon Meng Motor Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	------	-------------------

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/05/16 16:17	Odometer Reading	1	Load JPG	☒
2	23/05/16 16:17	Chassis Number	1	Load JPG	☒
3	23/05/16 16:17	General View	1	Load JPG	☒
4	23/05/16 16:17	General View	1	Load JPG	☒
5	23/05/16 16:17	General View	1	Load JPG	☒
6	23/05/16 16:17	General View	1	Load JPG	☒
7	23/05/16 16:17	General View	1	Load JPG	☒
8	23/05/16 16:17	General View	1	Load JPG	☒
9	23/05/16 16:17	General View	1	Load JPG	☒
10	23/05/16 16:17	General View	1	Load JPG	☒
11	23/05/16 16:17	General View	1	Load JPG	☒
12	23/05/16 16:17	General View	1	Load JPG	☒
13	23/05/16 16:17	General View	1	Load JPG	☒
14	23/05/16 16:17	General View	1	Load JPG	☒
15	23/05/16 16:17	General View	1	Load JPG	☒
16	23/05/16 16:17	General View	1	Load JPG	☒
17	23/05/16 16:17	General View	1	Load JPG	☒
18	23/05/16 16:17	General View	1	Load JPG	☒
19	23/05/16 16:17	General View	1	Load JPG	☒
20	23/05/16 16:17	General View	1	Load JPG	☒
21	23/05/16 16:17	General View	1	Load JPG	☒
22	23/05/16 16:17	General View	1	Load JPG	☒
23	23/05/16 16:17	General View	1	Load JPG	☒
24	23/05/16 16:17	General View	1	Load JPG	☒
25	23/05/16 16:17	General View	1	Load JPG	☒
26	23/05/16 16:17	General View	1	Load JPG	☒
27	23/05/16 16:17	General View	1	Load JPG	☒
28	23/05/16 16:17	General View	1	Load JPG	☒
29	23/05/16 16:17	General View	1	Load JPG	☒
30	23/05/16 16:17	General View	1	Load JPG	☒
31	23/05/16 16:17	General View	1	Load JPG	☒
32	23/05/16 16:17	General View	1	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	23/05/16 16:17	General View	 Load JPG	☒
34	23/05/16 16:17	General View	 Load JPG	☒
35	23/05/16 16:17	General View	 Load JPG	☒
36	23/05/16 16:17	General View	 Load JPG	☒
37	23/05/16 16:17	General View	 Load JPG	☒
38	23/05/16 16:17	General View	 Load JPG	☒
39	23/05/16 16:17	General View	 Load JPG	☒
40	23/05/16 16:17	General View	 Load JPG	☒
41	23/05/16 16:17	General View	 Load JPG	☒
42	23/05/16 16:17	General View	 Load JPG	☒
43	23/05/16 16:17	General View	 Load JPG	☒
44	23/05/16 16:17	General View	 Load JPG	☒
45	23/05/16 16:17	General View	 Load JPG	☒
46	23/05/16 16:17	General View	 Load JPG	☒
47	23/05/16 16:17	General View	 Load JPG	☒
48	23/05/16 16:17	General View	 Load JPG	☒
49	23/05/16 16:17	General View	 Load JPG	☒
50	23/05/16 16:17	General View	 Load JPG	☒
51	23/05/16 16:17	General View	 Load JPG	☒
52	23/05/16 16:17	General View	 Load JPG	☒
53	23/05/16 16:17	General View	 Load JPG	☒
54	23/05/16 16:17	General View	 Load JPG	☒
55	23/05/16 16:17	General View	 Load JPG	☒
56	23/05/16 16:17	General View	 Load JPG	☒
57	23/05/16 16:17	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/05/16 10:46	EMAIL_ABS	 Load PDF	
2	20/05/16 10:46	GBB4963K TP GIA REORT_ABS	 Load PDF	
3	20/05/16 10:46	YN5161R INNSURED GIA REPORT_ABS	 Load PDF	
4	20/05/16 14:17	E-filed GIA report - TP	 Load PDF	
5	22/06/16 10:52	TO LKK	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/08/16 12:08	LETTER TO OI	 Load PDF	
2	11/08/16 19:33	PIR - AGAINST OI	 Load PDF	
3	26/06/19 10:50	GIA SEARCH	 Load PDF	
4	03/07/19 09:59	AUTHORISATION TO ACT	 Load PDF	
5	03/07/19 09:59	RELEASE VOUCHER	 Load PDF	
6	03/07/19 09:59	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YN5161R (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D 1KD
	GBB4963K (TP veh)		(M)
Date of Accident:	18/05/2016		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		21,898.72
Final Repair Cost	:	\$		11,021.00
Loss of Use	:	\$		960.00
Rental (if any)	:	\$		12.00 days at \$80.00 per day
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		days
	:	\$		
Final Settlement Sum	:	\$		11,983.00

Is Third Party Workshop GIA Registered?	[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)					
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____					
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)					
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Woon Meng Motor Pte Ltd	:	\$ 11,983.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

03 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16009377/T1WA3S2

Date: 03/07/2019

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1487242
Claimant Vehicle No :	GBB4963K	Insured Vehicle No :	YN5161R
Date of Loss:	18/05/2016	Nature of Claim:	TP
		Claim No:	C0384414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB4963K	Engine No:	1KD1925410
Make & Model:	TOYOTA DYNA 150, 3.0 D 1KD (M)	Chassis No:	JTFAT35Y80K200583
Reg. Date:	15/05/2009 (Man. Year: 2009)	Odometer:	275805 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	135 R12 (D)
Front Left Side:	Maxtrek 5 mm	Rear Left Side:	Maxtrek 5/5 mm
Front Right Side:	Maxtrek 5 mm	Rear Right Side:	Maxtrek 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,164.22	10,208.39	5,955.83	36.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,670.00	1,630.00	37.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,464.22	12,878.39	7,585.83	37.07
Approved Total (Overridden) (S\$)		10,300.00		
(S\$)	20,464.22	10,300.00	10,164.22	49.67
+ GST 7.00/7.00% (S\$)	1,432.50	721.00	711.50	49.67
Nett Amount (S\$)	21,896.72	11,021.00	10,875.72	49.67
+ Loss of Use (12.0 x S\$80.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,983.00		

INSPECTION

Date of Assignment:	20/05/2016	
Date Inspected:	20/05/2016	Inspected At: Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jul 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 1KD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB4963K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS (CONSISTENT)	Necessary	1,484.20 FL	*1,484.20 FL
2	1		*FRONT WINDSCREEN RUBBER (CONSISTENT)	Necessary	305.00 FL	*305.00 FL
3	1		*FRONT UPPER PANEL (CONSISTENT)	Bent	275.00 FL	*275.00 FL
4	1		*FRONT UPPER PANEL MOULDING (CONSISTENT)	Deformed	275.00 FL	*275.00 FL
5	1		*FRONT UPPER PANEL LOWER GARNISH (CONSISTENT)	Deformed	275.00 FL	*275.00 FL
6	1		*FRONT WIPER SIDE GARNISH (CONSISTENT)	N/s Deformed/O/s Not Necessary	262.00 FL	*131.00 FL
7	1		*FRONT UPPER SIDE PANEL LOWER GARNISH (CONSISTENT)	N/s Deformed/O/s Not Necessary	260.00 FL	*130.00 FL
8	1		*NOZZLE (CONSISTENT)	Not Necessary	47.00 FL	*- FL
9	1		*FRONT WIPER ARM (CONSISTENT)	N/s Bent / O/s Not Necessary	244.60 FL	*122.30 FL
10	1		*FRONT WIPER ARM COVER (CONSISTENT)	N/s Cut / O/s Not Necessary	23.60 FL	*11.80 FL
11	2		*FRONT WIPER LINK (CONSISTENT)	Not Necessary	690.00 FL	*- FL
12	1		*FRONT WIPER BLADE (CONSISTENT)	N/s Cut / O/s Not Necessary	170.00 FL	*85.00 FL
13	1		*FRONT WIPER MOTOR (CONSISTENT)	Not Necessary	715.00 FL	*- FL
14	1		*FRONT CORNER PANEL N/S (CONSISTENT)	Bent	285.00 FL	*285.00 FL
15	1		*FRONT PANEL (CONSISTENT)	Bent	1,100.00 FL	*1,100.00 FL
16	1		*DYNA (CONSISTENT)	Necessary	145.00 FL	*145.00 FL
17	1		*FRONT CENTER GRILLE (CONSISTENT)	Cut	510.00 FL	*510.00 FL
18	1		*FRONT CENTER GRILLE MOULDING (CONSISTENT)	Cut	31.55 FL	*31.55 FL
19	1		*EMBLEM (CONSISTENT)	Necessary	165.00 FL	*165.00 FL
20	1		*FRONT HEADLAMP N/S (CONSISTENT)	Cracked	725.00 FL	*725.00 FL
21	1		*FRONT HEADLAMP LOWER SEAL (CONSISTENT)	Necessary	30.00 FL	*30.00 FL
22	1		*FRONT BUMPER (CONSISTENT)	Bent	475.00 FL	*475.00 FL
23	1		*FRONT BUMPER BRACKET (CONSISTENT)	N/s Bent / O/s Not Necessary	310.00 FL	*155.00 FL
24	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Not Necessary	219.00 FL	*- FL
25	1		*FRONT SIDE MIRROR STAY N/S (CONSISTENT)	Bent	450.00 FL	*450.00 FL
26	1		*FRONT DOOR N/S (CONSISTENT)	Bent	1,600.00 FL	*1,600.00 FL
27	2		*FRONT DOOR HINGE (CONSISTENT)	Bent	171.00 FL	*171.00 FL
28	1		*FRONT DOOR CHECK N/S (CONSISTENT)	Bent	125.00 FL	*125.00 FL
29	1		*FRONT POWER WINDOW MOTOR N/S (CONSISTENT)	Not Necessary	580.00 FL	*- FL
30	1		*FRONT DOOR REGULATOR N/S (CONSISTENT)	Bent	321.00 FL	*321.00 FL
31	1		*FRONT DOOR OUTER MOULDING N/S (CONSISTENT)	Deformed	155.00 FL	*155.00 FL
32	1		*D4D (CONSISTENT)	Necessary	165.00 FL	*165.00 FL
33	1		*LOGO (CONSISTENT)	Necessary	165.00 FL	*165.00 FL
34	1		*FRONT DOOR INNER TRIM N/S (CONSISTENT)	Deformed	565.00 FL	*565.00 FL
35	1		*FRONT DOOR RUBBER N/S (CONSISTENT)	Necessary	195.00 FL	*195.00 FL
36	1		*FRONT DOOR PILLAR INNER PROTECTOR N/S (CONSISTENT)	Not Necessary	211.00 FL	*- FL
37	1		*FRONT DOOR STEP GARNISH N/S (CONSISTENT)	Not Necessary	300.00 FL	*- FL
38	1		*SPARE TANK (CONSISTENT)	Not Necessary	180.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*WIPER TANK (CONSISTENT)	Not Necessary	170.00 FL	*- FL
40	1		*FRONT WHEEL PANEL N/S (CONSISTENT)	Repair	410.00 FL	*- FL
41	1		*FRONT WHEEL PANEL OUTER MOULDING N/S (CONSISTENT)	Not Necessary	85.00 FL	*- FL
42	1		*FRONT DASHBOARD (CONSISTENT)	Deformed	950.00 FL	*950.00 FL
43	1		*AIR CON HEATER (CONSISTENT)	Cracked	1,100.00 FL	*1,100.00 FL
44	1		*AIR CON BLOWER (CONSISTENT)	Cracked	880.00 FL	*880.00 FL
45	1		*SUCTION HOSE (CONSISTENT)	Not Necessary	230.00 FL	*- FL
46	1		*DISCHARGE HOSE (CONSISTENT)	Not Necessary	250.00 FL	*- FL
47	1		*FRONT RADIATOR (CONSISTENT)	Not Necessary	2,415.00 FL	*- FL
48	1		*FRONT PILLAR N/S (CONSISTENT)	Repair	388.10 FL	*- FL
49	1		*FRONT INNER PILLAR N/S (CONSISTENT)	Repair	375.91 FL	*- FL
50	1		*FRONT ERP BRACKET (CONSISTENT)	Necessary	15.00 FS	*15.00 FS
51	1		*FRONT NUMBER PLATE (CONSISTENT)	Necessary	25.00 FS	*25.00 FS
52	1		*COOLANT (CONSISTENT)	Not Necessary	30.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) 21,528.96 13,597.85
 - List Item Discount on L Items 25.00/25.00% (S\$) 5,364.74 3,389.46

Total Parts (S\$) 16,164.22 10,208.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE.	New	70.00	70.00
2	TO REMOVE, REPLACE & INSTALL DAMAGED PARTS.	New	2,200.00	1,200.00
3	TO R&R FRONT WINDSCREEN GLASS.	New	120.00	120.00
4	TO REMOVE & INSTALL DOOR MECHANISM & CHECK FOR FUNCTION.	New	180.00	60.00
5	TO R&R FRONT DASHBOARD.	New	250.00	180.00
6	TO R&R AIR CON SYSTEM. TO REFILL & TOP UP AIR CON GAS.	New	180.00	100.00
7	TO R&R FRONT RADIATOR.	New	150.00	0.00
8	TO R&R WIRING.	New	150.00	40.00
9	TO PUTTY & SPRAY PAINTING.	New	1,000.00	900.00
Gross Labour Cost (\$\$)			4,300.00	2,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >