

INS. CASE OWNER:

CC 4/LPC1600 9611, G/WB3

LKK:

IDAC:

Surveyor:

XGQ

DOI:

ASSIGNMENT

25/5/16

Date / Time:

25/5/16

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGP 984T

Name of Insured:

CHAM CHUAN HAO

Insured Tel No.:

HP: 96775894

Excess Sec II :SS

D.O.A: 19/5/16

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

15/16/16/VPO5/018791

Policy No.:

215VPO5005862

Make / Model:

SUZUKI

Place of Accident:

JUNG OF SLIM BARRACKS ROSE
& ONE NORTH LINK

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Accord



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/5/16
WVIASGN 16772 - X
SGP 984T - 4/LPC16004502/KAW3 DCA-MB/

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: POLPO

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P S\$ 12,368.70

(10 days) Reduction:

82 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with Celia Lai:

Email ☒ Call ☐

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

4a.

If NO or B 28, Ass. Lia:

Repair Cost: (W/GST)

S\$ 13,204.59

Loss of Rental (LOR):

S\$ 3500.00 (35 days) X \$100

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

TOWING

S\$ 80.00

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 16786.59

Global Sum S\$ 16700.00

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$450

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 16700.00

Name 1:

Accord Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

ASS. REC. BY:

REF:

033/LPC16009611/Ab

Special Instruction:

Surveyor: Alu Riang**ASSIGNMENT (Office)**From (Person): Gerald Poh

of

IPCDate/Time: 21/05/2016 5:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJN 167TZ

Insured:

SGP 981T

at Workshop m/s

Accord Auto

Tel:

9740 0999

of

Blk 10 Amk Ind Park 2A #03-11

Policy No:

Claim No:

15/16/16/VP05/018791

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/05/2016**CA / REV / REP. / REV 24 HRS WPI**

H.O.D. Endorsement:

Date/Time:

25/05/2016 4:36pm

Person Contacted:

JessyVehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJN 166TZ - X</u>
	<u>SGP 981T - 03/LPC16009611/K4h3</u>
	<u>DUP: K1052016</u>

08/11/13

REF: 19C

Surveyor: Xed

ASSIGNMENT

From:

Date: 25/05/2016

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SIN 16672

at Workshop m/s

Accord Auto

of

8/2 10 AMK 100 Rdk 2A #03-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$32K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

108

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIN 16773

Yr Regn:

05 Feb 2009

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Fiat Bravo

c.c. 1368

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZFA 178 0000 4.204174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55ZR16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

25-05-16

Survey held at

w/s

3pm

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/5

Estimate will give later - limit \$20k.

30/1/18

confirm US \$8650.00 with 8 working days

\$10833.5 12368.78

(201-1) \$8412.00 821-1)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC16009611/Gwb3		
100 BEACH ROAD #19-00 SHAW TOWERSINGAPORE 189702		Date : 25-05-2016		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGP 984T	Veh. Inspected	SJN 1677Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	15/16/16/VP05/018791	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	24/05/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/05/2016	Inspection Date	25/05/2016	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 24 May, 2016 5:59 PM
To: Catherine Chong (LKK Auto)
Cc: ERIC WOO JUN KIAT
Subject: FW: Accident involved SJN1667Z & SGP984T DOA:19/05/2016
Attachments: lonpac1.pdf

Our Ref : 15/16/16/VP05/018791

Dear Catherine,

Kindly proceed to arrange accordingly.

*25/05/2016 @ 9:36 am
Jessy veh in*

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
100 Beach Road, #19-00 Shaw Tower, Singapore 189702
Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]
Sent: Tuesday, 24 May, 2016 5:55 PM
To: GERALD POH WEE BIN
Cc: ERIC WOO JUN KIAT
Subject: Re: Accident involved SJN1667Z & SGP984T DOA:19/05/2016

Hi,

Please arrange Marcus Chua for PRI.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile: (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

On Tue, May 24, 2016 at 5:45 PM, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Our Ref : 15/16/16/VP05/018791

Dear Jessy,

We attached a list of our motor surveyors for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]

Sent: Tuesday, 24 May, 2016 9:44 AM

To: ERIC WOO JUN KIAT; GERALD POH WEE BIN

Cc: Gilbert Ng

Subject: Accident involved SJN1667Z & SGP984T DOA:19/05/2016

Hi,

Kindly assist arrange Pri-repair inspection for SJN1667Z @ AMK Autopoint #03-11, this vehicle in workshop.

Please provide us 10 surveyor name list.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A

#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile: (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

Shu Pei (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 30 May, 2016 4:05 PM
To: Shu Pei (LKK Auto)
Cc: ERIC WOO JUN KIAT
Subject: RE: Accident involved SJN1667Z & SGP984T DOA:19/05/2016 ***LKK
REF:CC4/LPC16009611/Gwb3
Attachments: 30052016155914.pdf

Our Ref : 15/16/16/VP05/018791

Dear Shi Pei,

We attached a copy of our insured's GIA report for your attention.

Kindly inform the case handler to let us have her view liability.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
100 Beach Road, #19-00 Shaw Tower, Singapore 189702
Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Shu Pei (LKK Auto) [mailto:shupeil@lkkauto.com]
Sent: Monday, 30 May, 2016 3:36 PM
To: GERALD POH WEE BIN
Cc: ERIC WOO JUN KIAT; LIONEL CHUA KOK KEONG; Admin A; Vivian Lau; Hsiao Tong; Zayyer
Subject: RE: Accident involved SJN1667Z & SGP984T DOA:19/05/2016 ***LKK REF:CC4/LPC16009611/Gwb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJN 1677Z at M/s Accord Auto Services Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that our preliminary advice is not ready yet.

Our case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Wednesday, 25 May, 2016 9:37 AM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments@lkkauto.com

Cc: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>

Subject: RE: Accident involved SJN1667Z & SGP984T DOA:19/05/2016

Dear Mr Gerald,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Tuesday, 24 May, 2016 5:59 PM

To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Cc: ERIC WOO JUN KIAT <ericwoo@lonpac.com>

Subject: FW: Accident involved SJN1667Z & SGP984T DOA:19/05/2016

Our Ref : 15/16/16/VP05/018791

Dear Catherine,

Kindly proceed to arrange accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Accord Auto(Claims) [<mailto:claims@mycarworkshop.com.sg>]

Sent: Tuesday, 24 May, 2016 5:55 PM

To: GERALD POH WEE BIN

Cc: ERIC WOO JUN KIAT

Subject: Re: Accident involved SJN1667Z & SGP984T DOA:19/05/2016

Hi,

Please arrange Marcus Chua for PRI.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile: (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

On Tue, May 24, 2016 at 5:45 PM, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Our Ref : 15/16/16/VP05/018791

Dear Jessy,

We attached a list of our motor surveyors for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]
Sent: Tuesday, 24 May, 2016 9:44 AM
To: ERIC WOO JUN KIAT; GERALD POH WEE BIN
Cc: Gilbert Ng
Subject: Accident involved SJN1667Z & SGP984T DOA:19/05/2016

Hi,

Kindly assist arrange Pri-repair inspection for SJN1667Z @ AMK Autopoint #03-11, this vehicle in workshop.

Please provide us 10 surveyor name list.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A

#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile: (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

Page 1

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2 A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Estimate

Lonpac Insurance BHD

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Attn: Motor Claims Department

Date : 30/05/2016

Vehicle No : SJN 1677 Z

Veh Make/Model: Fiat Bravo 1.4A

YOM: 2008

Chassis No. : ZFA19800004204174

Date of Accident: 19/05/2016

No	Unit	Description	Amount \$
Balance c/f			\$ 9,604.00
<u>Nett Items:-</u>			
31	1 pc	FRONT SUPPORT PANEL SIDE PANEL RH X NN	\$ 100.00 X
32	1 pc	AIR-CON CONDENSER BT	\$ 850 1,109.00 /
33	2 pcs	AIR-CON CONDENSER TOP MOUNTING @ \$24.00 BT	\$ 48.00 /
34	2 pcs	AIR-CON CONDENSER LOWER MOUNTING @ \$29.00 X NN	\$ 58.00 X
35	1 pc	AIR-CON DISCHARGE HOSE X	\$ 560.00 X
36	1 pc	AIR-CON INTAKE HOSE X	\$ 347.00 X
37	1 pc	AIR-CON FAN BLADE AND MOTOR X NN	\$ 941.00 X
38	1 pc	AIR-CON FAN COWLING X	\$ 308.00 X
39	1 pc	RADIATOR BT	\$ 967.00 /
40	1 pc	RADIATOR TOP MOUNTING DT	\$ 23.00 /
41	1 pc	RADIATOR LOWER MOUNTING X	\$ 23.00 X
42	1 pc	RADIATOR FAN MOTOR X	\$ 986.00 X
43	1 pc	RADIATOR FAN COWLING X NN	\$ 239.00 X
44	1 pc	RADIATOR FAN BLADE X	\$ 260.00 X
45	1 pc	FRONT RH AIR INTAKE DUCT X	\$ 120.00 X
46	1 pc	FRONT RH SHOCK ABSORBER X	\$ 446.00 X
47	1 pc	FRONT RH SHOCK ABSORBER TOP MOUNTING X	\$ 96.00 X
48	1 pc	FRONT RH KNUCKLE ARM X	\$ 1,446.00 X
49	1 pc	FRONT RH KNUCKLE BEARING KIT X NN	\$ 225.00 X
50	1 pc	FRONT RH KNUCKLE BEARING HUP X	\$ 220.00 X
51	1 pc	FRONT RH LOWER ARM X	\$ 460.00 X
52	1 pc	FRONT RH ANTI ROLL BAR LEUK X	\$ 97.00 X
53	1 pc	FRONT ENGINE LOWER SPLASH SHIELD CENTRE ee	\$ 363.00 /
54	1 pc	FRONT ENGINE LOWER SPLASH SHIELD RH X	\$ 245.00 X
55	1 pc	FRONT ENGINE LOWER SPLASH SHIELD LH X	\$ 185.00 X
56	1 pc	FUSE BOX X NN	\$ 770.00 X
57	1 pc	FRONT RH SUBFRAME X	\$ 561.00 X
58	2 pcs	FRONT WINDSCREEN SIDE FRAME LH & RH @ \$182.00 X	\$ 364.00 X
59	2 pcs	FRONT WINDSCREEN MOULDING LH & RH @ \$235.00 X	\$ 470.00 X
60	1 pc	WINDSCREEN TANK AND MOTOR X	\$ 325.00 X
			\$ 21,966.00
Balance b/f			\$ 21,966.00

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2 A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Estimate

Lonpac Insurance BHD

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Attn: Motor Claims Department

Date : 30/05/2016

Vehicle No : SJN 1677 Z

Veh Make/Model: Fiat Bravo 1.4A

YOM: 2008

Chassis No. : ZFA19800004204174

Date of Accident: 19/05/2016

No	Unit	Description	Amount S
Balance c/f			\$ 21,966.00
<u>Nett Items:-</u>			
61	1 pc	HORN ASSY X	\$ 180.00 X
62	1 pc	FRONT FENDER UNIT WHEELHOUSE X	\$ 698.00 X
63	1 pc	FRONT RH CHSSIS SUB FRAME X	\$ 560.00 X
64	1 pc	BATTERY BRACKET X	\$ 300.00 X
65	1 pc	FRONT WIRE HARNESS X	\$ 230.00 X
66	1 pc	FRONT BUMPER LOWER AIR GRILLE X - CPA	\$ 148.00 X
67	1 pc	FRONT TURBO CHARGER AIR COOLER X - BT	\$ 1,068.00 X
68	2 pcs	TURBO CHARGER AIR COOLER HOSE @ \$120.00 X	\$ 240.00 X
69	1 pc	TURBO CHARGER UNIT X	\$ 4,300.00 X
70	2 pcs	TURBO CHARGE SILENCER HOSE @ \$130.00 X	\$ 260.00 X
71	1 pc	TURBO CHARGE VACUUM WILD X	\$ 180.00 X
72	1 pc	GEAR BOX MOUNTING LH X - CPA	\$ 288.00 X
73	1 pc	ENGINE EXHAUST MANIFOLD X	\$ 1,635.00 X
74	1 pc	ENGINE THROTTLE VALUE UNIT X	\$ 2,200.00 X
75	1 pc	ENGINE RH MOUNTING X	\$ 320.00 X
76	1 pc	ENGINE FRONT MOUNTING X	\$ 268.00 X
77	1 pc	ENGINE CRANK SHAFT PULLEY X	\$ 320.00 X
78	1 pc	EXHAUST MANIFOLD HEAT SHIELD X - Buc	\$ 67.00 X
79	1 pc	ENGINE TIMING COVER TOP X	\$ 145.00 X
80	1 pc	ENGINE TIMING COVER LOWER X	\$ 137.00 X
81	1 pc	ENGINE TIMING BELT & TENSION BEARING X	\$ 177.00 X
82	1 pc	EXHAUST FRONT PIPE X	\$ 972.00 X
83	1 pc	AIR CON COMPRESSOR X	\$ 2,824.00 X
84	1 pc	AIR CON COMPRESSOR BELT X	\$ 52.00 X
85	1 pc	BELT TENSION PULLEY X	\$ 110.00 X
86	1 pc	RADIATOR SPARE TANK X	\$ 145.00 X
87	1 pc	RADIATOR SPARE TANK HOSE X	\$ 282.00 X
88	1 pc	AIR DUCT X	\$ 280.00 X
Nett item total:			\$ 40,352.00

Balance b/f \$ 40,352.00

Page 3

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2 A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Estimate

Lonpac Insurance BHD

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Attn: Motor Claims Department

Date : 30/05/2016

Vehicle No : SJN 1677 Z

Veh Make/Model: Fiat Bravo 1.4A

YOM: 2008

Chassis No. : ZFA19800004204174

Date of Accident: 19/05/2016

No	Unit	Description	Amount \$
		Balance c/f	\$ 40,352.00

Special Nett Items:-

1	1 pc	FRONT NUMBER PLATE WITH HOLDER	\$ 55.00	40
2	1 pc	FRONT RH TYRE X	\$ 310.00	X
3	1 pc	FRONT RH WHEEL RIM X	\$ 700.00	X
4	1 pc	RADIATOR COOLANT	\$ 25.00	-
5	1 pc	BATTERY UNIT X	\$ 150.00	X
	2 pcs	SPRAY TANK HOSE @ \$10.00 X	\$ 20.00	X
		Special Nett item total:	\$ 1,260.00	65

Labour Charges:-

1	Spray Painting to All Affected Areas.	\$ 150.00	1200
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area.	\$ 2,100.00	1200
3	Towing Fee	\$ 100.00	50
4	Anti Rust Treatment.	\$ 120.00	80
5	To Check Wiring System & Light.	\$ 150.00	30
6	To Check & Adjust Front Wheel Aligment.	\$ 100.00	X
7	To remove/replace front RH suspension parts.	\$ 350.00	X
8	To remove/refix engine to assist on repair.	\$ 250.00	X
9	To remove/replace aircon condenser, mounting, hose, dryer & etc, and top up gas.	\$ 450.00	60
10	To remove/replace radiator, fan, hose, mounting and top up coolant.	\$ 250.00	40
11	To adjust front chassis subframe on car o'liner.	\$ 300.00	X
12	To decode engine warning light & etc.	\$ 400.00	X
13	To remove/replace engine, gear box, mounting & etc.	\$ 180.00	X
14	To remove/replace alternator and test far proper operation.	\$ 300.00	X
15	To remove/replace turbo charger, hose turbo charger air cooler & etc.	\$ 250.00	40
		\$ 5,450.00	2700

Sub-Total	\$ 47,062.00
7% GST	\$ 3,294.34
Total	\$ 50,356.34

12368.78

48412

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2 A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Estimate

Lonpac Insurance BHD

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Attn: Motor Claims Department

Date : 30/05/2016

Vehicle No : SJN 1677 Z

Veh Make/Model: Fiat Bravo 1.4A

YOM: 2008

Chassis No. : ZFA19800004204174

Date of Accident: 19/05/2016

No	Unit	Description	Amount S
<u>Nett Items:-</u>			
1	1 pc	BONNET	\$ 920.00
2	2 pcs	BONNET HINGE @ \$117.00	\$ 234.00
3	1 pc	BONNET INSULATOR PAD	\$ 187.00
4	10 pcs	BONNET INSULATOR PAD CLIPS @ \$6.20	\$ 62.00
5	2 pcs	BONNET SPRAY NOZZLE @ \$18.00	\$ 36.00
6	1 pc	BONNET INNER LOCK	\$ 136.00
7	1 pc	FRONT RH FENDER	\$ 462.00
8	1 pc	FRONT RH FENDER SPLASH SHIELD	\$ 443.00
9	10 pc	FRONT RH FENDER SPLASH SHIELD CLIPS @ \$4.00	\$ 40.00
10	1 pc	FRONT LH FENDER	\$ 462.00
11	1 pc	FRONT LH FENDER SPLASH SHIELD	\$ 443.00
12	10 pc	FRONT LH FENDER SPLASH SHIELD CLIPS @ \$4.00	\$ 40.00
13	1 pc	FRONT BUMPER	\$ 888.00
14	2 pcs	FRONT BUMPER BRACKET @ \$58.00	\$ 116.00
15	1 pc	FRONT BUMPER REINFORCEMENT	\$ 573.00
16	10 pc	FRONT BUMPER CLIPS @ \$4.00	\$ 40.00
17	2 pcs	FRONT BUMPER SIDE RETAINER @ \$68.00	\$ 136.00
18	2 pcs	FRONT BUMPER SIDE ATTACHMENT @ \$42.00	\$ 84.00
19	1 pc	FRONT BUMPER TOW COVER	\$ 66.00
20	1 pc	FRONT BUMPER LOWER SPLASH SHIELD	\$ 420.00
21	1 pc	FRONT GRILLE	\$ 200.00
22	1 pc	FRONT GRILLE LOGO	\$ 95.00
23	1 pc	FRONT GRILLE INNER AIR DUCT	\$ 260.00
24	2 pcs	FRONT FOG LAMP LH & RH @ \$322.00	\$ 644.00
25	2 pcs	FRONT FOG LAMP COVER LH & RH @ \$87.00	\$ 174.00
26	1 pc	HEADLAMP LH	\$ 855.00
27	1 pc	HEADLAMP LOWER PANEL LH	\$ 80.00
28	1 pc	HEADLAMP RH	\$ 855.00
29	1 pc	HEADLAMP LOWER PANEL RH	\$ 80.00
30	1 pc	FRONT SUPPORT PANEL	\$ 473.00
31	1 pc	FRONT SUPPORT PANEL SIDE PANEL LH	\$ 100.00
			\$ 9,604.00
Balance b/f			\$ 9,604.00

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2 A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Estimate

Lonpac Insurance BHD
100 Beach Road
#19-00 Shaw Tower
Singapore 189702
Attn: Motor Claims Department

Date : 30/05/2016
Vehicle No : SJN 1677 Z
Veh Make/Model: Fiat Bravo 1.4A
YOM: 2008
Chassis No. : ZFA19800004204174
Date of Accident: 19/05/2016

No	Unit	Description	Amount \$
Balance c/f			\$ 9,604.00
<u>Nett Items:-</u>			
31	1 pc	FRONT SUPPORT PANEL SIDE PANEL RH	\$ 100.00
32	1 pc	AIR-CON CONDENSER	\$ 1,109.00
33	2 pcs	AIR-CON CONDENSER TOP MOUNTING @ \$24.00	\$ 48.00
34	2 pcs	AIR-CON CONDENSER LOWER MOUNTING @ \$29.00	\$ 58.00
35	1 pc	AIR-CON DISCHARGE HOSE	\$ 560.00
36	1 pc	AIR-CON INTAKE HOSE	\$ 347.00
37	1 pc	AIR-CON FAN BLADE AND MOTOR	\$ 941.00
38	1 pc	AIR-CON FAN COWLING	\$ 308.00
39	1 pc	RADIATOR	\$ 967.00
40	1 pc	RADIATOR TOP MOUNTING	\$ 23.00
41	1 pc	RADIATOR LOWER MOUNTING	\$ 23.00
42	1 pc	RADIATOR FAN MOTOR	\$ 986.00
43	1 pc	RADIATOR FAN COWLING	\$ 239.00
44	1 pc	RADIATOR FAN BLADE	\$ 260.00
45	1 pc	FRONT RH AIR INTAKE DUCT	\$ 120.00
46	1 pc	FRONT RH SHOCK ABSORBER	\$ 446.00
47	1 pc	FRONT RH SHOCK ABSORBER TOP MOUNTING	\$ 96.00
48	1 pc	FRONT RH KNUCKLE ARM	\$ 1,446.00
49	1 pc	FRONT RH KNUCKLE BEARING KIT	\$ 225.00
50	1 pc	FRONT RH KNUCKLE BEARING HUP	\$ 220.00
51	1 pc	FRONT RH LOWER ARM	\$ 460.00
52	1 pc	FRONT RH ANTI ROLL BAR LEUK	\$ 97.00
53	1 pc	FRONT ENGINE LOWER SPLASH SHIELD CENTRE	\$ 363.00
54	1 pc	FRONT ENGINE LOWER SPLASH SHIELD RH	\$ 245.00
55	1 pc	FRONT ENGINE LOWER SPLASH SHIELD LH	\$ 185.00
56	1 pc	FUSE BOX	\$ 770.00
57	1 pc	FRONT RH SUBFRAME	\$ 561.00
58	2 pcs	FRONT WINDSCREEN SIDE FRAME LH & RH @ \$182.00	\$ 364.00
59	2 pcs	FRONT WINDSCREEN MOULDING LH & RH @ \$235.00	\$ 470.00
60	1 pc	WINDSCREEN TANK AND MOTOR	\$ 325.00
			\$ 21,966.00
Balance b/f			\$ 21,966.00

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2 A
 #03-11 AMK Autopoint Singapore 568047
 Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Estimate

Lonpac Insurance BHD
 100 Beach Road
 #19-00 Shaw Tower
 Singapore 189702
 Attn: Motor Claims Department

Date : 30/05/2016
 Vehicle No : SJN 1677 Z
 Veh Make/Model: Fiat Bravo 1.4A
 YOM: 2008
 Chassis No. : ZFA19800004204174
 Date of Accident: 19/05/2016

No	Unit	Description	Amount \$
Balance c/f			\$ 21,966.00

Nett Items:-

61	1 pc	HORN ASSY	\$ 180.00
62	1 pc	FRONT FENDER UNIT WHEELHOUSE	\$ 698.00
63	1 pc	FRONT RH CHSSIS SUB FRAME	\$ 560.00
64	1 pc	BATTERY BRACKET	\$ 300.00
65	1 pc	FRONT WIRE HARNESS	\$ 230.00
66	1 pc	FRONT BUMPER LOWER AIR GRILLE	\$ 148.00
67	1 pc	FRONT TURBO CHARGER AIR COOLER	\$ 1,068.00
68	2 pcs	TURBO CHARGER AIR COOLER HOSE @ \$120.00	\$ 240.00
69	1 pc	TURBO CHARGER UNIT	\$ 4,300.00
70	2 pcs	TURBO CHARGE SILENCER HOSE @ \$130.00	\$ 260.00
71	1 pc	TURBO CHARGE VACUUM WILD	\$ 180.00
72	1 pc	GEAR BOX MOUNTING LH	\$ 288.00
73	1 pc	ENGINE EXHAUST MANIFOLD	\$ 1,635.00
74	1 pc	ENGINE THROTTLE VALUE UNIT	\$ 2,200.00
75	1 pc	ENGINE RH MOUNTING	\$ 320.00
76	1 pc	ENGINE FRONT MOUNTING	\$ 268.00
77	1 pc	ENGINE CRANK SHALT PULLEY	\$ 320.00
78	1 pc	EXHAUST MANIFOLD HEAT SHIELD	\$ 67.00
79	1 pc	ENGINE TIMING COVER TOP	\$ 145.00
80	1 pc	ENGINE TIMING COVER LOWER	\$ 137.00
81	1 pc	ENGINE TIMING BELT & TENSION BEARING	\$ 177.00
82	1 pc	EXHAUST FRONT PIPE	\$ 972.00
83	1 pc	AIR CON COMPRESSOR	\$ 2,824.00
84	1 pc	AIR CON COMPRESSOR BELT	\$ 52.00
85	1 pc	BELT TENSION PULLEY	\$ 110.00
86	1 pc	RADIATOR SPARE TANK	\$ 145.00
87	1 pc	RADIATOR SPARE TANK HOSE	\$ 282.00
88	1 pc	AIR DUCT	\$ 280.00
Nett item total:			\$ 40,352.00

Balance b/f \$ 40,352.00

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2 A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516

Estimate

Lonpac Insurance BHD
100 Beach Road
#19-00 Shaw Tower
Singapore 189702
Attn: Motor Claims Department

Date : 30/05/2016
Vehicle No : SJN 1677 Z
Veh Make/Model: Fiat Bravo 1.4A
YOM: 2008
Chassis No. : ZFA19800004204174
Date of Accident: 19/05/2016

No	Unit	Description	Amount \$
Balance c/f			\$ 40,352.00
<u>Special Nett Items:-</u>			
1	1 pc	FRONT NUMBER PLATE WITH HOLDER	\$ 55.00
2	1 pc	FRONT RH TYRE	\$ 310.00
3	1 pc	FRONT RH WHEEL RIM	\$ 700.00
4	1 pc	RADIATOR COOLANT	\$ 25.00
5	1 pc	BATTERY UNIT	\$ 150.00
	2 pcs	SPRAY TANK HOSE @ \$10.00	\$ 20.00
Special Nett item total:			\$ 1,260.00
<u>Labour Charges:-</u>			
1		Spray Painting to All Affected Areas.	\$ 150.00
2		Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area.	\$ 2,100.00
3		Towing Fee	\$ 100.00
4		Anti Rust Treatment.	\$ 120.00
5		To Check Wiring System & Light.	\$ 150.00
6		To Check & Adjust Front Wheel Alignment.	\$ 100.00
7		To remove/replace front RH suspension parts.	\$ 350.00
8		To remove/refix engine to assist on repair.	\$ 250.00
9		To remove/replace aircon condenser, mounting, hose, dryer & etc, and top up gas.	\$ 450.00
10		To remove/replace radiator, fan, hose, mounting and top up coolant.	\$ 250.00
11		To adjust front chassis subframe on car o'liner.	\$ 300.00
12		To decode engine warning light & etc.	\$ 400.00
13		To remove/replace engine, gear box, mounting & etc.	\$ 180.00
14		To remove/replace alternator and test far proper operation.	\$ 300.00
15		To remove/replace turbo charger, hose turbo charger air cooler & etc.	\$ 250.00
			\$ 5,450.00
Sub-Total			\$ 47,062.00
7% GST			\$ 3,294.34
Total			\$ 50,356.34

WLL
Hsiao Tong (LKKAUTO)


From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 22 January 2019 11:22 AM
To: Vivian Lau (LKKAUTO)
Cc: MT_Claim_SG
Subject: ACCIDENT INVOLVING SJN1677Z & SGP984T ON 19.5.2016

Our Ref : 15/16/16/VP05/018791
Your Ref : CC4/LPC16009611/Gwb3

Dear Vivian,

Kindly advise if the third party is pursuing his claim.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Jia Le (LKK Auto)

From: Vic (LKKAuto)
Sent: Wednesday, 12 June 2019 6:23 PM
To: Jia Le (LKK Auto)
Subject: FW: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016
LKK REF CC4/LPC16009611/Gdb3 [External Confidential]

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Wednesday, 12 June, 2019 4:46 PM
To: Vic (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016 LKK REF
CC4/LPC16009611/Gdb3 [External Confidential]

Lonpac External - Confidential


Dear Vic,

Kindly peruse through the documents and advise if the claim for rental of vehicle for 50 days is in order.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]
Sent: Wednesday, 12 June, 2019 4:27 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Vic (LKKAuto); Jia Le (LKK Auto)
Subject: RE: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016 [External Confidential]
LKK REF CC4/LPC16009611/Gdb3

Dear Gerald,

We refer to your below email.

Please find attached parts invoices as requested for your reference.

For your approval and/or further instruction please.

Thank you.

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Tuesday, 25 June 2019 2:34 PM
To: Accord Claims(AV)
Cc: Admin A; CS A Team
Subject: RE: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016 LKK REF: CC4/LPC16009611/Ghb3s2
Attachments: SJN 1677Z.pdf

Without Prejudice

Dear Sirs/Mdm,

Please duly sign the DV enclosed and return the original DV to us (LKK) for our necessary action.

Thank you.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) [mailto:avclaims@mycarworkshop.com.sg]

Sent: Tuesday, 25 June 2019 1:32 PM

To: Jia Le (LKK Auto)

Cc: Admin A; CS A Team

Subject: Re: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016 LKK REF: CC4/LPC16009611/Ghb3s2

Dear Jia Le,

Agree on your offer.

Kindly let us have the discharge voucher.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Mon, Jun 24, 2019 at 5:30 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Sirs/Mdm,

ACCIDENT INVOLVING SGP 984T & SJN 1677Z ON 19/05/2016

We refer to the above matter.

We propose settlement at a global sum of **\$16,700.00(all-in)**.

Please confirm acceptance.

“Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) [mailto:avclaims@mycarworkshop.com.sg]

Sent: Thursday, 25 April 2019 6:16 PM

To: Hsiao Tong (LKKAuto)

Cc: Admin A; CS A Team

Subject: Re: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016 LKK REF: CC4/LPC16009611/Ghb3s2

Dear Hsiao Tong,

As spoken, we take order the parts by tel-commutation after survey conducted.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Thu, Apr 25, 2019 at 11:54 AM Accord Claims(AV) <avclaims@mycarworkshop.com.sg> wrote:

Dear Hsiao Tong,

We refer your email as below.

We have attached supplier invoice for your reference of the Purchase Order number at the side LH at the invoice. For your information, the supplier do not have the purchase order documents for us.

We also appreciate an early reply.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Thu, Apr 25, 2019 at 11:11 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We noted that you have submitted a copy of Delivery Order(DO). However, we would like to request a copy of purchase order(PO) documents for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler (*on behalf of Vic*)

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 25 April 2019 7:51 AM

To: 'Accord Claims(AV)' <avclaims@mycarworkshop.com.sg>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: RE: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016

Dear Celia,

Thank you for the email.

Dear Vic,

Kindly assist

FYNA Our Ref : CC4/LPC16009611/Ghb3s2

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) [<mailto:avclaims@mycarworkshop.com.sg>]
Sent: Wednesday, 24 April 2019 1:33 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: You Ref:15/16/16/LP05/018791 (Lonpac) Our Ref: SJN1677Z DOA:19.5.2016

Dear Officer In Charge,

Kindly refer assist update us any status/ update as above mentioned.

Our LOD submitted on Nov 2018. Till date we still have receive any reply from your.

Kindly advise.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC16009611/Gdb3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 12-07-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGP 984T	Veh. Inspected	SJN 1677Z	
Policy No.	Z15VP05005263	Coverage (\$)	0.00	
Claim No.	15/16/16/VP05/018791	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	25/05/2016	
2. Vehicle Particulars & Condition				
Make & Model	FIAT BRAVO	c.c	1368	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ZFA19800004204174	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55ZR16	MICHELIN	5 mm	
L/H Front Tyre	205/55ZR16	MICHELIN	5 mm	
R/H Rear Tyre	205/55ZR16	MICHELIN	5 mm	
L/H Rear Tyre	205/55ZR16	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/05/2016	Inspection Date	25/05/2016	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 1677Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET (N)	BUCKLED	920.00	920.00
2	BONNET HINGE @ \$117.00 (N)	BENT	234.00	234.00
1	BONNET INSULATOR (N)	DEFORMED	187.00	187.00
10	BONNET INSULATOR PAD CLIPS @ \$6.20 (N)	NECESSARY	62.00	62.00
2	BONNET SPRAY NOZZLE @ \$18.00 (N)	NOT NECESSARY	36.00	-
1	BONNET INNER LOCK (N)	DISTORTED	136.00	136.00
1	FRONT RH FENDER (N)	BUCKLED	462.00	462.00
1	FRONT RH FENDER SPLASH SHIELD (N)	NOT NECESSARY	443.00	-
10	FRONT RH FENDER SPLASH SHIELD CLIPS @ \$4.00 (N)	NOT NECESSARY	40.00	-
1	FRONT LH FENDER (N)	BENT	462.00	462.00
1	FRONT LH FENDER SPLASH SHIELD (N)	NOT NECESSARY	443.00	-
10	FRONT LH FENDER SPLASH SHIELD CLIPS @ \$4.00 (N)	NOT NECESSARY	40.00	-
1	FRONT BUMPER (N)	DISTORTED	888.00	780.00
2	FRONT BUMPER BRACKET @ \$58.00 (N)	NOT NECESSARY	116.00	-
1	FRONT BUMPER REINFORCEMENT (N)	BENT	573.00	573.00
10	FRONT BUMPER CLIPS @ \$4.00 (N)	NECESSARY	40.00	40.00
2	FRONT BUMPER SIDE RETAINER @ \$68.00 (N)	NECESSARY	136.00	136.00
2	FRONT BUMPER SIDE ATTACHMENT @ \$42.00 (N)	NOT NECESSARY	84.00	-
1	FRONT BUMPER TOW COVER (N)	MISSING	66.00	66.00
1	FRONT BUMPER LOWER SPLASH SHIELD (N)	CRACKED	420.00	141.00
1	FRONT GRILLE (N)	MISSING	200.00	200.00
1	FRONT GRILLE LOGO (N)	MISSING	95.00	95.00
1	FRONT GRILLE INNER AIR DUCT (N)	NOT NECESSARY	260.00	-
2	FRONT FOG LAMP LH & RH @ \$322.00 (N)	CRACKED	644.00	285.00
2	FRONT FOG LAMP COVER LH & RH @ \$87.00 (N)	CUT	174.00	70.20
1	HEADLAMP LH (N)	DISTORTED	855.00	680.00
1	HEADLAMP LOWER PANEL LH (N)	NOT NECESSARY	80.00	-
1	HEADLAMP RH (N)	CRACKED	855.00	680.00
1	HEADLAMP LOWER PANEL RH (N)	NOT NECESSARY	80.00	-
1	FRONT SUPPORT PANEL (N)	BUCKLED	473.00	473.00
1	FRONT SUPPORT PANEL SIDE PANEL LH (N)	NOT NECESSARY	100.00	-

Report Ref No. CC4/LPC16009611/Gdb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL SIDE PANEL RH (N)	NOT NECESSARY	100.00	-
1	AIR-CON CONDENSER (N)	BENT	1,109.00	850.00
2	AIR-CON CONDENSER TOP MOUNTING @ \$24.00 (N)	BENT	48.00	48.00
2	AIR-CON CONDENSER LOWER MOUNTING @ \$29.00 (N)	NOT NECESSARY	58.00	-
1	AIR-CON DISCHARGE HOSE (N)	NOT NECESSARY	560.00	-
1	AIR-CON INTAKE HOSE (N)	NOT NECESSARY	347.00	-
1	AIR-CON FAN BLADE AND MOTOR (N)	NOT NECESSARY	941.00	-
1	AIR-CON FAN COWLING (N)	NOT NECESSARY	308.00	-
1	RADIATOR (N)	BENT	967.00	967.00
1	RADIATOR TOP MOUNTING (N)	BENT	23.00	23.00
1	RADIATOR LOWER MOUNTING (N)	NOT NECESSARY	23.00	-
1	RADIATOR FAN MOTOR (N)	NOT NECESSARY	986.00	-
1	RADIATOR FAN COWLING (N)	NOT NECESSARY	239.00	-
1	RADIATOR FAN BLADE (N)	NOT NECESSARY	260.00	-
1	FRONT RH AIR INTAKE DUCT (N)	NOT NECESSARY	120.00	-
1	FRONT RH SHOCK ABSORBER (N)	NOT NECESSARY	446.00	-
1	FRONT RH SHOCK ABSORBER TOP MOUNTING (N)	NOT NECESSARY	96.00	-
1	FRONT RH KNUCKLE ARM (N)	NOT NECESSARY	1,446.00	-
1	FRONT RH KNUCKLE BEARING KIT (N)	NOT NECESSARY	225.00	-
1	FRONT RH KNUCKLE BEARING HUP (N)	NOT NECESSARY	220.00	-
1	FRONT RH LOWER ARM (N)	NOT NECESSARY	460.00	-
1	FRONT RH ANTI ROLL BAR LEUK (N)	NOT NECESSARY	97.00	-
1	FRONT ENGINE LOWER SPLASH SHIELD CENTRE (N)	DEFORMED	363.00	363.00
1	FRONT ENGINE LOWER SPLASH SHIELD RH (N)	NOT NECESSARY	245.00	-
1	FRONT ENGINE LOWER SPLASH SHIELD LH (N)	NOT NECESSARY	185.00	-
1	FUSE BOX (N)	NOT NECESSARY	770.00	-
1	FRONT RH SUBFRAME (N)	NOT NECESSARY	561.00	-
2	FRONT WINDSCREEN SIDE FRAME LH & RH @ \$182.00 (N)	NOT NECESSARY	364.00	-
2	FRONT WINDSCREEN MOULDING LH & RH @ \$235.00 (N)	NOT NECESSARY	470.00	-
1	WINDSCREEN TANK AND MOTOR (N)	NOT NECESSARY	325.00	-
1	HORN ASSY (N)	NOT NECESSARY	180.00	-
1	FRONT FENDER UNIT WHEELHOUSE (N)	NOT NECESSARY	698.00	-

Report Ref No. CC4/LPC16009611/Gdb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH CHASSIS SUB FRAME (N)	NOT NECESSARY	560.00	-
1	BATTERY BRACKET (N)	NOT NECESSARY	300.00	-
1	FRONT WIRE HARNESS (N)	NOT NECESSARY	230.00	-
1	FRONT BUMPER LOWER AIR GRILLE (N)	CRACKED	148.00	148.00
1	FRONT TURBO CHARGER AIR COOLER (N)	BENT	1,068.00	1,068.00
2	TURBO CHARGER AIR COOLER HOSE @ \$120.00 (N)	NOT NECESSARY	240.00	-
1	TURBO CHARGER UNIT (N)	NOT NECESSARY	4,300.00	-
2	TURBO CHARGE SILENCER HOSE @ \$130.00 (N)	NOT NECESSARY	260.00	-
1	TURBO CHARGE VACUUM WILD (N)	NOT NECESSARY	180.00	-
1	GEAR BOX MOUNTING LH (N)	CRACKED	288.00	288.00
1	ENGINE EXHAUST MANIFOLD (N)	NOT NECESSARY	1,635.00	-
1	ENGINE THROTTLE VALUE UNIT (N)	NOT NECESSARY	2,200.00	-
1	ENGINE RH MOUNTING (N)	NOT NECESSARY	320.00	-
1	ENGINE FRONT MOUNTING (N)	NOT NECESSARY	268.00	-
1	ENGINE CRANK SHAFT PULLEY (N)	NOT NECESSARY	320.00	-
1	EXHAUST MANIFOLD HEAT SHIELD (N)	BUCKLED	67.00	67.00
1	ENGINE TIMING COVER TOP (N)	NOT NECESSARY	145.00	-
1	ENGINE TIMING COVER LOWER (N)	NOT NECESSARY	137.00	-
1	ENGINE TIMING BELT & TENSION BEARING (N)	NOT NECESSARY	177.00	-
1	EXHAUST FRONT PIPE (N)	NOT NECESSARY	972.00	-
1	AIR CON COMPRESSOR (N)	NOT NECESSARY	2,824.00	-
1	AIR CON COMPRESSOR BELT (N)	NOT NECESSARY	52.00	-
1	BELT TENSION PULLEY (N)	NOT NECESSARY	110.00	-
1	RADIATOR SPARE TANK (N)	NOT NECESSARY	145.00	-
1	RADIATOR SPARE TANK HOSE (N)	NOT NECESSARY	282.00	-
1	AIR DUCT (N)	NOT NECESSARY	280.00	-
	LESS 10% DISCOUNT		-	-1,050.42
			40,352.00	9,453.78
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE WITH HOLDER (SN)	BENT	55.00	40.00
1	FRONT RH TYRE (SN)	NOT NECESSARY	310.00	-
1	FRONT RH WHEEL RIM (SN)	NOT NECESSARY	700.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	25.00	25.00

Report Ref No. CC4/LPC16009611/Gdb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BATTERY UNIT (SN)	NOT NECESSARY	150.00	-
2	SPRAY TANK HOSE @ \$10.00 (SN)	NOT NECESSARY	20.00	-
			1,260.00	65.00
	LABOUR			
	SPRAY PAINTING TO ALL AFFECTED AREAS.		1,500.00	1,200.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.		2,100.00	1,200.00
	TOWING FEE.		100.00	50.00
	ANTI RUST TREATMENT.		120.00	80.00
	TO CHECK WIRING SYSTEM & LIGHT.		150.00	30.00
	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REMOVE / REPLACE FRONT RH SUSPENSION PARTS.	NOT NECESSARY	350.00	-
	TO REMOVE / REFIX ENGINE TO ASSIST REPAIR.	NOT NECESSARY	250.00	-
	TO REMOVE / REPLACE AIRCON CONDENSER, MOUNTING, HOSE, DRYER & ETC, AND TOP UP GAS.		450.00	60.00
	TO REMOVE / REPLACE RADIATOR, FAN, HOSE, MOUNTING AND TOP UP COOLANT.		250.00	40.00
	TO ADJUST FRONT CHASSIS SUBFRAME ON CAR O LINER.	NOT NECESSARY	300.00	-
	TO DECODE ENGINE WARNING LIGHT & ETC.	NOT NECESSARY	400.00	-
	TO REMOVE / REPLACE ENGINE, GEAR BOX, MOUNTING & ETC.		180.00	150.00
	TO REMOVE / REPLACE ALTERNATOR AND TEST FOR PROPER OPERATION.	NOT NECESSARY	300.00	-
	TO REMOVE / REPLACE TURBO CHARGER, HOSE TURBO CHARGER AIR COOLER & ETC.		250.00	40.00
			6,800.00	2,850.00
GRAND TOTAL			48,412.00	12,368.78
RECOMMENDED COST OF REPAIRS				12,368.78

Report Ref No. CC4/LPC16009611/Gdb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.