

INS. CASE OWNER:

CC 4/AXA1600

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L/YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 3,980.00

(6

days)

Reduction:

62.45

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

IF NO or B 28, Ass. Lia:

Repair Cost:

S\$ 4,258.60

Loss of Rental (LOR):

S\$ 450.00

(3

days)

x \$150.00

Loss of Use (LOU):

S\$ -

(5

x

days)

Loss of Income (LOI):

S\$ -

(5

x

days)

LOR only ☒ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

S\$

5.35

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$ 4,713.95

Global Sum S\$:

4,700.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 4,700.00

Name 1:

EIA-1 Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Surveyor:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s EWI

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$79K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 9BE78917 Yr Regn: MMR 1206

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

M Truck / Trailer or

Make: Toyota Dena 3.0 c.c. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 2363 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2318023417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175 / 75 / R15

R: 145 / R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 25/05/2016 D.O.I. 27/05/2016

Survey held at Recovery

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/6/2016

1/31 \$3,480.00 (Red 6,76370 / 62.95%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

1,311.10 ✓
52.00 ✓
98.10 ✓
112.40 ✓
250.00 ✓
15.00 ✓
15.00 ✓
40.00 ✓
800.00 ✓
800.00 ✓
30.00 ✓
40.00 ✓

248.00 ✓
57.10 ✓
72.00 ✓

166.00 ✓
89.50 ✓
248.70 ✓
139.00 ✓
52.00 ✓
325.20 X
132.20 X

612.00 ✓

212.00 ✓
385.70 ✓
125.00 ✓

File 4593
NO :

Vehicle No.
GBE 7891Z

Model
TOYOTA DYNA

Rental 7 days

Total List Price	\$	4,438.00
Discount		25%
List Price	\$	3,328.50
Total Nett Price	\$	-
Discount		25%
Nett Price	\$	-
Total Special Nett	\$	320.00
Total Labour	\$	1,670.00
Grand Total	\$	5,318.50
Discount 20%		20%
Lump Sum	\$	4,254.80

Columns	List Price
A	Nett Price
C	Special Nett
D	Labour
E	

\$ 3,980.60
X 75%
\$ 2,985.45
+ \$ 320.00
+ \$ 1,670.00
\$ 4,975.45
X 80%
\$ 3,980.36

L/S: \$ 3,980.00 //
With 7 working days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBE 7891Z
Vehicle Model : TOYOTA DYNA
Accident Date : 25.05.2016
Original Reg Date : 24.03.2016

Date : 26.05.2016
Chassis : KDY2318023417
TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate	✓		± 1311.10	
2	2 pcs	Tailgate Side Lock	HS ✓	⑥ 52.24	± 104.01	BT
3	2 pcs	Tailgate Side Lock Bracket	NS ✓	⑥ 98.10	± 196.20	BT
4	2 pcs	Tailgate Side Lock Lower Bracket	NS ✓	⑥ 112.40	± 224.80	BT
5	2 pcs	Tailgate Side Stopper	✓	⑥ 46	± 92.00	XNN
6	4 pcs	Tailgate Hinges	✓	⑥ 62	± 248.00	BT
7	1 pc	Tailgate Sticker DYNA	✓		± 57.10	NEC
8	1 pc	Tailgate Sticker 1500kg	✓		± 72.00	NEC
9	1 pc	Tailgate Lower Cross Member	R ✓		± 687.00	
10	2 pcs	Tailgate Lower Cross Member Reflectors	✓	⑥ 83	± 166.00	CRA
11	1 pc	Rear Number Plate Base Bracket	✓		± 89.50	
12	2 pcs	Taillamps	NS CRA ✓	⑥ 248.70	± 497.40	
13	2 pcs	Taillamps Base	NS CRA ✓	⑥ 139	± 278.00	
14	2 pcs	Taillamps Bottom Reflectors	NS CRA ✓	⑥ 52	± 104.00	
15	1 pc	Spare Tyre Carrier	?		± 325.20	XNN
16	1 pc	Spare Tyre Carrier Bracket	?		± 152.20	XNN
17	1 pc	Rear Exhaust Pipe	X		± 313.50	NN
18	2 pcs	Rear Exhaust Mountings	X	⑥ 81.20	± 162.40	NN
19	1 pc	Rear Exhaust Mountings Bracket	X		± 61.50	NN
20	1 pc	Rear Chassis Frame Center Cross Member	✓		± 612.00	DIS
21	1 pc	Rear Side Gate Bottom Cross Member LH	R X		± 875.10	
22	1 pc	Rear Mudguard LH (Rear)	12. X		± 150.90	
23	1 pc	Rear Mudguard LH Bracket (Rear)	R X		± 85.10	
24	1 pc	Rear Mudflap LH	✓		± 92.00	
25	1 pc	Rear Step Bracket	✓		± 212.00	
26	1 pc	Rear Side Luggage Box LH	✓		± 381.70	RK 38
27	1 pc	Rear Side Luggage Box Bracket LH	✓		± 125.00	BT

Special Nett

1	1 pc	Tailgate Top Cover Plate	250	350.00	250 BT
2	1 pc	Tailgate Sticker 70km/h	15	15.00	JREC
3	1 pc	Tailgate Sticker 13pax	15	15.00	
4	1 pc	Rear Number Plate	40	50.00	40 dis

C/F

320

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBE 7891Z

B/F

Labour charge

Panel Beating	800	1,200.00	800
Spray painting	800	1,000.00	800
Check Wiring	30	40.00	30
Anti rust	40	100.00	40
Remove and install rear exhaust silencer.	—	120.00	X
		<u>1,643.70</u>	

1670

Not Butcher
 HS Repair
 After paint Done
 LK Auto (MA)

27/6/2016 1200hrs

(6) Days

List price - \$3,980.60

- 25%
 \$2,985.45
 + SIN \$ 320.00
 + Labour \$ 1,670.00
 \$4,975.45
 X 80%

\$3,980.36 = L/S \$3,980.00
 with 6 days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBE 7891Z
Vehicle Model : TOYOTA DYNA
Accident Date : 25.05.2016
Original Reg Date : 24.03.2016

Date : 26.05.2016
Chassis : KDY2318023417
TP Ins. : AXA

ESTIMATE

1	1 pc	Tailgate	✓ ✓		± 1311.10	
2	2 pcs	Tailgate Side Lock	NS OS-NH ✓	⑥ 52.44	± 104.08	BT
3	2 pcs	Tailgate Side Lock Bracket	NS OS-NH ✓	⑥ 98.10	± 196.20	BT
4	2 pcs	Tailgate Side Lock Lower Bracket	NS OS-NH ✓	⑥ 112.40	± 224.80	BT
5	2 pcs	Tailgate Side Stopper	X X	⑥ 46	± 92.00	X N N
6	4 pcs	Tailgate Hinges	✓ ✓	⑥ 62	± 248.00	BT
7	1 pc	Tailgate Sticker DYNA	✓ ✓		± 57.10	NEC
8	1 pc	Tailgate Sticker 1500kg	✓ ✓		± 72.00	NEC
9	1 pc	Tailgate Lower Cross Member	R ✓		± 687.00	
10	2 pcs	Tailgate Lower Cross Member Reflectors	✓ ✓	⑥ 83	± 166.00	CRA
11	1 pc	Rear Number Plate Base Bracket	✓ ✓		± 89.50	
12	2 pcs	Taillamps	NS CRA OS-NH ✓	⑥ 243.70	± 487.40	
13	2 pcs	Taillamps Base	NS CRA OS-NH ✓	⑥ 139.44	± 278.88	
14	2 pcs	Taillamps Bottom Reflectors	NS CRA OS-NH ✓	⑥ 52.44	± 104.88	
15	1 pc	Spare Tyre Carrier	?	✓	± 325.20	X N N
16	1 pc	Spare Tyre Carrier Bracket	?	✓	± 152.20	X N N
17	1 pc	Rear Exhaust Pipe	X X		± 513.50	N N
18	2 pcs	Rear Exhaust Mountings	X X	⑥ 81.20	± 162.40	N N
19	1 pc	Rear Exhaust Mountings Bracket	X X		± 61.50	N N
20	1 pc	Rear Chassis Frame Center Cross Member	✓ ✓		± 612.00	DIS
21	1 pc	Rear Side Gate Bottom Cross Member LH	R X		± 875.10	
22	1 pc	Rear Mudguard LH (Rear)	12. X X		± 152.90	
23	1 pc	Rear Mudguard LH Bracket (Rear)	R X		± 85.10	
24	1 pc	Rear Mudflap LH	me X		± 95.00	
25	1 pc	Rear Step Bracket	bt ✓		± 212.00	
26	1 pc	Rear Side Luggage Box LH	✓ ✓		± 382.70	RK 38
27	1 pc	Rear Side Luggage Box Bracket LH	✓ ✓		± 125.00	BT

Special Nett

1	1 pc	Tailgate Top Cover Plate	250	350.00	250 BT
2	1 pc	Tailgate Sticker 70km/h	15	✓ 15.00	JREC
3	1 pc	Tailgate Sticker 13pax	15	✓ 15.00	
4	1 pc	Rear Number Plate	40	50.00	40 dis.

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBE 7891Z

B/F

Labour charge

Panel Beating	800	1,200.00	800
Spray painting	800	1,000.00	800
Check Wiring	30	40.00	30
Anti rust	40	100.00	40
Remove and install rear exhaust silencer.	—	120.00	X
		<u>1,670.00</u>	1670.

Not Authorised
HS Dapin
After paint Photo
Hk Auto (M4)
27/6/2016 1200hrs

(6-11 days)



D.O.A. 25/5/2016
Bal: 9 yrs 10 mths

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 3218D

Vehicle Details

Vehicle No.: GBE7891Z

Vehicle to be Exported: Yes

Intended De-registration Date: 27 May 2016

Vehicle Make: TOYOTA

Vehicle Model: DYNA 3.0 DIESEL TURBO M/T 2WD

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1KD2586794

Chassis No.: KDY2318023417

Maximum Power Output: -

Open Market Value: \$33,237.00

Original Registration Date: 24 Mar 2016 ✓

First Registration Date: 24 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$1,662.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Mar 2026 ✓

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$32,625.00

COE Rebate Amount: \$26,100.00

Total Rebate Amount: \$26,100.00 ✓

The information contained herein is correct as at 26 May 2016

OK

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)
Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO.: 201316380R

Vehicle Number : GBE 7891Z
Vehicle Model : TOYOTA DYNA
Accident Date : 25.05.2016
Original Reg Date : 24.03.2016

Date :
Chassis :
TP Ins.

26.05.2016
KDY2318023417

AXA

ESTIMATE

1	1 pc	Tailgate			1311.10
2	2 pcs	Tailgate Side Lock	HS	104.00	196.20
3	2 pcs	Tailgate Side Lock Bracket	HS	112.40	224.80
4	2 pcs	Tailgate Side Lock Lower Bracket	HS	46	92.00
5	2 pcs	Tailgate Side Stopper		62	124.00
6	4 pcs	Tailgate Hinges			172.00
7	1 pc	Tailgate Sticker DYNA			68.00
8	1 pc	Tailgate Sticker 1500kg			166.00
9	1 pc	Tailgate Lower Cross Member		83	83.00
10	2 pcs	Tailgate Lower Cross Member Reflectors			494.40
11	1 pc	Rear Number Plate Base Bracket		139	139.00
12	2 pcs	Taillamps		52	104.00
13	2 pcs	Taillamps Base			325.20
14	2 pcs	Taillamps Bottom Reflectors			182.20
15	1 pc	Spare Tyre Carrier			513.50
16	1 pc	Spare Tyre Carrier Bracket			184.40
17	1 pc	Rear Exhaust Pipe			612.00
18	2 pcs	Rear Exhaust Mountings			515.10
19	1 pc	Rear Exhaust Mountings Bracket			100.90
20	1 pc	Rear Chassis Frame Center Cross Member			85.10
21	1 pc	Rear Side Gate Bottom Cross Member LH			92.00
22	1 pc	Rear Mudguard LH (Rear)			212.00
23	1 pc	Rear Mudguard LH Bracket (Rear)			251.50
24	1 pc	Rear Mudflap LH			125.00
25	1 pc	Rear Step Bracket			
26	1 pc	Rear Side Luggage Box LH			
27	1 pc	Rear Side Luggage Box Bracket LH			

Special Nett

1	1 pc	Tailgate Top Cover Plate		350.00
2	1 pc	Tailgate Sticker 70km/h		15.00
3	1 pc	Tailgate Sticker 13pax		15.00
4	1 pc	Rear Number Plate		50.00

C/F




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC4/AXA16009822/M1zb3	
8 SHENTON WAY #27-01SINGAPORE 068811		Date : 27-05-2016	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJZ 2921Z	Veh. Inspected	GBE 7891Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/05/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/05/2016	Inspection Date	27/05/2016
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBE 7891Z
Vehicle Model : TOYOTA DYNA
Accident Date : 25.05.2016
Original Reg Date : 24.03.2016

Date : 26.05.2016
Chassis : KDY2318023417
TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate	✓		
2	2 pcs	Tailgate Side Lock	NS ✓		
3	2 pcs	Tailgate Side Lock Bracket	NS ✓		
4	2 pcs	Tailgate Side Lock Lower Bracket	NS ✓		
5	2 pcs	Tailgate Side Stopper	✓		
6	4 pcs	Tailgate Hinges	✓		
7	1 pc	Tailgate Sticker DYNA	✓		
8	1 pc	Tailgate Sticker 1500kg	NS ✓		
9	1 pc	Tailgate Lower Cross Member	R ✓		
10	2 pcs	Tailgate Lower Cross Member Reflectors	✓		
11	1 pc	Rear Number Plate Base Bracket	NS ✓		
12	2 pcs	Taillamps	NS ✓		
13	2 pcs	Taillamps Base	NS ✓		
14	2 pcs	Taillamps Bottom Reflectors	NS ✓		
15	1 pc	Spare Tyre Carrier	?		
16	1 pc	Spare Tyre Carrier Bracket	?		
17	1 pc	Rear Exhaust Pipe	✓		
18	2 pcs	Rear Exhaust Mountings	✓		
19	1 pc	Rear Exhaust Mountings Bracket	✓		
20	1 pc	Rear Chassis Frame Center Cross Member	✓		
21	1 pc	Rear Side Gate Bottom Cross Member LH	R ✓		
22	1 pc	Rear Mudguard LH (Rear)	12. ✓		
23	1 pc	Rear Mudguard LH Bracket (Rear)	R ✓		
24	1 pc	Rear Mudflap LH	NS ✓		
25	1 pc	Rear Step Bracket	NS ✓		
26	1 pc	Rear Side Luggage Box LH	✓		
27	1 pc	Rear Side Luggage Box Bracket LH	✓		

Special Nett

1	1 pc	Tailgate Top Cover Plate		350.00	250
2	1 pc	Tailgate Sticker 70km/h		15.00	
3	1 pc	Tailgate Sticker 13pax		15.00	
4	1 pc	Rear Number Plate		50.00	40 dis.

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBE 7891Z

B/F

Labour charge

Panel Beating		1,200.00	800
Spray painting		1,000.00	800
Check Wiring		40.00	30
Anti rust		100.00	40
Remove and install rear exhaust silencer.		120.00	X

Not Buthon
45 Days
After paint Photo
Ltk Auto (M)
27/6/2016 1200hrs
6-7 days

Poh Kin (LKKAuto)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Monday, 25 March 2019 4:29 PM
To: Poh Kin (LKKAuto)
Cc: Admin A
Subject: Re: RTA involving vehicle nos. SJZ 2921Z and GBE 7891Z on 25.05.2016 - TP AXA

WITHOUT PREJUDICE

Dear Poh Kin,

Agree on your offer \$ 4700

Kindly arrange DV to us.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk B #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Mon, 25 Mar 2019 at 08:40, Poh Kin (LKKAuto) <pohkin@lkkauto.com> wrote:

"Without Prejudice"

"Save As To Costs"

Our Ref: CC4/AXA16009822/M1fb3

Your Ref: GEB 7891Z

Dear Sir/Madam,

We refer to the above matter.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 25 March 2019 8:41 AM
To: 'Chia Sin Muk'
Cc: Admin A
Subject: RE: RTA involving vehicle nos. SJZ 2921Z and GBE 7891Z on 25.05.2016 - TP AXA

Importance: High

"Without Prejudice"

"Save As To Costs"

Our Ref: CC4/AXA16009822/M1fb3
Your Ref: GEB 7891Z

Dear Sir/Madam,

We refer to the above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer at global sum of **\$ 4,700.00(all in)**:

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Chia Sin Muk [mailto:em1autopteltd@gmail.com]

Sent: Monday, 21 January 2019 10:32 AM

Print Received Message

This mail is associated with :

***GBE7891Z (C0385201)**

[SJZ2921Z]

TP

EM-1 AUTO PTE LTD

May 25 2016 10:00AM

[TAN PEI LING BERNADETTE]

Em-1 Auto Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 22/03/2019 13:58 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4713.95) - GBE7891Z - Claim Handler: Richard Ang

Approved:4713.95.

Print Sent Message

This mail is associated with :

***GBE7891Z (C0385201)**

[SJZ2921Z]

TP

EM-1 AUTO PTE LTD

May 25 2016 10:00AM

[TAN PEI LING BERNADETTE]

Em-1 Auto Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 15/03/2019 16:39 PM.
To richard.angbs@axa.com.sg
CC AXA_SG; pohkin@lkkauto.com; admin-a@lkkauto.com
Subject <Seek Mandate> (C0385201)

Our Ref: CC4/AXA16009822/M1fb3
Your Ref: **C0385201**

Dear Richard,

Liability: Insured collided into the rear of third party vehicle. Liability is down against our insured.

We did clarify with OI (Ms Tan) the nature of the accident and she agree to settle and aware that NCD (if any) is affected.

Immediate Advice (with mandate) have been uploaded in Merimen. We hereby seek your approval to offer Third Party repairer M/s "EM-1 Auto Pte Ltd" is as follows: -

1) COR(w/gst): \$4,258.60 + 2) Loss of Rental (3daysx\$150.00: \$450.00 +3) LTA: 5.35 =Total: **\$4,713.95.**

**06days recommendation for repair.

**All the relevant documents had been uploaded in Merimen.

For your approval/Instruction please. PohKin - 15/03/2019

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/03/2019

Survey Details:

Date of loss	25-May-16
Date of appointment	27-May-16
Date of survey	27-May-16
Location of survey	EM-1 AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	GBE 7891Z
Make and Model	TOYOTA DYNA 3.0 DIESEL TURBO - 2982CC
Date of registration	24/3/2016
Excess	
Market Value	\$79,000
Part Rebate	\$26,100
Nett Loss	\$52,900

Repair details:

Initial Estimate	\$ 10,743.70
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,305.45	list price -20%
Check items (estimate)	\$ -	
Labour	\$ 1,670.00	
Total (I/B/I)	\$ 4,975.45	
Lump Sum(if applicable)	\$ 3,980.00	after -20%

Number of days for repair	6
---------------------------	---

Poh Kin (LKKAuto)

Subject: FW: LOD - GBE 7891Z DOA 25.05.2016 - TP AXA
Attachments: 7891-29082018134740.pdf

----- Forwarded message -----

From: **Chia Sin Muk** <em1autopteltd@gmail.com>
Date: Mon, 14 Jan 2019 at 13:15
Subject: Fwd: LOD - GBE 7891Z DOA 25.05.2016 - TP AXA
To: Team A <admin-a@lkkauto.com>

WITHOUT PREJUDICE

Dear Sir/Madam,

Please find the attached LOD.

COR \$ 4,258.60
LTA \$ 5.35
LOR \$ 450.00
Total : \$ 4,713.95

Kindly arrange for settlement.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk B #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.



Auto
Consultants
Pte Ltd

51 CUBA AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

27 July 2016

TAN PEI LING BERNADETTE
Blk 196 Bishan Street 13
#08-563
Singapore 570196

Dear Sir/Madam,

OUR REF : CC4/AXA16009822/M1zb3
YOUR REF : SJZ 2921Z

**ACCIDENT INVOLVING SJZ 2921Z AND GBE 7891Z ALONG / AYE LORNIE RD
BEFORE PIE TURNING ON 25/5/2016**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **M/s EM-1 AUTO PTE LTD** acting on behalf of the owner of **GBE 7891Z** against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties (front-to-rear collision) where you had hit third-party vehicle from the rear, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to zayyer@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2409 or email us at zayer@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Zayer
LKK Auto Consultants Pte Ltd

Cc *AXA Insurance Singapore Pte Ltd
(Motor Claims Dept)*

LETTER OF AUTHORISATION

ACCIDENT INVOLVING (any vehicle) GBE78912 and SJ229812,
ON 25/5/16 ALONG Lorne Rd towards Queensway

I, Pin Dewor, NRIC No. / Company Reg. No.
52843218D of (address) _____

Postal Code _____, the registered owner (or authorised agent) of motor vehicle registration number
GBE78912 hereby authorize your workshop EM-1 Auto Pte Ltd (Company/GST REG.No. : 201316380R)

Blk 8 #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(ies) responsible for the accident.
3. To instruct EM-1 Auto Pte Ltd on my/our behalf to negotiate a settlement with the third party and/ or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto Pte Ltd by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.

I authorize you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorize you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto Pte Ltd, and should I get approval from EM-1 Auto Pte Ltd to bank in the said cheques, I agree to pay EM-1 Auto Pte Ltd the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto Pte Ltd or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto Pte Ltd or the Repairer.

Signature: _____

Company Stamp:
(if applicable)



Name: _____

NRIC No: _____

Contact No: _____

Date: _____

Yang Yony Dorp

G6947777L

87821829

25/5/16



Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJZ 2001Z (Insd veh)	Model: Toyota GYNA - 3.00
	QBE 7801Z (TP veh)	
Date of Accident/ Time:	25/05/2016	

Repair Estimate	\$	10,743.70	
Final Repair Cost	\$	4,258.00	(\$3,980.00 + 7%gst)
Loss of Use	\$	N/A	days at \$ per day
Rental (if any)	\$	400.00	3 days at \$ 150.00 per day
LT / GIA Search Fee	\$	5.35	
Others:	\$	N/A	
	\$	N/A	
Final Settlement Sum	\$	4,700.00	

Payee Name : EM-1 Auto Pte Ltd

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability: [0.00] (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: [0.00] (%)	Assessed Liability (*): [0.00] (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 Signature of workshop representative / Workshop stamp Name of Representative: Chin Sin Muk Date: 7/5/19	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: Chang Mee Choo Date: 7/5/19
 Signature of AXA's surveyor/representative: Name of AXA's surveyor/representative: MCF Date: 7/5/2019	

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

TAX INVOICE

M/S PIN DECOR

Invoice No : 19/00135/4593TP

Date : 29-Mar-2019

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Date of Accident : 25-May-2016
Our Client's Vehicle Number : GBE 7891Z
Vehicle Make / Model : TOYOTA DYNA
Your Insurer : SJZ 2921Z

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (REcommended by LKK Mr Ma)	3,980.00	278.60	4,258.60 SR

SGD (Four Thousand Two Hundred Fifty-Eight And
Cents Sixty only)

GRAND TOTAL

4,258.60

Subject to 7% GST

278.60



Authorised Signature and Company Stamp

B 萬豐利汽車服務

BAN HONG LEE MOTOR SERVICES

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000
Reg. No: 26310200M
TOWING SERVICE: 9182 8211 (After 10.30pm)

Truck Rental
Motor Repair
Motor Insurance Claims
Insurance Agent
Dealer In Used Car
Authorised Carpool Service Centre

車及貨車出租
汽車修理
保險賠償
代售保險
買賣汽車
輪胎及零件

GBE 78917



車輛出租合同

VEHICLE RENTAL AGREEMENT

Date: 26/5/16
Owner: BAN HONG LEE MOTOR SERVICES ("the owner")
Hirer: Pin Decor
Address: 3018 Bedok North St 5 #05-40 EastLink S'486132
NRIC / Co. Reg. No: 5284318D
Tel: _____ Fax: _____ H/P: _____

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: YJ1963R		Agreement No.: 135783	
Driver's Particulars			
Name: Yang Yorp Dong		Odometer: _____	
Address: Blk 27 Upper Changi Rd #13-678		Date & Time Out: 26/5/16 1010	
		Date & Time In: 28/5/16 1517	
V/C No: G6947797L	Dr/Licence No: G6947797L	Hour @\$ _____	
Date of Issue: 21/2/12	Occupation: _____	3 Days @\$ 150/-	
Date of Birth: 27/12/76	Tools: Ulw set Spare Tyre: another set	Wks @\$ _____	
		Mths @\$ _____	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive), Hirer unconditionally agrees to pay Owner S\$ _____ comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$ 3000/- excess for collision/damage to first party, (i.e.) BAN HONG LEE MOTOR SERVICES (including windscreen) plus loss of earning while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable): _____

Sub-Total: _____

Balance To Pay: 8450/-



PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

BAN HONG LEE MOTOR SERVICES

Authorised Signature



Hirer's Signature



GRE 7/9/12

Text size + -



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 26 May 2016 / 10:01:02

Receipt Date/Time : 26 May 2016 / 10:01:02

Tax Invoice/Receipt

Receipt No. : ITNET-00000-160526-000343

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SJZ2921Z
As at 25 May 2016/10:00:00
Insurance Co: AXA INSURANCE SINGAPORE PTE LTD

1 Insurance Enquiry - SJZ2921Z Enquiry Fee 20160526095911921665	5.00	0.35	5.35
Sub-Total	5.00	0.35	5.35
Total Before Rounding	5.00	0.35	5.35
Rounding Difference			0.00
Total Amount Payable			5.35
Paid By			
20160526095949750	Direct Debit: eNETS Debit (Internet Banking)		5.35
Total			5.35
Cash Change			0.00
Tendered Amount			5.35
Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 May 2016		27 May 2016 14:30 Edit Adj Rpt	S\$3,980.00 Edit Estimates	S\$3,980.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	TAN PEI LING BERNADETTE, ID: S71262181, Tel: +6591773127, Email: bernadette.pl@gmail.com		
Main Claimant:	PIN DECOR, Co. Reg. No.: 52843218D		
Vehicle Reg. No.:	GBE7891Z	Date of Loss:	25/05/2016 10:00 - :59 [2 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0385201	Policy/Cover Note No.:	GA050042 (Comprehensive)
Vehicle Reg. No. (Insured):	SJZ2921Z	Policy No. (Claimant):	5078668886
		Excess:	S\$0.00
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Richard Ang]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 07/06/2016]		
Driver/Custodian (Insured):	TAN PEI LING BERNADETTE (44 / Female), NRIC: S71262181, Tel: +6591773127 Email: bernadette.pl@gmail.com		
Adj Asg. Remarks:	XS NIL		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (22/03/2019): Alert - Adj Mandate Approved (S\$4713.95) - GBE7891Z - Claim Handler: Richard Ang
- AXA_SG (21/07/2017): Re: Direct Settlement - Accident Involving SJZ2921Z (OI : AXA - C0385201) and GB...
- AXA_SG (27/05/2016): New TP Assignment - C0385201/GA050042

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE7891Z (C0385201)
[SJZ2921Z]
TP
PIN DECOR
May 25 2016 10:00AM
[TAN PEI LING BERNADETTE]
Em-1 Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
2	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
3	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
4	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
5	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
6	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
7	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
8	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
9	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
10	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
11	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
12	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
13	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
14	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
15	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
16	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
17	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
18	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
19	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
20	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
21	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
22	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
23	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
24	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
25	27/05/16 18:00	General View							Load JPG	<input checked="" type="checkbox"/>	
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)						Thumbnail	Print		
1	26/05/16 12:45	Email_ABS							Load PDF		
2	26/05/16 12:45	Co claimant_ABS							Load PDF		
3	26/05/16 12:45	SJZ2921Z INSD GIA Report_ABS							Load PDF		
4	27/05/16 14:07	E-filed GIA report - INSD SJZ2921Z							Load PDF		
5	27/05/16 14:07	E-filed GIA report - TP							Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	30/05/16 15:07	TP ESTIMATE- MARKED							Load PDF		
2	29/08/18 10:51	LKK RESURVEY PHOTO							Load PDF		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	29/08/18 10:51	LKK SURVEY PHOTO	Load PDF	
4	15/03/19 16:32	LETTER TO OI	Load PDF	
5	15/03/19 16:33	Immediate Advice (with mandate) dated 15.03.2019	Load PDF	
6	15/03/19 16:33	PRAF and COE rebate form	Load PDF	
7	15/03/19 16:33	TP estimate- Marked - revise	Load PDF	
8	15/05/19 11:29	RENTAL RECEIPT	Load PDF	
9	15/05/19 11:29	WORKSHOP INVOICE	Load PDF	
10	15/05/19 11:29	AUTHORISATION TO ACT FORM	Load PDF	
11	15/05/19 11:29	LTA SEARCH	Load PDF	
12	15/05/19 11:29	DS FORM	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJZ2921Z (Insd veh)	Model:	TOYOTA DYNA 350 3.0 D (M)
	GBE7891Z (TP veh)		
Date of Accident:	25/05/2016		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X]	Yes	<input type="checkbox"/> []	No	
Repair Estimate	:	\$			11,495.76	
Final Repair Cost	:	\$			4,258.60	
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$			450.00	3 days
LTA / GIA Search Fee	:	\$			5.35	
Others:	:	\$			0.00	
	:	\$				
Final Settlement Sum (Global Sum)	:	\$			4,700.00	

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Pte Ltd	: \$	4,700.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

15 May
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16009822/M1FB3Q2

Date: 15/05/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA050042

Claimant Vehicle No : GBE7891Z

Insured Vehicle No :

SJZ2921Z

Date of Loss: 25/05/2016

Nature of Claim:

TP

Claim No: C0385201

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE7891Z

Make & Model: TOYOTA DYNA 350, 3.0 D (M)

Engine No: 1KD2586794

Reg. Date: 24/03/2016 (Man. Year: 2016)

Chassis No: KDY2318023417

Colour: White

Odometer: 2363 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/75 R15

Rear Tyre Size:

145 R13

Front Left Side: Bridgestone 8 mm

Rear Left Side:

Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side:

Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,283.70	3,305.45	4,978.25	60.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,670.00	790.00	32.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,743.70	4,975.45	5,768.25	53.69
Approved Total (Overridden) (S\$)		3,980.00		
(S\$)	10,743.70	3,980.00	6,763.70	62.96
+ GST 7.00/7.00% (S\$)	752.06	278.60	473.46	62.96
Nett Amount (S\$)	11,495.76	4,258.60	7,237.16	62.96
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		4,713.95		
Global Sum Settlement (S\$)		4,700.00		

INSPECTION

Date of Assignment: 27/05/2016

Date Inspected: 27/05/2016 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,
#01-68
Singapore 575643

Estimated Period of Repair: 6.0 days

Adjuster: MA CHIN FOOK

Manager: Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 May 2019)	
Parts:	N/A	TOYOTA DYNA 350 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE7891Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (CONSISTENT)	Bent	1,311.10 F	*1,311.10 FL
2	1		*TAILGATE SIDE LOCK (CONSISTENT)	N/S Bent	104.00 F	*52.00 FL
3	1		*TAILGATE SIDE LOCK BRACKET (CONSISTENT)	N/S Bent	196.20 F	*98.10 FL
4	1		*TAILGATE SIDE LOCK LOWER BRACKET (CONSISTENT)	N/S Bent	224.80 F	*112.40 FL
5	2		*TAILGATE SIDE STOPPER (CONSISTENT)	Not Necessary	92.00 F	*- FL
6	4		*TAILGATE HINGES (CONSISTENT)	Bent	248.00 F	*248.00 FL
7	1		*TAILGATE STICKER DYNA (CONSISTENT)	Necessary	57.10 F	*57.10 FL
8	1		*TAILGATE STICKER 1500KG (CONSISTENT)	Necessary	72.00 F	*72.00 FL
9	1		*TAILGATE LOWER CROSS MEMBER (CONSISTENT)	Repair	687.00 F	*- FL
10	2		*TAILGATE LOWER CROSS MEMBER REFLECTORS (CONSISTENT)	Cracked	166.00 F	*166.00 FL
11	1		*REAR NUMBER PLATE BASE BRACKET (CONSISTENT)	Bent	89.50 F	*89.50 FL
12	1		*TAILLAMPS (CONSISTENT)	N/S Cracked	497.40 F	*248.70 FL
13	1		*TAILLAMPS BASE (CONSISTENT)	N/S Cracked	278.00 F	*139.00 FL
14	1		*TAILLAMPS BOTTOM REFLECTORS (CONSISTENT)	N/S Cracked	104.00 F	*52.00 FL
15	1		*SPARE TYRE CARRIER (CONSISTENT)	Not Necessary	325.20 F	*- FL
16	1		*SPARE TYRE CARRIER BRACKET (CONSISTENT)	Not Necessary	132.20 F	*- FL
17	1		*REAR EXHAUST PIPE (CONSISTENT)	Not Necessary	513.50 F	*- FL
18	2		*REAR EXHAUST MOUNTINGS (CONSISTENT)	Not Necessary	154.40 F	*- FL
19	1		*REAR EXHAUST MOUNTINGS BRACKET (CONSISTENT)	Not Necessary	61.50 F	*- FL
20	1		*REAR CHASSIS FRAME CENTER CROSS MEMBER (CONSISTENT)	Distorted	612.00 F	*612.00 FL
21	1		*REAR SIDE GATE BOTTOM CROSS MEMBER LH (CONSISTENT)	Repair	875.10 F	*- FL
22	1		*REAR MUDGUARD LH (REAR) (CONSISTENT)	Repair	152.90 F	*- FL
23	1		*REAR MUDGUARD LH BRACKET (REAR) (CONSISTENT)	Repair	85.10 F	*- FL
24	1		*REAR MUDFLAP LH (CONSISTENT)	Serviceable	92.00 F	*- FL
25	1		*REAR STEP BRACKET (CONSISTENT)	Bent	212.00 F	*212.00 FL
26	1		*REAR SIDE LUGGAGE BOX LH (CONSISTENT)	Buckled	385.70 F	*385.70 FL
27	1		*REAR SIDE LUGGAGE BOX BRACKET LH (CONSISTENT)	Bent	125.00 F	*125.00 FL
28	1		*TAILGATE TOP COVER PLATE (CONSISTENT)	Bent	350.00 FS	*250.00 FS
29	1		*TAILGATE STICKER 70KM/H (CONSISTENT)	Necessary	15.00 FS	*15.00 FS
30	1		*TAILGATE STICKER 13 PAX (CONSISTENT)	Necessary	15.00 FS	*15.00 FS
31	1		*REAR NUMBER PLATE (CONSISTENT)	Distorted	50.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					8,283.70	4,300.60
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	995.15
Total Parts (\$\$)					8,283.70	3,305.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	CHECK WIRING	New	40.00	30.00
4	ANTI RUST	New	100.00	40.00
5	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (\$\$)			2,460.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >