

22/03/2002

ASS. REC. BY:

REF:

08/III16010381/Gtb 02

Special Instruction:

Surveyor:

Ang Chung

**ASSIGNMENT (Office)**

From (Person):

Isabelle Tan

of

Jill

Date/Time:

06062016 210pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN 1589E

Insured:

SHA 7091R

at Workshop m/s

L Soon Auto

Tel:

0482 1513

of

Blk 10 Nank Ind Park CA #03-18

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02062016

CA / REV / REP. / REV 24 HRS "wp"

H.O.D. Endorsement:

Date/Time:

06062016 232pm

Person Contacted:

m/s: Lee

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGN 1589E - X

SHA 7091R - 03 / ATB 16008731 / H12b3

DIA: 030616

8/11/13

AE 3. REC. BY: YKA

REF: III

# ASSIGNMENT

(2016)

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s L Soon

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$18K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 70 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGN1589E Yr Regn: 09 Nov 2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota wish c.c. 1794

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 198475 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 7NE100331561

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. \_\_\_\_\_ D.O.I. 06-06-16

Survey held at W/S 4:10pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>06/6</u>	<u>Estimate will give later</u>
	<u>Submit</u> <u>US \$2000</u> (Red: 6839.23 : 75%)
	<u>70%</u>
	RECEIVED 30 MAY 2018

Date/Time, File Pass to?

☐

Prel. Report

☒

Final Report

1) 30/5 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

250

10

260

Report Format: TP

Lump Sum / I.B.I: (\$ 2200)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III16010381/Gvb

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 06-06-2016



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7091R	Veh. Inspected	SGN 1589E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	ISABELLE TAN	Assign Date	06/06/2016

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	02/06/2016	Inspection Date	06/06/2016
Survey held at	L SOON AUTO SERVICES 10 ANG MO KIO INDUSTRIAL PARK 2A #03-18 AMK AUTO POINT SINGAPORE 568407		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Catherine Chong (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Monday, 6 June, 2016 2:10 PM  
**To:** 'yvonnelim@visionlawllc.com'  
**Cc:** Adeline Tham; Roger Yap; Zuhaidah Samsuri; assignments@lkkauto.com  
**Subject:** RE: Accdt Inv SHA7091R (III) & SGN1589E on 02.06.2016  
**Attachments:** SHA7091R SGN1589E Vision law llc.pdf; SGN1589E LOCATION.pdf

Dear Sir/Mdm,

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO : SGN1589E

III INSURED VEHICLE NO. : SHA7091R

DATE OF LOSS : 02.06.2016

We acknowledge receipt of your letter dated 03.06.2016

Our insured has reported the above accident to us.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

-You have agreed to the appointment of our surveyor.

Therefore, we have appointed our surveyor **LKK Auto Consultants** to conduct the pre-repair survey.

This claim is handled by Ms Aida

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

**Thank You.**

Isabelle Tan  
Motor Claims Department  
India International Insurance Pte Ltd  
64 Cecil Street #04/#05 IOB Building  
Singapore 049711  
Tel : 63476100, Ext-243, Fax : 62244174  
E-mail: isabelle@iii.com.sg

---

**From:** Motor Claim - III  
**Sent:** Friday, June 03, 2016 2:19 PM  
**To:** 'yvonnelim@visionlawllc.com' <yvonnelim@visionlawllc.com>  
**Cc:** Adeline Tham <adelinetham@iii.com.sg>; Roger Yap <Roger@iii.com.sg>  
**Subject:** Accdt Inv SHA7091R (III) & SGN1589E on 02.06.2016

Dear Sir/Mdm,

We acknowledge receipt of your letter dated [03.06.2016] and the enclosures on [03.06.2016].

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Isabelle Tan  
Motor Claims Department  
India International Insurance Pte Ltd  
64 Cecil Street #04/#05 IOB Building  
Singapore 049711  
Tel : 63476100, Ext-243, Fax : 62244174  
E-mail: [isabelle@iii.com.sg](mailto:isabelle@iii.com.sg)

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Text size + -

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 5058F

**Vehicle Details**

Vehicle No.: SGN1589E

Vehicle to be Exported: No

Intended De-registration  
Date: 07 Jun 2016

Vehicle Make: TOYOTA

Vehicle Model: WISH 1.8 A

Primary Colour: Blue

Manufacturing Year: 2006

Engine No.: 1ZZ2722141

Chassis No.: ZNE100331561

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$19,142.00

Original Registration  
Date: 09 Nov 2006

First Registration Date: 09 Nov 2006

Transfer Count: 0

Actual ARF Paid: \$21,057.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry  
Date: 08 Nov 2016

PARF Rebate Amount: \$10,528.00

**Intended COE Rebate Details**

COE Expiry Date: 08 Nov 2016

COE Category: B - Car (1601cc &amp; above)

COE Period(Years): 10

QP Paid: \$13,811.00

COE Rebate Amount: \$579.00

**Total Rebate Amount: \$11,107.00**

The information contained herein is correct as at 07 Jun 2016

OK

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/06/2016 10:59
Date Of Accident	02/06/2016 21:30
Exact Location Of Accident	SLIP RD FROM CTE TOWARDS ANG MO KIO
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN1589E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WONG AH KUM
NRIC No	S0545058F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97474547
Alternative Phone No	Office-97278890

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

### Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5017263503-09 (CLASSIC)
Cover Note Number	

### Driver

Name of Driver	WONG HENG LOCK
NRIC No	S8217641A
Date Of Birth	06/08/1962
Occupation	Indoor
Date Of Driving Pass	21/10/2002
Driving Experience	13 Years And 7 Months
Gender	Male
Mobile Number	(Local) +65-83281616
Fax Number	
Contact Number	Office-97474547
Email Address	NOEMAIL

Address	15 CATCUS CRESCENT
Postcode	S809749
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Children
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	Unknown - REFER TO SKETCH PLAN
Weather Conditions	Clear
Road Surface	Dry

#### Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN. ATTENDED BY : SUSAN

Are accident photos available for attachment?	Yes
---	-----

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7091R
Vehicle Make/Model/Colour	TAXI
Details Of Properties	
Name of Driver	LAW HWA THIAM
NRIC/Passport Number	
Contact Number	97886246
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	



3 Jun. 2016 10:51


No. 8967 P. 3


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorised Driver.
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
  8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

IVAC BUKIT BATOK (VAC)  
 511 Bukit Batok St 23  
 Singapore 650545  
 Tel: 6567 9427 / 6560 3312  
 Fax: 6569 0722  
 Email: vacbb@singnet.com.sg


- 3 JUN 2016

  
 Policyholder's Signature / Date & Time

  
 Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



3. Jun. 2016 10:51

No. 8967 P. 2

Describe Circumstances of the Accident

On this date ( 02.06.2016 ) at about ( 09 : 30 pm ) I was/had ( driving / riding / reversing / parked )

My vehicle registration number: (SN 1589 E) All Along (172 Towards) Aug 10/10/10 All Slip Road

- Exiting CTE Ang Mo Kio Ave S slip road towards ITE.
- Stopped at STOP SIGN to give way to oncoming traffic
- Condot Taxi did not observe that my car was stopped / not moving and knocked into the back of my car

↳ SHA 7091 R

- Both cars stopped by roadside to exchange particulars & details

### Declaration

I/We declare the foregoing particulars are true in every respect.

Wsh-

Policyholder's Signature / Date &  
Time



Driver's Signature (If driver is not the policyholder) Date  
& Time

**IDAC BUKIT BATOK (VAC)**  
511 Bukit Belok St 23  
Singapore 659545  
Tel: 6537 9427 / 6560 3312  
Fax: 6569 0722  
Email: vacbb@singnet.com.sg

Witnessed by Reporting Centre  
Personnel

1800  
L S  
w/p.

**L Soon Auto Services**  
No.10 Ang Mo Kio Industrial Park 2A  
#03-18 Ang Mo Kio Auto Point  
Singapore 568047  
Tel: 6482 1513 Fax: 6556 2590

Ang Mo Kio  
CS/11160381/416  
Denise / Kuo Qiang

## SGN1589E Toyota Wish

Qty			Part Description	Unit Price	Part Price
1	1		Rear bumper assy	\$ 859.20	def ✓
2	2		Rear bumper bracket	\$ 80.30	ht ✓
3	2		Rear bumper side retainer	\$ 88.60	ht ✓
4	2		Rear bumper reflector	\$ 125.60	nec ✓
5	1		Rear tailgate assy	\$ 1,476.90	RX
6	1		Rear tailgate lock mechanism	\$ 215.20	RX
7	1		Rear tailgate lock catch	\$ 65.60	ht
8	1		Rear tailgate lock switch	\$ 179.00	SVC ✓
9	1		Rear tailgate centre logo	\$ 48.90	NN ✓
10	1		Rear tailgate weatherstrip	\$ 186.30	NN ✓
11	2		Rear tailgate rubber stopper	\$ 36.00	NN ✓
12	2		Rear tailgate hinges	\$ 87.20	NN ✓
13	2		Rear tailgate damper	\$ 262.20	NN ✓
14	1		Rear tailgate windscreen moulding	\$ 188.00	NN ✓
15	1		Rear left taillamp	\$ 698.20	SVC ✓
16	1		Rear right taillamp	\$ 698.20	ht ✓
17	1		Rear right fender inner garnish	\$ 425.10	SVC ✓
18	1		Rear right air duct ventilator	\$ 110.40	SVC ✓
19	1		Rear end lower panel	\$ 527.30	RX
20	1		Rear end lower panel inner garnish	\$ 226.80	SVC ✓
21	1		Rear end lower panel top garnish	\$ 128.60	SVC ✓
22	1		Rear spare tyre lock holder	\$ 326.50	RX
23	1		Rear exhaust muffler assy	\$ 882.30	RX
24	2		Rear exhaust muffler rubber mounting	\$ 36.80	SVC ✓
25	1		Rear exhaust muffler heat shield	\$ 173.10	SVC ✓

\$ 8,132.30

Less 25%

\$ 2,033.08

\$ 6,099.23

Special Nett Items

1	10	Rear bumper clips	\$ 50.00	Nec ✓
2	1	Rear tailgate windscreen sealant	\$ 80.00	NN ✓
3	8	Rear right fender inner garnish clips	\$ 30.00	NN ✓
4	1	Rear end lower panel sealant	\$ 120.00	NN ✓
5	6	Rear end lower panel inner garnish clips	\$ 20.00	Nec ✓
6	4	Rear end lower panel top garnish clips	\$ 20.00	Nec ✓
7	2	Rear bumper reverse sensor	\$ 250.00	Nec ✓
8	1	Rear no plate with garnish	\$ 80.00	NN ✓
			\$ 650.00	

**Total Parts****\$ 6,749.23**

**L Soon Auto Services**  
**No.10 Ang Mo Kio Industrial Park 2A**  
**#03-18 Ang Mo Kio Auto Point**  
**Singapore 568047**

**SGN1589E Toyota Wish**

No	Description	Labour Charge	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 800.00	400
2	To putty and spray painting rear portion.	\$ 800.00	500
3	To check rear lighting and wiring.	\$ 50.00	30
4	To apply anti rust proofing to rear affected area.	\$ 120.00	NNX
5	To remove and install rear tailgate lock mechanism.	\$ 80.00	NN +
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 120.00	60
7	To remove and install rear exhaust muffler.	\$ 100.00	NN +
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50.
9	To remove and install rear windscreen to facilitate the repair.	\$ 140.00	NNX
<b>Total labour :</b>		<b>\$ 2,290.00</b>	

**Total parts : \$ 6,749.23**

**Total labour : \$ 2,290.00**

**Total repair cost : \$ 9,039.23**

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III16010381/GTBN2

Date: 30/05/2018

## REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SGN1589E	Insured Vehicle No :	SHA7091R
Date of Loss:	02/06/2016	Nature of Claim:	TP
		Claim No:	N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGN1589E	Engine No:	1ZZ2722141
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100331561
Reg. Date:	09/11/2006 (Man. Year: 2006)	Odometer:	198475 km
Colour:	Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,749.22	1,728.92	5,020.30	74.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,040.00	1,250.00	54.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,039.22</b>	<b>2,768.92</b>	<b>6,270.30</b>	<b>69.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,039.22</b>	<b>2,200.00</b>	<b>6,839.22</b>	<b>75.66</b>

## INSPECTION

Date of Assignment:	06/06/2016	
Date Inspected:	06/06/2016 Inspected At:	L Soon Auto Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-18 AMK Auto Point Singapore 568407
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 30 May 2018)	
<b>Parts:</b>	N/A	TOYOTA WISH 1.8 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGN1589E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER ASSY	Deformed	859.20 FL	*859.20 FL
2	2	*REAR BUMPER BRACKET	Bent	80.30 FL	*80.30 FL
3	2	*REAR BUMPER SIDE RETAINER	Bent	88.60 FL	*88.60 FL
4	2	*REAR BUMPER REFLECTOR	Necessary	125.60 FL	*125.60 FL
5	1	*REAR TAILGATE ASSY	Repair	1,476.90 FL	*- FL
6	1	*REAR TAILGATE LOCK MECHANISM	Repair	215.20 FL	*- FL
7	1	*REAR TAILGATE LOCK CATCH	Repair	65.60 FL	*- FL
8	1	*REAR TAILGATE LOCK SWITCH	Serviceable	179.00 FL	*- FL
9	1	*REAR TAILGATE CENTRE LOGO	Not Necessary	48.90 FL	*- FL
10	1	*REAR TAILGATE WEATHERSTRIP	Not Necessary	186.30 FL	*- FL
11	2	*REAR TAILGATE RUBBER STOPPER	Not Necessary	36.00 FL	*- FL
12	2	*REAR TAILGATE HINGES	Not Necessary	87.20 FL	*- FL
13	2	*REAR TAILGATE DAMPER	Not Necessary	262.20 FL	*- FL
14	1	*REAR TAILGATE WINDSCREEN MOULDING	Not Necessary	188.00 FL	*- FL
15	1	*REAR LEFT TAILLAMP	Serviceable	698.20 FL	*- FL
16	1	*REAR RIGHT TAILLAMP	Cracked	698.20 FL	*698.20 FL
17	1	*REAR RIGHT FENDER INNER GARNISH	Serviceable	425.10 FL	*- FL
18	1	*REAR RIGHT AIR DUCT VENTILATOR	Serviceable	110.40 FL	*- FL
19	1	*REAR END LOWER PANEL	Repair	527.30 FL	*- FL
20	1	*REAR END LOWER PANEL INNER GARNISH	Serviceable	226.80 FL	*- FL
21	1	*REAR END LOWER PANEL TOP GARNISH	Serviceable	128.60 FL	*- FL
22	1	*REAR SPARE TYRE LOCK HOLDER	Repair	326.50 FL	*- FL
23	1	*REAR EXHAUST MUFFLER ASSY	Repair	882.30 FL	*- FL
24	2	*REAR EXHAUST MUFFLER RUBBER MOUNTING	Serviceable	36.80 FL	*- FL
25	1	*REAR EXHAUST MUFFLER HEAT SHIELD	Serviceable	173.10 FL	*- FL
26	10	*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
27	1	*REAR TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
28	8	*REAR RIGHT FENDER INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
29	1	*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
30	1	*REAR END LOWER PANEL INNER GARNISH CLIPS (6 Pcs)	Necessary	20.00 FS	*20.00 FS
31	4	*REAR END LOWER PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
32	2	*REAR BUMPER REVERSE SENSOR	Necessary	250.00 FS	*250.00 FS
33	1	*REAR NO PLATE WITH GARNISH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,782.30</b>	<b>2,191.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,033.08</b>	<b>462.98</b>
<b>Total Parts (\$\$)</b>	<b>6,749.22</b>	<b>1,728.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	800.00	400.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	800.00	500.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	-
5	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	-
6	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	120.00	60.00
7	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER	New	100.00	-
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
9	TO REMOVE AND INSTALL REAR WINDSCREEN TO FACILITATE THE REPAIR	New	140.00	-
Gross Labour Cost (\$\$)			2,290.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >