

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHC 5912A - III

Candy

Not Authorised

1.B.1

£ 7124.80

Recovery B4 paint

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5912A - CANDY
 VF1ABL15AUC281432
 RENAULT
 LATITUDE
 04.06.2016
III

PART			LIST	
1	1	FENDER PANEL FRT LH	\$	<i>R</i> 602.95 X
2	1	FENDER WHEELARCH FRT LH (Linner)	\$	<i>Sm</i> 107.33 X
3	1	DOOR FRT LH	\$	<i>Bt</i> 2,188.20 ✓
4	1	DOOR HANDLE OUTER FRT LH	\$	<i>Sm</i> 198.55 X
5	1	DOOR HANDLE COVER FRT LH	\$	<i>Sm</i> 10.17 X
6	1	DOOR MIRROR LH	\$	<i>Sm</i> 1,141.08 X
7	1	DOOR SEAL FRT LH	\$	<i>Sm</i> 52.83 X
8	1	ROCKER PANEL OUTER LH	\$	<i>Bt</i> 759.61 ✓
9	1	DOOR REAR LH	\$	<i>Bt</i> 2,188.20 ✓
10	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sm</i> 97.31 X
11	1	FENDER PANEL REAR LH	\$	<i>R</i> 2,537.80 X
12	1	FENDER WHEELARCH REAR LH (Linner)	\$	<i>Sm</i> 418.06 X
13	1	BUMPER COVER REAR	\$	<i>Bt</i> 852.66 ✓
14	1	BUMPER LOWER REAR	\$	<i>Sm</i> 591.41 X
15	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 33.55 X
16	1	BUMEP R BRACKET SIDE LH REAR(Taillamp lo	\$	<i>Sm</i> 104.59 X
17	1	BUMEP R RETAINER LH REAR	\$	<i>Sm</i> 34.61 X
18	1	TAILLAMP LH	\$	<i>Sm</i> 425.04 X

TOTAL	\$	12,343.94
10%	\$	1,234.39
	\$	11,109.55

Specical Nett

1	1	DOOR STICKER "Trans-cab"	\$	<i>na</i> 80.00 <i>Gas</i>
2	1	DOOR STICKER "Classic"	\$	<i>na</i> 30.00 <i>155m</i>
3	1	DOOR STICKER "6555-3333"	\$	<i>na</i> 80.00 <i>Gas</i>

TOTAL	\$	190.00
TOTAL PARTS	\$	11,299.55

Panel beating, knocking and straightening the
 necessary portion, remove and renewal of
 parts, adjust and realign the same

\$ 2,800.00 *800*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5912A - III**Candy**

To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>11000</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>1200</i>
To rust-proofing of the affected areas.	\$	170.00 <i>600</i>

TOTAL	\$	6,530.00
Over All Total	\$	17,829.55

(PARTS BY PARTS) Repair Days**10 Days***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *before* after spray painting
- To display damaged part(s) during res. if any
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: