

INS. CASE OWNER:

CC 4/AIG1601 0743, AIG 624

LKK:
IDAC:

Surveyor:

Adrian

DOI:

9/6/16

Date / Time:

9/6/16

Registered in Merimen:

10/6/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHH 72162

Name of Insured:

AMH LIMON LAM

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

7/6/16

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

AMH WEL LHOAH

Driver Tel No.:

16048080

(VL: YES / NO)

Claim No.:

903626294956

Policy No.:

100309130

Make / Model:

V81V0

Place of Accident:

SLE TWDS YISIRUN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHH 72162

9KX 3278D

SHL 1428H



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

N-51

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
14/6/16	9KX 3278D - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
7/7/16 @ 5:20	Called OI, no response.	Call OI: 07/09/16	8/7/16
5/7/16 @ 5:19	called OI, not response available.	After call ltr to OI: 08/09/16	
8/7/16 @ 5:20	called OI also no response.	Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		FIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	
21/7/16 @ 4:56	Called OI no response		
" " 4:57	called OI no response.		
24/08/16 @ 10:00	file pass to typist to prepare report.		
10/08/16 @ 9:49	called OI & OI2 both no response.		
07/09/16 @ 11:41AM	called OI for any 096448080. OI2 DOES NOT WANT TO LITIGATE ANYTHING WITH ANY OTHER PARTY EXCEPT WITH HIS INSURANCE CO.		
PRELIN 20-07-17	LIABILITY IS DOWN & SUBJECT TO BOLA CHAIN COLLISION. TO EXPEDITE SETTLEMENT SOONEST POSSIBLE.		
FINALIZATION 20/07/18	TO MONITOR MANDATE APPROVAL	Confirm by:	
Repair Cost:	S\$ 39,500/- (21 days) Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT	Date/Time: 25/10/14 Confirm with: Cabme	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 28	If NO or B 28, Ass. Lia: 100%	
Repair Cost:	S\$ 42,265.00	(3 veh, C.G. OI2 LAST VEH)	
Loss of Rental (LOR):	S\$ 3,780.00 (21 days)		
Loss of Use (LOU):	S\$ - (\$ x days)		
Loss of Income (LOI):	S\$ - (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	S\$ 5.35		
Medical:	S\$		
Disbursement:	S\$ 360.00 2 Trips (e.g. Tow/Independent)		
Legal Cost:	S\$		
Total:	S\$ 46,410.35 Global Sum S\$:		
FINAL PAYMENT	Date/Time: Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	S\$ 46410.35 Name 1: N-51 Automotive Pte Ltd		
Payee 2: (Strike if N.A.)	S\$ Name 2:		
Payee 3: (Strike if N.A.)	S\$ Name 3:		

x pending acceptance.

Surveyor: Adrian

ASSIGNMENT

From: _____ Date: 09-06-2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 3328D

at Workshop m/s N-51 Automotive

of 2 KOKA Bukit Ave 2 #01-18

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKX3328D Yr Regn: 2009, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q5 c.c 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 99605 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8R7AA042491

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45R20

R: 255/45R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 09/06/16

Survey held at N51

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1P AIG.

L/S \$34,500 (Red \$62067.97 G.I.V.)

MV: \$76,000 (est)

1-TPR Rate: \$35,941 (est)

Net Value: \$40,059 (est)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC4/AIG16010743/Ayb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 10-06-2016	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGH 7216Z	Veh. Inspected	SKX 3328D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/06/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/06/2016	Inspection Date	09/06/2016	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

HONG GUANGYUAN

BLK 222 ANG MO KIO AVE 1 #03-711

SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON AUXILLIARY FAN ASSY	1	580.99	580.99 ✗
AIRCON AUXILLIARY FAN HIGH PRESSURE MODULE	1	680.95	680.95 ✗
AIRCON CONDENSER <i>Best</i>	1	817.30	817.30 ✓
AIRCON CONDENSER AIR GUIDE CLIPS L/R	6	6.50	39.00 ✗
AIRCON CONDENSER AIR GUIDE L/R	2	49.77	99.54 ✗
AIRCON COOLING PIPE	1	900.77	900.77 ✗
AIRCON DISCHARGE PIPE	1	799.33	799.33 ✗
AIRCON HIGH PRESSURE SENSOR	1	900.77	900.77 ✗
AIRCON OUTSIDE TEMPERATURE SENSOR	1	200.99	200.99 ✗
AIRCON SUCTION PIPE	1	833.75	833.75 ✗
AUTOTRANSMISSION COOLER <i>Best</i>	1	800.33	800.33 ✓
DRUMPET HORN BRACKET L/R	2	89.77	179.54 ✗
DRUMPET HORN L/R	2	211.99	423.98 ✗
ENGINE LOWER UNDER COVER	1	500.31	500.31 ✗
ENGINE TURBO COOLER	1	300.17	300.17 ✗
ENGINE TURBO COOLER HOSE 'INLET'	1	211.95	211.95 ✗
ENGINE TURBO COOLER HOSE 'OUTLET'	1	260.77	260.77 ✗
FRONT AIR DUCT <i>Hot phr</i>	1	150.33	150.33 ✗

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

FRONT AIR DUCT HOSE	1	140.97	140.97 ✓
FRONT AIR DUCT HOSE CLIPS	2	6.50	13.00 ✓
FRONT AIRBAG IMPACT SENSOR L/R	2	260.97	521.94 ✓
FRONT BONNET	1	2830.97	2,830.97 ✓
FRONT BONNET CABLE	1	140.31	140.31 ✓
FRONT BONNET DAMPER L/R	2	105.70	211.40 ✓
FRONT BONNET HINGES L/R	2	140.97	281.94 ✓
FRONT BONNET INNER LOCK HANDLE	1	90.99	90.99 ✓
FRONT BONNET INSULATOR MAT	1	220.99	220.99 ✓
FRONT BONNET MECHANISM LOCK	1	214.70	214.70 ✓
FRONT BONNET NOZZLE L/R	2	203.77	407.54 ✓
FRONT BONNET RUBBER GUIDE STOPPER L/R	4	29.77	119.08 ✓
FRONT BONNET WEATHER STRIP L/R	2	30.17	60.34 ✓
FRONT BUMPER 'CENTER'	1	170.97	170.97 ✓
FRONT BUMPER FOGLAMP GARNISH L/R	2	135.70	271.40 ✓
FRONT BUMPER FOGLAMP L/R	2	267.70	535.40 ✓
FRONT BUMPER INNER SPONGE	1	140.31	140.31 ✓
FRONT BUMPER L/R	2	850.75	1,701.50 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HONG GUANGYUAN
 BLK 222 ANG MO KIO AVE 1 #03-711
 SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

FRONT BUMPER LOWER DIFFUSER <i>del</i>	1	400.33	400.33 ✓
FRONT BUMPER LOWER RUBBER MOULDING <i>not in</i>	1	100.17	100.17 ✓
FRONT BUMPER LOWER SIDE RETAINER L/R <i>del</i>	2	49.77	99.54 ✓
FRONT BUMPER LOWER UNDER COVER <i>del</i>	1	139.77	139.77 ✓
FRONT BUMPER NOZZLE COVER L/R <i>del</i>	2	50.99	101.98 ✓
FRONT BUMPER NUMBER PLATE SCREW GARNISH L/R	2	20.17	40.34 ✓
FRONT BUMPER PARKING SENSOR 'ORIGINAL'	4	217.77	871.08 ✓
FRONT BUMPER PARKING SENSOR HOLDER	4	49.95	199.80 ✓
FRONT BUMPER PARKING SENSOR RUBBER SEAL	4	7.11	28.44 ✓
FRONT BUMPER PARKING SENSOR WIRE HARNESS - SET <i>del</i>	1	472.80	472.80 ✓
FRONT BUMPER REINFORCEMENT <i>del</i>	1	417.70	417.70 ✓
FRONT BUMPER REINFORCEMENT BRACKET L/R <i>del</i>	2	160.71	321.42 ✓
FRONT BUMPER SIDE RETAINER L/R <i>del</i>	2	50.77	101.54 ✓
FRONT BUMPER TOW HOOK COVER <i>del</i>	1	48.77	48.77 ✓
FRONT GRILLE <i>del</i>	1	675.70	675.70 ✓
FRONT GRILLE 'LOGO' EMBLEM <i>del</i>	1	65.50	65.50 ✓
FRONT GRILLE 'QUATTRO' EMBLEM	1	90.77	90.77 ✓
FRONT HEADLAMP BACK COVER L/R <i>del</i>	4	90.97	363.88 ✓

*** This is a computer-generated document which requires no signature. ***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

FRONT HEADLAMP H.I.D BARLAST 'ORIGINAL' L/R	2	770.97	1,541.94	X
FRONT HEADLAMP H.I.D BULB 'ORIGINAL' L/R	2	500.99	1,001.98	X
FRONT HEADLAMP L/R <i>cauled</i>	2	200.97 200.97	401.94 401.94	✓
FRONT HEADLAMP LOWER BRACKET 'INNER' L/R	2	117.33	234.66	✓
FRONT HEADLAMP LOWER BRACKET 'OUTER' L/R	2	109.71	219.42	✓
FRONT HEADLAMP NOZZLE HOSE - SET	1	270.71	270.71	X
FRONT HEADLAMP NOZZLE L/R	2	240.99	481.98	✓
FRONT HEADLAMP TOP BRACKET L/R	2	120.97	241.94	X
FRONT LH PASSENGER SEAT SAFETY BELT	1	760.77	760.77	✓
FRONT RH DRIVE SEAT SAFETY BELT	1	760.77	760.77	✓
FRONT RH FENDER	1	690.70	690.70	X
FRONT RH FENDER BRACKET	1	65.77	65.77	✓
FRONT RH FENDER INNER SHIELD	1	197.70	197.70	✓
FRONT RH FENDER INNER SPONGE	1	30.99	30.99	✓
FRONT RH FENDER TOP BRACKET	1	29.70	29.70	✓
FRONT SUPPORT PANEL	1	772.70	772.70	✓
FRONT SUPPORT PANEL TOP GARNISH	1	140.99	140.99	✓
RADIATOR (AUTO)	1	772.70	772.70	✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

RADIATOR AUXILLIARY FAN ASSY	1	760.99	760.99 ✓
RADIATOR FAN COWLING	1	270.99	270.99 ✓
RADIATOR LOWER AIR GUIDE	1	100.97	100.97 ✓
RADIATOR LOWER BRACKET L/R	2	99.71	199.42 ✓
RADIATOR LOWER HOSE	1	260.99	260.99 ✓
RADIATOR LOWER RUBBER BUSH L/R	2	49.77	99.54 ✓
RADIATOR SPARE TANK HOSE	1	130.91	130.91 ✓
RADIATOR TOP HOLDER CLIPS L/R	2	6.50	13.00 ✓
RADIATOR TOP HOSE	1	260.17	260.17 ✓
RADIATOR TOP RUBBER BUSH L/R	2	40.17	80.34 ✓
REAR BUMPER	1	1032.70	1,032.70 ✓
REAR BUMPER LOWER DIFFUSER	1	477.30	477.30 ✓
REAR BUMPER REFLECTOR LAMP L/R	2	238.70	477.40 ✓
REAR BUMPER REINFORCEMENT	1	499.77	499.77 ✓
REAR BUMPER REINFORCEMENT BRACKET L/R	2	150.15	300.30 ✓
REAR BUMPER REVERSE SENSOR 'ORIGINAL'	4	217.77	871.08 ✓
REAR BUMPER REVERSE SENSOR HOLDER	4	49.95	199.80 ✓
REAR BUMPER REVERSE SENSOR RUBBER SEAL	4	7.11	28.44 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR BUMPER REVERSE SENSOR WIRE HARNESS - SET <i>Not in</i>	1	470.99	470.99 ✓
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	49.77	99.54 ✓
REAR BUMPER TOW HOOK COVER L/R <i>changed</i>	2	50.15	100.30 ✓
REAR END PANEL <i>Distorted</i>	1	1400.99	1,400.99 ✓
REAR END PANEL INNER TOP CHROME GARNISH <i>changed</i>	1	299.30	299.30 ✓
REAR END PANEL INNER TOP CHROME GARNISH CLIPS <i>new</i>	6	6.50	39.00/0 ✓
REAR END PANEL LOCK STRIKER	1	100.97	100.97 ✓
REAR END PANEL LOCK STRIKER COVER <i>changed</i>	1	49.75	49.75 ✓
REAR END PANEL TAILGATE CLOSE SENSOR	1	140.97	140.97 ✓
REAR FENDER INNER AIR VENT L/R <i>Not in</i>	2	97.90	195.80 ✓
REAR FENDER INNER SHIELD L/R <i>new</i>	2	211.70	423.40 ✓
REAR FENDER INNER UPHOLSTERY TRIM BOARD COVER L/R <i>Not in</i>	2	667.70	1,335.40 ✗
REAR FENDER INNER UPHOLSTERY TRIM BOARD L/R <i>changed</i>	2	700.99	1,401.98 ✓
REAR SPEAKER UPHOLSTERY BOARD <i>Not in</i>	1	1280.99	1,280.99 ✗
REAR SUB CHASSIS FRAME CROSS MEMBER <i>Bye</i>	1	1255.70	1,255.70 ✗
REAR SUB CHASSIS FRAME L/R <i>Bye</i>	2	1400.97	2,801.94 ✗
REAR SUSPENSION ABS SENSOR L/R <i>Not in</i>	2	211.70	423.40 ✗
REAR SUSPENSION CROSS MEMBER <i>Best</i>	1	1060.77	1,060.77 ✓

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR SUSPENSION CROSS MEMBER BRACKET <i>Best</i>	2	400.97	801.94 ✓
REAR SUSPENSION CROSS MEMBER SCREW <i>Best</i>	4	16.77	67.08 ✓
REAR SUSPENSION DRIVE SHAFT ASSY L/R <i>not seen</i>	2	2427.30	4,854.60 ✗
REAR SUSPENSION KNUCKLE ARM BEARING L/R <i>new</i>	2	500.67	1,001.34 ✓
REAR SUSPENSION KNUCKLE ARM L/R <i>Best</i>	2	987.30	1,974.60 ✓
REAR SUSPENSION LEVERING SENSOR L/R <i>MS</i>	2	499.77	999.54 ✓
REAR SUSPENSION LOWER ARM L/R <i>Best</i>	2	813.77	1,627.54 ✓
REAR SUSPENSION SHOCK ABSORBER L/R <i>Best</i>	2	1307.30	2,614.60 ✓
REAR SUSPENSION SHOCK ABSORBER STOPPER L/R <i>3 new</i>	2	90.77	181.54 ✗
REAR SUSPENSION SHOCK ABSORBER TOP MOUNTING L/R	2	129.77	259.54 ✗
REAR SUSPENSION STABILIZER BAR <i>Best</i>	1	380.77	380.77 ✓
REAR SUSPENSION STABILIZER BAR BRACKET L/R <i>Best</i>	2	70.97	141.94 ✓
REAR SUSPENSION STABILIZER BAR LINK L/R <i>3 Best</i>	2	130.77	261.54 ✓
REAR SUSPENSION TRAILING ARM L/R	2	400.97	801.94 ✓
REAR SUSPENSION UPPER ARM L/R	2	466.99	933.98 ✓
REAR TAILGATE <i>Best</i>	1	2997.30	2,997.30 ✓
REAR TAILGATE '207' EMBLEM <i>3 new</i>	1	100.97	100.97 ✓
REAR TAILGATE 'LOGO' EMBLEM	1	99.71	99.71 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HONG GUANGYUAN
 BLK 222 ANG MO KIO AVE 1 #03-711
 SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR TAILGATE 'Q5' EMBLEM	1	90.77	90.77 ✓
REAR TAILGATE 'QUATTRO' EMBLEM	1	85.77	85.77 ✓
REAR TAILGATE DAMPER L/R	2	120.77	241.54 ✗
REAR TAILGATE HINGES GARNISH L/R	2	90.97	181.94 ✗
REAR TAILGATE HINGES L/R	2	211.70	423.40 ✗
REAR TAILGATE INNER TRIM BOARD	1	599.71	599.71 ✓
REAR TAILGATE MECHANISM LOCK GARNISH	1	100.97	100.97 ✗
REAR TAILGATE MECHANISM LOCK WITH MOTOR	1	170.97	170.97 ✗
REAR TAILGATE NUMBER PLATE LAMP L/R	2	49.97	99.94 ✗
REAR TAILGATE OUTER LOCK HANDLE SWITCH	1	180.99	180.99 ✗
REAR TAILGATE RUBBER GUIDE STOPPER L/R	4	40.33	161.32 ✗
REAR TAILGATE WEATHER STRIP	1	299.71	299.71 ✓
REAR TAILGATE WINDSCREEN COMPLETE WITH MOULDING	1	1007.93	1,007.93 ✓
REAR TAILGATE WINDSCREEN INNER GARNISH 'TOP'	1	199.71	199.71 ✗
REAR TAILGATE WINDSCREEN INNER GARNISH L/R	2	140.17	280.34 ✗
REAR TAILLAMP BACK COVER L/R	2	40.17	80.34 ✗
REAR TAILLAMP CLIPS L/R	4	6.50	26.00 ✓
REAR TAILLAMP L/R	2	1245.70	2,491.40 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR TWIN EXHAUST ALUMINIUM HEAT SHIELD L/R <i>comp'd</i>	2	270.97	541.94 ✓
REAR TWIN EXHAUST BRACKET L/R <i>dyd</i>	2	99.71	199.42 ✓
REAR TWIN EXHAUST END CHROME PIPE L/R <i>not sh</i>	2	400.97	801.94 ✗
REAR TWIN EXHAUST GASKET L/R <i>sh</i>	2	40.17	80.34 ✓
REAR TWIN EXHAUST RUBBER MOUNTING L/R <i>not sh</i>	4	90.71	362.84 ✗
REAR TWIN EXHAUST SILENCER BOX <i>Box</i>	1	997.30	997.30 ✓
REAR WELL PANEL <i>Deled</i>	1	1400.97	1,400.97 ✓
REAR WELL PANEL INNER TOOLS SPONGE <i>inled</i>	1	200.93	200.93 ✓
REAR WELL PANEL INNER TOP BATTERY SPONGE <i>not sh</i>	1	199.71	199.71 ✓
REAR WELL PANEL INNER TOP BATTERY TERMINAL MODULE <i>not sh</i>	1	580.97	580.97 ✗
REAR WELL PANEL INNER TOP BATTERY TRAY <i>Deled</i>	1	215.71	215.71 ✓
REAR WELL PANEL INNER TOP SIDE UPHOLSTERY TRIM BRACKET L/R <i>not sh</i>	2	140.97	281.94 ✗
REAR WELL PANEL INNER TOP SIDE UPHOLSTERY TRIM L/R <i>not sh</i>	2	500.33	1,000.66 ✗
REAR WELL PANEL INNER TOP SUB WOOFER RETAINER LOCK <i>dyd</i>	1	150.71	150.71 ✓
REAR WELL PANEL INNER TOP SUB WOOFER RETAINER LOCK HOLDER <i>not sh</i>	1	150.77	150.77 ✗
REAR WELL PANEL INNER TOP SUB WOOFER UNIT 'ORIGINAL' <i>dyd</i>	1	400.71	400.71 ✓
REAR WELL PANEL INNER TOP TRAY <i>Deled</i>	1	280.93	280.93 ✓
REAR WELL PANEL INNER TOP UPHOLSTERY BOARD <i>not sh</i>	1	729.70	729.70 ✗

*** This is a computer-generated document which requires no signature.***

48244 53
43420 07

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR BUMPER REFLECTOR LAMP WIRE HARNESS L/R - SET	2	799.75	1,599.50
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	30.00	60.00
REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS L/R - SET	2	30.00	60.00
REAR TAILGATE INNER CAR CAMERA RECORDER	1	800.00	800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	30.00	30.00
REAR TAILGATE NUMBER PLATE '3D'	1	190.00	190.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILGATE WINDSCREEN SEALANT	1	100.00	100.00
REAR WELL PANEL INNER JACKING TOOLS	1	180.00	180.00
REAR WELL PANEL INNER TOP BATTERY	1	350.00	350.00
REAR WELL PANEL INSULATOR MAT	1	280.00	280.00
Subtotal before discount			8,920.50
Percentage discount 0%			0.00
Sub-total 2			8,920.50
Parts-total			93,177.92

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To reset system after repair works

120

180.00

800.00

200

*** This is a computer-generated document which requires no signature. ***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HONG GUANGYUAN
 BLK 222 ANG MO KIO AVE 1 #03-711
 SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

Subtotal before discount			84,257.42
Percentage discount 0%			0.00
Sub-total 1			84,257.42
AUTOTRANSMISSION FLUID - BOT <i>new</i>	1	120.00	120.00 <i>80</i>
ENGINE LOWER UNDER COVER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT BONNET INSULATOR MAT CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT BUMPER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT BUMPER NUMBER PLATE <i>new</i>	1	25.00	25.00 ✓
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT SUPPORT PANEL TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
RADIATOR COOLANT - BOT <i>new</i>	1	80.00	80.00 <i>50</i>
REAR 20" SPORT RIM L/R <i>new</i>	2	1350.00	2,700.00 ✓
REAR 225/45 R 20 101W TYRE L/R <i>new</i>	2	980.00	1,960.00 ✓
REAR BUMPER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR BUMPER REFLECTOR LAMP BRAKE BULB L/R <i>new</i>	4	12.00	48.00 ✓
REAR BUMPER REFLECTOR LAMP REVERSE BULB L/R <i>new</i>	2	12.00	24.00 ✓
REAR BUMPER REFLECTOR LAMP SIGNAL BULB L/R <i>new</i>	2	12.00	24.00 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

~~180.00~~ 150

To remove, reinstall tailgate windscreen

~~150.00~~ 120

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

~~580.00~~ 450

To road test driving, check and resetting wheel alignments system.

~~180.00~~ 80

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~140.00~~ 80

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

~~1,500.00~~ 100

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

~~1,250.00~~ 700

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

~~160.00~~ 120

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~2,750.00~~ 180

To mount vehicle on to Car 'O' Liner.

~~400.00~~ +

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ ✓

Labour Total

8,390.00

Parts & Labour Total

101,567.92

*** This is a computer-generated document which requires no signature.***

page 12

total : 49485.07

4/s: 39.5K

21 Days.

39.5K



MYCARFORUM
MARKETPLACE

Buy / Sell Parts & Accessories

> click here to visit now!

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 for 6 weeks.

Post an Ad

Advertiser Login

Ways of Selling

2015 Mercedes-Benz C200 At \$180000.



Very Low Mileage, Good
Condition, Beautiful Unit,
Excellent Condition, Like New
Direct Owner

- Free VICOM evaluation
- Free grooming and 6
- In-house workshop e
- Member of SVTA and
- 100% deposit refund

YONG LEE





Browse by Category

Sort by Date Po

8 vehicles

AUDI Q5

Advanced Search

	Make	Model	Price	Reg Date	Gear	Eng Cap	Mileage
Search Selection	AUDI Q5		Any	2009	Any	Any	Any
	Audi Q5 2.0 TFSI		\$72,000	26-Jun-2009	Auto	1,984 cc	86,000 km
Number Plate Will Be Retain. If Interested Please Call For Viewing Arrangement.							
Posted: 08-Jun-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi							
	Audi Q5 2.0 TFSI Quattro		\$82,800	15-Dec-2009	Auto	1,984 cc	-
GOOD NEWS. MAS New Regulation Loan Up To 60% Or 70%. What Are You Waiting For, Hurry Come To View Your Dream Car At Car Fully Service & Maintain By Agent! Immaculate Condition! Lowes...							
Oscars Auto							
Posted: 05-Jun-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi							
	Audi Q5 2.0 TFSI		\$75,500	27-May-2009	Auto	1,984 cc	89,000 km
Down Payment At \$8k, Monthly At \$1600 Only. Agent Unit, Full Agent Maintain, Cheapest In Town! Peace Of Mind! Well Maintain, Depreciation! Accident Free! High Trade In And High In House Loan Av...							
Privilege Motors Pte Ltd							
Posted: 02-Jun-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi							
	Audi Q5 2.0 TFSI		\$68,800	30-Apr-2009	Auto	1,984 cc	-
Maintenance Done At Premium Auto. Perfect Ice Silver Metallic On Black Seats With Upgraded 19" Sport Rims. Nice Number.							
Posted: 02-Jun-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi							

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Compare

**Audi Q5 2.0 TFSI****\$80,000**

10-Dec-2009

Auto

1,984 cc

88,000 km

Car Fully Service And Maintain By Agent! Immaculate Condition! Lowest Depreciation For A Sporty And Spacious SUV. Flawless Ex Very Well Kept Interior. View To Believe, SMS To Enqu...

Posted: 28-May-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi

**Audi Q5 2.0 TFSI Quattro****\$79,988**

10-Nov-2009

Auto

1,984 cc

90,000 km

Original Paint Work. 2.0 TFSI Engine Mated With 7 Speed DSG Gearbox For Smooth And Quick Driving Experience, Low Mileage C Owner's Second Car. Buy With A Peace In Mind! To Find Out More ...

Posted: 23-May-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi

**Audi Q5 2.0 TFSI****\$82,500**

10-Nov-2009

Auto

1,984 cc

-

Posted: 29-Apr-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi

**Audi Q5 2.0 TFSI Quattro****\$82,888**

01-Jun-2009

Auto

1,984 cc

94,814 km

Owner's Consignment, Viewing Upon Appointment Only. Owner Upgrading To New Car. Regularly Maintained And Well Taken Car Expenses Spared. Sporty And Powerful SUV. Hassle Free Loan And ...

Posted: 25-Apr-2016 Tags: 2009 Audi Q5, Audi Q5, Audi, Q5, Used Audi

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Reg Date

Gear

Eng Cap

Mileage

For old advertisements, view [Expired ads](#)

sgCarMart is the number one car classifieds for buying Singapore cars and if you want to buy used vehicles, including new cars, parallel import cars manufacturers such as Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates, ERP rates Singapore, and even source for car insurance. With the wealth of information we have, it's no surprise that sgCarMart.com always turns up if you search Singapore, used AUDI Q5 Singapore, used AUDI Q5, used vehicles Singapore or even buy used AUDI Q5 Singapore. We have new car dealers comprehensive dealers, and used car dealers on our site. Find new car price lists, new car photos and new car promotions, and also motoring advice, car reviews & car partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, beauty and wellness, mover, car performance parts commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy.

- [Home](#)
- [New Car](#)
- [Used Car](#)
- [Sell Car](#)
- [Motoring Directory](#)
- [Products Guide](#)
- [Article](#)
- [Forum](#)
- [Tool & Tip](#)

© 2004-2016 sgCarMart. All rights reserved.

[Compare](#)

- Singapore Reckless Drivers Videos
- Accident between Taxi and cyclist
- Singapore public servants' computers to have no In...

AUDI Q5 Price Range 2009 Transmission Vehicle Type

Home » Used Cars » Oscars Auto » Audi Q5 2.0 TFSI Quattro

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Tyres



Audi Q5 2.0 TFSI Quattro

Overview Financial Accessories Similar Research Photos Map



Add to Compare Add to Shortlist Add a Note Report Error More Actions

Car Details

Price	\$82,800
Road Tax	\$1,194 /yr (Excl 2015/16 rebate)
Transmission	Auto
Engine Cap	1,984 cc
Power	155.0 kW (207 bhp) View specs of the Audi Q5 (2009-2012)
Reg Date	15-Dec-2009
Mileage	-

Features Responsive 2.0 TFSI Engine. 7 Speed S-Tronic Transmission, Intelligent Quattro AWD, Paddle Shift, LED Daytime Running Lights.

Accessories Auto Headlights And Rain Sensors, Audi Drive Select, MMI, Front And Rear Parking Sensors.

Description GOOD NEWS, MAS New Regulation Loan Up To 60% Or 70%. What Are You Waiting For, Hurry Come To View Your Dream Car And Get It. One Owner Car Fully Service & Maintain By Agent! Immaculate Condition! Lowest Depreciation For A Sporty And Spacious SUV. Flawless Exterior Paintwork With Very Well-kept Interior. View To Believe, Don't Wait! Call Now!

COE	\$19,289	?
OMV	\$44,724	?
Depreciation	N.A. Use tl	?

or to get estimated figure



Seller Information

Company	C
	»
	»
Address	7
	S

Compare

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 2496Z

Vehicle Details

Vehicle No.: SKX3328D

Vehicle to be Exported: No

Intended De-registration Date: 08 Jun 2016

Vehicle Make: AUDI

Vehicle Model: Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Primary Colour: Grey

Manufacturing Year: 2009

Engine No.: CDN079710

Chassis No.: WAUZZZ8R7AA047491

Maximum Power Output: 155.0 kW (207 bhp)

Open Market Value: \$44,750.00

Original Registration Date: 14 Dec 2009

First Registration Date: 14 Dec 2009

Transfer Count: 2

Actual ARF Paid: \$44,750.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Dec 2019

PARF Rebate Amount: \$29,087.00

Intended COE Rebate Details

COE Expiry Date: 13 Dec 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$19,901.00

COE Rebate Amount: \$6,854.00

Total Rebate Amount: \$35,941.00

The information contained herein is correct as at 08 Jun 2016

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 16 April 2019 5:51 PM
To: Sabrina (N-51)
Cc: Admin A
Subject: RE: [AIG]: Your Ref: SKX3328D Our Ref: CC4/AIG16010743/Amb3q2 [ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016]

Without Prejudice
(save as to costs)

Dear Sabrina,

As spoken, we are of the view that our offer of LOR is fair & reasonable as your client vehicle is Audi Q5(1984cc).

Kindly re-consider our offer as follows: -

COST OF REPAIR (w/GST)	\$42,265.00
LOSS OF RENTAL (21days x \$180.00)	\$ 3,780.00
LTA SEARCH	\$ 5.35
TOWING FEE (3 TRIPS)(120 x 3days)	\$ 360.00
TOTAL	\$ 46,410.35

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sabrina (N-51) <sabrina@n51.com.sg>
Sent: Wednesday, 10 April 2019 6:43 PM
To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Re: [AIG]: Your Ref: SKX3328D Our Ref: CC4/AIG16010743/Amb3qr ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016

REMINDER

Hsiao Tong (LKKAUTO)

From: Sabrina (N-51) <sabrina@n51.com.sg>
Sent: Wednesday, 17 April 2019 5:28 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: Re: [AIG]: Your Ref: SKX3328D Our Ref: CC4/AIG16010743/Amb3q2 [ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016]

Dear Hsiao Tong,

We refer to the above matter.
We agreed as per your offer.

Regards,

Sabrina
N-51 Automotive Pte Ltd
Office : 6842 0051 Fax : 6744 0510
www.n51.com.sg



On Tue, Apr 16, 2019 at 5:50 PM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Dear Sabrina,

As spoken, we are of the view that our offer of LOR is fair & reasonable as your client vehicle is Audi Q5(1984cc).

Kindly re-consider our offer as follows: -

COST OF REPAIR (w/GST)	\$42,265.00
LOSS OF RENTAL (21days x \$180.00)	\$ 3,780.00

LTA SEARCH	\$ 5.35
TOWING FEE (3 TRIPS) (120 x 3days)	\$ 360.00
TOTAL	\$ 46,410.35

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sabrina (N-51) <sabrina@n51.com.sg>

Sent: Wednesday, 10 April 2019 6:43 PM

To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Re: [AIG]: Your Ref: SKX3328D Our Ref: CC4/AIG16010743/Amb3qr ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016

REMINDER

Dear All,

Refer to the above subject.

There appears to be no developments to this matter.

Kindly let us hear from you within 10 working days from this email.


Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg



On Wed, Mar 20, 2019 at 10:55 AM Sabrina (N-51) <sabrina@n51.com.sg> wrote:

Dear Olivia,

We maintain our propose as \$190.00 X 21 days = \$3990.00

Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg



On Sat, Mar 16, 2019 at 3:44 PM Olivia Lau (LKKAuto) <olivialau@lkkauto.com> wrote:

LKK Ref: CC4/AIG16010743/Amb3

Without Prejudice

Hi Sabrina,

We refer to your email of 08/08/2018, and our Bevan's email of 21/05/2018.

Our Principal's offer is maintained at \$180.00 x 21 days = \$3,780.00, which is according to benchmark rates.

We seek your kind acceptance, to wrap up this matter.

Thank you.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Sabrina (N-51) [<mailto:sabrina@n51.com.sg>]

Sent: Wednesday, 8 August, 2018 3:38 PM

To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: [AIG]: Your Ref: SKX3328D Our Ref: CC4/AIG16010743/Amb3qr ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016

COST OF REPAIR	\$42,265.00
LOSS OF RENTAL (190 x 21days)	\$ 3,990.00
LTA SEARCH	\$ 5.35
TOWING FEE (3 TRIPS)(120 x3)	\$ 360.00
TOTAL	\$46,620.35

Dear Olivia,

Yes we confirm, as per above.

LOR \$190.00 X 21 Days = \$3990.00

Thanks


Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg



On Fri, Aug 3, 2018 at 5:58 PM, Olivia Lau (LKKAuto) <olivialau@lkkauto.com> wrote:

Without Prejudice

Hi Sabrina,

I refer to your email of 29/06/2018. Sorry for our delay in reply.

Kindly confirm if this is your latest proposal – “We reject and propose Loss of Rental of \$190.00 X 21 days = \$3990.00.”

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Sabrina (N-51) [mailto:sabrina@n51.com.sg]

Sent: Friday, 29 June, 2018 11:55 AM

To: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>

Subject: Re: Your Ref: SKX3328D Our Ref: CC4/AIG16010743/Amb3qr ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016

Dear Bevan,

Refer to your email dated 11/07/2018.

Thank you for hold on this case.

We reject and propose Loss of Rental of \$190.00 X 21 days = \$3990.00.

Please revert.

Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg

<input type="checkbox"/>	<table border="1"><tr><td data-bbox="548 1814 686 2047"><input type="checkbox"/></td><td data-bbox="686 1814 815 2047"><input type="checkbox"/></td></tr></table>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>		

On Tue, Jun 12, 2018 at 2:32 PM, Sabrina (N-51) <sabrina@n51.com.sg> wrote:

Dear Bevan,

Pls hold in this case.

Will reply u asap.


Regards,

Sabrina

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6744 0510

www.n51.com.sg



On Mon, Jun 11, 2018 at 4:15 PM, Bevan Lim (LKK Auto) <bevanlim@lkkauto.com> wrote:

Without Prejudice

Dear Sabrina,

We refer to our offer dated 21/05/2018

Kindly revert acceptance for an amicable settlement.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Bevan Lim (LKK Auto)

Sent: Monday, 21 May 2018 2:20 PM

To: 'Sabrina (N-51)' <sabrina@n51.com.sg>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Your Ref: SKX3328D Our Ref: CC4/AIG16010743/Amb3qr ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016

Your Ref: **SKX3328D**

Without Prejudice

Our Ref: CC4/AIG16010743/Amb3qr

Dear Sirs,

ACCIDENT INVOLVING SGH7216Z(AIG) & SKX3328D ON 07/06/2016

We refer to the above matter.

We propose settlement as follows:

COST OF REPAIR	\$42,265.00
LOSS OF RENTAL (180 x21days)	\$ 3,780.00
LTA SEARCH	\$ 5.35
TOWING FEE (3 TRIPS)(120 x3)	\$ 360.00
TOTAL	\$46,410.35

Kindly confirm.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510
Email: sales@n51.com.sg
Company Reg. No.: 200616038C
GST Registration No.: 200616038C

31-Jul-2017

Our Ref: CLM13568 / Jun-25 (2016)

AIG ASIA PACIFIC INSURANCE PTE LTD
NO. 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120

ATTN: MOTOR CLAIMS DEPARTMENT

Dear Sir @ Mdm,

Re: Accident involving SKX 3328 D & SGH 7216 Z on 07/06/2016
Along SLE towards CTE after Woodlands Ave 12 exit

We refer to the above accident which was caused due to the negligence of your Insured driver of vehicle No: SGH 7216 Z whose vehicle was insured with you at the material date of the accident.

We are proposing for a direct settlement on the claims as following exclude personal injury in respect of claim arising out of the abovementioned accident.

Cost of Repairs	\$ 42,265.00	(Include 7% GST)
Car Rental	\$ 5,250.00	
Towing Fee	\$ 360.00	
LTA Search	\$ 5.35	
	<u>\$ 47,880.35</u>	

We enclosed herein the following documents for your necessary attention.

- 1) Our Final Repair Bill No: CLM13568
- 2) Good Way Rent-A-Car Pte Ltd - Invoice No: GPLIN0000172 , VHA No.: 0266
- 3) Autobay Towing - SKX 3328 D (receipt attached)
- 4) LTA Search Fee
- 5) Letter of Authorisation To Act
- 6) Release Voucher (AIG Express Third Party Claim)

We look forward to your prompt reply.

Yours faithfully,


N-51 Automotive Pte Ltd
S.Y. NEO
Managing Director



Print Received Message

This mail is associated with :

***SKX3328D (9036762949SG)
[SGH7216Z]**

TP
HONG GUANG YUAN
Jun 7 2016 5:00PM
[Ang Choon Liang]
N-51 Automotive Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on **21/05/2018 12:24 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$46410.35) - SKX3328D - Claim Handler: Sivaguru Raja, Jeevan Raj

Approved:46410.35.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG16010743/Ayb3

08 SEPTEMBER 2016

ANG CHOON LIANG
BLK 426 PASIR RIS DRIVE 6
#12-61
SINGAPORE 510426

Dear Sir/Madam,

ACCIDENT INVOLVING SGH 7216Z / SKX 3328D / OTHERS ON 07.06.2016

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Syaf
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: NurSyafiqah@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

I, HONG GUANGYUAN (the third party claimant) of BLK 222 ANG MO KIO
AVE 1 #03-711 (S) 560222 (address), owner of SKX 3328 D (vehicle no.)
hereby authorize N-51 AUTOMOTIVE PTE LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or ~~loss of use~~ ("claim") for my vehicle
no. SKX 3328 D that was damaged pursuant to the accident which occurred on 07/06/2016
(date) along SLE TOWARDS ITE AFTER WOODLANDS AVE (location) involving vehicle no/s
SGH 7216 Z 12 EXIT ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 09 (day) of JUNE (month) 20 16 (year)

Provide always that this discharge of my
claim for damages relating to the damage to
my vehicle shall not prejudice or affect or
preclude me from making a further claim for
general and special damages for my personal
injuries sustained in the same accident.



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, N-51 AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$42,265.00 (Repair Cost), S\$3480.00 (Loss of rental ~~use~~), S\$366.35 (Disbursement), for vehicle no. SKY3328 D that was damaged pursuant to the accident which occurred on 07/06/16 (date) along SLE TOWARDS CTE AFTER WOODLANDS AVE 12 ^{EXIT} (location) involving vehicle no/s SGH 7216 Z. This is pursuant to the inspection conducted on 09/06/16 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HONG GUANGYUAN ("the third party claimant") of vehicle no. SKY 3328 D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKY 3328 D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of April (month) 2019 (year)



LW

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.



Signed by appointed surveyor

Signed by "the workshop" (with chop)

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

TAX INVOICE

Date : 28/07/2017
Date in : 07/06/2016
Vehicle Num. : SKX3328D
Make/Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR-2009
Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710
Accident Date : 07/06/2016
Claim No : CLM13568
Reference : JUN-25/2016
Policy No. : GA083309/1 (23/12/2016)

LUMPSUM REPAIR BILL
REF : CLM13568 - N51 DATED 09/06/2016
BY LKK

Amount S\$
39,500.00



E. & O.E.	Sub S\$:	39,500.00
	Add GST (7%) S\$:	2,765.00
	Total Amount S\$:	42,265.00

for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃



Invoice

SKX3328D
HONG GUANG YUAN
BLK 222 ANG MO KIO AVE 1
#03-711
S(560222)

Invoice No : GPLIN0000172
Invoice Date : 30/6/2016
Due Date : 30/6/2016
VHA No : 0266
Referral ID : N001

Description :	Amount
Rental for 21 Day/s @ \$250 per Day	\$5,250

Vehicle No : SKT 5627 Z

Vehicle Description : Harrier 2.0A

Rental Period : 07/06/2016 to 28/06/2016

Total Amount Payable : \$5,250

GOOD WAY RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875

Tel: 6315 8479 H/P: 9833 0807

GPLIN172

VHA No: 0266

UEN: 201505120D

VEHICLE RENTAL AGREEMENT

SKR33280 (N-51)

HIRER'S PARTICULAR		Vehicle No: <u>SKT56272</u> Replace Veh No:	
Name: (as in I/C) <u>HONG GUANG YUAN</u>		Mileage Out: _____ Mileage In: _____	
NRIC/PASSPORT No: <u>S 81224962</u>		Make & Model: <u>TOYOTA HARRIER</u> Auto/Manual Group:	
Address (Res): <u>BK 722 ANG MO KIO AVE 1</u>		Out : Date <u>07 JUN 2016</u> Time: <u>(9:30) hrs</u>	
<u>#03-211 S(560222)</u>		HIRE / PERIOD EXPIRY _____ Time: _____	
Name & Address of Employer _____		NON-WAIVER EXCESS=\$ <u>3000/1</u>	
Occupation: _____ Driving Exp: _____		CHARGES	
Driving Licence No: <u>91224962</u> D/L Type: Local / International		Daily <u>21</u> @ \$ <u>250</u> per day <u>\$5250</u>	
Issue Date: <u>01/02/2006</u> Date of Birth: <u>24/08/1981</u>		Weekly @ \$ _____ per week	
Tel: (O) _____ (R) _____ HP/PG <u>9613 2484</u>		Monthly @ \$ _____ per month	
ADDITIONAL DRIVER'S PARTICULARS		Hours @ \$ _____ per hour	
Name: (as in I/C) _____		Others @ \$ _____	
NRIC/PASSPORT No: _____		CDW @ \$ _____ per day/month	
Address (Res): _____		PAI @ \$ _____ per day/month	
Driving License No: _____ D/L Type: Local / International		Delivery/Collection Service	
Issue Date: _____ Date of Birth: _____		SUB-TOTAL \$	
Occupation: _____ Driving Exp: _____		PETROL LEVEL	
VEHICLE CHECK LIST		Out E 1/4 1/2 3/4 F	
D - DENTS		In E 1/4 1/2 3/4 F	
S - SCRATCHES		EXTENSION	
A - ACCIDENTS		Misc. _____	
		TOTAL CHARGES \$	
ACCESSORIES CHECK			
<input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio/Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges		Hirer's Signature _____ Additional Driver's Signature _____	

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given GOOD WAY RENT-A-CAR PTE LTD in connection with this agreement is true.

***IMPORTANT**

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY GOOD WAY RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN " SINGAPORE OF HIRER / DRIVER " FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO GOOD WAY RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	 SIGNATURE OF HIRER/DRIVER
<u>28/06/16</u>	<u>17:35 hrs</u>				

AUTOBAY TOWING

1 Kaki Bukit Avenue 6
#01-55 AutoBay @ Kaki Bukit
Singapore 417883
Tel: 9015 8686 (Ah Boon)

CASH SALE

No. _____

Date: 7/6/16

(N-51)

SKX33281

Sold to: _____

CROWN

Item	Quantity	Description	Unit Price	Amount
		SLE to Auto Hub		8120
		King Rollby		1
E. & O. E.			Sub Total :	
			GST Tax :	
			Total :	8120

Issued by: _____

AUTOBAY TOWING

1 Kaki Bukit Avenue 6
#01-55 AutoBay @ Kaki Bukit
Singapore 417883
Tel: 9015 8686 (Ah Boon)

CASH SALE

No. _____

Date: 8/6/16

(N-51)

SKX32881

Sold to: _____

CROWN

Item	Quantity	Description	Unit Price	Amount
		Auto Hub to Auto Bay		8240
		Reporting Two Trips		1
		King Rollby		
E. & O. E.			Sub Total :	
			GST Tax :	
			Total :	8240

Issued by: _____



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 08 Jun 2016 / 12:57:52

Receipt Date/Time : 08 Jun 2016 / 12:57:52

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180608-000721

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
	Result of Insurance Enquiry - SGH7216Z As at 07 Jun 2016/17:45:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SGH7216Z Enquiry Fee 20160608125640295781	5.00	0.35	5.35
	Sub-Total	5.00	0.35	5.35
	Total Before Rounding	5.00	0.35	5.35
	Rounding Difference			0.00
	Total Amount Payable			5.35
	Paid By			
	xxxxxxxxxxxx4258		Credit Card: Visa/MasterCard	5.35
	Total			5.35
	Cash Change			0.00
	Tendered Amount			5.35
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jun 2016 Edit Reg		09 Jun 2016 00:00 Edit Adj Rpt	\$539,500.00 Edit Estimates	\$539,500.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Ang Choon Liang , ID: S1311253C, Tel: +6596659493								
Main Claimant:	HONG GUANG YUAN , ID: S8122496Z								
Vehicle Reg. No.:	SKX3328D	Date of Loss:	07/06/2016 17:00 - :59 [77 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9036762949SG	Policy/Cover Note No.:	2100309130 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGH7216Z	Policy No. (Claimant):	GA083309/1						
		Excess:							
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Sivaguru Raja, Jeevan Raj] jeevansivagum@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/06/2016]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (21/05/2018): Alert - Adj Mandate Approved (\$546410.35) - SKX3328D - Claim Handler: Sivaguru R... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents



















































*SKX3328D (9036762949SG)
[SGH7216Z]
TP
HONG GUANG YUAN
Jun 7 2016 5:00PM
[Ang Choon Liang]
N-51 Automotive Pte Ltd



































Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print						
1	(Draft)		Third Party Express Settlement – Payment Breakdown														Edit						
Assessment Reports															1 per page			<input checked="" type="checkbox"/>					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail			Print						
1	14/06/16 10:05		Accident Statement From: SC - Reg. No: SGH7216Z, Claimant: ANG CHOON LIANG														Load HTM						
Photos/Images															3 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print						
1	31/07/17 13:47		General View														Load JPG						
2	31/07/17 13:47		General View														Load JPG						
3	31/07/17 13:47		Chassis Number														Load JPG						
4	31/07/17 13:47		General View														Load JPG						
5	31/07/17 13:47		General View														Load JPG						
6	31/07/17 13:47		General View														Load JPG						
7	31/07/17 13:47		General View														Load JPG						
8	31/07/17 13:47		General View														Load JPG						
9	31/07/17 13:47		General View														Load JPG						
10	31/07/17 13:47		General View														Load JPG						
11	31/07/17 13:47		General View														Load JPG						
12	31/07/17 13:47		General View														Load JPG						
13	31/07/17 13:47		General View														Load JPG						
14	31/07/17 13:47		General View														Load JPG						
15	31/07/17 13:47		General View														Load JPG						
16	31/07/17 13:47		General View														Load JPG						
17	31/07/17 13:47		General View														Load JPG						
18	31/07/17 13:47		General View														Load JPG						
19	31/07/17 13:47		General View														Load JPG						
20	31/07/17 13:47		General View														Load JPG						
21	31/07/17 13:47		General View														Load JPG						
22	31/07/17 13:47		General View														Load JPG						
23	31/07/17 13:47		General View														Load JPG						
24	31/07/17 13:47		General View														Load JPG						
25	31/07/17 13:47		General View														Load JPG						
26	31/07/17 13:47		General View														Load JPG						
27	31/07/17 13:47		General View														Load JPG						
28	31/07/17 13:47		General View														Load JPG						
29	31/07/17 13:47		General View														Load JPG						
30	31/07/17 13:47		General View														Load JPG						

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	31/07/17 13:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
181	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	31/07/17 13:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
221	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
222	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
226	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
227	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
228	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
229	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
230	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
231	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
232	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
233	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
234	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
235	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
236	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
237	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
238	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
239	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
240	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
241	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
242	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
243	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
244	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
245	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
246	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
247	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
248	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
249	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
250	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
251	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
252	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
253	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
254	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
255	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
256	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
257	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
258	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
259	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
260	31/07/17 13:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/16 12:31	EMAIL FROM AIG DD 09062016	 Load PDF	
2	10/06/16 14:06	TP GIA REPORT	 Load PDF	
3	07/09/16 12:12	LETTER TO OI	 Load PDF	
4	31/07/17 14:25	TP ESTIMATE- MARKED	 Load PDF	
5	12/09/17 14:24	TOWING FEE	 Load PDF	
6	12/09/17 14:24	RENTAL RECEIPT	 Load PDF	
7	12/09/17 14:24	LTA SEARCH	 Load PDF	
8	21/03/18 11:20	COE rebate	 Load PDF	
9	21/03/18 11:20	Market Value	 Load PDF	
10	26/04/19 09:55	WORKSHOP INVOICE	 Load PDF	
11	26/04/19 09:55	AUTHORISATION TO ACT FORM	 Load PDF	
12	26/04/19 09:55	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGH7216Z (Insd veh)	Model:	AUDI Q5 2.0 (A)
	SKX3328D (TP veh)		
Date of Accident:	07/06/2016		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		112,548.36
Final Repair Cost	:	\$		42,265.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		21 days
LTA / GIA Search Fee	:	\$		5.35
Others:	:	\$		360.00
	:	\$		
Final Settlement Sum	:	\$		46,410.35

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 100 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	N-51 Automotive Pte Ltd	:	\$ 46,410.35
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

26 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG16010743/APB3Q2

Date: 26/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100309130
Claimant Vehicle No : SKX3328D **Insured Vehicle No :** SGH7216Z
 Date of Loss: 07/06/2016 Nature of Claim: TP Claim No: 9036762949SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX3328D**
 Make & Model: AUDI Q5, 2.0 (A) Engine No: CDN079710
 Reg. Date: 14/12/2009 (Man. Year: 2009) Chassis No: WAUZZZ8R7AA047491
 Colour: Black Odometer: 99605 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/45 R20 Rear Tyre Size: 255/45 R20
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	96,795.38	44,595.08	52,200.30	53.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,390.00	4,940.00	3,450.00	41.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	105,185.38	49,535.08	55,650.30	52.91
Approved Total (Overridden) (S\$)		39,500.00		
(S\$)	105,185.38	39,500.00	65,685.38	62.45
+ GST 7.00/7.00% (S\$)	7,362.98	2,765.00	4,597.98	62.45
Nett Amount (S\$)	112,548.36	42,265.00	70,283.36	62.45
+ Car Rental (21.0 x S\$180.00/day) (S\$)		3,780.00		
+ Doc/Search Fee (S\$)		5.35		
+ Other Costs (S\$)		360.00		
Nett Liability (S\$)		46,410.35		

INSPECTION

Date of Assignment: 09/06/2016
 Date Inspected: 09/06/2016 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI

BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIRCON AUXILLIARY FAN ASSY	Not Necessary	580.99 F	*- FL
2	1		*AIRCON AUXILLIARY FAN HIGH PRESSURE MODULE	Not Necessary	680.95 F	*- FL
3	1		*AIRCON CONDENSER	Bent	817.30 F	*817.30 FL
4	6		*AIRCON CONDENSER AIR GUIDE CLIPS L/R	Not Necessary	39.00 F	*- FL
5	2		*AIRCON CONDENSER AIR GUIDE L/R	Not Necessary	99.54 F	*- FL
6	1		*AIRCON COOLING PIPE	Not Necessary	900.77 F	*- FL
7	1		*AIRCON DISCHARGE PIPE	Not Necessary	799.33 F	*- FL
8	1		*AIRCON HIGH PRESSURE SENSOR	Not Necessary	900.77 F	*- FL
9	1		*AIRCON OUTSIDE TEMPERATYRE SENSOR	Not Necessary	200.99 F	*- FL
10	1		*AIRCON SUCTION PIPE	Not Necessary	833.75 F	*- FL
11	1		*AUTOTRASMISSION COOLER	Bent	800.33 F	*800.33 FL
12	2		*DRUMPET HORN BRACKET L/R	Not Necessary	179.54 F	*- FL
13	2		*DRUMPET HORN L/R	Not Necessary	423.98 F	*- FL
14	1		*ENGINE LOWER UNDER COVER	Not Necessary	500.31 F	*- FL
15	1		*ENGINE TURBO COOLER	Not Necessary	300.17 F	*- FL
16	1		*ENGINE TURBO COOLER HOSE INLET	Not Necessary	211.95 F	*- FL
17	1		*ENGINE TURBO COOLER HOSE OUTLET	Not Necessary	260.77 F	*- FL
18	1		*FRONT AIR DUCT	Not Necessary	150.33 F	*- FL
19	1		*FRONT AIR DUCT HOSE	Not Necessary	140.97 F	*- FL
20	2		*FRONT AIR DUCT HOSE CLIPS	Not Necessary	13.00 F	*- FL
21	2		*FRONT AIRBAG IMPACT SENSOR L/R	Not Necessary	521.94 F	*- FL
22	1		*FRONT BONNET	Dented	2,830.97 F	*2,830.97 FL
23	1		*FRONT BONNET CABLE	Not Necessary	140.31 F	*- FL
24	2		*FRONT BONNET DAMPER L/R	Not Necessary	211.40 F	*- FL
25	2		*FRONT BONNET HINGE L/R	Not Necessary	281.94 F	*- FL
26	1		*FRONT BONNET INNER LOCK HANDLE	Not Necessary	90.99 F	*- FL
27	1		*FRONT BONNET INSULATOR MAT	Not Necessary	220.99 F	*- FL
28	1		*FRONT BONNET MECHABNISM LOCK	Not Necessary	214.70 F	*- FL
29	2		*FRONT BONNET NOZZLE L/R	Not Necessary	407.54 F	*- FL
30	4		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Not Necessary	119.08 F	*- FL
31	2		*FRONT BONNET WEATHER STRIP L/R	Not Necessary	60.34 F	*- FL
32	1		*FRONT BUMPER CENTER	Deformed	170.97 F	*170.97 FL
33	2		*FRONT BUMPER FOGLAMP GARNISH L/R	Not Necessary	271.40 F	*- FL
34	2		*FRONT BUMPER FOGLAMP L/R	Cracked	535.40 F	*535.40 FL
35	1		*FRONT BUMPER INNER SPONGE	Deformed	140.31 F	*140.31 FL
36	2		*FRONT BUMPER L/R	Deformed	1,701.50 F	*1,701.50 FL
37	1		*FRONT BUMPER LOWER DIFFUSER	Deformed	400.33 F	*400.33 FL
38	1		*FRONT BUMPER LOWER RUBBER MOULDING	Not Necessary	100.17 F	*- FL
39	2		*FRONT BUMPER LOWER SIDE RETAINER L/R	Necessary	99.54 F	*99.54 FL
40	1		*FRONT BUMPER LOWER UNDER COVER	Not Necessary	139.77 F	*- FL
41	2		*FRONT BUMPER NOZZLE COVER L/R	Not Necessary	101.98 F	*- FL
42	2		*FRONT BUMPER NUMBER PLATE SCREW GARNISH L/R	Not Necessary	40.34 F	*- FL
43	4		*FRONT BUMPER PARKING SENSOR ORIGINAL	Not Necessary	871.08 F	*- FL
44	4		*FRONT BUMPER PARKING SENSOR HOLDER	Not Necessary	199.80 F	*- FL
45	4		*FRONT BUMPER PARKING SENSOR RUBBER SEAL	Not Necessary	28.44 F	*- FL
46	1		*SET FRONT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	472.80 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER REINFORCEMENT	Bent	417.70 F	*417.70 FL
48	2		*FRONT BUMPER REINFORCEMENT BRACKET L/R	Bent	321.42 F	*321.42 FL
49	2		*FRONT BUMPER SIDE RETAINER L/R	Necessary	101.54 F	*101.54 FL
50	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	48.77 F	*- FL
51	1		*FRONT GRILLE	Cracked	675.70 F	*675.70 FL
52	1		*FRONT GRILLE LOGO EMBLEM	Necessary	65.50 F	*65.50 FL
53	1		*FRONT GRILLE QUATTRO EMBLEM	Necessary	90.77 F	*90.77 FL
54	4		*FRONT HEADLAMP BACK COVER L/R	Not Necessary	363.88 F	*- FL
55	2		*FRONT HEADLAMP H.I.D BARLAST ORIGINAL L/R	Not Necessary	1,541.94 F	*- FL
56	2		*FRONT HEADLAMP H.I.D BULB ORIGINAL L/R	Not Necessary	1,001.98 F	*- FL
57	2		*FRONT HEADLAMP L/R	Cracked	4,019.40 F	*4,019.40 FL
58	2		*FRONT HEADLAMP LOWER BRACKET INNER L/R	Cracked	234.66 F	*234.66 FL
59	2		*FRONT HEADLAMP LOWER BRACKET OUTER L/R	Cracked	219.42 F	*219.42 FL
60	1		*SET FRONT HEADLAMP NOZZLE HOSE	Not Necessary	270.71 F	*- FL
61	2		*SET FRONT HEADLAMP NOZZLE L/R	Damaged	481.98 F	*481.98 FL
62	2		*FRONT HEADLAMP TOP BRACKET L/R	Not Necessary	241.94 F	*- FL
63	1		*FRONT LH PASSENGER SEAT SAFETY BELT	Activated	760.77 F	*760.77 FL
64	1		*FRONT RH DRIVE SEAT SAFETY BELT	Activated	760.77 F	*760.77 FL
65	1		*FRONT RH FENDER	Repair	690.70 F	*- FL
66	1		*FRONT RH FENDER BRACKET	Not Necessary	65.77 F	*- FL
67	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	197.70 F	*- FL
68	1		*FRONT RH FENDER INNER SPONGE	Not Necessary	30.99 F	*- FL
69	1		*FRONT RH FENDER TOP BRACKET	Not Necessary	29.70 F	*- FL
70	1		*FRONT SUPPORT PANEL	Cracked	772.70 F	*772.70 FL
71	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	140.99 F	*140.99 FL
72	1		*RADIATOR (AUTO)	Bent	772.70 F	*772.70 FL
73	1		*RADIATOR AUXILLIARY FAN ASSY	Not Necessary	760.99 F	*- FL
74	1		*RADIATOR FAN COWLING	Not Necessary	270.99 F	*- FL
75	1		*RADIATOR LOWER AIR GUIDE	Not Necessary	100.97 F	*- FL
76	2		*RADIATOR LOWER BRACKET L/R	Not Necessary	199.42 F	*- FL
77	1		*RADIATOR LOWER HOSE	Not Necessary	260.99 F	*- FL
78	2		*RADIATOR LOWER RUBBER BUSH L/R	Not Necessary	99.54 F	*- FL
79	1		*RADIATOR SPARE TANK HOSE	Not Necessary	130.91 F	*- FL
80	2		*RADIATOR TOP HOLDER CLIPS L/R	Not Necessary	13.00 F	*- FL
81	1		*RADIATOR TOP HOSE	Not Necessary	260.17 F	*- FL
82	2		*RADIATOR TOP RUBBER BUSH L/R	Necessary	80.34 F	*80.34 FL
83	1		*REAR BUMPER	Distorted	1,032.70 F	*1,032.70 FL
84	1		*REAR BUMPER LOWER DIFFUSER	Distorted	477.30 F	*477.30 FL
85	2		*REAR BUMPER REFLECTOR LAMP L/R	Cracked	477.40 F	*477.40 FL
86	1		*REAR BUMPER REINFORCEMENT	Bent	499.77 F	*499.77 FL
87	2		*REAR BUMPER REINFORCEMENT BRACKET L/R	Bent	300.30 F	*300.30 FL
88	1		*REAR BUMPER REVERSE SENSOR ORIGINAL (4PCS)	Damaged (2 PCS ONLY)	871.08 F	*435.54 FL
89	4		*REAR BUMPER REVERSE SENSOR HOLDER	Not Necessary	199.80 F	*- FL
90	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	28.44 F	*28.44 FL
91	1		*SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	470.99 F	*- FL
92	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	99.54 F	*99.54 FL
93	2		*REAR BUMPER TOW HOOK COVER L/R	Damaged	100.30 F	*100.30 FL
94	1		*REAR END PANEL	Distorted	1,400.99 F	*1,400.99 FL
95	1		*REAR END PANEL INNER TOP CHROME GARNISH	Deformed	299.30 F	*299.30 FL
96	1			Necessary	39.00 F	*10.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR END PANEL INNER TOP CHROME GARNISH CLIPS (6PCS)			
97	1		*REAR END PANEL LOCK STRIKER	Damaged	100.97 F	*100.97 FL
98	1		*REAR END PANEL LOCK STRIKER COVER	Damaged	49.75 F	*49.75 FL
99	1		*REAR END PANEL TAILGATE CLOSE SENSOR	Damaged	140.97 F	*140.97 FL
100	2		*REAR FENDER INNER AIR VENT L/R	Not Necessary	195.80 F	*- FL
101	2		*REAR FENDER INNER SHIELD L/R	Not Necessary	423.40 F	*- FL
102	2		*REAR FENDER INNER UPHOLSTERY TRIM BOARD COVER L/R	Not Necessary	1,335.40 F	*- FL
103	2		*REAR FENDER INNER UPHOLSTERY TRIM BOARD L/R	Cracked	1,401.98 F	*1,401.98 FL
104	1		*REAR SPEAKER UPHOLSTERY BOARD	Not Necessary	1,280.99 F	*- FL
105	1		*REAR SUB CHASSIS FRAME CROSS MEMBER	Repair	1,255.70 F	*- FL
106	2		*REAR SUB CHASSIS FRAME L/R	Repair	2,801.94 F	*- FL
107	2		*REAR SUSPENSION ABS SENSOR L/R	Not Necessary	423.40 F	*- FL
108	1		*REAR SUSPENSION CROSS MEMBER	Bent	1,060.77 F	*1,060.77 FL
109	2		*REAR SUSPENSION CROSS MEMBER BRACKET	Bent	801.94 F	*801.94 FL
110	4		*REAR SUSPENSION CROSS MEMBER SCREW	Bent	67.08 F	*67.08 FL
111	2		*REAR SUSPENSION DRIVE SHAFT ASSY L/R	Not Necessary	4,854.60 F	*- FL
112	2		*REAR SUSPENSION KNUCKLE ARM BEARING L/R	Necessary	1,001.34 F	*1,001.34 FL
113	2		*REAR SUSPENSION KNUCKLE ARM L/R	Bent	1,974.60 F	*1,974.60 FL
114	2		*REAR SUSPENSION LEVERING SENSOR L/R	Not Necessary	999.54 F	*- FL
115	2		*REAR SUSPENSION LOWER ARM L/R	Bent	1,627.54 F	*1,627.54 FL
116	2		*REAR SUSPENSION SHOCK ABSORBER L/R	Bent	2,614.60 F	*2,614.60 FL
117	2		*REAR SUSPENSION SHOCK ABSORBER STOPPER L/R	Not Necessary	181.54 F	*- FL
118	2		*REAR SUSPENSION SHOCK ABSORBER TOP MOUNTING L/R	Not Necessary	259.54 F	*- FL
119	1		*REAR SUSPENSION STABILIZER BAR	Bent	380.77 F	*380.77 FL
120	2		*REAR SUSPENSION STABILIZER BAR BRACKET L/R	Bent	141.94 F	*141.94 FL
121	2		*REAR SUSPENSION STABILIZER BAR LINK L/R	Bent	261.54 F	*261.54 FL
122	2		*REAR SUSPENSION TRAILING ARM L/R	Bent	801.94 F	*801.94 FL
123	2		*REAR SUSPENSION UPPER ARM L/R	Bent	933.98 F	*933.98 FL
124	1		*REAR TAILGATE	Dented	2,997.30 F	*2,997.30 FL
125	1		*REAR TAILGATE 207 EMBLEM	Necessary	100.97 F	*100.97 FL
126	1		*REAR TAILGATE LOGO EMBLEM	Necessary	99.71 F	*99.71 FL
127	1		*REAR TAILGATE Q5 EMBLEM	Necessary	90.77 F	*90.77 FL
128	1		*REAR TAILGATE QUATTRO EMBLEM	Necessary	85.77 F	*85.77 FL
129	2		*REAR TAILGATE DAMPER L/R	Not Necessary	241.54 F	*- FL
130	2		*REAR TAILGATE HINGES GARNISH L/R	Not Necessary	181.94 F	*- FL
131	2		*REAR TAILGATE HINGES L/R	Not Necessary	423.40 F	*- FL
132	1		*REAR TAILGATE INNER TRIM BOARD	Deformed	599.71 F	*599.71 FL
133	1		*REAR TAILGATE MECHANISM LOCK GARNISH	Not Necessary	100.97 F	*- FL
134	1		*REAR TAILGATE MECHANISM LOCK WITH MOTOR	Not Necessary	170.97 F	*- FL
135	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	99.94 F	*- FL
136	1		*REAR TAILGATE OUTER LOCK HANDLE SWITCH	Not Necessary	180.99 F	*- FL
137	4		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	161.32 F	*- FL
138	1		*REAR TAILGATE WEATHER STRIP	Necessary	299.71 F	*299.71 FL
139	1		*REAR TAILGATE WINDSCREEN COMPLETE WITH MOULDING	Necessary	1,007.93 F	*1,007.93 FL
140	1		*REAR TAILGATE WINDSCREEN INNER GARNISH TOP	Not Necessary	199.71 F	*- FL
141	2		*REAR TAILGATE WINDSCREEN INNER GARNISH L/R	Not Necessary	280.34 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
142	2		*REAR TAILLAMP BACK COVER L/R	Necessary	80.34 F	*40.00 FL
143	4		*REAR TAILLAMP CLIPS L/R	Cracked	26.00 F	*26.00 FL
144	2		*REAR TAILLAMP L/R	Necessary	2,491.40 F	*2,491.40 FL
145	2		*REAR TWIN EXHAUST ALUMINIUM HEAT SHIELD L/R	Crumpled	541.94 F	*541.94 FL
146	2		*REAR TWIN EXHAUST BRACKET L/R	Damaged	199.42 F	*199.42 FL
147	2		*REAR TWIN EXHAUST END CHROME PIPE L/R	Not Necessary	801.94 F	*- FL
148	2		*REAR TWIN EXHAUST GASKET L/R	Necessary	80.34 F	*80.34 FL
149	4		*REAR TWIN EXHAUST RUBBER MOUNTING L/R	Not Necessary	362.84 F	*- FL
150	1		*REAR TWIN EXHAUST SILENCER BOX	Bent	997.30 F	*997.30 FL
151	1		*REAR WELL PANEL	Dented	1,400.97 F	*1,400.97 FL
152	1		*REAR WELL PANEL INNER TOOLS SPONGE	Cracked	200.93 F	*200.93 FL
153	1		*REAR WELL PANEL INNER TOP BATTERY SPONGE	Not Necessary	199.71 F	*- FL
154	1		*REAR WELL PANEL INNER TOP BATTERY TERMINAL MODULE	Not Necessary	580.97 F	*- FL
155	1		*REAR WELL PANEL INNER TOP BATTERY TRAY	Deformed	215.71 F	*215.71 FL
156	2		*REAR WELL PANEL INNER TOP SIDE UPHOLSTERY TRIM BRACKET L/R	Not Necessary	281.94 F	*- FL
157	2		*REAR WELL PANEL INNER TOP SIDE UPHOLSTERY TRIM L/R	Not Necessary	1,000.66 F	*- FL
158	1		*REAR WELL PANEL INNER TOP SUB WOOFER RETAINER LOCK	Damaged	150.71 F	*150.71 FL
159	1		*REAR WELL PANEL INNER TOP SUB WOOFER RETAINER LOCK HOLDER	Not Necessary	150.77 F	*- FL
160	1		*REAR WELL PANEL INNER TOP SUB WOOFER UNIT ORIGINAL	Damaged	400.71 F	*400.71 FL
161	1		*REAR WELL PANEL INNER TOP TRAY	Deformed	280.93 F	*280.93 FL
162	1		*REAR WELL PANEL INNER TOP UPHOLSTERY BOARD	Not Necessary	729.70 F	*- FL
163	1		*AUTOTRANSMISSION FLUID -BOT	Necessary	120.00 FS	*80.00 FS
164	1		*SET ENGINE LOWER UNDER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
165	1		*SET FRONT BONNET INSULATOR MAT CLIPS	Not Necessary	30.00 FS	*- FS
166	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
167	1		*FRONT BUMPER NUMBER PLATE	Bent	25.00 FS	*25.00 FS
168	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
169	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
170	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
171	1		*RADIATOR COOLANT -BOT	Necessary	80.00 FS	*50.00 FS
172	2		*REAR 20 SPORT RIM L/R	Not Necessary	2,700.00 FS	*- FS
173	2		*REAR 225/45 R20 101W TYRE L/R	Not Necessary	1,960.00 FS	*- FS
174	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
175	4		*REAR BUMPER REFLECTOR LAMP BRAKE BULB L/R	Not Necessary	48.00 FS	*- FS
176	2		*REAR BUMPER REFLECTOR LAMP REVERSE BULB L/R	Not Necessary	24.00 FS	*- FS
177	2		*REAR BUMPER REFLECTOR LAMP SIGNAL BULB L/R	Not Necessary	24.00 FS	*- FS
178	2		*SET REAR BUMPER REFLECTOR LAMP WIRE HARNESS L/R	Not Necessary	1,599.50 FS	*- FS
179	2		*SET REAR FENDER INNER SHIELD CLIPS L/R	Not Necessary	60.00 FS	*- FS
180	2		*SET REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS L/R	Necessary	60.00 FS	*60.00 FS
181	1		*REAR TAILGATE INNER CAR CAMERA RECORDER	Damaged	800.00 FS	*500.00 FS
182	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
183	1		*REAR TAILGATE NUMBER PLATE 3D	Not Necessary	190.00 FS	*- FS
184	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
185	1		*SET REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
186	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
187	1		*REAR WELL PANEL INNER JACKING TOOLS	Not Necessary	180.00 FS	*- FS
188	1		*REAR WELL PANEL INNER TOP BATTERY	Not Necessary	350.00 FS	*- FS
189	1		*REAR WELL PANEL INSULATOR MAT	Necessary	280.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	96,795.38	49,419.53
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	4,824.45
Total Parts (S\$)	96,795.38	44,595.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHARGE AIR CON PARTS ,VACUUMS ,REFILL AIR CON GAS	New	180.00	120.00
2	TO RESET SYSTEM AFTER REPAIR WORKS	New	800.00	200.00
3	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	180.00	150.00
4	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
5	TO REMOVE,CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ,ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB AND ETC	New	580.00	450.00
6	TO ROAD TEST DRIVING ,CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM	New	180.00	80.00
7	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	80.00
8	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R) ,SPARE TYRE PANEL AND REAR BUMPER	New	1,500.00	1,000.00
9	TO RE-SPRAY PAINTING ON THE FRONT BONNET ,FRONT SUPPORT PANEL ,FRONT FENDER (L/R) AND FRONT BUMPER	New	1,250.00	700.00
10	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	160.00	120.00
11	TO PROVIDE LABOUR,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,750.00	1,800.00
12	TO MOUNT VEHICLE ON TO CAR O LINER	New	400.00	0.00
13	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	120.00
Gross Labour Cost (\$\$)			8,390.00	4,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >