

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

TP 116
3008

2008 Dec

mv: 75K

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON AUXILLIARY FAN ASSY	1	580.99	580.99 X
AIRCON AUXILLIARY FAN HIGH PRESSURE MODULE	1	680.95	680.95 X
AIRCON CONDENSER Best	1	817.30	817.30 ✓
AIRCON CONDENSER AIR GUIDE CLIPS L/R	6	6.50	39.00 X
AIRCON CONDENSER AIR GUIDE L/R	2	49.77	99.54 X
AIRCON COOLING PIPE	1	900.77	900.77 X
AIRCON DISCHARGE PIPE	1	799.33	799.33 X
AIRCON HIGH PRESSURE SENSOR	1	900.77	900.77 X
AIRCON OUTSIDE TEMPERATURE SENSOR	1	200.99	200.99 X
AIRCON SUCTION PIPE	1	833.75	833.75 X
AUTOTRANSMISSION COOLER Best	1	800.33	800.33 ✓
DRUMPET HORN BRACKET L/R	2	89.77	179.54 X
DRUMPET HORN L/R	2	211.99	423.98 X
ENGINE LOWER UNDER COVER	1	500.31	500.31 X
ENGINE TURBO COOLER	1	300.17	300.17 X
ENGINE TURBO COOLER HOSE 'INLET'	1	211.95	211.95 X
ENGINE TURBO COOLER HOSE 'OUTLET'	1	260.77	260.77 X
FRONT AIR DUCT	1	150.33	150.33 X

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

FRONT AIR DUCT HOSE	1	140.97	140.97 ✓
FRONT AIR DUCT HOSE CLIPS	2	6.50	13.00 ✓
FRONT AIRBAG IMPACT SENSOR L/R	2	260.97	521.94 ✓
FRONT BONNET <i>Detd</i>	1	2830.97	2,830.97 ✓
FRONT BONNET CABLE	1	140.31	140.31 ✓
FRONT BONNET DAMPER L/R	2	105.70	211.40 ✓
FRONT BONNET HINGES L/R	2	140.97	281.94 ✓
FRONT BONNET INNER LOCK HANDLE	1	90.99	90.99 ✓
FRONT BONNET INSULATOR MAT	1	220.99	220.99 ✓
FRONT BONNET MECHANISM LOCK	1	214.70	214.70 ✓
FRONT BONNET NOZZLE L/R	2	203.77	407.54 ✓
FRONT BONNET RUBBER GUIDE STOPPER L/R	4	29.77	119.08 ✓
FRONT BONNET WEATHER STRIP L/R	2	30.17	60.34 ✓
FRONT BUMPER 'CENTER' <i>Detd</i>	1	170.97	170.97 ✓
FRONT BUMPER FOGLAMP GARNISH L/R <i>mem</i>	2	135.70	271.40 ✓
FRONT BUMPER FOGLAMP L/R <i>caused</i>	2	267.70	535.40 ✓
FRONT BUMPER INNER SPONGE <i>Detd</i>	1	140.31	140.31 ✓
FRONT BUMPER L/R <i>Detd</i>	2	850.75	1,701.50 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

FRONT BUMPER LOWER DIFFUSER	1	400.33	400.33 ✓
FRONT BUMPER LOWER RUBBER MOULDING	1	100.17	100.17 ✓
FRONT BUMPER LOWER SIDE RETAINER L/R	2	49.77	99.54 ✓
FRONT BUMPER LOWER UNDER COVER	1	139.77	139.77 ✓
FRONT BUMPER NOZZLE COVER L/R	2	50.99	101.98 ✓
FRONT BUMPER NUMBER PLATE SCREW GARNISH L/R	2	20.17	40.34 ✓
FRONT BUMPER PARKING SENSOR 'ORIGINAL'	4	217.77	871.08 ✓
FRONT BUMPER PARKING SENSOR HOLDER	4	49.95	199.80 ✓
FRONT BUMPER PARKING SENSOR RUBBER SEAL	4	7.11	28.44 ✓
FRONT BUMPER PARKING SENSOR WIRE HARNESS - SET	1	472.80	472.80 ✓
FRONT BUMPER REINFORCEMENT	1	417.70	417.70 ✓
FRONT BUMPER REINFORCEMENT BRACKET L/R	2	160.71	321.42 ✓
FRONT BUMPER SIDE RETAINER L/R	2	50.77	101.54 ✓
FRONT BUMPER TOW HOOK COVER	1	48.77	48.77 ✓
FRONT GRILLE	1	675.70	675.70 ✓
FRONT GRILLE 'LOGO' EMBLEM	1	65.50	65.50 ✓
FRONT GRILLE 'QUATTRO' EMBLEM	1	90.77	90.77 ✓
FRONT HEADLAMP BACK COVER L/R	4	90.97	363.88 ✓

*** This is a computer-generated document which requires no signature. ***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HONG GUANGYUAN
 BLK 222 ANG MO KIO AVE 1 #03-711
 SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

FRONT HEADLAMP H.I.D BARLAST 'ORIGINAL' L/R <i>not new</i>	2	770.97	1,541.94 X
FRONT HEADLAMP H.I.D BULB 'ORIGINAL' L/R	2	500.99	1,001.98 X
FRONT HEADLAMP L/R <i>cracked</i>	2	200.97 200.97 <i>4019.4</i>	401.94 /
FRONT HEADLAMP LOWER BRACKET 'INNER' L/R <i>cracked</i>	2	117.33	234.66 /
FRONT HEADLAMP LOWER BRACKET 'OUTER' L/R	2	109.71	219.42 /
FRONT HEADLAMP NOZZLE HOSE - SET <i>not new</i>	1	270.71	270.71 X
FRONT HEADLAMP NOZZLE L/R <i>cracked</i>	2	240.99	481.98 /
FRONT HEADLAMP TOP BRACKET L/R <i>not new</i>	2	120.97	241.94 X
FRONT LH PASSENGER SEAT SAFETY BELT <i>Activated</i>	1	760.77	760.77 /
FRONT RH DRIVE SEAT SAFETY BELT	1	760.77	760.77 /
FRONT RH FENDER <i>rip</i>	1	690.70	690.70 X
FRONT RH FENDER BRACKET <i>2</i>	1	65.77	65.77 X
FRONT RH FENDER INNER SHIELD <i>not new</i>	1	197.70	197.70 X
FRONT RH FENDER INNER SPONGE	1	30.99	30.99 /
FRONT RH FENDER TOP BRACKET	1	29.70	29.70 /
FRONT SUPPORT PANEL <i>cracked</i>	1	772.70	772.70 /
FRONT SUPPORT PANEL TOP GARNISH <i>Deformed</i>	1	140.99	140.99 /
RADIATOR (AUTO) <i>Best</i>	1	772.70	772.70 /

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

RADIATOR AUXILIARY FAN ASSY	1	760.99	760.99	✓
RADIATOR FAN COWLING	1	270.99	270.99	✓
RADIATOR LOWER AIR GUIDE	1	100.97	100.97	✓
RADIATOR LOWER BRACKET L/R	2	99.71	199.42	✓
RADIATOR LOWER HOSE	1	260.99	260.99	✓
RADIATOR LOWER RUBBER BUSH L/R	2	49.77	99.54	✓
RADIATOR SPARE TANK HOSE	1	130.91	130.91	✓
RADIATOR TOP HOLDER CLIPS L/R	2	6.50	13.00	✓
RADIATOR TOP HOSE	1	260.17	260.17	✓
RADIATOR TOP RUBBER BUSH L/R	2	40.17	80.34	✓
REAR BUMPER	1	1032.70	1,032.70	✓
REAR BUMPER LOWER DIFFUSER	1	477.30	477.30	✓
REAR BUMPER REFLECTOR LAMP L/R	2	238.70	477.40	✓
REAR BUMPER REINFORCEMENT	1	499.77	499.77	✓
REAR BUMPER REINFORCEMENT BRACKET L/R	2	150.15	300.30	✓
REAR BUMPER REVERSE SENSOR 'ORIGINAL'	4	217.77	871.08	✓
REAR BUMPER REVERSE SENSOR HOLDER	4	49.95	199.80	✓
REAR BUMPER REVERSE SENSOR RUBBER SEAL	4	7.11	28.44	✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR BUMPER REVERSE SENSOR WIRE HARNESS - SET <i>Not in</i>	1	470.99	470.99 <i>X</i>
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	49.77	99.54 <i>✓</i>
REAR BUMPER TOW HOOK COVER L/R <i>changed</i>	2	50.15	100.30 <i>✓</i>
REAR END PANEL <i>Distorted</i>	1	1400.99	1,400.99 <i>✓</i>
REAR END PANEL INNER TOP CHROME GARNISH <i>changed</i>	1	299.30	299.30 <i>✓</i>
REAR END PANEL INNER TOP CHROME GARNISH CLIPS <i>new</i>	6	6.50	39.00 <i>10</i>
REAR END PANEL LOCK STRIKER	1	100.97	100.97 <i>✓</i>
REAR END PANEL LOCK STRIKER COVER <i>changed</i>	1	49.75	49.75 <i>✓</i>
REAR END PANEL TAILGATE CLOSE SENSOR	1	140.97	140.97 <i>✓</i>
REAR FENDER INNER AIR VENT L/R <i>Not in</i>	2	97.90	195.80 <i>✓</i>
REAR FENDER INNER SHIELD L/R <i>new</i>	2	211.70	423.40 <i>✓</i>
REAR FENDER INNER UPHOLSTERY TRIM BOARD COVER L/R <i>Not in</i>	2	667.70	1,335.40 <i>X</i>
REAR FENDER INNER UPHOLSTERY TRIM BOARD L/R <i>needed</i>	2	700.99	1,401.98 <i>✓</i>
REAR SPEAKER UPHOLSTERY BOARD <i>Not in</i>	1	1280.99	1,280.99 <i>X</i>
REAR SUB CHASSIS FRAME CROSS MEMBER <i>Ryie</i>	1	1255.70	1,255.70 <i>X</i>
REAR SUB CHASSIS FRAME L/R <i>Ryie</i>	2	1400.97	2,801.94 <i>X</i>
REAR SUSPENSION ABS SENSOR L/R <i>Not in</i>	2	211.70	423.40 <i>X</i>
REAR SUSPENSION CROSS MEMBER <i>Best</i>	1	1060.77	1,060.77 <i>✓</i>

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HONG GUANGYUAN
 BLK 222 ANG MO KIO AVE 1 #03-711
 SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR SUSPENSION CROSS MEMBER BRACKET <i>Best</i>	2	400.97	801.94 ✓
REAR SUSPENSION CROSS MEMBER SCREW <i>Best</i>	4	16.77	67.08 ✓
REAR SUSPENSION DRIVE SHAFT ASSY L/R <i>not done</i>	2	2427.30	4,854.60 ✗
REAR SUSPENSION KNUCKLE ARM BEARING L/R <i>new</i>	2	500.67	1,001.34 ✓
REAR SUSPENSION KNUCKLE ARM L/R <i>Best</i>	2	987.30	1,974.60 ✓
REAR SUSPENSION LEVERING SENSOR L/R <i>new</i>	2	499.77	999.54 ✓
REAR SUSPENSION LOWER ARM L/R <i>Best</i>	2	813.77	1,627.54 ✓
REAR SUSPENSION SHOCK ABSORBER L/R <i>Best</i>	2	1307.30	2,614.60 ✓
REAR SUSPENSION SHOCK ABSORBER STOPPER L/R <i>3 new</i>	2	90.77	181.54 ✗
REAR SUSPENSION SHOCK ABSORBER TOP MOUNTING L/R	2	129.77	259.54 ✗
REAR SUSPENSION STABILIZER BAR <i>Best</i>	1	380.77	380.77 ✓
REAR SUSPENSION STABILIZER BAR BRACKET L/R <i>Best</i>	2	70.97	141.94 ✓
REAR SUSPENSION STABILIZER BAR LINK L/R <i>2 Best</i>	2	130.77	261.54 ✓
REAR SUSPENSION TRAILING ARM L/R	2	400.97	801.94 ✓
REAR SUSPENSION UPPER ARM L/R	2	466.99	933.98 ✓
REAR TAILGATE <i>sealed</i>	1	2997.30	2,997.30 ✓
REAR TAILGATE '207' EMBLEM <i>3 new</i>	1	100.97	100.97 ✓
REAR TAILGATE 'LOGO' EMBLEM	1	99.71	99.71 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR TAILGATE 'Q5' EMBLEM	1	90.77	90.77 ✓
REAR TAILGATE 'QUATTRO' EMBLEM	1	85.77	85.77 ✓
REAR TAILGATE DAMPER L/R	2	120.77	241.54 ✗
REAR TAILGATE HINGES GARNISH L/R	2	90.97	181.94 ✗
REAR TAILGATE HINGES L/R	2	211.70	423.40 ✗
REAR TAILGATE INNER TRIM BOARD	1	599.71	599.71 ✓
REAR TAILGATE MECHANISM LOCK GARNISH	1	100.97	100.97 ✗
REAR TAILGATE MECHANISM LOCK WITH MOTOR	1	170.97	170.97 ✗
REAR TAILGATE NUMBER PLATE LAMP L/R	2	49.97	99.94 ✗
REAR TAILGATE OUTER LOCK HANDLE SWITCH	1	180.99	180.99 ✗
REAR TAILGATE RUBBER GUIDE STOPPER L/R	4	40.33	161.32 ✗
REAR TAILGATE WEATHER STRIP	1	299.71	299.71 ✓
REAR TAILGATE WINDSCREEN COMPLETE WITH MOULDING	1	1007.93	1,007.93 ✓
REAR TAILGATE WINDSCREEN INNER GARNISH 'TOP'	1	199.71	199.71 ✗
REAR TAILGATE WINDSCREEN INNER GARNISH L/R	2	140.17	280.34 ✗
REAR TAILLAMP BACK COVER L/R	2	40.17	80.34 ✗
REAR TAILLAMP CLIPS L/R	4	6.50	26.00 ✓
REAR TAILLAMP L/R	2	1245.70	2,491.40 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR TWIN EXHAUST ALUMINIUM HEAT SHIELD L/R <i>compd.</i>	2	270.97	541.94 ✓
REAR TWIN EXHAUST BRACKET L/R <i>2nd</i>	2	99.71	199.42 ✓
REAR TWIN EXHAUST END CHROME PIPE L/R <i>not new</i>	2	400.97	801.94 ✗
REAR TWIN EXHAUST GASKET L/R <i>new</i>	2	40.17	80.34 ✓
REAR TWIN EXHAUST RUBBER MOUNTING L/R <i>not new</i>	4	90.71	362.84 ✗
REAR TWIN EXHAUST SILENCER BOX <i>Box</i>	1	997.30	997.30 ✓
REAR WELL PANEL <i>2nd</i>	1	1400.97	1,400.97 ✓
REAR WELL PANEL INNER TOOLS SPONGE <i>included</i>	1	200.93	200.93 ✓
REAR WELL PANEL INNER TOP BATTERY SPONGE <i>new</i>	1	199.71	199.71 ✗
REAR WELL PANEL INNER TOP BATTERY TERMINAL MODULE <i>new</i>	1	580.97	580.97 ✗
REAR WELL PANEL INNER TOP BATTERY TRAY <i>2nd</i>	1	215.71	215.71 ✓
REAR WELL PANEL INNER TOP SIDE UPHOLSTERY TRIM BRACKET L/R <i>new</i>	2	140.97	281.94 ✗
REAR WELL PANEL INNER TOP SIDE UPHOLSTERY TRIM L/R <i>new</i>	2	500.33	1,000.66 ✗
REAR WELL PANEL INNER TOP SUB WOOFER RETAINER LOCK <i>2nd</i>	1	150.71	150.71 ✓
REAR WELL PANEL INNER TOP SUB WOOFER RETAINER LOCK HOLDER <i>new</i>	1	150.77	150.77 ✗
REAR WELL PANEL INNER TOP SUB WOOFER UNIT 'ORIGINAL' <i>2nd</i>	1	400.71	400.71 ✓
REAR WELL PANEL INNER TOP TRAY <i>2nd</i>	1	280.93	280.93 ✓
REAR WELL PANEL INNER TOP UPHOLSTERY BOARD <i>not new</i>	1	729.70	729.70 ✗

*** This is a computer-generated document which requires no signature. ***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

HONG GUANGYUAN
 BLK 222 ANG MO KIO AVE 1 #03-711
 SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

Subtotal before discount			84,257.42
Percentage discount 0%			0.00
Sub-total 1			84,257.42
AUTOTRANSMISSION FLUID - BOT <i>new</i>	1	120.00	120.00 <i>80</i>
ENGINE LOWER UNDER COVER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT BONNET INSULATOR MAT CLIPS - SET <i>new</i>	1	30.00	30.00 +
FRONT BUMPER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT BUMPER NUMBER PLATE <i>new</i>	1	25.00	25.00 ✓
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
FRONT SUPPORT PANEL TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
RADIATOR COOLANT - BOT <i>new</i>	1	80.00	80.00 <i>50</i>
REAR 20" SPORT RIM L/R <i>new</i>	2	1350.00	2,700.00 +
REAR 225/45 R 20 101W TYRE L/R <i>new</i>	2	980.00	1,960.00 +
REAR BUMPER CLIPS - SET <i>new</i>	1	30.00	30.00 ✓
REAR BUMPER REFLECTOR LAMP BRAKE BULB L/R <i>new</i>	4	12.00	48.00 ✓
REAR BUMPER REFLECTOR LAMP REVERSE BULB L/R <i>new</i>	2	12.00	24.00 ✓
REAR BUMPER REFLECTOR LAMP SIGNAL BULB L/R <i>new</i>	2	12.00	24.00 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

REAR BUMPER REFLECTOR LAMP WIRE HARNESS L/R - SET	2	799.75	1,599.50
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	30.00	60.00
REAR FENDER INNER UPHOLSTERY TRIM BOARD CLIPS L/R - SET	2	30.00	60.00
REAR TAILGATE INNER CAR CAMERA RECORDER	1	800.00	800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	30.00	30.00
REAR TAILGATE NUMBER PLATE '3D'	1	190.00	190.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILGATE WINDSCREEN SEALANT	1	100.00	100.00
REAR WELL PANEL INNER JACKING TOOLS	1	180.00	180.00
REAR WELL PANEL INNER TOP BATTERY	1	350.00	350.00
REAR WELL PANEL INSULATOR MAT	1	280.00	280.00
Subtotal before discount			8,920.50
Percentage discount 0%			0.00
Sub-total 2			8,920.50
Parts-total			93,177.92

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To reset system after repair works

120

180.00

800.00

200

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HONG GUANGYUAN
BLK 222 ANG MO KIO AVE 1 #03-711
SINGAPORE 560222

Contact : 86132484, 91089899

ESTIMATE

Repair Code : CLM13568

Date in : 07/06/2016

Vehicle Num. : SKX3328D

Model : AUDI Q5 2.0L TFSI QUATTRO AT D/AB HID 4WD 5DR

Chassis/Eng# : WAUZZZ8R7AA047491/CDN079710

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

~~180.00~~ 150

To remove, reinstall tailgate windscreen

~~150.00~~ 120

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

~~580.00~~ 450

To road test driving, check and resetting wheel alignments system.

~~180.00~~ 80

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~140.00~~ 80

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

~~1,500.00~~ 1000

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

~~1,250.00~~ 700

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

~~160.00~~ 120

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~2,750.00~~ 1800

To mount vehicle on to Car 'O' Liner.

~~400.00~~ X

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ ✓

Labour Total

8,390.00

Parts & Labour Total

101,567.92

*** This is a computer-generated document which requires no signature.***

page 12

total : 49485.07

4/5: 39.5K

21 days.

39.5K