

INS: CASE OWNER:

Kumar | CCH/AIG160

10792, A1939

LKK:  
IDAC:

Surveyor:

Adrian

DOI:

13/6/16

Date / Time:

10/6/16

Registered in Merimen:

10/6/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

5JX80045

Claim No.:

865333711056

Name of Insured:

Acquisition Pte Ltd

Policy No.:

Insured Tel No.:

HP:

96640641

Make / Model:

Audi Q7-3.6 P31 Quattro S-line

Excess Sec II :SS

D.O.A.:

9/6/16

Place of Accident:

East coast parkway East Block  
near parking lot

Is driver the owner?

(YES NO)

Nature of Accident:

If NO, Driver Name / Age:

Ism Johnson

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

96640641

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

5JX80045

5JW5954K

SHD1899B



INSRS:

WSP:

Tel:

Liability:

01

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

TP:

N-51



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

14/6/16

16/6/16

21/01/16 @ 10:35AM

SPOKE TO BT MR IAN @ 96640641.  
HE CONFIRMED ACCIDENT DETAILS & REAR  
ENDED TP IN C.C. INFORMED TP CLAIMS  
& NCD ISSUES.  
SENT LETTER TO BT. FILE PASS TO QA.

16/08/16

BMAIL CAPABILITY CHECK.  
PENDING INVESTIGATION

13-11-17

TO EXPEDITE PROCESS OF SETTLEMENT.  
FINISHED.

22/06/18

TP UNKNOWN. NO TP LOD IN YET.  
BMAIL TO HQ TO TEMP. CLOSE  
CASE.

30/10/18

TP LOD IN.  
TYPE REPORT FOR HANDLER APPROVAL

PRELIMINARY ADVICE

Date/Time:

Sent By:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

9,800.00 (21 days) Reduction: 73 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

100% (Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0.1

Repair Cost:

SS

10,486.00

(5 veh. CC, 0.4M VEH) -

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

(\$ x days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

SS

54.35

Medical:

SS

-

Disbursement:

SS

153.50

(e.g. Tow/Independent)

Legal Cost:

SS

-

Total:

SS

10,673.85

Global Sum SS: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

10,673.85

Name 1:

N-51 AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

320.00

18/10/18

ASS. REC. BY: Adrian Ling

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGW 5954K Yr Regn: 2007, JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Verna c.c. 1399Colour: Silver A/C: Insured / Std / NI / NASp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHCM 41AR7H126615Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15R: 195/55R15BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 13/06/16Survey held at N51Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction              |
|-------------|-----------------------------------|
|             | <u>TP ALG</u>                     |
|             | <u>L10 \$9,800.00</u>             |
|             | <u>CRSD - \$26,547.50 (73.7%)</u> |
|             | <u>WV: \$16,000.00</u>            |
|             | <u>UTA: \$2,000.00</u>            |
|             | <u>NETT: \$</u>                   |

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                           |                            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                        |                                                                                           | Ref : CC4/AIG16010792/Ahg3 |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120                                                                             |                                                                                           | Date : 10-06-2016          |  |
|                                                                                                                                           |                                                                                           | Code : AIG                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                           |                            |                                                                                     |
| Insured Veh.                                                                                                                              | SJX 8004S                                                                                 | Veh. Inspected             | SGW 5954K                                                                           |
| Policy No.                                                                                                                                |                                                                                           | Coverage (\$)              | 0.00                                                                                |
| Claim No.                                                                                                                                 |                                                                                           | Excess (\$)                | 0.00                                                                                |
| Assign From                                                                                                                               |                                                                                           | Assign Date                | 10/06/2016                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                           |                            |                                                                                     |
| Make & Model                                                                                                                              |                                                                                           | c.c                        | 0                                                                                   |
| Engine No.                                                                                                                                | HIDDEN                                                                                    | Year of Reg.               |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                           | Colour                     |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                         | Steering                   |                                                                                     |
| Brakes                                                                                                                                    |                                                                                           | Modification               |                                                                                     |
| General                                                                                                                                   |                                                                                           |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                           |                            |                                                                                     |
|                                                                                                                                           | Size                                                                                      | Make                       | Balance                                                                             |
| R/H Front Tyre                                                                                                                            |                                                                                           |                            | mm                                                                                  |
| L/H Front Tyre                                                                                                                            |                                                                                           |                            | mm                                                                                  |
| R/H Rear Tyre                                                                                                                             |                                                                                           |                            | mm                                                                                  |
| L/H Rear Tyre                                                                                                                             |                                                                                           |                            | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                           |                            |                                                                                     |
|                                                                                                                                           |                                                                                           |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                           |                            |                                                                                     |
| Accident Date                                                                                                                             | 09/06/2016                                                                                | Inspection Date            | 13/06/2016                                                                          |
| Survey held at                                                                                                                            | N-51 AUTOMOTIVE PL<br>2 KAKI BUKIT AVE 2<br>#01-17 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                           |                            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                            |                                                                                     |

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C



2007 July

OTHELLO,  
BLK 106 TOWER ROAD #06-438  
SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

### Parts and Labour Assesment

| Description of part                                      | Qty | Unit Price | Amount   |
|----------------------------------------------------------|-----|------------|----------|
| AIR CLEANER BOX 'LOWER' <i>cracked</i>                   | 1   | 48.00      | 48.00 ✓  |
| AIR CLEANER BOX 'TOP'                                    | 1   | 49.00      | 49.00 ✓  |
| AIR CLEANER BOX HOSE <i>deformed</i>                     | 1   | 92.00      | 92.00 ✓  |
| AIR RESONATOR BOX <i>photo show</i>                      | 1   | 47.00      | 47.00 ✗  |
| AIR RESONATOR BOX HOSE                                   | 1   | 121.00     | 121.00 ✗ |
| AIRCON AUXILLIARY FAN ASSY <i>Distorted</i>              | 1   | 420.00     | 420.00 ✓ |
| AIRCON CONDENSER <i>Distorted</i>                        | 1   | 720.00     | 720.00 ✓ |
| AIRCON CONDENSER LOWER RUBBER BUSH L/R <i>photo show</i> | 2   | 18.00      | 36.00 ✓  |
| AIRCON CONDENSER TOP RUBBER BUSH L/R                     | 2   | 16.00      | 32.00 ✓  |
| AIRCON COOLING PIPE                                      | 1   | 123.00     | 123.00 ✗ |
| AIRCON DISCHARGE PIPE                                    | 1   | 184.80     | 184.80 ✗ |
| AIRCON SUCTION PIPE                                      | 1   | 164.00     | 164.00 ✗ |
| BATTERY BRACKET <i>ALL</i>                               | 1   | 15.00      | 15.00 ✗  |
| BATTERY LOWER PANEL                                      | 1   | 91.00      | 91.00 ✗  |
| BATTERY TRAY                                             | 1   | 31.00      | 31.00 ✗  |
| ENGINE ALTERNATOR ASSY                                   | 1   | 602.00     | 602.00 ✗ |
| ENGINE ALTERNATOR BELT                                   | 1   | 27.00      | 27.00 ✗  |
| ENGINE MOUNTING 'FRT'                                    | 1   | 281.00     | 281.00 ✗ |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                                   |   |         |            |
|---------------------------------------------------|---|---------|------------|
| ENGINE MOUNTING 'FRT' BRACKET                     | 1 | 119.00  | 119.00 ✓   |
| EXHAUST CATALYTIC CONVERTER                       | 1 | 1955.00 | 1,955.00 ✓ |
| EXHAUST CATALYTIC CONVERTER ALUMINIUM HEAT SHIELD | 1 | 61.00   | 61.00 ✓    |
| EXHAUST CATALYTIC LAMDA SENSOR                    | 1 | 321.00  | 321.00 ✓   |
| FRONT AIR DUCT                                    | 1 | 110.30  | 110.30 ✓   |
| FRONT AIR DUCT CLIPS                              | 2 | 6.50    | 13.00 ✓    |
| FRONT BONNET Distorted                            | 1 | 724.00  | 724.00 ✓   |
| FRONT BONNET CABLE Not seen                       | 1 | 68.00   | 68.00 ✓    |
| FRONT BONNET HINGES L/R Bent                      | 2 | 48.00   | 96.00 ✓    |
| FRONT BONNET INNER LOCK HANDLE Not seen           | 1 | 25.00   | 25.00 ✓    |
| FRONT BONNET MECHANISM LOCK Damaged               | 1 | 55.80   | 55.80 ✓    |
| FRONT BONNET RUBBER GUIDE STOPPER L/R Not seen    | 7 | 6.80    | 47.60 ✓    |
| FRONT BONNET STAND Not seen                       | 1 | 23.00   | 23.00 ✓    |
| FRONT BONNET STAND HOLDER CLIPS                   | 1 | 6.50    | 6.50 ✓     |
| FRONT BONNET WEATHER STRIP OK                     | 1 | 22.80   | 22.80 ✓    |
| FRONT BUMPER Distorted                            | 1 | 412.00  | 412.00 ✓   |
| FRONT BUMPER INNER SPONGE Cracked                 | 1 | 101.00  | 101.00 ✓   |
| FRONT BUMPER LOWER CENTER GRILLE Cracked          | 1 | 75.80   | 75.80 ✓    |

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                                   |   |        |            |
|---------------------------------------------------|---|--------|------------|
| FRONT BUMPER LOWER RUBBER MOULDING <i>not new</i> | 1 | 43.00  | 43.00 ✓    |
| FRONT BUMPER REINFORCEMENT <i>Best</i>            | 1 | 195.00 | 195.00 ✓   |
| FRONT BUMPER SIDE RETAINER L/R <i>new</i>         | 2 | 28.00  | 56.00 ✓    |
| FRONT BUMPER TOW HOOK COVER <i>Best</i>           | 1 | 22.00  | 22.00 ✓    |
| FRONT FENDER BRACKET L/R <i>not new</i>           | 2 | 18.00  | 36.00 ✗    |
| FRONT FENDER INNER SHIELD L/R                     | 2 | 44.00  | 88.00 ✗    |
| FRONT FENDER L/R <i>Buckled</i>                   | 2 | 303.00 | 606.00 ✓   |
| FRONT FENDER SIGNAL LAMP L/R <i>not new</i>       | 2 | 33.00  | 66.00 ✓    |
| FRONT GRILLE <i>cracked</i>                       | 1 | 258.00 | 258.00 ✓   |
| FRONT GRILLE 'LOGO' EMBLEM <i>new</i>             | 1 | 28.00  | 28.00 ✓    |
| FRONT GRILLE CLIPS <i>new</i>                     | 4 | 6.50   | 26.00 ✓    |
| FRONT HEADLAMP BACK COVER L/R <i>not new</i>      | 2 | 39.80  | 79.60 ✓    |
| FRONT HEADLAMP CLIPS L/R <i>new</i>               | 4 | 6.50   | 26.00 ✓    |
| FRONT HEADLAMP L/R <i>cracked</i>                 | 2 | 356.00 | 712.00 ✓   |
| FRONT HEADLAMP LOWER BRACKET L/R <i>Best</i>      | 2 | 16.00  | 32.00 ✓    |
| FRONT POWER STEERING COOLER PIPE <i>not new</i>   | 1 | 88.00  | 88.00 ✗    |
| FRONT SUB CHASSIS FRAME L/R <i>Repair</i>         | 2 | 934.00 | 1,868.00 ✗ |
| FRONT SUPPORT PANEL <i>Distorted</i>              | 1 | 803.30 | 803.30 ✓   |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                        |   |         |            |
|----------------------------------------|---|---------|------------|
| FUSE BOX COVER ASSY                    | 1 | 2237.00 | 2,237.00 ✓ |
| HORN                                   | 1 | 77.00   | 77.00 ✓    |
| POWER STEERING BELT                    | 1 | 48.00   | 48.00 ✓    |
| POWER STEERING HOSE                    | 2 | 208.00  | 416.00 ✓   |
| POWER STEERING PUMP ASSY               | 1 | 785.00  | 785.00 ✓   |
| RADIATOR (AUTO) Distorted              | 1 | 594.00  | 594.00 ✓   |
| RADIATOR AUXILLIARY FAN ASSY Distorted | 1 | 481.00  | 481.00 ✓   |
| RADIATOR CAP                           | 1 | 18.00   | 18.00 ✓    |
| RADIATOR LOWER HOSE                    | 1 | 40.00   | 40.00 ✓    |
| RADIATOR LOWER RUBBER BUSH L/R         | 2 | 12.00   | 24.00 ✓    |
| RADIATOR SPARE TANK HOSE               | 1 | 28.00   | 28.00 ✓    |
| RADIATOR TOP BRACKET L/R               | 2 | 48.00   | 96.00 ✓    |
| RADIATOR TOP HOSE                      | 1 | 19.00   | 19.00 ✓    |
| RADIATOR TOP RUBBER BUSH L/R           | 2 | 12.00   | 24.00 ✓    |
| REAR BOOTLID Distorted                 | 1 | 729.00  | 729.00 ✓   |
| REAR BOOTLID 'LOGO' EMBLEM             | 1 | 24.00   | 24.00 ✓    |
| REAR BOOTLID 'M1.4' EMBLEM             | 1 | 22.00   | 22.00 ✓    |
| REAR BOOTLID 'VERNA' EMBLEM            | 1 | 28.00   | 28.00 ✓    |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

2017

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                                        |   |        |          |
|--------------------------------------------------------|---|--------|----------|
| REAR BOOTLID HINGES L/R <i>Est</i>                     | 2 | 75.00  | 150.00 ✓ |
| REAR BOOTLID INNER UPHOLSTERY TRIM <i>crumpled</i>     | 1 | 132.00 | 132.00 ✓ |
| REAR BOOTLID MECHANISM LOCK <i>Damaged</i>             | 1 | 63.00  | 63.00 ✓  |
| REAR BOOTLID MECHANISM LOCK GARNISH <i>Not New</i>     | 1 | 54.00  | 54.00 ✗  |
| REAR BOOTLID NUMBER PLATE LAMP L/R <i>Not New</i>      | 2 | 61.00  | 122.00 ✗ |
| REAR BOOTLID OUTER GARNISH <i>cracked</i>              | 1 | 170.00 | 170.00 ✓ |
| REAR BOOTLID OUTER GARNISH CLIPS <i>New</i>            | 4 | 6.50   | 26.00 ✓  |
| REAR BOOTLID OUTER KEY LOCK <i>Damaged</i>             | 1 | 42.10  | 42.10 ✓  |
| REAR BOOTLID OUTER KEY LOCK RUBBER SEAL <i>New</i>     | 1 | 18.00  | 18.00 ✓  |
| REAR BOOTLID RUBBER GUIDE STOPPER L/R <i>Not New</i>   | 2 | 13.10  | 26.20 ✗  |
| REAR BOOTLID WEATHER STRIP <i>Est</i>                  | 1 | 72.60  | 72.60 ✓  |
| REAR BUMPER <i>Distorted</i>                           | 1 | 491.80 | 491.80 ✓ |
| REAR BUMPER INNER SIDE SHIELD CLIPS L/R <i>Not New</i> | 8 | 6.50   | 52.00 ✗  |
| REAR BUMPER INNER SIDE SHIELD L/R <i>New</i>           | 2 | 25.00  | 50.00 ✗  |
| REAR BUMPER INNER SPONGE <i>cracked</i>                | 1 | 82.80  | 82.80 ✓  |
| REAR BUMPER REINFORCEMENT <i>Distorted</i>             | 1 | 136.80 | 136.80 ✓ |
| REAR BUMPER REINFORCEMENT LOWER BRACKET <i>Damaged</i> | 1 | 19.00  | 19.00 ✓  |
| REAR BUMPER REINFORCEMENT TOP BRACKET <i>Damaged</i>   | 2 | 19.00  | 38.00 ✓  |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*



Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                                        |   |         |            |
|--------------------------------------------------------|---|---------|------------|
| REAR BUMPER SIDE RETAINER L/R <i>new</i>               | 2 | 23.00   | 46.00 ✓    |
| REAR EXHAUST ALUMINIUM HEAT SHIELD <i>crumpled</i>     | 1 | 85.00   | 85.00 ✓    |
| REAR EXHAUST GASKET <i>new</i>                         | 1 | 8.50    | 8.50 ✓     |
| REAR EXHAUST RUBBER MOUNTING <i>Not new</i>            | 2 | 19.50   | 39.00 ✗    |
| REAR EXHAUST SILENCER BOX <i>best</i>                  | 1 | 442.50  | 442.50 ✓   |
| REAR LH FENDER <i>Buckled</i>                          | 1 | 1023.00 | 1,023.00 ✓ |
| REAR LH FENDER INNER AIR VENT <i>Not new</i>           | 1 | 28.00   | 28.00 ✗    |
| REAR LH FENDER INNER PANEL <i>Repair</i>               | 1 | 897.00  | 897.00 ✗   |
| REAR LH FENDER INNER UPHOLSTERY TRIM <i>Deformed</i>   | 1 | 138.00  | 138.00 ✓   |
| REAR LH FENDER PETROL LID COVER <i>2 new</i>           | 1 | 55.00   | 55.00 ✗    |
| REAR LH FENDER PETROL LID MECHANISM LOCK <i>new</i>    | 1 | 48.00   | 48.00 ✗    |
| REAR RH FENDER <i>Buckled</i>                          | 1 | 1023.00 | 1,023.00 ✓ |
| REAR RH FENDER INNER AIR VENT <i>Not new</i>           | 1 | 28.00   | 28.00 ✗    |
| REAR RH FENDER INNER PANEL <i>Repair</i>               | 1 | 897.00  | 897.00 ✗   |
| REAR RH FENDER INNER UPHOLSTERY TRIM <i>torn</i>       | 1 | 165.00  | 165.00 ✓   |
| REAR SPEAKER PANEL <i>Repair</i>                       | 1 | 378.00  | 378.00 ✗   |
| REAR SPEAKER PANEL TOP UPHOLSTERY BOARD <i>not new</i> | 1 | 339.00  | 339.00 ✗   |
| REAR SUB CHASSIS FRAME L/R <i>Repair</i>               | 2 | 1095.00 | 2,190.00 ✗ |

\*\*\* This is a computer-generated document which requires no signature \*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                                          |    |          |                                  |
|----------------------------------------------------------|----|----------|----------------------------------|
| REAR TAILLAMP CLIPS <i>me</i>                            | 4  | 6.50     | 26.00 ✓                          |
| REAR TAILLAMP INNER PANEL L/R <i>Dented</i>              | 2  | 470.00   | <del>940.00</del> <sup>204</sup> |
| REAR TAILLAMP L/R <i>cracked</i>                         | 2  | 238.00   | 476.00 ✓                         |
| REAR WHEEL HOUSE PANEL ASSY L/R <i>Repair</i>            | 2  | 897.00   | 1,794.00 ✓                       |
| REAR WINDSCREEN INNER GARNISH CLIPS L/R <i>2 not new</i> | 10 | 6.50     | 65.00 ✓                          |
| REAR WINDSCREEN INNER GARNISH L/R                        | 2  | 71.00    | 142.00 ✓                         |
| REAR WINDSCREEN MOULDING <i>rec</i>                      | 1  | 47.80    | 47.80 ✓                          |
| SPARE TYRE PANEL <i>Distorted</i>                        | 1  | 468.10   | 468.10 ✓                         |
| SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD <i>Rehd</i>  | 1  | 339.00   | <del>339.00</del> <sup>215</sup> |
| SPARE TYRE RETAINER LOCK <i>rest</i>                     | 1  | 25.00    | 25.00 ✓                          |
| SPARE TYRE SIDE PANEL L/R <i>Repair</i>                  | 2  | 98.00    | 196.00 ✓                         |
| WASHER TANK <i>2 not new</i>                             | 1  | 35.00    | 35.00 ✓                          |
| WASHER TANK MOTOR                                        | 1  | 72.00    | 72.00 ✓                          |
| Subtotal before discount                                 |    | 13500.70 | 32,245.70                        |
| Percentage discount 20%                                  |    | 10800.56 | 6,449.14                         |
| Sub-total 1                                              |    |          | 25,796.56                        |
| BATTERY <i>Not new</i>                                   | 1  | 380.00   | 380.00 ✓                         |
| FRONT BUMPER CLIPS - SET <i>new</i>                      | 1  | 30.00    | 30.00 ✓                          |

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                                             |   |        |                        |
|-------------------------------------------------------------|---|--------|------------------------|
| FRONT BUMPER NUMBER PLATE <i>Best</i>                       | 1 | 25.00  | 25.00 ✓                |
| FRONT BUMPER NUMBER PLATE HOLDER <i>Del d</i>               | 1 | 50.00  | <del>50.00</del> 30 ✓  |
| FRONT FENDER INNER SHIELD CLIPS L/R - SET <i>2</i>          | 2 | 30.00  | 60.00 ✓                |
| FRONT HEADLAMP BULB L/R                                     | 2 | 40.00  | 80.00 ✓                |
| FRONT HEADLAMP PARKING BULB L/R                             | 2 | 10.00  | 20.00 ✓                |
| FRONT HEADLAMP SIGNAL BULB L/R                              | 2 | 15.00  | 30.00 ✓                |
| POWER STEERING FLUID - BOT                                  | 1 | 25.00  | 25.00 ✓                |
| RADIATOR COOLANT - BOT <i>new</i>                           | 1 | 80.00  | <del>80.00</del> 40 ✓  |
| REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS - SET <i>new</i>   | 1 | 30.00  | 30.00 ✓                |
| REAR BOOTLID NUMBER PLATE <i>Best</i>                       | 1 | 25.00  | 25.00 ✓                |
| REAR BOOTLID NUMBER PLATE HOLDER <i>Del d</i>               | 1 | 50.00  | <del>50.00</del> 30 ✓  |
| REAR BOOTLID REFLECTOR STICKER L/R - SET <i>new</i>         | 1 | 190.00 | 190.00 ✓               |
| REAR BUMPER CLIPS - SET <i>new</i>                          | 1 | 30.00  | 30.00 ✓                |
| REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>             | 1 | 350.00 | <del>350.00</del> 40 ✓ |
| REAR BUMPER RIVET - SET <i>new</i>                          | 1 | 40.00  | 40.00 ✓                |
| REAR LH FENDER INNER UPHOLSTERY TRIM CLIPS - SET <i>new</i> | 1 | 30.00  | 30.00 ✓                |
| REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET <i>new</i> | 1 | 30.00  | 30.00 ✓                |
| REAR SPEAKER PANEL SPEAKER L/R <i>Not new</i>               | 2 | 180.00 | 360.00 ✓               |

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

|                                        |   |        |                         |
|----------------------------------------|---|--------|-------------------------|
| REAR TAILLAMP BRAKE BULB L/R           | 4 | 12.00  | 48.00 ✓                 |
| REAR TAILLAMP REVERSE BULB L/R         | 2 | 12.00  | 24.00 ✓                 |
| REAR TAILLAMP SIGNAL BULB L/R          | 2 | 12.00  | 24.00 ✓                 |
| REAR WINDSCREEN SEALANT                | 1 | 100.00 | <del>100.00</del> 60 ✓  |
| SPARE TYRE                             | 1 | 280.00 | 280.00 ✓                |
| SPARE TYRE PANEL INNER BRAKE DOWN SIGN | 1 | 150.00 | 150.00 ✓                |
| SPARE TYRE PANEL INNER JACKING TOOL    | 1 | 180.00 | 180.00 ✓                |
| SPARE TYRE PANEL INSULATOR MAT         | 1 | 350.00 | <del>350.00</del> 150 ✓ |
| Subtotal before discount               |   |        | 3,071.00                |
| Percentage discount 0%                 |   |        | 0.00                    |
| Sub-total 2                            |   |        | 3,071.00                |
| Parts-total                            |   |        | <b>28,867.56</b>        |

## LABOUR

|                                                                                                                                                   |                           |
|---------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|
| To remove, change air con parts, vacuums, refill air con gas.                                                                                     | <del>180.00</del> 120 ✓   |
| To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.                       | <del>180.00</del> 100 ✓   |
| To remove and refit rear windscreen(to FR)                                                                                                        | <del>150.00</del> 120 ✓   |
| To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)                                             | <del>140.00</del> 80 ✓    |
| To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel. | <del>2,000.00</del> 140 ✓ |
| To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.                                               | <del>1,250.00</del> 80 ✓  |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

OTHELLO .  
 BLK 106 TOWER ROAD #06-438  
 SINGAPORE 322106

Contact : 62999282 90674660

## ESTIMATE

Repair Code : CLM13572

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Model : HYUNDAI VERNA 1.4 AUTO

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

~~160.00~~ 80

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~2,750.00~~ 25

To mount vehicle on to Car 'O' Liner.

5220

~~400.00~~ X

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ 80

**Labour Total**

**7,330.00**

**Parts & Labour Total**

**36,197.56**

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 10

total : 16280.56

h/c 98K

21 Days.

98K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**Vic (LKKAUTO)**

---

**From:** Vic (LKKAUTO)  
**Sent:** Monday, 15 August, 2016 3:00 PM  
**To:** sales@n51.com.sg; sabrina@n51.com.sg  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** Your Ref: SGW 5954K\_ACCIDENT INVOLVING VEHICLES SJX 8004S / SGW 5954K / OTHERS ON 09/06/2016

Your Ref: SGW 5954K  
Our Ref: CC4/AIG16010792/Ahg3

"WITHOUT PREJUDICE"

Dear Sir/Madam,

**ACCIDENT INVOLVING VEHICLES SJX 8004S / SGW 5954K / OTHERS ON 09/06/2016**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## Print Received Message

This mail is associated with :

**\*SGW5954K (8653337110SG)  
[SJX8004S]**

TP

OTHELLO

Jun 9 2016 12:00AM

[OCEANVISION PTE LTD]

N-51 Automotive Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 12/12/2018 14:40 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10673.85) - SGW5954K - Claim Handler: Kumar, Arulmani

Approved:10673.85.



# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921  
Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510  
Email: sales@n51.com.sg  
Company Reg. No.: 200616038C  
GST Registration No.: 200616038C

21-Aug-2018

Our ref: CLM13572 / SGW5954K / JUN-29/2016

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
NO.78 SHENTON WAY  
#07-16 CHARTIS BUILDING  
SINGAPORE 079120

**ATTN: MOTOR CLAIMS DEPARTMENT**

Dear Sir @ Mdm,

**Re: Accident involving SGW5954K & SJX8004S on 09/06/2016**  
**Along ECP expressway before Marina Parade exit**

We refer to the above accident which was caused due to the negligence of your insured driver of vehicle No: **SJX8004S** whose vehicle was insured with you at the material date of the accident.

We are proposing for a direct settlement on the claims as following **EXCLUDE** personal injury in respect of claim arising out of the abovementioned accident.

|                      |                               |
|----------------------|-------------------------------|
| Cost of repairs      | \$ 10,486.00 (Include 7% GST) |
| Towing Fee           | \$ 53.50                      |
| Towing Fee           | \$ 100.00                     |
| LTA Search           | \$ 5.35                       |
| 3rd Party GIA Report | \$ 29.00                      |
|                      | <b>S \$ 10,673.85</b>         |

We enclosed herein the following documents for your necessary attention.

- 1) Our Final Repair Bill No: CLM13572
- 2) Island Recovery Services - No: 1103941
- 3) Autobay Towing - SGW5954K (receipt attached)
- 4) LTA Search Fee
- 5) 3rd Party Report - GR-16-066538, GR-16-066539
- 6) Letter Authorisation To Act
- 7) Release Voucher (AIG Express Third Party Claim)

Any correspondence, kindly email to [sabrina@n51.com.sg](mailto:sabrina@n51.com.sg)

We look forward to your prompt reply.

Yours faithfully,



**N-51 Automotive Pte Ltd**  
S.Y. NEO  
Managing Director





## Nur Syafiqah (LKKAuto)

---

**From:** Nur Syafiqah (LKKAuto)  
**Sent:** Wednesday, 27 July, 2016 10:52 AM  
**To:** IAN@OCEANVISION.COM.SG  
**Cc:** Nur Syafiqah (LKKAuto); Vic (LKKAuto); Admin A  
**Subject:** ACCIDENT INVOLVING SJX 8004S / SGW 5954K / OTHERS ON 09.06.2016

REF NO: CC4/AIG16010792/Ahg3

27 JULY 2016

OCEANVISION PTE LTD  
40A TOH CRESCENT  
SINGAPORE 507952

Dear Sir/Madam,

### ACCIDENT INVOLVING SJX 8004S / SGW 5954K / OTHERS ON 09.06.2016

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,

**Syaf** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-5792 | email: [NurSyafiqah@lkkauto.com](mailto:NurSyafiqah@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## AUTHORISATION TO ACT

I, OTHELLO (the third party claimant) of BLK 106 TOWER ROAD  
#06-438 (S) 322106 (address), owner of SWN 5454K (vehicle no.)  
hereby authorize N-51 AUTOMOTIVE PTE LTD ("the workshop") to act for me  
with respect to my claim for repair costs and/or ~~rental~~ and/or loss of use ("claim") for my vehicle  
no. SWN 5454K that was damaged pursuant to the accident which occurred on 09/06/2016  
(date) along ELP EXPRESSWAY BEFORE MARINE PARADE <sup>EXIT</sup> (location) involving vehicle no/s  
SJK 8004 S ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 09 (day) of JUNE (month) 2016 (year)



Signed by "the third party claimant"

(with chop if applicable)



Signed by "the workshop"

(with chop)

I provide always that this discharge of my  
responsibility for damages relating to the damage  
to my vehicle shall not prejudice or  
prevent me from making a further  
claim for special damages for my  
losses sustained in the same accident.

**RELEASE VOUCHER**  
**(AIG Express Third Party Claim)**

"We/I, N-51 AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,486.00 (Repair Cost), S\$ — (Loss of ~~rental~~/use), S\$ 167.85 (Disbursement), for vehicle no. SGW 5954 K that was damaged pursuant to the accident which occurred on 07/06/16 (date) along ELP EXPRESSWAY PASIR MARINE PARADE EXIT (location) involving vehicle no/s SJK 8004 S. This is pursuant to the inspection conducted on 12/10/2016 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner OTHELLO ("the third party claimant") of vehicle no. SGW 5954 K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGW 5954 K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of Nov. (month) 2016 (year)



LKK

Signed by appointed surveyor



[Signature]

Signed by "the workshop" (with chop)

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921

Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

AIG ASIA PACIFIC INSURANCE PTE. LTD.

NO. 78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

OTHELLO .

BLK 106 TOWER ROAD #06-438

SINGAPORE 322106

Contact : 62999282 90674660

## TAX INVOICE

Date : 31/07/2018

Date in : 09/06/2016

Vehicle Num. : SGW5954K

Make/Model : HYUNDAI VERNA 1.4 AUTO-2006

Chassis/Eng# : KMHCM41AR7U126615/G4EE6650518

Accident Date : 09/06/2016

Claim No : CLM13572

Reference : JUN-29/2016

Policy No. : 5080624581 (25/05/2017)

Amount S\$  
9,800.00

LUMP SUM REPAIR BILL

REF : CLM13572 - N51 DATED 13/10/2016

BY DIRECT



|           |                      |           |
|-----------|----------------------|-----------|
| E. & O.E. | Sub S\$ :            | 9,800.00  |
|           | Add GST ( 7% ) S\$ : | 686.00    |
|           | Total Amount S\$ :   | 10,486.00 |

for N-51 AUTOMOTIVE PTE LTD





## ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719  
Telephone : 6747 7400 Email: islandrecovery@ymail.com  
Facsimile : 6844 7233 Web: www.islandrecovery.com.sg  
Co. Reg. 53120056L GST Reg. No: M90370499P

Cash Sales/ Work Order

NO. 1103941

Date: 09/06/16

M/S:

H-51

Vehicle No:

SHW 5954 K.

Model :

AVANTE

From:

ECP FORM RD.

Time Start:

To:

AVIO HUB #01-18

Time End:

Remarks:

ACCIDENT

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Loaded

☐ Basement/ Multi Carpark

☐ Low Body Kit/ Low Spoiler

☐ Open Door

\$ 50/-

☐ Using King Doiley

☐ Dismantle Brake/ Shaft

☐ Crane Up/ Winch Out

GST 7% 3.5/-

AMOUNT S\$

53.50/-

bizSAFE<sub>3</sub>

Important Note:

Received By

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

YIC3697R  
CHUAN  
Island Recovery Services

AUTOBAY TOWING  
1 Kaki Bukit Avenue  
#01-55 AutoBay @ Kaki Bukit  
Singapore 417883  
Tel: 9015 8686 (Ah Soon)

## CASH SALE

(N-51)

No. \_\_\_\_\_

Sold to: \_\_\_\_\_

SGW 5954K

Date: 10/6/16

| Item       | Quantity | Description           | Unit Price  | Amount |
|------------|----------|-----------------------|-------------|--------|
|            |          | Auto Hubs to Ubi: 100 |             | 100    |
|            |          | Reported Two Trips    |             |        |
|            |          |                       |             |        |
|            |          |                       |             |        |
|            |          |                       |             |        |
|            |          |                       |             |        |
|            |          |                       |             |        |
|            |          |                       |             |        |
| E. & O. E. |          |                       | Sub Total : |        |
|            |          |                       | GST Tax :   |        |
|            |          |                       | Total :     | 100    |

Issued by: \_\_\_\_\_



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 10 Jun 2016 / 11:47:14

Receipt Date/Time : 10 Jun 2016 / 11:47:14

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-160610-000684

Previous Receipt No. :

| S/N Item Description/<br>Business Transaction Reference<br>No. | Amount<br>Before<br>GST (S\$) | GST<br>Amount<br>(S\$) | Amount<br>After GST<br>(S\$) |
|----------------------------------------------------------------|-------------------------------|------------------------|------------------------------|
|                                                                |                               |                        |                              |
| Result of Insurance Enquiry - SJX8004S                         |                               |                        |                              |
| As at 09 Jun 2016/15:45:00                                     |                               |                        |                              |
| Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.             |                               |                        |                              |
| 1 Insurance Enquiry - SJX8004S                                 |                               |                        |                              |
| Enquiry Fee                                                    | 5.00                          | 0.35                   | 5.35                         |
| 20160610114431133310                                           |                               |                        |                              |
| <b>Sub-Total</b>                                               | 5.00                          | 0.35                   | 5.35                         |
| <b>Total Before Rounding</b>                                   | 5.00                          | 0.35                   | 5.35                         |
| <b>Rounding Difference</b>                                     |                               |                        | 0.00                         |
| <b>Total Amount Payable</b>                                    |                               |                        | 5.35                         |
| Paid By                                                        |                               |                        |                              |
| xxxxxxxxxxxx4258                                               | Credit Card:                  |                        | 5.35                         |
|                                                                | Visa/MasterCard               |                        |                              |
| <b>Total</b>                                                   |                               |                        | 5.35                         |
| <b>Cash Change</b>                                             |                               |                        | 0.00                         |
| <b>Tendered Amount</b>                                         |                               |                        | 5.35                         |
| <b>Excess Refundable Amount</b>                                |                               |                        | 0.00                         |

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-16-066538

Date of Request: 14/06/2016

Your Ref No: WALK IN MAXAM

N-51 AUTOMOTIVE PTE LTD  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
SINGAPORE 417921

Dear Sir/Madam,

Your Vehicle No: SGW5954K

Date of Accident: 09/06/2016

Place of Accident: ECP EXPRESSWAY BEF MARINE PARADE EXIT

Involving Vehicle No: SHD1899B, SJX8004S, SGP1606D, SBE8113E

| DESCRIPTION                      | AMOUNT (S\$) |
|----------------------------------|--------------|
| E-File Search Fee (Public)       | 14.02        |
| GST Amount                       | 0.98         |
| Total Amount Due (GST Inclusive) | 15.00        |

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

10 Anson Road, #06-16 International Plaza, Singapore 079903

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-16-066539

Date of Request: 14/06/2016

Your Ref No: WALK IN MAXAM

N-51 AUTOMOTIVE PTE LTD  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
SINGAPORE 417921

Dear Sir/Madam,

Date of Accident: 09/06/2016

Vehicle No: SGW5954K

Place of Accident: ECP B4 MARINE PARADE EXIT

Involving Vehicle No: SJX8004S

With reference to your application for the accident report, we have attached the following accident reports as requested:

| DOCUMENTS                        | ACCIDENT LOCATION         | PER DOC (S\$) | QTY | AMOUNT (S\$) |
|----------------------------------|---------------------------|---------------|-----|--------------|
| SJX8004S                         | ECP B4 MARINE PARADE EXIT | 14.00         | 1   | 13.08        |
| GST Amount                       |                           |               |     | 0.92         |
| Total Amount Due (GST Inclusive) |                           |               |     | 14.00        |

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                   |                                                      |                                                |            |                                                                 |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 10 Jun 2016<br><a href="#">Edit Reg</a> |               | 10 Jun 2016 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$9,800.00</b><br><a href="#">Edit Estimates</a> | <b>S\$9,800.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

|                             |                                                                                                                           |                        |                                                                              |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|
| Insured:                    | OCEANVISION PTE LTD, Co. Reg. No.: 199405332D                                                                             |                        |                                                                              |
| Main Claimant:              | OTHELLO, Co. Reg. No.: 53337503K                                                                                          |                        |                                                                              |
| Vehicle Reg. No.:           | SGW5954K                                                                                                                  | Date of Loss:          | 09/06/2016 00:00 - :59<br>[107 Months and 8 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 8653337110SG                                                                                                         | Policy/Cover Note No.: | 2100083660                                                                   |
| Vehicle Reg. No. (Insured): | SJX8004S                                                                                                                  | Policy No. (Claimant): | 5080624581                                                                   |
|                             |                                                                                                                           | Excess:                |                                                                              |
| Repairer:                   | N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051            |                        |                                                                              |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kumar, Arulmani] arulmanikumar@aig.com |                        |                                                                              |
| Claimant's Insurer:         | NTUC Income Insurance Co-operative Ltd (HQ) - Tel:                                                                        |                        |                                                                              |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/06/2016]            |                        |                                                                              |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG\_EXPRESS (12/12/2018): Alert - Adj Mandate Approved (S\$10673.85) - SGW5954K - Claim Handler: Kumar, Aru...

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

\*SGW5954K (8653337110SG)  
[SJX8004S]  
TP  
OTHELLO  
Jun 9 2016 12:00AM  
[OCEANVISION PTE LTD]  
N-51 Automotive Pte Ltd

|                                                                                                                                                                     |                 |                                                                                                         |                                                                                 |                                              |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|----------------------------------------------|
| <a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a> |                 |                                                                                                         | <b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>    |                                              |
| <b>Letters/Correspondences</b>                                                                                                                                      |                 |                                                                                                         |                                                                                 |                                              |
|                                                                                                                                                                     |                 |                                                                                                         | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |                                              |
| No                                                                                                                                                                  | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                                                                       | Thumbnail                                                                       | Print                                        |
| 1                                                                                                                                                                   | (Draft)         | Third Party Express Settlement – Payment Breakdown                                                      |                                                                                 | Edit                                         |
| <b>Assessment Reports</b>                                                                                                                                           |                 |                                                                                                         |                                                                                 |                                              |
|                                                                                                                                                                     |                 |                                                                                                         | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |                                              |
| No                                                                                                                                                                  | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                                               | Thumbnail                                                                       | Print                                        |
| 1                                                                                                                                                                   | 14/06/16 14:07  | <b>Accident Statement</b><br><small>From: SC - Reg. No: SJX8004S, Claimant: OCEANVISION PTE LTD</small> |                                                                                 | Load HTM                                     |
| <b>Photos/Images</b>                                                                                                                                                |                 |                                                                                                         |                                                                                 |                                              |
|                                                                                                                                                                     |                 |                                                                                                         | 3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |                                              |
| No                                                                                                                                                                  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                                                       | Thumbnail                                                                       | Print                                        |
| 1                                                                                                                                                                   | 14/06/16 10:05  | Chassis Number                                                                                          |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 2                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 3                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 4                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 5                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 6                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 7                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 8                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 9                                                                                                                                                                   | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 10                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 11                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 12                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 13                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 14                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 15                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 16                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 17                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 18                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 19                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 20                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 21                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 22                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 23                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 24                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 25                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 26                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 27                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 28                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 29                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |
| 30                                                                                                                                                                  | 14/06/16 10:06  | General View                                                                                            |                                                                                 | Load JPG <input checked="" type="checkbox"/> |

| Letters/Correspondences |                |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 31                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 32                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 33                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                      | 14/06/16 10:06 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                      | 14/06/16 10:06 | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 54                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 55                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 56                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 57                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 58                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 59                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 60                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61                      | 14/06/16 10:06 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62                      | 23/04/18 19:32 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 63                      | 23/04/18 19:32 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 64                      | 23/04/18 19:32 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 65                      | 23/04/18 19:32 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 66                      | 23/04/18 19:32 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 67                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 68                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 69                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 70                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 71                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 72                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 73                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 74                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 75                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 76                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 77                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 78                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 79                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 80                      | 23/04/18 19:33 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                 |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 81                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 82                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 83                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 84                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                      | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 100                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 101                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 102                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 103                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 104                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 105                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 106                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 107                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 108                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 109                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 110                     | 23/04/18 19:33  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation           |                 |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 1                       | 10/06/16 17:11  | NOTIFICATION FROM WORKSHOP        |  Load PDF |                                     |
| 2                       | 10/06/16 17:11  | EMAIL FROM AIG DD 10062016        |  Load PDF |                                     |
| 3                       | 14/06/16 10:04  | TP GIA REPORT & POLICE REPORT     |  Load PDF |                                     |
| 4                       | 27/07/16 11:02  | LETTER TO OI                      |  Load PDF |                                     |
| 5                       | 24/04/18 10:15  | TP ESTIMATE - MARKED              |  Load PDF |                                     |
| 6                       | 15/10/18 15:18  | EMAIL TO AIG                      |  Load PDF |                                     |
| 7                       | 15/10/18 15:23  | EMAIL TO TP                       |  Load PDF |                                     |
| 8                       | 10/12/18 09:38  | GIA SEARCH                        |  Load PDF |                                     |
| 9                       | 10/12/18 09:38  | LTA SEARCH                        |  Load PDF |                                     |
| 10                      | 10/12/18 09:38  | TOWING FEE                        |  Load PDF |                                     |
| 11                      | 28/01/19 09:28  | WORKSHOP INVOICE                  |  Load PDF |                                     |
| 12                      | 28/01/19 09:28  | AUTHORISATION TO ACT FORM         |  Load PDF |                                     |
| 13                      | 28/01/19 09:28  | Release Voucher                   |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|----------------------------------------------|-------|------|-------|
| There are no document checklists configured. |       |      |       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                       |
|-------------------|---------------------|--------|-----------------------|
| Vehicle No:       | SJX8004S (Insd veh) | Model: | HYUNDAI VERNA 1.4 (A) |
|                   | SGW5954K (TP veh)   |        |                       |
| Date of Accident: | 09/06/2016          |        |                       |

|                       |   |                              |                                        |                        |
|-----------------------|---|------------------------------|----------------------------------------|------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |                        |
| Repair Estimate       | : | \$                           | 38,731.39                              |                        |
| Final Repair Cost     | : | \$                           | 10,486.00                              |                        |
| Loss of Use           | : | \$                           |                                        | days at \$0.00 per day |
| Rental (if any)       | : | \$                           | 0.00                                   | days                   |
| LTA / GIA Search Fee  | : | \$                           | 34.35                                  |                        |
| Others: Towing Fee    | : | \$                           | 153.50                                 |                        |
|                       | : | \$                           |                                        |                        |
| Final Settlement Sum  | : | \$                           | 10,673.85                              |                        |

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ 0 \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                         |   |              |
|----------------------------------------|-------------------------|---|--------------|
| 1)                                     | N-51 Automotive Pte Ltd | : | \$ 10,673.85 |
| 2)                                     |                         | : | \$           |
| 3)                                     |                         | : | \$           |

JOANNE LEE KHANG MIN

28 Jan

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG16010792/AHA3Q2

Date: 28/01/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100083660  
**Claimant Vehicle No :** SGW5954K **Insured Vehicle No :** SJX8004S  
 Date of Loss: 09/06/2016 Nature of Claim: TP Claim No: 8653337110SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW5954K**  
 Make & Model: HYUNDAI VERNA, 1.4 (A) Engine No: G4EE6650518  
 Reg. Date: 01/07/2007 (Man. Year: 2007) Chassis No: KMHCM41AR7U126615  
 Colour: Silver Odometer: 0 km  
 Engine Capacity: 1399 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's       | Difference       | Diff %       |
|------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                    | 28,867.56        | 11,569.76        | 17,297.80        | 59.92        |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00             |              |
| Labour                                   | 7,330.00         | 5,280.00         | 2,050.00         | 27.97        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00             |              |
| Towing                                   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>36,197.56</b> | <b>16,849.76</b> | <b>19,347.80</b> | <b>53.45</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>9,800.00</b>  |                  |              |
| (S\$)                                    | 36,197.56        | 9,800.00         | 26,397.56        | 72.93        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>2,533.83</b>  | <b>686.00</b>    | <b>1,847.83</b>  | <b>72.93</b> |
| <b>Nett Amount (S\$)</b>                 | <b>38,731.39</b> | <b>10,486.00</b> | <b>28,245.39</b> | <b>72.93</b> |
| <b>+ Doc/Search Fee (S\$)</b>            |                  | <b>34.35</b>     |                  |              |
| <b>+ Other Costs (S\$)</b>               |                  | <b>153.50</b>    |                  |              |
| <b>Nett Liability (S\$)</b>              |                  | <b>10,673.85</b> |                  |              |

### INSPECTION

Date of Assignment: 10/06/2016  
 Date Inspected: 13/06/2016 Inspected At: N-51 Automotive Pte Ltd (HQ)  
 BLK 2 KAKI BUKIT, #01-17/18 KAKI



BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 21.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                        | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *AIR CLEANER BOX LOWER                             | Cracked       | 48.00 FL    | *48.00 FL  |
| 2   | 1   |          | *AIR CLEANER BOX TOP                               | Cracked       | 49.00 FL    | *49.00 FL  |
| 3   | 1   |          | *AIR CLEANER BOX HOSE                              | Deformed      | 92.00 FL    | *92.00 FL  |
| 4   | 1   |          | *AIR RESONATOR BOX                                 | Not Necessary | 47.00 FL    | *- FL      |
| 5   | 1   |          | *AIR RESONATOR BOX HOSE                            | Not Necessary | 121.00 FL   | *- FL      |
| 6   | 1   |          | *AIRCON AUXILLIARY FAN ASSY                        | Distorted     | 420.00 FL   | *420.00 FL |
| 7   | 1   |          | *AIRCON CONDENSER                                  | Distorted     | 720.00 FL   | *720.00 FL |
| 8   | 2   |          | *AIRCON CONDENSER LOWER RUBBER BUSH L/R            | Necessary     | 36.00 FL    | *36.00 FL  |
| 9   | 2   |          | *AIRCON CONDENSER TOP RUBBER BUSH L/R              | Necessary     | 32.00 FL    | *32.00 FL  |
| 10  | 1   |          | *AIRCON COOLING PIPE                               | Not Necessary | 123.00 FL   | *- FL      |
| 11  | 1   |          | *AIRCON DISCHARGE PIPE                             | Not Necessary | 184.80 FL   | *- FL      |
| 12  | 1   |          | *AIRCON SUCTION PIPE                               | Not Necessary | 164.00 FL   | *- FL      |
| 13  | 1   |          | *BATTERY BRACKET                                   | Not Necessary | 15.00 FL    | *- FL      |
| 14  | 1   |          | *BATTERY LOWER PANEL                               | Not Necessary | 91.00 FL    | *- FL      |
| 15  | 1   |          | *BATTERY TRAY                                      | Not Necessary | 31.00 FL    | *- FL      |
| 16  | 1   |          | *ENGINE ALTERNATOR ASSY                            | Not Necessary | 602.00 FL   | *- FL      |
| 17  | 1   |          | *ENGINE ALTERNATOR BELT                            | Not Necessary | 27.00 FL    | *- FL      |
| 18  | 1   |          | *ENGINE MOUNTING FRT                               | Not Necessary | 281.00 FL   | *- FL      |
| 19  | 1   |          | *ENGINE MOUNTING FRT BRACKET                       | Not Necessary | 119.00 FL   | *- FL      |
| 20  | 1   |          | *EXHAUST CATALYTIC CONVERTER                       | Not Necessary | 1,955.00 FL | *- FL      |
| 21  | 1   |          | *EXHAUST CATALYTIC CONVERTER ALUMINIUM HEAT SHIELD | Not Necessary | 61.00 FL    | *- FL      |
| 22  | 1   |          | *EXHAUST CATALYTIC LAMDA SENSOR                    | Not Necessary | 321.00 FL   | *- FL      |
| 23  | 1   |          | *FRONT AIR DUCT                                    | Not Necessary | 110.30 FL   | *- FL      |
| 24  | 2   |          | *FRONT AIR DUCT CLIPS                              | Not Necessary | 13.00 FL    | *- FL      |
| 25  | 1   |          | *FRONT BONNET                                      | Distorted     | 724.00 FL   | *724.00 FL |
| 26  | 1   |          | *FRONT BONNET CABLE                                | Not Necessary | 68.00 FL    | *- FL      |
| 27  | 2   |          | *FRONT BONNET HINGES L/R                           | Bent          | 96.00 FL    | *96.00 FL  |
| 28  | 1   |          | *FRONT BONNET INNER LOCK HANDLE                    | Not Necessary | 25.00 FL    | *- FL      |
| 29  | 1   |          | *FRONT BONNET MECHANISM LOCK                       | Damaged       | 55.80 FL    | *55.80 FL  |
| 30  | 7   |          | *FRONT BONNET RUBBER GUIDE STOPPER L/R             | Not Necessary | 47.60 FL    | *- FL      |
| 31  | 1   |          | *FRONT BONNET STAND                                |               | 23.00 FL    | *- FL      |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                         | Condition                            | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------------|--------------------------------------|-------------|------------|
| 32  | 1   |          | *FRONT BONNET STAND HOLDER CLIPS    | Not<br>Necessary<br>Not<br>Necessary | 6.50 FL     | *- FL      |
| 33  | 1   |          | *FRONT BONNET WEATHER STRIP         | Cut                                  | 22.80 FL    | *22.80 FL  |
| 34  | 1   |          | *FRONT BUMPER                       | Distorted                            | 412.00 FL   | *412.00 FL |
| 35  | 1   |          | *FRONT BUMPER INNER SPONGE          | Cracked                              | 101.00 FL   | *101.00 FL |
| 36  | 1   |          | *FRONT BUMPER LOWER CENTER GRILLE   | Cracked                              | 75.80 FL    | *75.80 FL  |
| 37  | 1   |          | *FRONT BUMPER LOWER RUBBER MOULDING | Not<br>Necessary                     | 43.00 FL    | *- FL      |
| 38  | 1   |          | *FRONT BUMPER REINFORCEMENT         | Bent                                 | 195.00 FL   | *195.00 FL |
| 39  | 2   |          | *FRONT BUMPER SIDE RETAINER L/R     | Necessary                            | 56.00 FL    | *56.00 FL  |
| 40  | 1   |          | *FRONT BUMPER TOW HOOK COVER        | Deformed                             | 22.00 FL    | *22.00 FL  |
| 41  | 2   |          | *FRONT FENDER BRACKET L/R           | Not<br>Necessary                     | 36.00 FL    | *- FL      |
| 42  | 2   |          | *FRONT FENDER INNER SHIELD L/R      | Not<br>Necessary                     | 88.00 FL    | *- FL      |
| 43  | 2   |          | *FRONT FENDER L/R                   | Buckled                              | 606.00 FL   | *606.00 FL |
| 44  | 2   |          | *FRONT FENDER SIGNAL LAMP L/R       | Not<br>Necessary                     | 66.00 FL    | *- FL      |
| 45  | 1   |          | *FRONT GRILLE                       | Cracked                              | 258.00 FL   | *258.00 FL |
| 46  | 1   |          | *FRONT GRILLE LOGO EMBLEM           | Necessary                            | 28.00 FL    | *28.00 FL  |
| 47  | 4   |          | *FRONT GRILLE CLIPS                 | Necessary                            | 26.00 FL    | *26.00 FL  |
| 48  | 2   |          | *FRONT HEADLAMP BACK COVER L/R      | Not<br>Necessary                     | 79.60 FL    | *- FL      |
| 49  | 4   |          | *FRONT HEADLAMP CLIPS L/R           | Necessary                            | 26.00 FL    | *26.00 FL  |
| 50  | 2   |          | *FRONT HEADLAMP L/R                 | Cracked                              | 712.00 FL   | *712.00 FL |
| 51  | 2   |          | *FORNT HEADLAMP LOWER BRACKET L/R   | Bent                                 | 32.00 FL    | *32.00 FL  |
| 52  | 1   |          | *FRONT POWER STEERING COOLER PIPE   | Not<br>Necessary                     | 88.00 FL    | *- FL      |
| 53  | 2   |          | *FRONT SUB CHASSIS FRAME L/R        | Repair                               | 1,868.00 FL | *- FL      |
| 54  | 1   |          | *FRONT SUPPORT PANEL                | Distorted                            | 803.30 FL   | *803.30 FL |
| 55  | 1   |          | *FUSE BOX COVER ASSY                | Not<br>Necessary                     | 2,237.00 FL | *- FL      |
| 56  | 1   |          | *HORN                               | Not<br>Necessary                     | 77.00 FL    | *- FL      |
| 57  | 1   |          | *POWER STEERING BELT                | Not<br>Necessary                     | 48.00 FL    | *- FL      |
| 58  | 2   |          | *POWER STEERING HOSE                | Not<br>Necessary                     | 416.00 FL   | *- FL      |
| 59  | 1   |          | *POWER STEERING PUMP ASSY           | Not<br>Necessary                     | 785.00 FL   | *- FL      |
| 60  | 1   |          | *RADIATOR (AUTO)                    | Distorted                            | 594.00 FL   | *594.00 FL |
| 61  | 1   |          | *RADIATOR AUXILLIARY FAN ASSY       | Distorted                            | 481.00 FL   | *481.00 FL |
| 62  | 1   |          | *RADIATOR CAP                       | Not<br>Necessary                     | 18.00 FL    | *- FL      |
| 63  | 1   |          | *RADIATOR LOWER HOSE                | Not<br>Necessary                     | 40.00 FL    | *- FL      |
| 64  | 2   |          | *RADIATOR LOWER RUBBER BUSH L/R     | Necessary                            | 24.00 FL    | *24.00 FL  |
| 65  | 1   |          | *RADIATOR SPARE TANK HOSE           | Not<br>Necessary                     | 28.00 FL    | *- FL      |
| 66  | 2   |          | *RADIATOR TOP BRACKET L/R           | Bent                                 | 96.00 FL    | *96.00 FL  |
| 67  | 1   |          | *RADIATOR TOP HOSE                  | Twisted                              | 19.00 FL    | *19.00 FL  |
| 68  | 2   |          | *RADIATOR TOP RUBBER BUSH L/R       | Necessary                            | 24.00 FL    | *24.00 FL  |
| 69  | 1   |          | *REAR BOOTLID                       | Distorted                            | 729.00 FL   | *729.00 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                               | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------|---------------|-------------|--------------|
| 70  | 1   |          | *REAR BOOTLID LOGO EMBLEM                 | Necessary     | 24.00 FL    | *24.00 FL    |
| 71  | 1   |          | *REAR BOOTLID M1.4 EMBLEM                 | Necessary     | 22.00 FL    | *22.00 FL    |
| 72  | 1   |          | *REAR BOOTLID VERNA EMBLEM                | Necessary     | 28.00 FL    | *28.00 FL    |
| 73  | 2   |          | *REAR BOOTLID HINGES L/R                  | Bent          | 150.00 FL   | *150.00 FL   |
| 74  | 1   |          | *REAR BOOTLID INNER UPHOLSTERY TRIM       | Crumpled      | 132.00 FL   | *132.00 FL   |
| 75  | 1   |          | *REAR BOOTLID MECHANISM LOCK              | Damaged       | 63.00 FL    | *63.00 FL    |
| 76  | 1   |          | *REAR BOOTLID MECHANISM LOCK GARNISH      | Not Necessary | 54.00 FL    | *- FL        |
| 77  | 2   |          | *REAR BOOTLID NUMBER PLATE LAMP L/R       | Not Necessary | 122.00 FL   | *- FL        |
| 78  | 1   |          | *REAR BOOTLID OUTER GARNISH               | Cracked       | 170.00 FL   | *170.00 FL   |
| 79  | 4   |          | *REAR BOOTLID OUTER GARNISH CLIPS         | Necessary     | 26.00 FL    | *26.00 FL    |
| 80  | 1   |          | *REAR BOOTLID OUTER KEY LOCK              | Damaged       | 42.10 FL    | *42.10 FL    |
| 81  | 1   |          | *REAR BOOTLID OUTER KEY LOCK RUBBER SEAL  | Necessary     | 18.00 FL    | *18.00 FL    |
| 82  | 2   |          | *REAR BOOTLID RUBBER GUIDE STOPPER L/R    | Not Necessary | 26.20 FL    | *- FL        |
| 83  | 1   |          | *REAR BOOTLID WEATHER STRIP               | Cut           | 72.60 FL    | *72.60 FL    |
| 84  | 1   |          | *REAR BUMPER                              | Distorted     | 491.80 FL   | *491.80 FL   |
| 85  | 8   |          | *REAR BUMPER INNER SIDE SHIELD CLIPS L/R  | Not Necessary | 52.00 FL    | *- FL        |
| 86  | 2   |          | *REAR BUMPER INNER SIDE SHIELD L/R        | Not Necessary | 50.00 FL    | *- FL        |
| 87  | 1   |          | *REAR BUMPER INNER SPONGE                 | Cracked       | 82.80 FL    | *82.80 FL    |
| 88  | 1   |          | *REAR BUMPER REINFORCEMENT                | Distorted     | 136.80 FL   | *136.80 FL   |
| 89  | 1   |          | *REAR BUMPER REINFORCEMENT LOWER BRACKET  | Damaged       | 19.00 FL    | *19.00 FL    |
| 90  | 2   |          | *REAR BUMPER REINFORCEMENT TOP BRACKET    | Damaged       | 38.00 FL    | *38.00 FL    |
| 91  | 2   |          | *REAR BUMPER SIDE RETAINER L/R            | Necessary     | 46.00 FL    | *46.00 FL    |
| 92  | 1   |          | *REAR EXHAUST ALUMINIUM HEAT SHIELD       | Crumpled      | 85.00 FL    | *85.00 FL    |
| 93  | 1   |          | *REAR EXHAUST GASKET                      | Necessary     | 8.50 FL     | *8.50 FL     |
| 94  | 2   |          | *REAR EXHAUST RUBBER MOUNTING             | Not Necessary | 39.00 FL    | *- FL        |
| 95  | 1   |          | *REAR EXHAUST SILENCER BOX                | Bent          | 442.50 FL   | *442.50 FL   |
| 96  | 1   |          | *REAR LH FENDER                           | Buckled       | 1,023.00 FL | *1,023.00 FL |
| 97  | 1   |          | *REAR LH FENDER INNER AIR VENT            | Not Necessary | 28.00 FL    | *- FL        |
| 98  | 1   |          | *REAR LH FENDER INNER PANEL               | Repair        | 897.00 FL   | *- FL        |
| 99  | 1   |          | *REAR LH FENDER INNER UPHOLSTERY TRIM     | Deformed      | 138.00 FL   | *138.00 FL   |
| 100 | 1   |          | *REAR LH FENDER PETROL LID COVER          | Not Necessary | 55.00 FL    | *- FL        |
| 101 | 1   |          | *REAR LH FENDER PETROL LID MECHANISM LOCK | Not Necessary | 48.00 FL    | *- FL        |
| 102 | 1   |          | *REAR RH FENDER                           | Buckled       | 1,023.00 FL | *1,023.00 FL |
| 103 | 1   |          | *REAR RH FENDER INNER AIR VENT            | Not Necessary | 28.00 FL    | *- FL        |
| 104 | 1   |          | *REAR RH FENDER INNER PANEL               | Repair        | 897.00 FL   | *- FL        |
| 105 | 1   |          | *REAR RH FENDER INNER UPHOLSTERY TRIM     | Torn          | 165.00 FL   | *165.00 FL   |
| 106 | 1   |          | *REAR SPEAKER PANEL                       | Repair        | 378.00 FL   | *- FL        |
| 107 | 1   |          | *REAR SPEAKER PANEL TOP UPHOLSTERY BOARD  | Not Necessary | 339.00 FL   | *- FL        |
| 108 | 2   |          | *REAR SUB CHASSIS FRAME L/R               | Repair        | 2,190.00 FL | *- FL        |
| 109 | 4   |          | *REAR TAILLAMP CLIPS                      | Necessary     | 26.00 FL    | *26.00 FL    |
| 110 | 2   |          | *REAR TAILLAMP INNER PANEL L/R            | Dented        | 940.00 FL   | *204.00 FL   |
| 111 | 2   |          | *REAR TAILLAMP L/R                        | Cracked       | 476.00 FL   | *476.00 FL   |
| 112 | 2   |          | *REAR WHEEL HOUSE PANEL ASSY L/R          | Repair        | 1,794.00 FL | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                     | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------------------|---------------|------------|------------|
| 113 | 10  |          | *REAR WINDSCREEN INNER GARNISH CLIPS L/R        | Not Necessary | 65.00 FL   | *- FL      |
| 114 | 2   |          | *REAR WINDSCREEN INNER GARNISH L/R              | Not Necessary | 142.00 FL  | *- FL      |
| 115 | 1   |          | *REAR WINDSCREEN MOULDING                       | Necessary     | 47.80 FL   | *47.80 FL  |
| 116 | 1   |          | *SPARE TYRE PANEL                               | Distorted     | 468.10 FL  | *468.10 FL |
| 117 | 1   |          | *SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD    | Deformed      | 339.00 FL  | *215.00 FL |
| 118 | 1   |          | *SPARE TYRE RETAINER LOCK                       | Bent          | 25.00 FL   | *25.00 FL  |
| 119 | 2   |          | *SPARE TYRE SIDE PANEL L/R                      | Repair        | 196.00 FL  | *- FL      |
| 120 | 1   |          | *WASHER TANK                                    | Not Necessary | 35.00 FL   | *- FL      |
| 121 | 1   |          | *WASHER TANK MOTOR                              | Not Necessary | 72.00 FL   | *- FL      |
| 122 | 1   |          | *BATTERY                                        | Not Necessary | 380.00 FS  | *- FS      |
| 123 | 1   |          | *SET FRONT BUMPER CLIPS                         | Necessary     | 30.00 FS   | *30.00 FS  |
| 124 | 1   |          | *FRONT BUMPER NUMBER PLATE                      | Bent          | 25.00 FS   | *25.00 FS  |
| 125 | 1   |          | *FRONT BUMPER NUMBER PLATE HOLDER               | Deformed      | 50.00 FS   | *30.00 FS  |
| 126 | 2   |          | *SET FRONT FENDER INNER SHIELD CLIPS L/R        | Not Necessary | 60.00 FS   | *- FS      |
| 127 | 2   |          | *FRONT HEADLAMP BULB L/R                        | Not Necessary | 80.00 FS   | *- FS      |
| 128 | 2   |          | *FRONT HEADLAMP PARKING BULB L/R                | Not Necessary | 20.00 FS   | *- FS      |
| 129 | 2   |          | *FRONT HEADLAMP SIGNAL BULB L/R                 | Not Necessary | 30.00 FS   | *- FS      |
| 130 | 1   |          | *BOT POWER STEERING FLUID                       | Not Necessary | 25.00 FS   | *- FS      |
| 131 | 1   |          | *BOT RADIATOR COOLANT                           | Necessary     | 80.00 FS   | *40.00 FS  |
| 132 | 1   |          | *SET REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS   | Necessary     | 30.00 FS   | *30.00 FS  |
| 133 | 1   |          | *REAR BOOTLID NUMBER PLATE                      | Bent          | 25.00 FS   | *25.00 FS  |
| 134 | 1   |          | *REAR BOOTLID NUMBER PLATE HOLDER               | Deformed      | 50.00 FS   | *30.00 FS  |
| 135 | 1   |          | *SET REAR BOOTLID REFLECTOR STICKER L/R         | Not Necessary | 190.00 FS  | *- FS      |
| 136 | 1   |          | *SET REAR BUMPER CLIPS                          | Necessary     | 30.00 FS   | *30.00 FS  |
| 137 | 1   |          | *SET REAR BUMPER REVERSE SENSOR                 | Damaged       | 350.00 FS  | *200.00 FS |
| 138 | 1   |          | *SET REAR BUMPER RIVET                          | Necessary     | 40.00 FS   | *40.00 FS  |
| 139 | 1   |          | *SET REAR LH FENDER INNER UPHOLSTERY TRIM CLIPS | Necessary     | 30.00 FS   | *30.00 FS  |
| 140 | 1   |          | *SET REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS | Necessary     | 30.00 FS   | *30.00 FS  |
| 141 | 2   |          | *REAR SPEAKER PANEL SPEAKER L/R                 | Not Necessary | 360.00 FS  | *- FS      |
| 142 | 4   |          | *REAR TAILLAMP BRAKE BULB L/R                   | Not Necessary | 48.00 FS   | *- FS      |
| 143 | 2   |          | *REAR TAILLAMP REVERSE BULB L/R                 | Not Necessary | 24.00 FS   | *- FS      |
| 144 | 2   |          | *REAR TAILLAMP SIGNAL BULB L/R                  | Not Necessary | 24.00 FS   | *- FS      |
| 145 | 1   |          | *REAR WINDSCREEN SEALANT                        | Necessary     | 100.00 FS  | *60.00 FS  |
| 146 | 1   |          | *SPARE TYRE                                     | Not Necessary | 280.00 FS  | *- FS      |
| 147 | 1   |          | *SPARE TYRE PANEL INNER BRAKE DOWN SIGN         | Not Necessary | 150.00 FS  | *- FS      |
| 148 | 1   |          | *SPARE TYRE PANEL INNER JACKING TOOL            | Not Necessary | 180.00 FS  | *- FS      |
| 149 | 1   |          | *SPARE TYRE PANEL INSULATOR MAT                 | Necessary     | 350.00 FS  | *150.00 FS |

Report was unsubmitted during this print-out.

| No.                                                | Qty | Part No. | Particulars | Condition | Repairer's | Amount    |
|----------------------------------------------------|-----|----------|-------------|-----------|------------|-----------|
| F=Franchise part. S=SpcNett. L=ListItemDisc.       |     |          |             |           |            |           |
| Sub Total (S\$)                                    |     |          |             |           | 35,316.70  | 14,274.70 |
| - List Item Discount on L Items 20.00/20.00% (S\$) |     |          |             |           | 6,449.14   | 2,704.94  |
| Total Parts (S\$)                                  |     |          |             |           | 28,867.56  | 11,569.76 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                                                   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                                                               |          |                 |                 |
| 1                              | TO REMOVE ,CHARGE AIR CON PARTS ,VACUUMS ,REFILL AIR CON GAS                                                                                                                  | New      | 180.00          | 120.00          |
| 2                              | TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR                                                     | New      | 180.00          | 100.00          |
| 3                              | TO REMOVE AND REFIT REAR WINDSCREEN (TO FR)                                                                                                                                   | New      | 150.00          | 120.00          |
| 4                              | TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT, TRIM GARNISH ,TRIN LINER CARPET (TO FR)                                                                          | New      | 140.00          | 80.00           |
| 5                              | TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL ,REAR FENDER (L/R) ,SPARE TYRE PANEL ,REAR BUMPER ,REAR DOORS (L/R), AND ROOF TOP PANEL                              | New      | 2,000.00        | 1,400.00        |
| 6                              | TO RE-SPRAY PAINTING ON THE FRONT BONNET ,FRONT SUPPORT PANEL ,FRONT FENDER (L/R) AND FRONT BUMPER                                                                            | New      | 1,250.00        | 800.00          |
| 7                              | TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT                                                                      | New      | 160.00          | 80.00           |
| 8                              | TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT | New      | 2,750.00        | 2,500.00        |
| 9                              | TO MOUNT VEHICLE ON TO CARO LINER                                                                                                                                             | New      | 400.00          | 0.00            |
| 10                             | TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL                                                                                                                    | New      | 120.00          | 80.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                                               |          | <b>7,330.00</b> | <b>5,280.00</b> |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;