

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05385

Vehicle Insured : SKH2017S
Accident Date : 18-Jun-2016

Date : 21-Jun-2016

Our Ref : 216095 (AXA) / CHAN

PAGE : 1

LIM KAI KUANG
3 ROBIN WALK
Singapore 258148

*Not Ashok
1.B.1
Resurvey BY paint*

ESTIMATED COST OF REPAIR FOR PORSCHE BOXSTER TIP EY928H

1 pc	Rear bumper fascia		<i>Pr</i> 1,484.50	✓
1 pc	Rear bumper top garnish		<i>Pr</i> 77.50	✓
1 pc	Rear bumper reinforcement		680.70	?
1 pc	Rear bumper inner sponge		121.50	?
1 pc	Rear bumper reinforcement covr		88.50	?
1 pc	Rear reinforcement absorber		83.60	?
1 pc	Rear reinforcement absorber seal		11.20	?
2 pcs	Rear bumper side retainer	@ S\$206.70	<i>MSD</i> 413.40	✓
2 pcs	Rear license plate lamp	@ S\$ 72.30	<i>CM</i> 144.60	✓
1 pc	Rear end panel		582.40	?
1 pc	Rear exhaust silencer box		<i>Pr</i> 3,215.50	✓
2 pcs	Rear exhaust connecting joint	@ S\$ 88.90	<i>Pr</i> 177.80	✓
2 pcs	Taillamp	@ S\$511.40	1,022.80	?
			8,104.00	
		Less 10% :	810.40	

CM 7,293.60 *2cm*
30.00 sn

1 pc Rear no plate

To remove rear boot carpet, side trim for renew end panel

120.00 *for*

To apply undersealing

80.00 ?

To putty and spray replaced parts

800.00 *Foot*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

900.00 ?

Total : S\$ 9,223.60

Singapore Dollars Nine Thousand and Two Hundred and Twenty Three and Cents Sixty Only

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To supply damaged part(s) during resurvey
- Part(s) are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: